

ASS. REC. BY:

REF

CS/MSG18010055/Dtd3

Special Instruction:

Surveyor
Menimen

Bryan

ASSIGNMENT (Office)

Mund Ashik

of

MSG

Date/Time: 1/6/18 @ 4:16pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHA 4661R

Insured:

SGK 6869E

at Workshop m/s

Chunni Motor

Tel:

68425119

of

Blk 10 # 01-05/06 TMK Autopoint

Policy No:

28809474QMY

Claim No:

Sum Insured:

Excess:

Make of Veh:

D.O.A. 31/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

(up)

H.O.D. Endorsement:

Date/Time:

9:57am 3/6/18

Person Contacted:

Irene

Vehicle ☒ IN ☐ OUT

Date/Time	Action/Instruction (✓) Estimate	
	SHA 4661R-NBA/MSG18009956/Y	DOA: 31/05/2018
	SGK 6869E-NBA/MSG18009956/Y	DOA: 31/05/2018
14/6-	Revert via menimen preli advise	
	Bryan say comfort price is like this	

Signature

ASSIGNMENT

C.O.E. Jan 2025

From: _____ Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____


Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: 9 ~~days~~ days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____ Person Contacted: _____

Vehicle: IN / OUT

Veh No: SHA 4661 R Yr Regn: 2017, Jan

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1685

Colour: Blue A/C: Insured / Std / NI / NA

Sp. Reading: 182339 T/Radio: Insured / Std / NI / NA

Eng/No: D4FDGU706870

C/No: KMHLB41WMH4098287

Gen. Cond: ☒ Good / Fair / Poor / BurntSteering: ☒ In Order / Jammed / Leaked / Burnt orBrake: ☒ In Order / Jammed / Leaked / Burnt orModi: ☒ N / S/Rim / STD A/Rim or

Tyre Size: F: 205/60 R16

R: — " —

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Camper

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 31/05/2018 D.O.I. 04/06/2018

Survey held at Churi AMK

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

N/S Front

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
02/07/18	M31G 86K 6869E Final report L/S 9650/- with 9 days delay. (Red: 8360 to 4610)

RECEIVED 02 JUL 2018

Date/Time, File Pass to?

JFA Typist
Date/Time, File Return to?
☐ : Preli. Report
☒ : Final Report

Days Of Repair: 9

Resurvey No. of Trip: 2

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)

Survey Fee:

Transportation:

S + RS. 31

Photos

Others

TOTAL

Report Format: TP

Lump Sum / I.B.I: (\$ 9650/-)

NAME
ADDRESS

Home Tel.:

VIN:

Registration: SHA 4661 R

Technician:

Mileage: 182339

Time Printed 4.6.18 11:30 AM

HYUNDAI I40

Front : Left

Actual	BEFORE	Specified Range
8°19'		-3°00' 3°00'
3°51'		-0°19' 5°41'
27°50'		-1°30' 1°30'
12°02'		
20°20'		

Camber
Caster
Toe
SAI
Included Angle
Turning Angle Diff.

Front : Right

Actual	BEFORE	Specified Range
2°23'		-3°00' 3°00'
4°02'		-0°19' 5°41'
0°01'		-1°30' 1°30'
14°37'		
17°00'		

Front

	Actual	BEFORE	Specified Range
Cross Camber	5°55'		-3°00' 3°00'
Cross Caster	-0°11'		-3°00' 3°00'
Cross SAI	-2°35'		-3°00' 3°00'
Total Toe	27°52'		-3°00' 3°00'
Cross Turn Diff.			

Rear : Left

Actual	BEFORE	Specified Range
-0°38'		-3°30' 2°30'
0°12'		-1°30' 1°30'

Camber
Toe

Rear : Right

Actual	BEFORE	Specified Range
-0°26'		-3°30' 2°30'
-0°01'		-1°30' 1°30'

Rear

	Actual	BEFORE	Specified Range
Cross Camber	-0°11'		-3°00' 3°00'
Total Toe	0°11'		-3°00' 3°00'
Thrust Angle	0°06'		-3°00' 3°00'

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins. Auth'd	Status
Main	01 Jun 2018		01 Jun 2018 16:16 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	VINOD KUMAR RAMGOPAL DIDWANIA, ID: S2601458A		
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R		
Vehicle Reg. No.:	SHA4661R	Date of Loss:	31/05/2018 10:00 - :59 [16 Months and 6 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP	Policy/Cover Note No.:	28809474QMY (Comprehensive) Coverage: 16/08/2017 - 15/08/2018
Vehicle Reg. No. (Insured):	SGK6869E	Policy No. (Claimant):	
		Excess:	
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 02/06/2018]		
Adj Asg. Remarks:	on WP Survey agreed on SJE OI NOT REPORTED CONTACT : LYNN OR IRENE AT 65425119 OR 65427162		

ASSOCIATED MAIL RECEIVED

[View All](#) [Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010055/Dtd3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-06-2018

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SGK 6869E	Veh. Inspected	SHA 4661R
Policy No.	A28809474QMY	Coverage (\$)	0.00
Claim No.	560089	Excess (\$)	0.00
Assign From	MERIMEN (MUHD ASHIK)	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	31/05/2018	Inspection Date	04/06/2018
Survey held at	CHUNNI MOTOR WORK PTE LTD BLK 10 ANG MO KIO IND. PARK 2A, #03-19 AMK AUTOPOINT SINGAPORE 568047.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Muhd Ashik B Madi

Date: 14 Jun 2018

Preliminary Advice

Insured Vehicle No	: SGK6869E	Accident Date	: 31/05/2018
TP Vehicle No	: SHA4661R	Assignment Date	: 01/06/2018
Make	: HYUNDAI I40	Est. Duration of Repair	: 7.00
Date of Inspection	: 04/06/2018		
Inspection At	: CHUNNI MOTOR WORK PTE LTD - AMK (HQ) BLK 10 #01-05/06, AMK AUTOPOINT SINGAPORE 568047		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages n/s front portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	18,010.56
Revised Amount	:S\$	12,093.24
Check Items (Estimated)	:S\$	0.00
Total	:S\$	12,093.24
Lump Sum Repair	:S\$	

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (x) The above survey was conducted on a 'without prejudice' basis.

MCD618070898 / ComfortDelGro Engineering Pte Ltd - Loyang
 ENTRY DATE & TIME: 01/06/2018 08:39
 SUBMITTED BY: Janet Lim Siong Gek

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	01/06/2018 08:39
Date Of Accident	31/05/2018 10:40
Exact Location Of Accident	CTE TUNNEL TWDS AYE BEFORE HAVELOCK RD EXIT
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHA4661R
Insured/Policyholder	
Name Of Registered Owner	COMFORT TRANSPORTATION PTE LTD
Co Reg No	199303821R
Email Address	FLEETSAFETY@CDGTAXI.COM.SG
Mobile Phone No	
Alternative Phone No	OFFICE-65508768
Vehicle Particulars	
Manufacturer	HYUNDAI
Model	I40
Exact Purpose for which vehicle was being used at time of accident	
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI
Insurance Company	
Name of Insurance Company	INDIA INTERNATIONAL INSURANCE PTE LTD
Type Of Coverage	THIRD PARTY FIRE AND/OR THEFT
Fleet Policy	YES
Policy Number	MCOM0015
Cover Note Number	
Driver	
Name of Driver	LUAH TIAN HWA
NRIC No	S1060482F
Date Of Birth	07/08/1947
Occupation	OUTDOOR
Date Of Driving Pass	16/04/1970
Driving Experience	48 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-98177900
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address BLK 639 ROWELL ROAD
#06-98
Postcode 200639
Was driver an employee of the Insured's Company NO
If No, Relationship of the Driver with the Insured OTHER - TAXI DRIVER
Vehicle Registration Number of Driver's Own Vehicle -
-
Insurance Company of Driver's Own Vehicle -
-

General Information of the Accident

Type Of Accident SIDE SWIPE
Weather Conditions CLEAR
Road Surface DRY

Other Information

Was any foreign vehicle involved in this accident? NO
Number of vehicles involved in the accident 2
Was any body injured in the Accident? NO
Was any injured conveyed to hospital by ambulance? NO
Was any other material or property damaged? YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance. NO
Number of Passengers (Including Driver) 2
Passenger 1 NAME: : -
GENDER: : MALE

Details of Police Action

Was the accident reported to the police? NO
If Yes, Please state which Police Station
Was notice of intended Prosecution given? NO
If Yes, against whom?

Circumstances of Accident

REFER ATTACHED


Attachment(s)

Are accident photos available for attachment? YES
Was there any video captured by Car Camera? YES
Remarks/ Reasons: -
Was there any audio recorded? NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SGK8869E
Vehicle Make/Model/Colour
Details Of Properties
Vehicle Category PRIVATE CAR
Name of Driver
NRIC/Passport Number S89107051
Contact Number
Address
Postcode
Insurance Company Name
Nature Of Damage FRONT RIGHT

SKETCH PLAN



Along CTE Tunnel Twds AYE Before Havelock Rd Exit.

DESCRIBE CIRCUMSTANCES OF THE ACCIDENT

On 31.05.2018 at about 10:40 Hrs, I was traveling along CTE Tunnel towards AYE before
Havelock Rd exit with one male passenger on board.
I was traveling on the extreme right lane. Suddenly, veh (B) (SGK 6869E) which was traveling on
my left cut into my lane. Thus collided onto my taxi (A) front left portion. As it took place so fast,
I could not take evasive action to prevent the collision.
I had company video fixed in my taxi and photos taken at scene to support my claims.
Veh (B) (SGK 6869E). Male driver, NRIC : S 89107051.
Nobody was conveyed by the ambulance as no injury at that point of time.

DECLARATION

I/We declare the foregoing particulars are true in every respect.

COMFORT TRANSPORTATION PTE LTD
CO. REG. NO. 199303821R

Policyholder's Signature
Date & Time:

Luah
Driver's Signature
(If driver is not the policyholder)
Date & Time: 31.05.2018 @ 17:00 Hrs

Rubini
Reporting Centre Personnel's Signature
Name: Rubini
NRIC/FIN No.:

CHUNNI MOTOR WORK PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHA 4661R

DATE : 31.05.2018

MAKE :

TEL : 6542 5119

MODEL : HYUNDAI i40

FAX : 6542 6039

MSIG

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Radiator Grille HAT CRUDE			\$ 1,480.00 X ✓
	Radiator Grille H Emblem NH			\$ 290.80 X
	Radiator Grille Chrome Moulding NH			\$ 395.50 X
	Front Bumper Cover CHD			\$ 1,052.20 ✓
	Front Bumper Sponge NH			\$ 142.20 X
	Front Bumper Reinforcement HH			\$ 526.10 X
	Front Bumper Bracket (RH) NH			\$ 24.60 2. X
	Headlamp Support Panel Assy 2 broken			\$ 1,067.50 2 ✓
	Headlamp (LH) 2 broken mounting			\$ 1,388.00 2 ✓
	Front Fender (LH) Dented			\$ 619.00 ✓ photo
	Front Fender Apron Panel (H) NH Dented			\$ 1,575.50 X ✓
	Front Fender Shield (LH) SVL			\$ 169.80 X
	Front Wheel Rim (LH) 2 15+			\$ 351.90 2 ✓
	Front Wheel Hub Cap (LH) broken			\$ 150.70 ✓
	Front Wheel Bearing 2 Dam			\$ 258.50 2 ✓
	Front Shock Absorber (Assy) (LH) 2 distorted			\$ 342.20 2 ✓
	Front Shock Absorber Mounting (LH) NH			\$ 75.10 X
	Front Drive Shaft (LH) NH			\$ 1,069.55 X
	Rack & Pinion Assy NH			\$ 2,184.00 X
	STG Tie End 2 distorted			\$ 69.50 2 ✓
	Front Suspension Lower Arm (LH) 2 distorted			\$ 715.10 2 ✓
	Knuckle Arm (LH) 2 distorted			\$ 582.95 2 ✓
	ABS Sensor, LH NH			\$ 261.50 X
	Wiring-Engine NH CRUDE			\$ 3,326.00 X ✓
	SUB TOTAL		12979.05	\$ 18,118.20
	LESS 20%		10383.24	\$ 3,623.64
	DISCOUNTED TOTAL			\$ 14,494.56
	Front Fender Advertisement Logo (LH) NEL			\$ 100.00 Nett ✓
	Front Tyre (LH) SVL		100/-	\$ 216.00 Nett X
				\$ 316.00
	Labour Charge			
	Panel Beating			\$ 1,000.00 600/-
	Spray Painting Charge			\$ 750.00 500/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Towing Charge			\$ 50.00 NH
	Remove/Refix Undercarriage (FRT)			\$ 400.00 2180/-
	FRT Wheel Alignment			\$ 120.00 60/-
	Remove/Refix Aircon & Refill Gas			\$ 150.00 NH
	Remove/Refix Dashboard			\$ 450.00 NH 150/-
	Remove/Refix Fuse Box		1610/-	\$ 180.00 NH 50/-
	TOTAL LABOUR			\$ 3,200.00
	ESTIMATE TOTAL			\$ 18,010.56
	04/06/2018 @ 1130am Not driving 98 days. 45km 7 days			12093.24

...CLAIM SUBFOLDER...(Pending for Survey Report)



















































CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	01 Jun 2018		01 Jun 2018 16:16 Edit Adj Rpt	S\$9,650.00 Edit Estimates	S\$9,650.00 View Rpt		Pending for Survey Report Cancel Case



















































Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by Insurer]									
Insured:	VINOD KUMAR RAMGOPAL DIDWANIA, ID: 52601458A								
Main Claimant:	COMFORT TRANSPORTATION PTE LTD, Co. Reg. No.: 199303821R								
Vehicle Reg. No.:	SHA4661R	Date of Loss:	31/05/2018 10:00 - :59 [16 Months and 6 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560089	Policy/Cover Note No.:	A28809474QMY (Comprehensive) Coverage: 16/08/2017 - 15/08/2018						
Vehicle Reg. No. (Insured):	SGK6869E	Policy No. (Claimant):							
		Excess:							
Repairer:	Chunni Motor Work Pte Ltd - Amk (HQ) Blk 10 #01-05/06, AMK Autopoint, 568047 Ang Mo Kio - Tel: 64836016								
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Muhd Ashik B Madi - 6594 2548]								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by BRYAN TANI] ... [Final Rpt due 01/07/2018]								
Adj Asg. Remarks:	on WP Survey agreed on SJE OI NOT REPORTED CONTACT : LYNN OR IRENE AT 65425119 OR 65427162								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SHA4661R (560089)
[SGK6869E]
TP
COMFORT TRANSPORTATION PTE LTD
May 31 2018 10:00AM
[VINOD KUMAR RAMGOPAL DIDWANIA]
Chunni Motor Work Pte Ltd - Amk

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Assessment Reports							1 per page		<input checked="" type="checkbox"/>	
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)						Thumbnail	Print	
1	04/06/18 14:20	Accident Statement From: SC - Reg. No: SGK6869E, Claimant: VINOD KUMAR RAMGOPAL DIDWANIA						Load HTM		
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	14/06/18 16:23	Adjuster Immediate Advice						Load HTM		
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	28/06/18 16:41	Front View Right						Load JPG	<input checked="" type="checkbox"/>	
2	28/06/18 16:41	Front View Left						Load JPG	<input checked="" type="checkbox"/>	
3	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
4	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
5	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
6	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
7	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
8	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
9	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
10	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
11	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
12	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
13	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
14	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
15	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
16	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
17	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
18	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
19	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
20	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
21	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
22	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
23	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
24	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
25	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
26	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
27	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
28	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
29	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
30	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
31	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	
32	28/06/18 16:41	General View						Load JPG	<input checked="" type="checkbox"/>	

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
				<input checked="" type="checkbox"/>
33	28/06/18 16:41	Odometer Reading	 Load JPG	<input checked="" type="checkbox"/>
34	28/06/18 16:41	Chassis Number	 Load JPG	<input checked="" type="checkbox"/>
35	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
36	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
37	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
38	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
39	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
40	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
41	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
42	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
43	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
44	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
45	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
46	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
47	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
48	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
49	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
50	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
51	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
52	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
53	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
54	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
55	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
56	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
57	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
58	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
59	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
60	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
61	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
62	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
63	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
64	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
65	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
66	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
67	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
68	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
69	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
70	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
71	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
72	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
73	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
74	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
75	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
76	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
77	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
78	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
79	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
80	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
81	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
82	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
83	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
84	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
85	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
86	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
87	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
88	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
89	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
90	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
91	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
92	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
93	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
94	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
95	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
96	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
97	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
98	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
99	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
100	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
101	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
102	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
103	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
104	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
105	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
106	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
107	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
108	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
109	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
110	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
111	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
112	28/06/18 16:44	Reinspection Photo	 Load JPG	<input checked="" type="checkbox"/>
113	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
114	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
115	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
116	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
117	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
118	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
119	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
120	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
121	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
122	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
123	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
124	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
125	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
126	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
127	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
128	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
129	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
130	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
131	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
132	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
133	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
134	28/06/18 16:44	Finishing Photo	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	01/06/18 11:26	Estimate	 Load PDF	
2	01/06/18 11:26	Survey Agree on SJE - LKK	 Load PDF	
3	02/06/18 16:37	update agents on liability	 Load HTM	
4	04/06/18 14:07	SHA4661R - Third party report	 Load PDF	
5	07/06/18 08:41	Third party driving licence	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607196R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010055/DTD3Q2

Date: 06/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.

Policy No:

A28809474QMY

Claimant Vehicle No: SHA4661R

Insured Vehicle No:

SGK6869E

Date of Loss: 31/05/2018

Nature of Claim: TP

Claim No: 560089

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHA4661R

Make & Model: HYUNDAI I40, 1.7 L CRDI AT ABS AIRBAG 4DR (A)

Engine No: D4FDGU706870

Reg. Date: 25/01/2017 (Man. Year: 2016)

Chassis No: KMHLB41UMHU098287

Colour: Blue

Odometer: 182339 km

Engine Capacity: 1685 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable): Yes Engine Modification:

No

Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16

Rear Tyre Size:

205/60 R16

Front Left Side: Campeon 6 mm

Rear Left Side:

Campeon 6 mm

Front Right Side: Campeon 6 mm

Rear Right Side:

Campeon 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	14,810.56	10,483.24	4,327.32	29.22
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,200.00	1,610.00	1,590.00	49.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	18,010.56	12,093.24	5,917.32	32.85
Approved Total (Overridden) (S\$)		9,650.00		
(S\$)	18,010.56	9,650.00	8,360.56	46.42
+ GST 7.00/7.00% (S\$)	1,260.74	675.50	585.24	46.42
Nett Amount (S\$)	19,271.30	10,325.50	8,945.80	46.42

INSPECTION

Date of Assignment: 01/06/2018

Date Inspected: 04/06/2018 Inspected At:

Chunni Motor Work Pte Ltd - Amk (HQ)

Blk 10 #01-05/06, AMK Autopoint

Singapore 568047

Estimated Period of Repair: 9.0 days

Adjuster: BRYAN TANI**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 05 Jul 2018)
Parts:	143	HYUNDAI I40 1.7 L CRDI AT ABS AIRBAG 4DR (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHA4661R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*RADIATOR GRILLE	Cracked	1,480.00 FL	*1,480.00 FL
2	1		*RADIATOR GRILLE H EMBLEM	Not Necessary	290.80 FL	*- FL
3	1		*RADIATOR GRILLE CHROME MOULDING	Not Necessary	395.50 FL	*- FL
4	1		*FRONT BUMPER COVER	Cut	1,052.20 FL	*1,052.20 FL
5	1		*FRONT BUMPER SPONGE	Not Necessary	142.20 FL	*- FL
6	1		*FRONT BUMPER REINFORCEMENT	Not Necessary	526.10 FL	*- FL
7	1		*FRONT BUMPER BRACKET (RH)	Not Necessary	24.60 FL	*- FL
8	1		*HEADLAMP SUPPORT PANEL ASSY	Broken	1,067.50 FL	*1,067.50 FL
9	1		*HEADLAMP (RH)	Mtg Broken	1,388.00 FL	*1,388.00 FL
10	1		*FRONT FENDER (LH)	Dented	619.00 FL	*619.00 FL
11	1		*FRONT FENDER APRON PANEL (LH)	Dented	1,575.50 FL	*1,575.50 FL
12	1		*FRONT FENDER SHIELD (LH)	Serviceable	169.80 FL	*- FL
13	1		*FRONT WHEEL RIM (LH)	Bent	351.90 FL	*351.90 FL
14	1		*FRONT WHEEL HUB CAP (LH)	Broken	150.70 FL	*150.70 FL
15	1		*FRONT WHEEL BEARING	Damaged	258.50 FL	*258.50 FL
16	1		*FRONT SHOCK ABSORBER (ASSY) (LH)	Distorted	342.20 FL	*342.20 FL
17	1		*FRONT SHOCK ABSORBER MOUNTING (LH)	Not Necessary	75.10 FL	*- FL
18	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,069.55 FL	*- FL
19	1		*RACK & PINION ASSY	Not Necessary	2,184.00 FL	*- FL
20	1		*STG TIE END	Distorted	69.50 FL	*69.50 FL
21	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	715.10 FL	*715.10 FL
22	1		*KNUCKLE ARM (LH)	Distorted	582.95 FL	*582.95 FL
23	1		*ABS SENSOR ,LH	Not Necessary	261.50 FL	*- FL
24	1		*WIRING -ENGINE	Cracked	3,326.00 FL	*3,326.00 FL
25	1		*FRONT FENDER ADVERTISEMENT LOGO (LH)	Necessary	100.00 FS	*100.00 FS
26	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	18,434.20	13,079.05
- List Item Discount on L Items 20.00/20.00% (\$\$)	3,623.64	2,595.81
Total Parts (\$\$)	14,810.56	10,483.24

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	1,000.00	600.00
2	SPRAY PAINTING CHARGE	New	750.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	180.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
8	REMOVE/REFIX AIRCON & REFILL GAS	New	150.00	0.00
9	REMOVE/REFIX DASHBOARD	New	450.00	150.00
10	REMOVE/REFIX FUSE BOX	New	180.00	50.00
Gross Labour Cost (\$\$)			3,200.00	1,610.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >