

NS CASE OWNER:

CC 4/FWD180 0060, Veb

LKK:

IDAC:

Surveyor:

Sathu

DOI:

4/6/18

Date / Time:

4/6/18

Registered in Merimen:

4/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

FV 5701R

Claim No.:

1201500006988

Name of Insured:

Tan Kim Seng

Policy No.:

PWNLM8-00000879

Insured Tel No.:

HP:

93871808

Make / Model:

Honda

Excess Sec II : \$S

D.O.A.:

1/6/18

Place of Accident:

BET TANAN RD

Is driver the owner?

(YES / NO)

Nature of Accident:

If NO, Driver Name / Age:

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Driver Tel No.:

(V/L: YES / NO)

Insured Liability: %

Final ? Yes / No

SHC 41970



INSRS:

WSP:

Tel:

Liability:

RMKS:

GMAI



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date / Time

70/6/18
AS/24SHC 41970 - MR (MCA 011867) / 4/6/18
FV 5701R - X

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

4-7-18

Email WSP TO REQUEST FOR VIDEO FOOTAGE

READ ON PIR, TP WAS CHARGED FOR CARELESS DRIVING.

SEEK APPROVAL TO REJECT TP CLAIM.

APPROVAL TO REJECT.

Email WSP TO REJECT TP CLAIM.

Reject Case

By (staff): Sathu

Approved by: Sathu

Date: 04-06-18

PRELIMINARY ADVICE Date/Time:

Sent By:

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

\$S

(

days)

Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

Confirm with

Email

Call

Final Liability:

\$S

(Agreed / Assessed) BOLA S/N No.:

37

If NO or B 28, Ass. Lia:

Repair Cost:

\$S

TP REAR ENDED 01

Loss of Rental (LOR):

\$S

(

days)

Loss of Use (LOU):

\$S

(\$

x

days)

Loss of Income (LOI):

\$S

(\$

x

days)

LOR only

LOU only

LOR + LOU

LOR + LOI

[Tick only one]

GIA/LTA Search

\$S

Medical:

\$S

Disbursement:

\$S

(e.g. Tow/ Independent)

Legal Cost

\$S

Total:

\$S

Global Sum \$S:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

\$S

Name 1:

Payee 2: (Strike if N.A.)

\$S

Name 2:

Payee 3: (Strike if N.A.)

\$S

Name 3:

COPY SENT

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TY

3) Survey fee:

7500.

REF: FWD

ASSIGNMENT

From: Date: 4/6/18

Estimated Cost:

OD ☒ TP / ☐ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SHC 4197D

at Workshop m/s

of 8MRT
60 woodlands Ind-park E4

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Request for a copy of video
footage
* no video

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 4 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS ^{up}

Vehicle: IN / OUT

Date: Person Contacted:

Date / Time Action / Instruction

Veh No: SHC 4197D

Yr Regn: 11 / 13

Type: M.Car / M.Cycle / Bus / Van / Lorry / ☒ Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius

c.c. 1798

Colour: Purple metallic

A/C: Insured / Std / NI / NA

Sp. Reading: 381733

T/Radio: Insured / Std / NI / NA

Eng/No: J7R5912099

C/No: JTDKN36U305708848

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Falken

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/6/2018 D.O.I. 4/6/2018

Survey held at:

Des. of Damages: ☒ Frt / ☒ Rear / ☒ O/S / N/S / U/C / Rooftop or

Front O/S

The U/C / Chassis frame / Body Structure affected due to collision.

TAX/06/18/2002

FWD

- FV5701R

Date/Time: File Pass to?

☐ : Preli. Report

Days Of Repair:

1)

☐ : Final Report

Resurvey No. of Trip:

Date/Time: File Return to?

Survey Fee:

2)

Add Fee: ☐ : Site Insp (\$)

Transportation

☐ : Interview (\$)

) \$ + RE \$

☐ : Tech. Insp (\$)

) Photos

☐ : Weekend (\$)

) Others

Report Format :

Lump Sum / I.B.I. (\$)

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FWD SINGAPORE PTE LTD		Ref : CC4/FWD18010060/Veb3		
6 TEMASEK BOULEVARD #18-01 SUNTEC TOWER 4SINGAPORE 038986		Date : 04-06-2018		
		Code : FWD		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	FV 5701R	Veh. Inspected	SHC 4197D	
Policy No.		Coverage (\$)	0.00	
Claim No.		Excess (\$)	0.00	
Assign From		Assign Date	04/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	01/06/2018	Inspection Date	04/06/2018	
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				

7-6-18 / 13:00
8-6-18 / 08:00

SMRT Accident Vehicle Repair Estimates

54-6-18 / 08:00

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4197D
Ref. No : TAX/06/18/2002
Reg. Date : 29/11/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LEE CHEN SIONG
Type of Accident : HEAD TO REAR
Date / Time of Accident : 01/06/2018 10:00:00 AM
Accident Reported Date / Time : 01/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle Issued? : No
Accident Repair Job Card No : 000024096382
Special Instruction to ARC, if any :
FV5701R - FWD
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang@lkkauto.com HP:90036121
Prepared Date : 01/06/2018 12:48:22 PM

8/6
4197



8:55
9.6.18
past
Recording Camera ☐ ☒
Radio Antenna ☐ ☒
1st witness ☒ Date 4.6.18
2nd witness ☒ Date 9.6.18

Supplementary
to Report to the Supplementary part 1st ✓

381794
LEE SHENG AUTO PTE LTD

Vehicle Return Date: 8-6-18
Vehicle Return Time: 17:55
SMRT staff sign: _____

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5708848

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,014.00	800.00
Total Spray Painting Charges :	2,052.00	1,000.00
Total Material Charges :	5,304.67	3,933.31
Other Charges :	1,010.00	680.00
TOTAL :	9,380.67	6,413.31
Lump Sum Total :	9,400.00	6,400.00
No. of Repair Days :	6.00	5.00 4 days
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	01/06/2018 03:44:57 PM	01/06/2018 03:54:08 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/06/2018 03:40:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

QN-1806-0510

Invoice No :

Quotation Date :

23/6

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/1/2018 3:40:47 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	800.00 700
Total Labour	1,014.00	800.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	200.00 ✓
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	100.00 ✓
TO REPSRAY FRONT HOOD	378.00	200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	180.00	100.00 ✓
TO RESPRAY FRONT FENDER RH	378.00	200.00 ✓
TO RESPRAY FRONT FENDER LH	378.00	200.00 X
TO RESPRAY ARM, FR WIPER, RH	180.00	0.00
Total Spray Painting & Panel Beating	2,052.00	1,000.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE / REFIT WINDSCREEN	120.00	60.00 ✓
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	450.00 <i>new SN</i>	450.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	50.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	100.00 ✓
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,010.00	680.00

4076

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
52119-47930		6505517	BUMPER FRT	1	482.00	25.00	361.50	Replace	Replace	No	DMG
52127-47903			COVER, FR BUMPER HOLE RH	1	18.50	25.00	13.88	Replace	Replace	No	CUT
52611-47080		6505518	BUMPER ENERGY ABSORBER FRT	1	78.80	25.00	59.10	Replace	Replace	No	CRK
52021-47023		6505539	BUMPER REINFORCEMENT FRT	1	498.40	25.00	373.80	Replace	Check	No	X
57013-47030			ARM SUB-ASSY, FR BUMPER RH	1	250.40	25.00	187.80	Replace	Check	No	X
53102-47020		6505541	BUMPER GRILLE SUB-ASSY, LOWER	1	311.10	25.00	233.32	Replace	Replace	No	CRK
81210-12230		6505439	FOG LAMP RH	1	295.20	10.00	265.68	Replace	Replace	No	BR
75310-47010		6505638	EMBLEM FRONT	1	86.50	25.00	64.87	Replace	Replace	No	CUT
52114-47140			BRACKET, FR BUMPER	1	110.40	25.00	82.80	Replace	Replace	No	CRK
			NUMBER PLATE	1	15.00	0.00	15.00	Replace	Replace	No	DT
			NUMBER PLATE FRAME	1	12.00	0.00	12.00	Replace	Replace	No	BR
52115-47040		6505515	BUMPER SUPPORT F/RH	1	76.40	25.00	57.30	Replace	Check	No	X
53301-47060		6505555	HOOD PANEL	1	748.10	25.00	561.08	Replace	Replace	No	NN
53395-47020			HOOD END PANEL SEAL	1	35.50	25.00	26.62	Replace	Replace	No	DT
53420-47070			HOOD HINGE LH	1	55.90	25.00	41.93	Replace	Replace	No	CUT
53410-47070			HOOD HINGE RH	1	55.90	25.00	41.93	Replace	Replace	No	DT
561014E909			WINDSCREEN FRT	1	1,543.80	25.00	1,157.85	Replace	Replace	No	CRK
75533-47050			WINDSCREEN MOULDING FRT	1	57.60	25.00	43.20	Replace	Replace	No	NEC
	COMMON		SEALANT W/SCREEN	2	37.00	0.00	74.00	Replace	Replace	No	CUT
85211-47100			ARM, FR WIPER, RH	1	296.80	25.00	222.60	Replace	Replace	No	BR
85212-47040			BLADE, FR WIPER, RH	1	86.20	25.00	64.65	Replace	Replace	No	NN
53201-47902			SUPPORT SUB-ASSY	1	1,460.40	25.00	1,095.30	Replace	Check	No	X
81130-47500		6505437	HEAD LAMP RH	1	945.20	10.00	850.68	Replace	Replace	No	SCR
53801-47050		6505557	FENDER FRT/RH	1	723.40	100.00	0.00	Replace	Repair	No	Y
75374-47051			NAME PLATE (HYBRID)	1	51.90	25.00	38.93	Replace	Replace	No	NEC
53875-47030		6505553	FENDER LINER FRT/RH	1	171.70	25.00	128.78	Replace	Replace	No	DT
53802-47050		6505558	FENDER FRT/LH	0	723.40	25.00	0.00	Replace	Not given	No	X
75374-47051			NAME PLATE (HYBRID)	0	51.90	25.00	0.00	Replace	Not given	No	X
52618-47050		6505540	BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace	No	TN

9449.10

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
55708-47101			WIPER GARNISH	1	614.00	25.00	460.50	Replace	Replace <i>S</i>	No <i>/</i>
TOTAL MATERIALS								6,630.86	4,916.64	
TOTAL MATERIALS(Discounted)								5,304.67	3,933.31	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
52618-47050		BUMPER FRT ABSORBER LOWER	1	127.70	25.00	95.77	Replace	Replace	No <i>x</i>
55708-47101		WIPER GARNISH	1	614.00	25.00	460.50	Replace	Replace	No <i>x</i>
TOTAL SUPPLEMENTARY MATERIALS						556.27			

1355.70

14875.80

Surveyor Finalize:

4916.67
 - 20%
 3933.34
 + 700
 + 1480
 6113.34

L/S: 6100/- @ 4 days

4916.64
 - 20%
 3933.31
 + 800.00
 + 1680.00
 6413.31

L/S \$6400/-

SMRT Accident Vehicle Repair Estimates

C11A

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHC4197D
Ref. No : TAX/06/18/2002
Reg. Date : 29/11/2013
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS
Name of Driver : LEE CHEN SIONG
Type of Accident : HEAD TO REAR
Date / Time of Accident : 01/06/2018 10:00:00 AM
Accident Reported Date / Time : 01/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096382
Special Instruction to ARC, if any :
FV5701R
Prepared Date : 01/06/2018 12:48:22 PM



Satya Sai
4/6/2018

- Lump Sum Repair
- Question mark Item photo
- photo after paint.

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKN36U30-5708848

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,014.00

0.00

Total Spray Painting Charges : 2,052.00

0.00

Total Material Charges : 5,758.87

5,758.87

Other Charges : 1,010.00

0.00

TOTAL : **9,834.87****0.00****Lum Sum Total** : **9,850.00****0.00**

No. of Repair Days : 6.00

~~0.00~~ 3 days

Prepared / Adjusted By :

Arc / Surveyor Sing Off Date : 01/06/2018 03:44:57 PM

01/06/2018 03:54:08 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 01/06/2018 03:40:36 PM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/1/2018 3:40:47 PM

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR FRONT PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT BUMPER LOWER GRILLE	180.00	0.00 100
TO REPSRAY FRONT HOOD	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 ?
TO RESPRAY FRONT FENDER RH	378.00	0.00 X
TO RESPRAY FRONT FENDER LH	378.00	0.00 X
TO RESPRAY ARM , FR WIPER , RH	180.00	0.00 X
Total Spray Painting & Panel Beating	2,052.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REMOVE / REFIT WINDSCREEN	120.00	0.00 60
TO PROVIDE LABOUR & MATERIAL FOR SOLAR FILM (NET)	450.00	0.00 ✓
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 100
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	1,010.00	0.00

Part 4.- Spare Parts / Material Usage

1. 2. 3. 4. 5. 6. 7. 8. 9. 10. 11. 12. 13. 14. 15. 16. 17. 18. 19. 20. 21. 22. 23. 24. 25. 26. 27. 28. 29. 30. 31. 32. 33. 34. 35. 36. 37. 38. 39. 40. 41. 42. 43. 44. 45. 46. 47. 48. 49. 50. 51. 52. 53. 54. 55. 56. 57. 58. 59. 60. 61. 62. 63. 64. 65. 66. 67. 68. 69. 70. 71. 72. 73. 74. 75. 76. 77. 78. 79. 80. 81. 82. 83. 84. 85. 86. 87. 88. 89. 90. 91. 92. 93. 94. 95. 96. 97. 98. 99. 100.

| Part Number | Portion | Stock No | Part Name | Qty | List Price (\$) | Discount (%) | Final Price (\$) | ARC Recommendation | Surveyor Approved | Photos Attached |
|--|---------|----------|-------------------------------------|-----|-----------------|--------------|------------------|--------------------|-------------------|-----------------|
| 52119-47930 | | 6505517 | BUMPER FRT ✓ DMG | 1 | 482.00 | 25.00 | 361.50 | Replace | Replace | No |
| 52127-47903 | | | COVER, FR BUMPER HOLE RH ✓ CUT | 1 | 18.50 | 25.00 | 13.88 | Replace | Replace | No |
| 52611-47080 | | 6505518 | BUMPER ENERGY ABSORBER FRT ? | 1 | 78.80 | 25.00 | 59.10 | Replace | Replace | No |
| 52021-47023 | | 6505539 | BUMPER REINFORCEMENT ? FRT | 1 | 498.40 | 25.00 | 373.80 | Replace | Replace | No |
| 57013-47030 | | | ARM SUB-ASSY, FR ? BUMPER RH | 1 | 250.40 | 25.00 | 187.80 | Replace | Replace | No |
| 53102-47020 | | 6505541 | BUMPER GRILLE SUB-ASSY, LOWER ✓ CRK | 1 | 311.10 | 25.00 | 233.32 | Replace | Replace | No |
| 81210-12230 | | 6505439 | FOG LAMP RH ✓ BR | 1 | 295.20 | 10.00 | 265.68 | Replace | Replace | No |
| 75310-47010 | | 6505638 | EMBLEM FRONT ✓ CUT | 1 | 86.50 | 25.00 | 64.87 | Replace | Replace | No |
| 52114-47140 | | | BRACKET, FR ? BUMPER | 1 | 110.40 | 25.00 | 82.80 | Replace | Replace | No |
| | | | NUMBER PLATE ✓ DT | 1 | 15.00 | 0.00 | 15.00 | Replace | Replace | No |
| | | | NUMBER PLATE FRAME ✓ BR | 1 | 12.00 | 0.00 | 12.00 | Replace | Replace | No |
| 52115-47040 | | 6505515 | BUMPER SUPPORT ? F/RH | 1 | 76.40 | 25.00 | 57.30 | Replace | Replace | No |
| 53301-47060 | | 6505555 | HOOD PANEL ✓ DT | 1 | 748.10 | 25.00 | 561.08 | Replace | Replace | No |
| 53395-47020 | | | HOOD END PANEL SEAL ✓ CUT | 1 | 35.50 | 25.00 | 26.62 | Replace | Replace | No |
| 53420-47070 | | | HOOD HINGE LH ? | 1 | 55.90 | 25.00 | 41.93 | Replace | Replace | No |
| 53410-47070 | | | HOOD HINGE RH ? | 1 | 55.90 | 25.00 | 41.93 | Replace | Replace | No |
| 561014E909 | | | WINDSCREEN FRT ✓ CRK | 1 | 1,543.80 | 25.00 | 1,157.85 | Replace | Replace | No |
| 75533-47050 | | | WINDSCREEN MOULDING FRT ✓ NEC | 1 | 57.60 | 25.00 | 43.20 | Replace | Replace | No |
| | COMMO N | | SEALANT W/SCREEN ✓ NEC | 2 | 37.00 | 0.00 | 74.00 | Replace | Replace | No |
| 85211-47100 | | | ARM, FR WIPER, RH ✓ CUT | 1 | 296.80 | 25.00 | 222.60 | Replace | Replace | No |
| 85212-47040 | | | BLADE, FR WIPER, RH ✓ BR | 1 | 86.20 | 25.00 | 64.65 | Replace | Replace | No |
| 53201-47902 | | | SUPPORT SUB-ASSY ? | 1 | 1,460.40 | 25.00 | 1,095.30 | Replace | Replace | No |
| 81130-47500 | | 6505437 | HEAD LAMP RH ✓ SCR | 1 | 945.20 | 10.00 | 850.68 | Replace | Replace | No |
| 53801-47050 | | 6505557 | FENDER FRT/RH R SCR | 1 | 723.40 | 25.00 | 542.55 | Replace | Replace | No |
| 75374-47051 | | | NAME PLATE (HYBRID) ✓ NEC | 1 | 51.90 | 25.00 | 38.93 | Replace | Replace | No |
| 53875-47030 | | 6505553 | FENDER LINER FRT/RH ✓ DT | 1 | 171.70 | 25.00 | 128.78 | Replace | Replace | No |
| 53802-47050 | | 6505558 | FENDER FRT/LH X | 1 | 723.40 | 25.00 | 542.55 | Replace | Replace | No |
| 75374-47051 | | | NAME PLATE (HYBRID) X | 1 | 51.90 | 25.00 | 38.92 | Replace | Replace | No |
| TOTAL MATERIALS | | | | | | | | 7,198.61 | 7,198.59 | |
| TOTAL MATERIALS(Discounted) | | | | | | | | 5,758.87 | 5,758.87 | |
| Added Spare Parts / Material Usage After Surveyor Signed off | | | | | | | | | | |

| Part
Number | Portion | Part Name | Qty | List Price
(\$) | Discount
(%) | Final Price
(\$) | ARC Check | Surveyor
Check | LT
Check |
|--------------------------------------|---------|-----------|-----|--------------------|-----------------|---------------------|-----------|-------------------|-------------|
| TOTAL SUPPLEMENTARY MATERIALS | | | | | | | | | |

Asher Sng (LKKAUTO)

From: Asher Sng (LKKAUTO)
Sent: Tuesday, 29 January 2019 11:52 AM
To: 'josey.loh@fwd.com'
Cc: motorclaims.sg@fwd.com
Subject: RE: SHC4197D - Survey (FWD) Our ref: 1201800006988
Attachments: FV5701R letter.pdf

Hi Josey,

We refer to the above matter.

Police investigation result clearly show that TP was charged for careless driving.

We are of the opinion that BOLA 27 shall be applied and liability is not in third party favour.

In view of the above, we are intending to reject TP claim.

For your approval/ comments/ instruction.

Thank You.

Best Regards,

Asher Sng | Case Handler

LKK Auto Consultants Pte Ltd

phone: 6841-6051 | email: ashersng@lkkauto.com | fax: 6741-4108

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



From: josey.loh@fwd.com <josey.loh@fwd.com>
Sent: Monday, 28 January 2019 11:05 AM
To: Asher Sng (LKKAUTO) <AsherSng@lkkauto.com>
Cc: motorclaims.sg@fwd.com
Subject: RE: SHC4197D - Survey (FWD) Our ref: 1201800006988

Hi Asher,

Please be informed that TP was charged for Careless Driving.



**SINGAPORE
POLICE FORCE**

Traffic Police
10 Ubi Avenue 3
Singapore 408865
Tel +65 6547 0000
Fax +65 6547 6259
www.police.gov.sg

Our Ref : TP/IP/32401/2018
Date : 23 July, 2018

TAN KIM SENG
APT BLK 572B WOODLANDS AVE 1
#09-836
SINGAPORE 732572

Dear Sir/Madam

**ACCIDENT INVOLVING FV5701R AND SHC4197D ON 01/06/2018 AT 1008 HRS, ALONG
BUKIT TIMAH ROAD.**

I refer to the above accident.

2. Please be informed that we have completed our investigations which shows that the driver of SHC4197D had committed an offence of Careless Driving under Rule 29 Road Traffic Rules. Action has been initiated against the said driver for the said offence.
3. If you have any queries, please contact the Investigation Officer, Irman at telephone 65476365 or via email at Irman_Mohamad_Said@spf.gov.sg

Yours faithfully

Juremah Ahmad SSI(2)
For Head, Traffic Investigation
Traffic Police
Singapore Police Force

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING

| Case | Notified | Est Submitted | Adj Assigned | Adj Rpt | Adj Submitted | Ins Auth'd | Status |
|------|---|---------------|---|--|--|------------|---|
| Main | 06 Jun 2018
Edit Reg | | 04 Jun 2018 00:00
Edit Adj Rpt | S\$6,100.00
Edit Estimates | S\$6,100.00
View Rpt | | Pending for Survey Report
Cancel Case |

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

| | | | |
|-----------------------------|---|------------------------|---|
| Insured: | Tan Kim Seng, ID: S2502466D | | |
| Main Claimant: | SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K | | |
| Vehicle Reg. No.: | SHC4197D | Date of Loss: | 01/06/2018 10:00 - :59
[54 Months and 3 Days From LTA Reg Date (Man Yr)] |
| Claim Type: | TP / 1201800006988 | Policy/Cover Note No.: | PNMC2018-00000879 (Third Party Only) |
| Vehicle Reg. No. (Insured): | FV5701R | Policy No. (Claimant): | D-18090213MFSH |
| | | Excess: | |
| Repairer: | SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628 | | |
| Handling Insurer: | FWD Singapore Pte. Ltd. (HQ) - Tel: 6727 5700 ... [Handled by Clara Li Zi Rong] | | |
| Claimant's Insurer: | MS First Capital Insurance Ltd (HQ) - Tel: 62222311 | | |
| Adjuster: | LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 13/06/2018] | | |

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

| Due Date | Priority | Type | Task Group | Subject | Handler | Assigned By | Completed On | Created On | Done? |
|-------------|----------|------|------------|---------|---------|-------------|--------------|------------|-------|
| No results. | | | | | | | | | |

Claim Documents

***SHC4197D (1201800006988)**
[FV5701R]

TP

SMRT TAXIS PTE LTD

Jun 1 2018 10:00AM

[Tan Kim Seng]

SMRT Automotive Services Pte Ltd

[Upload Documents](#)
[Upload Photos](#)
[Compose New Letter](#)

View
[View in Browser](#)

Assessment Reports

| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|----------------|-----------------------------------|--|-------------------------------------|
| 1 | 05/06/18 15:45 | Adjuster Immediate Advice |  Load HTM | ☒ |

Photos/Images

| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
|----|-----------------|-----------------------------------|--|-------------------------------------|
| 1 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 2 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 3 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 4 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 5 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 6 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 7 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 8 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 9 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 10 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 11 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 12 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 13 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 14 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 15 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 16 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 17 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 18 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 19 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 20 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 21 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 22 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 23 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 24 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 25 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 26 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 27 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 28 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 29 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 30 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 31 | 05/06/18 09:35 | General View |  Load JPG | ☒ |
| 32 | 05/06/18 09:35 | General View |  Load JPG | ☒ |

| Assessment Reports | | | 1 per page ▼ | ✓ |
|--------------------|-----------------|-----------------------------------|--|-------|
| No | Finalized On | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 33 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 34 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 35 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 36 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 37 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 38 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 39 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 40 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 41 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 42 | 05/06/18 09:35 | Chassis Number |  Load JPG | ✓ |
| 43 | 05/06/18 09:35 | Odometer Reading |  Load JPG | ✓ |
| 44 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 45 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 46 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 47 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 48 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 49 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 50 | 05/06/18 09:35 | General View |  Load JPG | ✓ |
| 51 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 52 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 53 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 54 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 55 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 56 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 57 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 58 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 59 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 60 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 61 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 62 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 63 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 64 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| 65 | 11/06/18 18:01 | Photo After Spray |  Load JPG | ✓ |
| Documentation | | | 1 per page ▼ | ✓ |
| No | Relabel/Reorder | LKK Auto Consultants Pte Ltd (HQ) | Thumbnail | Print |
| 1 | 04/06/18 16:21 | EMAIL FROM FWD DD 04062018 |  Load PDF | |
| 2 | 04/06/18 16:21 | TP ESTIMATE |  Load PDF | |
| 3 | 04/06/18 16:21 | TP GIA REPORT |  Load PDF | |
| 4 | 05/06/18 18:24 | TP ESTIMATE- MARKED |  Load PDF | |
| 5 | 09/04/19 11:20 | APPROVAL TO REJECT TP CLAIM |  Load PDF | |
| 6 | 09/04/19 11:20 | EMAIL WSP TO REJECT TP CLAIM |  Load PDF | |
| 7 | 09/04/19 11:23 | OI PIR |  Load PDF | |
| No | Finalized On | FWD Singapore Pte. Ltd. (HQ) | Thumbnail | Print |
| 1 | 25/06/18 14:18 | OI GIA Report |  Load PDF | |
| 2 | 19/07/18 18:58 | Scene Photo (01) |  Load JPG | ✓ |
| 3 | 19/07/18 18:58 | Scene Photo (02) |  Load JPG | ✓ |

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/FWD18010060/VEB3S2

Date: 16/04/2019

REFERENCE

| | | | |
|-----------------------|-------------------------|----------------------|-------------------|
| Handling Insurer: | FWD Singapore Pte. Ltd. | Policy No: | PNMC2018-00000879 |
| Claimant Vehicle No : | SHC4197D | Insured Vehicle No : | FV5701R |
| Date of Loss: | 01/06/2018 | Nature of Claim: | TP |
| | | Claim No: | 1201800006988 |

DESCRIPTION & IDENTIFICATION OF VEHICLE

| | | | |
|-----------------------------|------------------------------|-------------|-------------------|
| Reg No: | SHC4197D | Engine No: | 2ZR5912099 |
| Make & Model: | TOYOTA PRIUS TAXI, 1.8 (A) | Chassis No: | JTDKN36U305708848 |
| Reg. Date: | 29/11/2013 (Man. Year: 2013) | Odometer: | 381733 km |
| Colour: | Maroon | | |
| Engine Capacity: | 1798 cc | | |
| Market Value/New Car Price: | N/A | | |
| Sum Insured (S\$): | Market Value/New Car Price | | |

CONDITION OF VEHICLE AT THE TIME OF SURVEY

| | | | | | |
|--------------------------|------|-------------------------|-----|--------------------------|-----|
| General Condition: | Fair | Steering (Serviceable): | Yes | Footbrake (Serviceable): | Yes |
| Handbrake (Serviceable): | Yes | Engine Modification: | No | Pre-accident Condition: | |

CONDITION OF TYRES

| | | | |
|-------------------|-------------|------------------|-------------|
| Front Tyre Size: | 195/65R15 | Rear Tyre Size: | 195/65R15 |
| Front Left Side: | Falken 6 mm | Rear Left Side: | Falken 6 mm |
| Front Right Side: | Falken 6 mm | Rear Right Side: | Falken 6 mm |

The above values represent the remaining tyre treads depth

| COST OF CLAIMS | Repairer's | Adjuster's | Difference | Diff % |
|--|------------------|-----------------|-----------------|--------------|
| Parts | 11,249.80 | 5,366.67 | 5,883.13 | 52.30 |
| Miscellaneous Items | 0.00 | 0.00 | 0.00 | |
| Labour | 3,626.00 | 1,730.00 | 1,896.00 | 52.29 |
| Paintwork Labour | 0.00 | 0.00 | 0.00 | |
| Towing | 0.00 | 0.00 | 0.00 | |
| Calculated Gross Total (S\$) | 14,875.80 | 7,096.67 | 7,779.13 | 52.29 |
| Approved Total (Overridden) (S\$) | | 6,100.00 | | |
| Nett Amount (S\$) | 14,875.80 | 6,100.00 | 8,775.80 | 58.99 |

INSPECTION

| | | |
|-----------------------------|------------|---|
| Date of Assignment: | 04/06/2018 | |
| Date Inspected: | 04/06/2018 | Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
60 Woodlands Industrial Park E4
Singapore 757705 |
| Estimated Period of Repair: | 4.0 days | |

Adjuster: Sathya Sai Kathirrasen

Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

| | | |
|----------------------|--|---|
| Part Source: | MRM-SG | Version: 1.0 (Last Synchronised: 16 Apr 2019) |
| Parts: | 144 | TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0) |
| Labour: | Repairer's | (Price-denominated Standard List) |
| Print Code: | (Unsubmitted, no print-code for SHC4197D) | |
| Validity: | These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page | |
| Further Info: | Items/values not in reference catalogue are prefixed with an asterisk *. | |

Recommended Parts

| No. | Qty | Part No. | Particulars | Condition | Repairer's | Amount |
|-----|-----|----------|---|---------------|------------|-------------|
| 1 | 1 | | *BUMPER FRT (DISC 25%) | Damaged | 482.00 F | *361.50 F |
| 2 | 1 | | *COVER, FR BUMPER HOLE RH (DISC 25%) | Cut | 18.50 F | *13.88 F |
| 3 | 1 | | *BUMPER ENERGY ABSORBER FRT (DISC 25%) | Cracked | 78.80 F | *59.10 F |
| 4 | 1 | | *BUMPER GRILLE SUB-ASSY, LOWER (DISC 25%) | Cracked | 311.10 F | *233.32 F |
| 5 | 1 | | *EMBLEM FRONT (DISC 25%) | Cut | 86.50 F | *64.87 F |
| 6 | 1 | | *BRACKET, FR BUMPER (DISC 25%) | Cracked | 110.40 F | *82.80 F |
| 7 | 1 | | *HOOD PANEL (DISC 25%) | Dented | 748.10 F | *561.08 F |
| 8 | 1 | | *HOOD END PANEL SEAL (DISC 25%) | Cut | 35.50 F | *26.62 F |
| 9 | 1 | | *HOOD HINGE LH (DISC 25%) | Dented | 55.90 F | *41.93 F |
| 10 | 1 | | *HOOD HINGE RH (DISC 25%) | Dented | 55.90 F | *41.93 F |
| 11 | 1 | | *WINDSCREEN FRT (DISC 25%) | Cracked | 1,543.80 F | *1,157.85 F |
| 12 | 1 | | *WINDSCREEN MOULDING FRT (DISC 25%) | Necessary | 57.60 F | *43.20 F |
| 13 | 1 | | *ARM, FR WIPER, RH (DISC 25%) | Cut | 296.80 F | *222.60 F |
| 14 | 1 | | *BLADE, FR WIPER, RH (DISC 25%) | Broken | 86.20 F | *64.65 F |
| 15 | 1 | | *NAME PLATE (HYBRID) (DISC 25%) | Necessary | 51.90 F | *38.93 F |
| 16 | 1 | | *FENDER LINER FRT/RH (DISC 25%) | Dented | 171.70 F | *128.78 F |
| 17 | 1 | | *BUMPER FRT ABSORBER LOWER (DISC 25%) | Torn | 127.70 F | *95.77 F |
| 18 | 1 | | *WIPER GARNISH (DISC 25%) | Torn | 614.00 F | *460.50 F |
| 19 | 1 | | *FOG LAMP RH (DISC 10%) | Broken | 295.20 F | *265.68 F |
| 20 | 1 | | *HEAD LAMP RH (DISC 10%) | Scratched | 945.20 F | *850.68 F |
| 21 | 1 | | *BUMPER REINFORCEMENT FRT | Not Necessary | 498.40 F | *- F |
| 22 | 1 | | *ARM SUB-ASSY, FR BUMPER RH | Not Necessary | 250.40 F | *- F |
| 23 | 1 | | *BUMPER SUPPORT F/RH | Not Necessary | 76.40 F | *- F |
| 24 | 1 | | *SUPPORT SUB-ASSY | Not Necessary | 1,460.40 F | *- F |
| 25 | 1 | | *FENDER FRT/LH | Not Necessary | 723.40 F | *- F |
| 26 | 1 | | *NAME PLATE (HYBRID) | Not Necessary | 51.90 F | *- F |
| 27 | 1 | | *BUMPER FRT ABSORBER LOWER | Not Necessary | 127.70 F | *- F |
| 28 | 1 | | *WIPER GARNISH | Not Necessary | 614.00 F | *- F |
| 29 | 1 | | *FENDER FRT/RH | Repair | 723.40 F | *- F |
| 30 | 1 | | *SOLAR FILM (SN) | Necessary | 450.00 F | *450.00 F |
| 31 | 1 | | *NUMBER PLATE (SN) | Dented | 15.00 F | *15.00 F |
| 32 | 1 | | *NUMBER PLATE FRAME (SN) | Broken | 12.00 F | *12.00 F |
| 33 | 2 | | *SEALANT W/SCREEN (SN) | Necessary | 74.00 F | *74.00 F |

F=Franchise part.

| | | |
|---------------------------|------------------|-----------------|
| Total Parts (\$\$) | 11,249.80 | 5,366.67 |
|---------------------------|------------------|-----------------|

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

| No | Particulars | Lab.Type | Repairer's | Amount |
|-------------------------|--|----------|------------|----------|
| <u>Labour Items</u> | | | | |
| 1 | PANEL BEATING & BODYWORK. | New | 1,014.00 | 700.00 |
| 2 | SPRAY PAINT. | New | 2,052.00 | 800.00 |
| 3 | TO REMOVE / REFIT WINDSCREEN. | New | 120.00 | 60.00 |
| 4 | TO CHECK WIRING AND SYSTEM FUNCTION. | New | 80.00 | 50.00 |
| 5 | TO APPLY RUST-PROOFING ON AFFECTED AREA. | New | 200.00 | 100.00 |
| 6 | TO REPLACE SUNDRY PARTS. | New | 100.00 | 20.00 |
| 7 | TO WASH AND VACUUM. | New | 60.00 | 0.00 |
| Gross Labour Cost (S\$) | | | 3,626.00 | 1,730.00 |

Report was unsubmitted during this print-out.

< END OF ESTIMATES >