

22/03/2012

ASS. REC. BY:

REF

es/msg18010069/71td3ⁿ²

Special Instruction:

Surveyor
Meinmer

Tautich

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

MSIA

Date/Time:

31/5/16 @ 5:03pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES/OD RES/EVA/INV/MV/CS

To Inspect Vehicle No:

SKB 7420

Insured:

SKX 9631M

at Workshop m/s

Performance Motor
303 Alexandra Rd

Tel:

6319 0174

of

Policy No:

80422344 QMY

Claim No:

559665

Sum Insured:

Excess:

Make of Veh:

D.O.A.

27/05/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS (wp)

07062018 @ 10am - 12pm

H.O.D. Endorsement:

Date/Time:

10:21am @ 4/6/18

Person Contacted:

Caroline

Vehicle IN/OUT

Date/Time	Action/Instruction (✓) Estimate
	SKB 74201 - CC3 / AIG 160 22298 / Geq 3q2
	SKX 9631M - x
08/6/18 @ 2:28pm	revised to Lionel Tan via Meinmer.
	Final \$7538.20 (red. 4032.95 ; 34%)

DUA: 19/11/2016

Vehicle

Tanpin

REF: MSIG

ASSIGNMENT

From:

Date:

07/06/18

Estimated Cost:

OD (TP) WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No

SKB 7420J
Performance Motor
303 Alexandra Rd

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:


(Client's Record)

10 am - 12pm
Gary

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

days Res.: Yes or No

Lum Sum:

% 3 Val: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No

SKB 7420J

Yr Regn:

2011 June

Type: M Car / M Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

BMW 320I

c.c.

1995

Colour:

Grey

A/C: Insured / Std / NI / NA

Sp. Reading

81298

T/Radio: Insured / Std / NI / NA

Eng/No:

81298

C/No:

WBAPG 56000 NM 26592

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modl: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

255/35 R18.

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal.

6

mm

R/Bal.

6

mm

L/Bal.

6

mm

L/Bal.

6

mm

D.O.A.

D.O.I.

7/1/8E/040

Survey held at

pm

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

RECEIVED 18 JUL 2018

18/7/2018

Date/Time: File Pass to?



: Preli. Report

18/7/2018 Typist



: Final Report

Date/Time: File Return to?

Days Of Repair:

5

Resurvey No. of Trip:

1

Survey Fee:

Transportation

5 + RS. SI

Photos

Others

TOTAL

Add Fee:



: Site Insp (\$



Interview (\$



Tech. Insp (\$



Week-end (\$

Report Format:

Lump Sum / I.B.I. (\$

7P
7538.70

200
10

210



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010069/T1td3

16 RAFFLES QUAY

#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 04-06-2018

Code : MSG



1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKX 9631M	Veh. Inspected	SKB 7420J
Policy No.	80422344QMY	Coverage (\$)	0.00
Claim No.	559665	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	27/05/2018	Inspection Date
Survey held at	PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

Note: This document has not been finalised.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 08 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKX9631M	Accident Date	: 27/05/2018
TP Vehicle No	: SKB7420J	Assignment Date	: 31/05/2018
Make	: BMW 320i	Est. Duration of Repair	: 6.00
Date of Inspection	: 07/06/2018		
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:SS	11,544.15
Revised Amount	:SS	7,239.60
Check Items (Estimated)	:SS	2,276.55
Total	:SS	9,516.15

Lump Sum Repair	:SS
-----------------	-----

Total Loss Consideration

New for Old Value	:SS
Pre-Accident Value	:SS
COE / PARF Rebate	:SS
Salvage Value	:SS
Margin for Repair	:SS

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	30 May 2018		31 May 2018 17:03 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CAO LIN, ID: S7869644C, Tel: +6593395327			
Main Claimant:	HARDY MARTIN JULIAN, ID: S2754917I			
Vehicle Reg. No.:	SKB7420J	Date of Loss:	27/05/2018 14:00 - :59 [83 Months and 3 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 559665	Policy/Cover Note No.:	80422344QMY (Comprehensive) Coverage: 04/01/2018 - 03/01/2019	
Vehicle Reg. No. (Insured):	SKX9631M	Policy No. (Claimant):		
		Excess:	\$700.00	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 01/06/2018]			
Driver/Custodian (Insured):	CAO LIN (40 / Female), NRIC: S7869644C, Tel: +6593395327			
Adj Asg. Remarks:	SJE - AGREED Please appoint LKK AUTO to conduct the survey . Kindly contact MS CAROLINE from PML @ 6319 0174 Liability : NON REPORTING			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Complete
No results.									

Shiau Chan (LKKAUTO)

From: Denise Tay (LKKAUTO)
Sent: Wednesday, 18 July 2018 3:11 PM
To: PBSP; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKB7420J

Dear Caroline,

Confirm final figure @ \$7538.20,5days.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: PBSP [mailto:pml-pbsp@simedarby.com.sg]
Sent: Monday, 16 July 2018 2:01 PM
To: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>; Taufikh (LKKAUTO) <Taufikh@lkkauto.com>; SUR <sur@lkkauto.com>
Subject: Re: FINAL REPORT / SKB7420J

Dear Denise

As requested, please refer to attach before paint photographs.

Kindly confirm COR.

Thank you.

Regards,
Caroline
C/o Performance Motors Limited - Body and Paint
303 Alexandra Road Singapore 159941
DID: 6319 0174 Fax: 6479 4601

From: Denise Tay (LKKAUTO) <denisetay@lkkauto.com>
Sent: Friday, 13 July 2018 4:52:13 PM
To: PBSP; Taufikh (LKKAUTO); SUR
Subject: RE: FINAL REPORT / SKB7420J

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No. M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47104
Date Estimated : 28/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -
Hardy Martin Julian
760 Bedok Reservoir Road
#08-01

Singapore 479245

- ACCOUNT - 40000
Cash Sales - Service
Singapore

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB7420J	NM26592	24/06/2011	320i/4 (A)	0

DESCRIPTION

To replace bumper and bootlid & attachment include knocking
cause by the accident

VALUE
2550 ✓ 3,400.00

Painting rear bumper, bootlid, tail panel ^x - photo

1738 ✓ 2,666.00

To check electrical wiring systems and lightings at the
rear section for proper function.

150 ✓ 177.00

To supply rear emboss number plate.

64 ✓ 83.00

To carry out body cavity preservation.
(Per panel).

100 ✓ 118.00

Sundries.

rec 20 150.00

Total Labour 1: 6,594.00

DESCRIPTION

BOOTLID
RR BUMPER CARRIER
RR BUMPER CTR GUIDE
RR BUMPER CTR BOTTOM GUIDE
RR BUMPER LH SIDE GUIDE (M)
RR BUMPER RH SIDE GUIDE (M)
RR BUMPER COVER (M)
RR BUMPER COVER (M)
RR BUMPER TOW HOOK COVER (M)
RR BUMPER (M)
EMBLEM ADHERED REAR 320I
PLAQUE 74MM
BOOTLID GASKET
DECOUPLING RING PDC TORQUE CONVERTE
PDC sensor

QTY	PRIC
1	1,156.60
1	424.25
1	31.60
1	61.20
1	57.05
1	57.05
1	79.70
1	79.70
1	45.60
1	1,247.70
1	62.55
1	69.50
1	82.25
4	5.05
4	368.80

VALUE

bt ✓ 1,156.60
? 424.25
? 31.60
de ✓ 61.20
? 57.05
? 57.05
x 79.70
de 79.70
y 45.60
de 1,247.70
nei 62.55
nei 69.50
nei 82.25
? 20.20
? 1,475.20

Total Parts : 4,950.15

Performance Motors Limited

A member of the Sime Darby Group

Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

319, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47104
Date Estimated : 28/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SKB7420J	NM26592	24/06/2011	320i/4 (A)	0

Claims OD / 3rd Party / Uninsured losses / Direct Settlement

Regi No. 7/6/18 Q1040

Date & Time 7/6/18 2:04:00

Surveyor's name Taufik

Surveyor's Tel 97495779

Approved Yes / No

Authorised By Taufik @ lkkauto.com

Days 5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Labour 1	:	6,594.00
Parts	:	4,950.15
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	808.09
Grand Total	:	12,352.24

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **

** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

Performance Motors Limited

A member of the Sime Darby Group
Co., Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47104
Date Estimated : 28/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Hardy Martin Julian
760 Bedok Reservoir Road
#08-01

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 479245

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE		
SKB7420J	NM26592	24/06/2011	320i/4 (A)	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
To replace bumper and attachments, boot lid include knocking out dents caused by the accident	2550.00		2,550.00			
To spray paint rear bumper and boot lid	1738.00		1,738.00			
To check electrical wiring systems and lightings at the rear section for proper function.	150.00		150.00			
To supply rear emboss number plate.	83.00		83.00			
To carry out body cavity preservation. (Per panel).	100.00		100.00			
Sundries.	80.00		80.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
BOOTLID	1,156.60	1.00		1,156.60
RR BUMPER CTR BOTTOM GUIDE	61.20	1.00		61.20
# RR BUMPER INSERT (M) *	158.45	1.00		158.45
RR BUMPER COVER (M)	79.70	1.00		79.70
RR BUMPER (M)	1,247.70	1.00		1,247.70
EMBLEM ADHERED REAR 320I	62.55	1.00		62.55
# GROMMET *	0.75	2.00		1.50
PLAQUE 74MM	69.50	1.00		69.50

SUPPLEMENTARY ITEMS

Total Labour :	4,701.00
Total Parts :	2,837.20
Total Labour & Parts :	7,538.20
Deduction for Excess :	
Total Repair Costs less Excess:	7,538.20
GST @7%:	527.67
Grand Total :	8,065.87

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47104
Date Estimated : 28/05/2018
Prepared By : Gary Poh Chai Hoon

Page No. :

REPAIR FOR -
Hardy Martin Julian
760 Bedok Reservoir Road
#08-01

- ACCOUNT - 66
MSIG Insurance (S) Pte Ltd
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

Singapore 479245

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEASE
SKB7420J	NM26592	24/06/2011	320i/4 (A)	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# RR BUMPER INSERT (M) *	158.45	1.00	new	158.45
# GROMMET *	0.75	2.00	new	1.50

Total Labour :	
Total Parts :	159.95
Total Labour & Parts :	159.95

LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010069/T1TD3N2

Date: 19/07/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	80422344QMY
Claimant Vehicle No :	SKB7420J	Insured Vehicle No :	SKX9631M
Date of Loss:	27/05/2018	Nature of Claim:	TP
		Claim No:	559665

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKB7420J	Engine No:	B230I819N46B20BD
Make & Model:	BMW 320I, 2.0 ABS D/AB 2WD 2DR GAS/D (A)	Chassis No:	WBAPG56000NM26592
Reg. Date:	24/06/2011 (Man. Year: 2010)	Odometer:	81298 km
Colour:	Grey		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	255/35 R18	Rear Tyre Size:	255/35 R18
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,343.10	3,000.20	2,342.90	43.85
Miscellaneous Items	0.00	0.00	0.00	
Labour	6,361.00	4,538.00	1,823.00	28.66
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (\$\$)	11,704.10	7,538.20	4,165.90	35.59
+ GST 7.00/7.00% (\$\$)	819.29	527.67	291.62	35.59
Nett Amount (\$\$)	12,523.39	8,065.87	4,457.52	35.59

INSPECTION

Date of Assignment: 31/05/2018

Date Inspected: 07/06/2018 Inspected At:

Performance Motors Limited
(Alexandra)
303 Alexandra Road, Sime Darby
Performance Centre
Singapore 159941

Estimated Period of Repair: 5.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jul 2018)
Parts:	M1-COUPE	BMW 320I 2.0 ABS D/AB 2WD 2DR GAS/D (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKB7420J)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No. Particulars	Condition	Repairer's	Amount
1	1	*BOOTLID	Bent	1,156.60 FS	*1,156.60 FS
2	1	*RR BUMPER CARRIER	Not Necessary	424.25 FS	*- FS
3	1	*RR BUMPER CTR GUIDE	Not Necessary	31.60 FS	*- FS
4	1	*RR BUMPER CTR BOTTOM GUIDE	Deformed	61.20 FS	*61.20 FS
5	1	*RR BUMPER LH SIDE GUIDE (M)	Not Necessary	57.05 FS	*- FS
6	1	*RR BUMPER RH SIDE GUIDE (M)	Not Necessary	57.05 FS	*- FS
7	1	*RR BUMPER COVER (M)	Not Necessary	79.70 FS	*- FS
8	1	*RR BUMPER COVER (M)	Deformed	79.70 FS	*79.70 FS
9	1	*RR BUMPET TOW HOOK COVER (M)	Not Necessary	45.60 FS	*- FS
10	1	*RR BUMPER (M)	Deformed	1,247.70 FS	*1,247.70 FS
11	1	*EMBLEM ADHERED REAR 320I	Necessary	62.55 FS	*62.55 FS
12	1	*PLAQUE 74MM	Necessary	69.50 FS	*69.50 FS
13	1	*BOOTLID GASKET	Not Necessary	82.25 FS	*- FS
14	4	*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	20.20 FS	*- FS
15	4	*PDC SENSOR	Not Necessary	1,475.20 FS	*- FS
16	1	*SUNDRIES	Necessary	150.00 FS	*80.00 FS
17	1	*REAR EMBOSS NUMBER PLATE	Bent	83.00 FS	*83.00 FS
18	1	*RR BUMPER INSERT (M)	Necessary	158.45 FS	*158.45 FS
19	2	*GROMMET	Necessary	1.50 FS	*1.50 FS
Total Parts (S\$)				5,343.10	3,000.20

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REPLACE BUMPER AND BOOTLID & ATTACHMENT INCLUDE KNOCKING CAUSE BY THE ACCIDENT	New	3,400.00	2,550.00
2	PAINTING REAR BUMPER,BOOTLID,TAIL PANEL	New	2,666.00	1,738.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS AT THE REAR SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (\$\$)			6,361.00	4,538.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >