

BH AUTO SERVICES PTE LTD

Blk 1, Sector C, Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636
Tel: 6559 8944 / Fax: 6269 2404

India International Insurance Pte Ltd

64 Cecil Street
#04-05 IOB Building
Singapore 049711
ATTN: MOTOR CLAIM DEPARTMENT

Tel : 63476100 Fax : 62244174

ACCIDENT REPAIR ON : SLJ8373B
MODEL : **RANGE ROVER SPORT 3.0**
POLICY NO : **VA1/GA331245**
CHASSIS NO : **SALLSAAG5DA804938**
MANUFACTURING YEAR : **2013**
DATE / TIME OF ACCIDENT: **02/06/2018** Time: **1330Hrs ALONG HILL STREET**
THIRD PARTY VEHICLE NO : **SHA3533J**

Date: **05/06/2018**

Page : 1 of 2

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

<u>Replacement Of Parts</u>		Quantity	Unit Price	Condition	Amount
S/N			S\$		S\$
1	Tailgate <i>X repair</i>	1	5400.00		5,400.00
2	Tailgate Lettering "Range Rover" <i>- mec</i>	1	269.00		269.00 /
3	Tailgate Lettering "Sport" <i>- mec</i>	1	59.00		59.00 /
4	Tailgate Lettering "HES" <i>- mec</i>	1	141.00		141.00 /
5	Tailgate Centre Moulding <i>X NA</i>	1	538.00		538.00
6	Tailgate Lower Garnish <i>- Cut</i>	1	588.00		588.00 /
7	Rear Windscreen Moulding <i>X mec</i>	1	408.00		408.00
8	Tailgate Weatherstrip <i>X</i>	1	134.00		134.00
9	Rear Bumper <i>- Re</i>	1	1910.00		1,910.00 /
10	Rear Bumper Side Retainer LH <i>- mec</i>	1	24.00		24.00 /
11	Rear Bumper Side Bracket LH <i>?</i>	1	75.00		75.00
12	Rear Bumper Side Retainer RH <i>X</i>	1	24.00		24.00
13	Rear Bumper Side Bracket RH <i>X</i>	1	75.00		75.00
14	Rear Bumper Centre Bracket <i>X</i>	1	150.00		150.00
15	Rear Bumper Lower Centre Garnish <i>- SCP</i>	1	116.00		116.00 /
16	Rear Bumper Reflector LH <i>- CRA</i>	1	77.00		77.00 /
17	Rear Bumper Sensor <i>- Om</i>	4	215.00		860.00 /
18	Rear Bumper Trade Plate <i>- RZPC</i>	1	142.00		142.00 /
19	Rear Bumper Reinforcement <i>?</i>	1	1367.00		1,367.00
20	End Panel <i>X repair</i>	1	1689.00		1,689.00
21	End Panel Top Garnish <i>X</i>	1	153.00		153.00
22	Tail Lamp LH <i>- CRA</i>	1	850.00		850.00 /
23	Tail Lamp Bracket <i>?</i>	1	515.00		515.00
24	Muffler Exhaust Tip <i>X repair</i>	1	751.40		751.40
Sub-Total:					16,315.40 <i>5036</i>
Less Discount 10%					1,631.54
Total Parts:					14,683.86 <i>4532.4</i>

Special Nett Items

1	Anti-rust coating <i>X</i>	2	80.00		160.00
2	Rear Bumper Clips <i>- mec</i>	10	4.50		45.00 /
3	Rear Windscreen Sealant <i>X</i>	1	100.00		100.00
Total Parts:					305.00

Labour Charges For Front and Side Portion

1	Provide skill labour to remove all damaged parts, panel beat, cut & weld if necessary and align all panel and reinstall all damaged parts.	300	1,500.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray with 2K paint with oven spray booth facilities	500	900.00
3	Provide skill labour to disconnect and check electrical wiring	-	30.00
4	Remove and refit rear windscreen	X	180.00
5	Remove and refit rear end panel lining and garnish to facilitate repairs	X	100.00
6	Reset management system with diagnostic fault e.g. sensor sensitivity	X	300.00
7	Remove and replace bumper sensor	40	100.00
8	Remove/realign/replace exhaust pipe to facilitate repairs	X	150.00
9	Mount vehicle onto chassis alignment bench and reset chassis alignment to recommended specifications	X	350.00

Total Labour:

3,610.00

Total Parts & Labour:

18,598.86

GST 7%

1,301.92

Grand Total:

19,900.78

Estimate Repair Duration

10 days

ACCIDENT VEHICLE OF : SLJ8373B

Page : 2 of 2

5447.4

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Gino Qiang
 Company : LKK
 Date : 06/6/18
 Time : _____
 Contact No: 82880282
 Email : Gino.Qiang@lkkauto.com

4 Days.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: