

(08/11/13)

Survey: Kelvin

REF:

CS/BW18010082/Kthb32

ASSIGNMENT

From: _____ Date: _____

Estimated Cost: _____

OD/TP/INS/TP RES/OD RES/EVA/INV/MV

To Inspected Vehicle No: _____

at Workshop m/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____

Sum Insured: _____ Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent?: Yes or No

GIA / PR Seen: _____ Consistent?: Yes or No

Est. Repairs: _____ days Res.: Yes or No

Lum Sum: _____ % 3 Val.: Yes or No

CA / .REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: _____ Person Contacted: _____

Veh No: SHD34604 Yr Regn: 18 Aug 2016

Type: M.Car / M.Cycle / Bus / Van / Lorry / Tug / Prime Mover /

Truck / Trailer or

Make: Hyundai I40 C.C. 1600Colour: Blue A/C: Ins Std / NI / NASp. Reading: _____ T/Radio: Ins Std / NI / NA

Eng/No: _____

C/No: KMHLD414MH409334

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order Jammed / Leaked / Burnt orBrake: In order Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD / R/Rim or

Tyre Size; F: 205/60R16

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or Campoon - FrontFront 7 mm Rear 7 mmR/Bal. 7 mm L/Bal. 7 mmD.O.A. 24/5/12 D.O.I. 4/6/12Survey held at (DGE (Loyang))

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

Rear o/s / Fnd

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time	Action / Instruction
	<u>Front Both chas Damaged</u>
	<u>unsafe to repair</u>
	<u>to scrap</u>
	<u>Bill to Comfort (Sin Ming)</u>
	<u>410 846011 - CS/EQL18W7567/Kthb3</u>
	<u>DIY: 210418</u>
	<u>RECEIVED 5 JUN 2018</u>

Date/Time, File Pass to?

☐ : Prell. Report

15/6 Typist

☐ : Final Report

Date/Time, File Return to?

2)

Report Format:

TP

Lump Sum / I.B.I: (\$ _____)

Days Of Repair: _____

Resurvey No. of Trip: _____

Add Fee:

☐ : Site Insp (\$ _____)☐ : Interview (\$ _____)☐ : Tech. Invs (\$ _____)☐ : Weekend (\$ _____)

Survey Fee:

Transportation:

____ \$ + RS ____ \$

Photos

Others

TOTAL

COMFORT DELGRO
ENGINEERING

VARS

(Pound)

Home	New Request	Search	VARS Reports	Administration	Welcome, Teo Yen Yee
------	-------------	--------	--------------	----------------	----------------------

Branch

AR Number: AR-05-18-000854
Maintenance Branch: BRADDELL

Vehicle Arrival Details

Check-In Mode: TOWED (Same Location)
Check-In At: 24/05/2018 16:30
Tow Driver's Name:
Tow Truck Reg. No.:

Vehicle Details

Taxi Registration No.: SHD3460U
Taxi Company: COMFORT TRANSPOR...
Taxi Insurer:
Taxi Model: SONATA

Hirer Details

Status: HIRER
Name: LAU FOOK YUEN
NRIC: S0149893B
License Issued Date:
License Expiry Date:
Address: 641 JURONG WEST STREET 61
#11-36 640641
Roled in accident: Hirer was the driver
Mobile Phone No: 90699489
Home Phone No: 65191758

Driver Details

Status: HIRER
Name: LAU FOOK YUEN
NRIC: S0149893B
License Issued:
License Expired:
Address: 641 JURONG WEST STREET 61
#11-36 640641
Mobile Phone No: 90699489
Home Phone No: 65191758

Accident Details

Accident Date: 24/05/2018 16:30
Downtime Start: 24/05/2018 16:30
Accident Location: BLK 641 JURONG WEST ST 61
Location Type: STRAIGHT ROAD
Traffic Control: NOT CONTROLLED
Traffic Flow: DUAL CARRIAGEWAY
Weather Condition: NOT SURE
Traffic Volume: NOT SURE
Road Condition: NOT SURE
Lighting Condition: DAYLIGHT
Taxi Damaged At: NOT SURE
Damage Severity: NOT SURE
Late Report Reason: -
Taxi Speed: NOT SURE
No. of Passengers: NOT SURE
Collision Type: SEE REMARKS BELOW
Brakes Applied: No
Reported To Police: No
Police Report No.:
Ambulance Called: No
Scene Photo Taken: No
Scene Video Taken: No
Driver Hospitalized: No

Remarks: ELECTRICAL BOX

Third Party Vehicle Details

Vehicle No	Involved Others	Owner Name	Owner NRIC	Damage At	Damage Se...	Involved T...
-						

Injured Person Details

Name	NRIC	Gender	Mobile Phone	In Vehicle No.	Role In Accident	Injury Type	Remarks
LAU FOOK YUEN	S0149893B	MALE		SHD3460U	TAXI DRIVER	SLIGHT	DRIVER IN HOSPITAL

Witness Details					
Name	NRIC	Gender	Home Phone	Role In Accident	Vehicle No.
No items to display.					

Vehicle No and Application Reference Number

AR Number: AR-05-18-000854
 Taxi Registration No.: SHD3460U

Taxi Claim Assessment Details

Initial Fault: FAF
 LOI: NO LOI
 Claim: OWN DAMAGE
 Repair By: COMPANY REPAIR (OD)
 Workshop: COMFORTDELGRO ENGINEERING
 [If Loss of Income is on hold, enquire only 3 months after collection of taxi]

Pending Decision:
 LOI Days:
 LOI Percent to Pay:
 Amount Paid:
 Remarks:

We have assessed the above mentioned accident case and made the following arrangement.

Assessed By: Teo Yen Yee
 Assessed On: 28/05/2018

I agree to the above-mentioned arrangement.
 I am further informed that the taxi rental GIRO shall not be deducted during the repair period, **effective 1 working day** after the reporting of this accident (weekdays) or **the following working day after Monday** (for Weekends).
 I also note that should there be a counter-claim against the CTPL's / CCPL's insurance by a Third Party, I am liable to pay another Third Party Excess of \$1,000.00 to CTPL / CCPL.
 I shall submit witness statement within 7 days from the date of this document.

I hereby confirm that there is no personal items left behind inside the vehicle.

Electronic Payment via GIRO - I (the hirer) am not a bankrupt and authorize ComfortDelGro Engineering Pte Ltd to credit Loss of Income payment to my account as given below:

Bank Name:
 Branch Name:

Bank Account No.:

Hirer Signature:

Hirer Name: LAU FOOK YUEN
 Hirer NRIC: S0149893B

Job Card

Job Card Type:

Job Card Number (auto):

Activity Chart

Accident Happened: 24/05/2018 16:30
 Vehicle Towed In: 24/05/2018 16:30
 Tow Driver's Name:
 Tow Truck Reg. No.:
 Accident Reported: 28/05/2018 15:51

Part Prices Received:
 Estimates Prepared:
 Estimates Faxed To Insurer:
 Vehicle Surveyed:
 Requisition Submitted To SCM:

All Parts Received:
 Repair Completed:
 Quality Checked:
 Customer Informed:
 Vehicle Collected:

A member of COMFORTDELGRO

Date/Time: 28.05.2018 17:10

Page : 1

Team: ARC Repair OD(CLSO)1

JOB CARD Sales Order:

JC NO305165637

CUSTOMER		REGN NO: SHD3460U	MILEAGE
MS COMFORT TRANSPORTATION PTE LTD		MAKE: HYUNDAI	FUEL
CUSTOMER NO. 7010045		MODEL I-40	E.....1/2.....F
ADDRESS 383 SIN MING DRIVE Singapore SINGAPORE 575717		DATE/TIME IN 24.05.2018 16:30	
(R) 65508755	(O)	YR OF MANU. 18.08.2016	TARGET DATE
(P)		CHASSIS CODE KMHLE41UMGU093321	COMPLETION DATE/TIME:
COUNT CARD NO.			

JOB DESCRIPTION

Accident Date: 24.05.2018
NATURE: TP/OD 24.05.18

/NO	LABOR CODE	DESCRIPTION
-----	------------	-------------

OP-REAR RH & PRT.

(216)

BOOKED & PASSED OUT BY:

107891002-91585

SERVICE ADVISOR

CUSTOMER'S SIGNATURE

Recognition Slip

Exit Pass

No.: SHD3460U

JU

Vehicle No.:

SHD3460U

Signature of Service Advisor

Signature/Date

Name of Service Advisor

Date

Returned to Service Reception upon collection

To be kept by Security Guard

COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO : SHD 3460U

DATE 1/6/2018 15:34

MAKE :

MODE L : HYUNDAI i40

Q'ty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover			\$ 562.30
	Front Bumper Sponge			\$ 142.20
	Front Bumper Reinforcement			\$ 526.10
	Front Bumper Grille (LH/RH)	\$	40.30	\$ 80.60
	Front Bumper Centre Grille			\$ 178.60
	Front Bumper Lip			\$ 62.50
	Front Bumper Bracket Top (LH/RH)	\$	22.40	\$ 44.80
	Front Bumper Retainer Mounting	\$	9.20	\$ 18.40
	Headlamp Support Top Cover			\$ 398.00
	Headlamp Support Panel Assy			\$ 1,067.50
	Headlamp (LH/RH)	\$	1,388.00	\$ 2,776.00
	Radiator			\$ 850.20
	Radiator Fan Blade,Cowling,Motor Assy			\$ 792.95
	Radiator Bracket (RH/LH)	\$	6.50	\$ 13.00
	Radiator Hose Upper			\$ 47.40
	Radiator Hose Lower			\$ 47.40
	Radiator Guard	\$	35.00	\$ 70.00
	Horn Unit (RH)			\$ 86.75
	Horn Wire			\$ 156.50
	Front Fender (LH/RH)	\$	619.00	\$ 1,238.00
	Front Fender Shield (LH/RH)	\$	169.80	\$ 339.60
	Front Fender Retainer	\$	9.20	\$ 18.40
	Aircon Condenser			\$ 1,137.35
	Wiper Container			\$ 61.90
	Wiper Container Motor			\$ 65.90
	Front Chasis Member	\$	1,575.85	\$ 3,151.70
	Gearbox			\$ 14,808.00
	Gearbox Mounting			\$ 342.50
	Inter Cooler			\$ 921.90
	Inter Cooler Mounting (2 PCS)			\$ 25.90
	Hose B To Inter Cooler			\$ 229.70
	Hose C To Inter Cooler Inlet			\$ 113.30
	Pipe To Inter Cooler			\$ 167.05
	Pipe To Inter Cooler Outlet			\$ 244.55
	SUB TOTAL			\$ 30,786.95
	LESS 20%			\$ 6,157.39
	DISCOUNTED TOTAL			\$ 24,629.56
	Front Number Plate			\$ 25.00
	Front No Plate Trim Cover			\$ 30.00
	Front Fender Advertisement Logo (LH/RH)	\$	100.00	\$ 200.00
				\$ 255.00

Parts Description/ Labour	Type	Unit Price	Amount
Labour Charge			
Panel Beating			\$ 1,200.00
Spray Painting Charge			\$ 600.00
Wiring Charge			\$ 50.00
Tuff Kote			\$ 50.00
Towing Charge			\$ 60.00
Frt Chassis Alignment			\$ 400.00
Remove/Refix Aircon & Refill Gas			\$ 150.00
Remove/Refix Engine/Gearbox			\$ 650.00
Remove/Refix Dashboard			\$ 450.00
Remove/Refix Fuse Box			\$ 180.00
TOTAL LABOUR			\$ 3,790.00
ESTIMATE TOTAL			\$ 28,674.56
<p>Koluh 16/16/1</p> <p>4/6/18 133 rks</p> <p>Front Buth chasis Danged</p> <p>unsate to repair</p> <p>to scrap</p>			
<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none"> • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer</p> <p>Signature:</p> <p>Date:</p>			
<p>This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.</p>			

COMFORT DELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE No : SHD 3460U

DATE 1/6/2018 15:38

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Rear Bumper			\$ 603.60	
	Rear Bumper			\$ -	
	Rear Bumper Reinforcement			\$ 504.35	
	Rear Bumper Reinforcement Bracket (LH/RH)		\$ 180.00	\$ 360.00	
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Bumper Sponge			\$ 143.40	
	Rear Bumper Under Cover			\$ 225.00	
	Tail Lamp (RH)			\$ 565.60	
	Tail Lamp Quarter Panel (RH)			\$ 97.90	
	Rear Panel			\$ 592.30	
	Rear Panel Garnish			\$ 57.70	
	Rear Panel Lower Panel			\$ 495.50	
	Spare Tyre Panel			\$ 900.50	
	Spare Tyre Panel Cushion			\$ 209.05	
	Rear Fender (RH)			\$ 2,020.10	
	Rear Fender Inner Panel (RH)			\$ 1,190.50	
	Rear Fender Inner Lining (RH)			\$ 164.40	
	Rear Fender Air-Duct			\$ 51.60	
	Rear Windscreen Moulding			\$ 60.00	
	SUB TOTAL			\$ 8,377.20	
	LESS 20%			\$ 1,675.44	
	DISCOUNTED TOTAL			\$ 6,701.76	
	Rear Bumper Reverse Sensor			\$ 135.70	Nett
	Rear Fender Advertisement Logo (LH/RH)		\$ 100.00	\$ 200.00	Nett
	Rear Windscreen Sealant			\$ 46.00	Nett
				\$ 381.70	
	Labour Charge				
	Panel Beating			\$ 1,000.00	
	Spray Painting Charge			\$ 1,000.00	
	Wiring Charge			\$ 50.00	
	Tuff Kote			\$ 50.00	
	Remove/Refix Cushion & Upholstery Rear			\$ 150.00	
	Remove/Refix Rear Windscreen Glass			\$ 120.00	
	Remove/Refix Reverse Sensor			\$ 120.00	
	TOTAL LABOUR			\$ 2,490.00	
	ESTIMATE TOTAL			\$ 9,573.46	

This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.



51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Our Ref : CS/QW18010082/K1tbs2

Date: 06th June 2018

Comfort Transportation Pte Ltd
383 Sin Ming Drive
Singapore 575717

Attn: Doris Lim

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE NO.: SHD 3460U
ACCIDENT ON 24/05/2018**

Instruction was received to inspect the vehicle Reg. No. SHD 3460U. The inspection was conducted on 04/06/2018 at the premises of M/s Comfortdelgro Engineering Pte Ltd, 59 Loyang Drive Singapore 508969.

The following vehicle information was recorded:

Registration Number	: SHD 3460U
Make/Model	: Hyundai I40
Year of Registration	: 2016
Body Colour	: Blue
Chassis Number	: KMHLB41UMGU093321
Engine Capacity	: 1685 cc

The following are our comments:-

- (a) The vehicle sustained damages at the rear o/s portion and front portion. (Details see photographs enclosed)

- (b) In view of this, we are of the opinion that it would be **unsafe** to proceed with the repairs due to extensive damages on the chassis under the category of **the section 2 of THE ROAD TRAFFIC ACT on THE MOTOR VEHICLES (CONSTRUCTION AND USE) (AMENDMENT NO.2) RULES 1989**, that:
- no vehicle shall be fitted with a replacement chassis or any body part where the chassis is an integral part of the vehicle.*
- and we therefore recommend it to be written off as **"Total Loss"**

Vehicle Inspected By:



KALVIN ANG WEI KUN
Automotive Assessor / Investigator



K.K.LAU
*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIARD, AM, NIJAAR(USA),
AM CATARI(CAN), M. MATA(USA), M. MATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.