

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT**Our File No:** CC4/AIG18010108/DEA3Q2
Date: 15/06/2021**REFERENCE**

Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd.	Policy No:	2100385762-03
Claimant Vehicle No :	SHA6086M	Insured Vehicle No :	SDH8995L
Date of Loss:	01/06/2018	Nature of Claim:	TP
		Claim No:	5311396350SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHA6086M		
Make & Model:	TOYOTA PRIUS HYBRID, 1.8 CVT (A)	Engine No:	2ZRS056587
Reg. Date:	19/07/2017 (Man. Year: 2017)	Chassis No:	JTDKB3FU903561522
Colour:	Blue	Odometer:	155756 km
Engine Capacity:	1798 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:		Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	13,270.35	9,719.09	3,551.26	26.76
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,320.00	1,410.00	910.00	39.22
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	15,590.35	11,129.09	4,461.26	28.62
+ GST 7.00/7.00% (S\$)	1,091.32	779.04	312.28	28.61

Nett Amount (S\$)	16,681.67	11,908.13	4,773.54	28.62
+ Loss of Use (6.0 x S\$50.00/day) (S\$)		300.00		
+ Car Rental (6.0 x S\$125.40/day) (S\$)		752.40		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		12,962.53		
Global Sum Settlement (S\$)		9,320.00		

INSPECTION

Date of Assignment: 01/06/2018

Date Inspected: 04/06/2018

Estimated Period of Repair: 6.0 days

Inspected At: Chunni Motor Work Pte Ltd (HQ)
Blk 10 Ang Mo Kio Industrial Park 2A, #03-19 AMK Autopoint
Singapore 568047

Adjuster: BRYAN TANI**Manager:** Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*LAMP ASSY ,FOG ,LH	Not Necessary	920.00 FL	*- FL
2	1		*FRONT BUMPER COVER	Cut	490.50 FL	*490.50 FL
3	1		*FRONT BUMPER CLIPS	Necessary	22.00 FL	*22.00 FL
4	1		*BRACKET ,FRONT BUMPER SIDE ,LH	Not Necessary	77.00 FL	*- FL
5	1		*UNIT ASSY ,HEADLAMP ,LH (LED)	Mtg Cracked	3,413.40 FL	*3,413.40 FL
6	1		*HEAD LAMP PANEL (LH)	Not Necessary	213.50 FL	*- FL
7	1		*TOP PANEL SIDE	Not Necessary	69.20 FL	*- FL
8	1		*BRACKET ,HEADLAMP MOUNTING ,LH	Not Necessary	25.50 FL	*- FL
9	1		*FENDER SUB-ASSY ,FRONT LH	Dented	933.10 FL	*933.10 FL
10	1		*FRONT FENDER SHIELD ,LH	Deformed	198.50 FL	*198.50 FL
11	1		*FRONT FENDER SHIELD CLIP	Necessary	14.90 FL	*14.90 FL
12	1		*FRONT FENDER HYBRID EMBLEM ,LH	Necessary	86.50 FL	*86.50 FL
13	1		*MIRROR ASSY ,OUTER REAR VIEW ,LH	Broken	1,374.00 FL	*1,374.00 FL
14	1		*COVER ,OUTER MIRROR ,LH	Broken	141.90 FL	*141.90 FL
15	1		*MIRROR OUTER ,LH	Broken	212.80 FL	*212.80 FL
16	1		*FRONT WHEEL RIM (LH)	Cut	1,570.55 FL	*1,570.55 FL
17	1		*FRONT WHEEL HUB BEARING (LH)	Damaged	559.94 FL	*559.94 FL
18	1		*FRONT SUSPENSION LOWER ARM (LH)	Distorted	631.90 FL	*631.90 FL
19	1		*FRONT SHOCK ABSORBER (LH)	Distorted	398.20 FL	*398.20 FL
20	1		*ABSORBER TOP MOUNTING LH	Not Necessary	196.20 FL	*- FL
21	1		*FRONT DRIVE SHAFT (LH)	Not Necessary	1,764.00 FL	*- FL
22	1		*RACK & PINION ASSY	Distorted	1,621.30 FL	*1,621.30 FL
23	1		*BAR ,STABILIZER	Distorted	352.40 FL	*352.40 FL
24	1		*LINK ASSY ,FRONT STABILIZER LH	Distorted	196.80 FL	*196.80 FL
25	1		*KNUCKLE ,STEERING ,LH	Distorted	580.80 FL	*580.80 FL
26	1		*END SUB-ASSY ,TIE ROD ,LH	Distorted	159.30 FL	*159.30 FL
27	1		*FRONT DOOR COMFORT LOGO	Not Necessary	75.00 FS	*- FS
28	1		*FRONT TYRE (LH)	Serviceable	216.00 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	16,515.19	12,958.79
- List Item Discount on L Items 20.00/25.00% (\$)	3,244.84	3,239.70
Total Parts (\$)	13,270.35	9,719.09

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING	New	750.00	600.00
2	SPRAY PAINTING CHARGE	New	900.00	500.00
3	WIRING CHARGE	New	50.00	30.00
4	TUFF KOTE	New	50.00	40.00
5	TOWING CHARGE	New	50.00	0.00
6	REMOVE/REFIX UNDERCARRIAGE (FRT)	New	400.00	180.00
7	FRT WHEEL ALIGNMENT	New	120.00	60.00
Gross Labour Cost (S\$)			2,320.00	1,410.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >