Adjuster Report Page 1 of 4

#### LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

#### VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18010151/K1EA3N2

D4FDGU621041

Date: 21/07/2020

**REFERENCE** 

Price:

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. 2100468750 Policy No: Claimant SHA8152S Insured Vehicle No: SJS79E

Vehicle No:

Date of Loss: 02/06/2018 Nature of Claim: ΤP Claim No: 1065069948SG

**DESCRIPTION & IDENTIFICATION OF VEHICLE** 

**SHA8152S** Reg No:

HYUNDAI 140, 1.7 D CRDI F/L ABS AIRBAG 4DR Make & Model: Engine No:

(A)

KMHLB41UMGU079796 Reg. Date: 12/11/2015 (Man. Year: 2015) Chassis No:

Colour: Yellow Odometer: 384462 km

1685 cc **Engine Capacity:** Market Value/New Car N/A

Market Value/New Car Price Sum Insured (S\$):

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 205/60 R16 Rear Tyre Size: 205/60 R16 Front Left Side: West Lake 7 mm Rear Left Side: West Lake 7 mm Front Right Side: Rear Right Side: West Lake 7 mm West Lake 7 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,915.76	1,398.00	1,517.76	52.05
Miscellaneous Items	0.00	0.00	0.00	
Labour	2,390.00	1,470.00	920.00	38.49
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	5,305.76	2,868.00	2,437.76	45.95
Approved Total (Overridden) (S\$)		2,300.00		
(S\$)	5,305.76	2,300.00	3,005.76	56.65
+ GST 7.00/7.00% (S\$)	371.40	161.00	210.40	56.65
Nett Amount (S\$)	5,677.16	2,461.00	3,216.16	56.65
+ Loss of Use (4.0 x S\$	50.00/day) (S\$)	200.00		
+ Car Rental (4.0 x S\$119.28/day) (S\$) + Doc/Search Fee (S\$)  Nett Liability (S\$)		477.12		
		7.49		
		3,145.61		
Global Sum S	3,140.00			

**INSPECTION** 

04/06/2018 Date of Assignment:

Date Inspected: 04/06/2018 Inspected At: ComfortDelGro Engineering Pte Ltd

(Loyang)

Adjuster Report Page 2 of 4

59 Loyang Drive Singapore 508969

Estimated Period of Repair: 3.0 days

Adjuster: KALVIN ANG WEI KUN Manager: Asher Sng Rong Yi

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

Adjuster Report Page 3 of 4

# **REPAIR DETAILS**

### **Recommended Parts**

Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1		*REAR DOOR (RH)	Repair	1,351.10 FL	*- FL	
1		*FRONT DOOR (RH)	Dented	1,403.05 FL	*1,403.05 FL	
1		*ROCKER PANEL OUTER GARNISH (RH)	Repair	483.60 FL	*- FL	
1		*REAR WHEEL HUP-CAP (RH)	Grazed	150.70 FL	*150.70 FL	
1		*REAR BUMPER (NPA)	Repair	0.00 FL	*-FL	
1		*REAR RH FENDER (NPA)	Repair	0.00 FL	*- FL	
1		*REAR BUMPER RUBBE MAT	Not Necessary	50.00 FS	*-FS	
1		*REAR DOOR COMFORTDELGRO & APPS STICKER (RH)	Necessary	80.00 FS	*80.00 FS	
1		*FRONT DOOR COLOURED COMFORT LOGO (RH)	Necessary	75.00 FS	*75.00 FS	
F=Franchise part. S=SpcNett. L=ListItemDisc.  Sub Total (S\$)				3,593.45	1,708.75	
- List Item Discount on L Items 20.00/20.00% (S\$)				677.69	310.75	
			Total Parts (S\$)	2,915.76	1,398.00	
Report was unsubmitted during this print-out.						
	1 1 1 1 1 1 1	1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1 1	1 *REAR DOOR (RH) 1 *FRONT DOOR (RH) 1 *ROCKER PANEL OUTER GARNISH (RH) 1 *REAR WHEEL HUP-CAP (RH) 1 *REAR BUMPER (NPA) 1 *REAR RH FENDER (NPA) 1 *REAR BUMPER RUBBE MAT 1 *REAR BUMPER RUBBE MAT 1 *REAR DOOR COMFORTDELGRO & APPS STICKER (RH) 1 *FRONT DOOR COLOURED COMFORT LOGO (RH) Inchise part. S=SpcNett. L=ListItemDisc List Item Discount on L Items 20	A Total Parts (S\$)  Particulars  Condition  Repair  Repair  Repair  Pented  Repair  REAR BUMPER (NPA)  Repair  Repair  REAR BUMPER (NPA)  Repair  Repair  REAR BUMPER RUBBE MAT  Not  Necessary  REAR DOOR COMFORTDELGRO & APPS STICKER  Repair  Not  Necessary  Necessary  Necessary  Necessary  List Item Discount on L Items 20.00/20.00% (S\$)	Total Parts (S\$)   Particulars   Condition   Repairer's	

Adjuster Report Page 4 of 4

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

### **Recommended Labour**

No	Particulars	Lab.Type	Repairer's	Amount
Lab	our Items			
1	PANEL BEATING -REPAIR REAR FENDER	New	560.00	400.00
2	SPRAY PAINTING CHARGE-DOOR X2, FENDER /BUMPER	New	1,250.00	1,000.00
3	WIRING CHARGE	New	50.00	0.00
4	TUFF KOTE	New	50.00	20.00
5	REMOVE/REFIX REVERSE SENSOR	New	120.00	0.00
6	TRANSFER OF DOOR	New	240.00	50.00
7	REAR WHEEL ALIGNMENT	New	120.00	0.00
	Gross Labou	r Cost (S\$)	2,390.00	1,470.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >