

15/07/18

INS. CASE OWNER:

CC 4/AXA1801

LKK:
IDAC:

Surveyor:

Sathya

DOI:

ASSIGNMENT

5/6/18

Date / Time:

5/6/18

Registered in Merimen:

5/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SHB 7935B

Name of Insured:

TRANS-LAB SERVICES PTE

Insured Tel No.:

HP:

Excess Sec II :SS

2500

D.O.A.:

1/6/18

Is driver the owner?

(YES / ☒ NO)

Nature of Accident:

If NO, Driver Name / Age:

Tay Heng Thiam

Driver Tel No.:

(V/L YES / NO)

Claim No.:

W477814

Policy No.:

VPX / P1680520

Make / Model:

HEVRAVE

Place of Accident:

74 Taxi Avenue

OI GIA REPORT:

☒ YES / NO

TP GIA REPORT:

☒ YES / NO

Insured Liability:

%

Final ? Yes / No

SHF 155K



INSRS:

WSP:

Tel:

Liability:

RMKS:

SMRT



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

5/6/18

in/n

12/6/18

29/8/18

2/10/18

29/11/18

SHF 155K - 11/10/18 (11/10/18) (11/10/18) (11/10/18)

SHB 7935B - X

email letter to O2

File pass to typist type report

seek mandate via merimen

mandate approve via merimen

RECEIVED 17 DEC 2018

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

12/6/18 email.
vival

Documentation Check List: Handler Typist

Notification ltr (if non-pickup):

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GLA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

PRELIMINARY ADVICE

Date/Time:

6/6/18

Sent By:

TAN

FINALIZATION

Date/Time:

Confirm with:

Confirm by:

Repair Cost:

SS

(

days) Reduction:

%

Email

Call

FINAL SETTLEMENT

Date/Time:

2/12/18

Confirm with:

Lee Gek.

Email

Call

Final Liability:

%

100 (Agreed / Assessed) BOLA S/N No.:

28

Repair Cost:

SS

4528.41

Loss of Rental (LOR):

SS

1143.61

(

9.5 days)

x 100.38

Loss of Use (LOU):

SS

475.00

(

50 x 9.5 days)

Loss of Income (LOI):

SS

(

S

x

days)

LOR only

☐

LOU only

☐

LOR + LOU

☐

LOR + LO

☐

[Tick only one]

GLA/LTA Search

SS

Medical:

SS

Disbursement:

SS

(e.g. Tow/ Independent)

Legal Cost

SS

Total:

SS

6147.02

Global Sum SS:

FINAL PAYMENT

Date/Time:

Confirm with:

Email

Call

Payee 1:

SS

6147.02

Name 1:

SMRT Taxis Pte Ltd

Payee 2: (Strike if N.A.)

SS

Name 2:

Payee 3: (Strike if N.A.)

SS

Name 3:

REF: AXA

mmmm

ASSIGNMENT

From: Date: 05062018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SHF 155K

at Workshop m/s: SMRT

of

Insured

Policy No:

Claims No:


Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 6 days Res.: Yes or No

Lum Sum: 2.8-2 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHF 155K Yr Regn: Nov / 2017

Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Prius 4 C.C. 1798

Colour: Purple Maroon A/C: Insured / Std / NI / NA

Sp. Reading: 61071 T/Radio: Insured / Std / NI / NA

Eng/No: 2ZRS108741

C/No: JTDKB3FU303575335

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 195/65 R15

R: 195/65 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 1/6/2018 D.O.I. 5/6/2018

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision

Date / Time Action / Instruction

28/11/18 Confirm 2.B-2 \$4528.41 with booking days

TAX/06/18/2005

AXA

- SHB 7935B

- JHD 8826R

(Red. \$15518.60
77.1)

Date/Time, File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time, File Return to?

2)

Add Fee: ☐ Site Insp (\$☐ Interview (\$☐ Tech. Insp (\$☐ Weekend (\$

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

) \$+RS \$

) Photos

) Others

Report Format :

Lump Sum / I.B.I. (\$

TOTAL



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
AXA INSURANCE PTE LTD		Ref : CC4/AXA18010165/Vwb3	
8 SHENTON WAY #24-01 AXA TOWERS SINGAPORE 068811		Date : 05-06-2018	
		Code : AXA2	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SHB 7935B	Veh. Inspected	SHF 155K
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	05/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	01/06/2018	Inspection Date	05/06/2018
Survey held at	SMRT AUTOMOTIVE SERVICES PTE LTD 60 WOODLANDS INDUSTRIAL PARK E4 SINGAPORE 757705		
5a. Remarks			
A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018		05 Jun 2018 09:37 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

Insured:	TRANS-CAB SERVICES PTE LTD, Co. Reg. No.: 200303878K			[Created by insurer]
Main Claimant:	SMRT TAXIS PTE LTD, Co. Reg. No.: 198905369K			
Vehicle Reg. No.:	SHF155K	Date of Loss:	01/06/2018 00:00 - :59	
Claim Type:	TP / C0473814	Policy/Cover Note No.:	P1680520 (Third Party Only)	
Vehicle Reg. No. (Insured):	SHB7935B	Policy No. (Claimant):		
		Excess:	S\$5,000.00	
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628			
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Ernest Tay - 6880 4835]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/06/2018]			
Driver/Custodian (Insured):	TAY HENG THIAM (66 / Male), NRIC: S0200427E, Tel: +6591993598			

ASSOCIATED MAIL RECEIVED

- AXA_SG (05/06/2018): New TP Assignment - C0473814/P1680520

[View All](#)[Compose Case Mail](#)

ALL ASSOCIATED TASKS

Due Date	Priority	Type	Task Group	Subject	Handler	View All	Search Tasks	Create New Task	Complete
No results,						Assigned By	Completed On	Created On	Done?



Vwb3

11-6-18 / 11:49

11-6-18 / 15:49

SMRT Automotive Service Pte Ltd

60 Woodlands Industrial Park E4, Singapore 757705

FAX Number : 63685592

Estimator Telephone Number : 68662623


Accident Reporting Number : 68662672

SMRT Accident Vehicle Repair Estimates

5-6-18 / 15:49

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
Ref. No : TAX/06/18/2005
Reg. Date : 28/11/2017
Vehicle Type : TAXI
Make : TOYOTA PRIUS
Model : PRIUS4
Name of Driver : LAU WEI SUN LAWRENCE
Type of Accident : CHAIN COLLISION
Date / Time of Accident : 01/06/2018 04:30:00 PM
Accident Reported Date / Time : 02/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by : Sebastian
Vehicle is Towed Back? : No
Towed Back Date/Time :
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096405
Special Instruction to ARC, if any :
SHB7935B (TRANSCAB) - AXA P/R
BEFORE PAINT PHOTO AND AFTER PAINT PHOTO, FOR CHECK ITEM AND REPLACE ITEM PLEASE CALL
SURVEYOR SEBASTIAN (LKK) & Email : sebastianeang@lkkauto.com HP: 90036121
Prepared Date : 02/06/2018 11:13:14 AM



Recording Camera

☐ ☒

Radio Antenna

☐ ☒

1st witness

M

Date

5-6-18

2nd witness

Date

61071 Kay

Supplementary

Referto the Supplementary part later

61128

LEE SENG AUTO PARTS

Vehicle Return Date

12-6-18

Vehicle Return Time

12:00

QC 12/6/18 15:36 p.m.

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303575335

Mileage : 0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges :	1,859.00	1,000.00
Total Spray Painting Charges :	2,412.00	600.00
Total Material Charges :	11,563.69	2,638.42
Other Charges :	1,040.00	290.00
TOTAL :	16,874.69	4,528.42
Lump Sum Total :	0.00	0.00
No. of Repair Days :	11.00	6.00 ✓
Prepared / Adjusted By :		SEBASTIAN (LKK)
Arc / Surveyor Sign Off Date :	04/06/2018 11:03:25 AM	05/06/2018 03:49:22 PM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/06/2018 11:03:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :	QN-1806-0405	Invoice No :	
Quotation Date :	19/6	Invoice Date :	
Invoice Amount :		Prepared Date :	

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	600.00 ✓
TO REPAIR FRONT PORTION	845.00	400.00 ✓
Total Labour	1,859.00	1,000.00 ✓

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	200.00 ✓
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00
TO RESPRAY REAR PANEL	180.00	0.00
TO RESPRAY TAIL GATE	378.00	0.00
TO RESPRAY TAILGATE OUTSIDE GARNISH	378.00	200.00 ✓
TO RESPRAY REAR SPOILER	180.00	0.00
TO REPSRAY FRONT BUMPER	378.00	200.00 ✓
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00
Total Spray Painting & Panel Beating	2,412.00	600.00 ✓

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	50.00 ✓
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	100.00 ✓
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	60.00 ✓
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	60.00 ✓
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00
TO REPLACE SUNDRY PARTS	100.00	20.00 ✓
TO WASH AND VACUUM	60.00	0.00
Total Other Costs	1,040.00	290.00 ✓

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
5215947913			COVER, RR BUMPER ASSY	1	423.90	25.00	317.92	Replace	Replace	No	DT
5202347030			REAR BUMPER REINFORCEMENT	1	318.80	25.00	239.10	Replace	Replace S	No	DT
5245347010			GUARD, RR BUMPER, LOWER	1	558.30	25.00	418.73	Replace	Replace S	No	DT
5216947020			COVER, GUARD RR BUMPER LOWER	1	14.80	25.00	11.10	Replace	Replace	No	DT
5257647040			RETAINER, RR BUMPER, LH	1	111.50	25.00	83.63	Replace	Check	No X	NN
5257547040			RETAINER, RR BUMPER, RH	1	112.70	25.00	84.53	Replace	Check	No X	
5246247030			PAD, RR BUMPER, RH & LH, 1	2	3.80 2.60	25.00	5.70	Replace	Check	No X	
5246247020			PAD, RR BUMPER, RH & LH, 2	2	3.80 2.60	25.00	5.70	Replace	Check	No X	
5246247010			PAD, RR BUMPER, RH & LH, 3	2	3.80 2.60	25.00	5.70	Replace	Check	No X	
5219147030			SEAL, RR BUMPER ARM, RH & LH	2	11.00 22	25.00	16.50	Replace	Check	No X	
5256647900			FILLER, RR BUMPER, LH	1	119.90	25.00	89.93	Replace	Check	No X	
5256547900			FILLER, RR BUMPER, RH	1	119.90	25.00	89.93	Replace	Check	No X	
			SENSOR REVERSE	1	180.00	0.00	180.00	Replace	Replace	No	SC
			PIXEL STICKER	2	60.00 120	0.00	120.00	Replace	Replace	No	NEC
5259247040			SEAL, RR BUMPER, LH	0	85.20	25.00	0.00	Replace	Not given	No X	NN
5259147050			SEAL, RR BUMPER, RH	0	85.20	25.00	0.00	Replace	Not given	No X	
5839947030			COVER, REAR FLOOR UNDER, LH	0	234.30	25.00	0.00	Replace	Not given	No X	
7697147010C0			COVER, REAR UNDER, CENTER	1	106.90	25.00	80.18	Replace	Check	No X	
5839847050			COVER, REAR FLOOR UNDER, RH	0	169.50	25.00	0.00	Replace	Not given	No X	
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK	1	629.60	25.00	472.35	Replace	Check	No X	
	COMMO N	4006314	SEALANT SIKAFLEX	0	37.00	0.00	0.00	Replace	Not given	No X	
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR	0	929.60	25.00	0.00	Replace	Not given	No X	
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY	0	891.20	25.00	0.00	Replace	Not given	No X	
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE	0	27.90	25.00	0.00	Replace	Not given	No X	
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR	0	19.70	25.00	0.00	Replace	Not given	No X	
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR	0	52.30	25.00	0.00	Replace	Not given	No X	

10 20 6.20

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached	
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR	0	52.30	25.00	0.00	Replace	Not given	No	X
7540348010			EMBLEM SUB-ASSY REAR	0	46.30	25.00	0.00	Replace	Not given	No	X
	COMMON		SMRT LOGO	0	7.80	0.00	0.00	Replace	Not given	No	X
			STICKER DECAL 6555 8888	0	21.60	0.00	0.00	Replace	Not given	No	X
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR	0	360.70	25.00	0.00	Replace	Not given	No	X
6471847080C0			END PANEL, COVER, DECK TRIM SERVICE HOLE	0	47.00	25.00	0.00	Replace	Not given	No	X
6471647130C0			END PANEL, COVER, DECK TRIM, REAR	0	122.80	25.00	0.00	Replace	Not given	No	X
7608547916			SPOILER SUB-ASSY, REAR	0	1,322.10	25.00	0.00	Replace	Not given	No	X
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH	1	438.10	10.00	394.29	Replace	Check	No	X
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace S	No	✓
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace S	No	✓
5211947962			COVER, FR BUMPER	1	495.50	25.00	371.62	Replace	Replace	No	✓
5212847906			COVER, FR BUMPER LH	0	28.10	25.00	0.00	Replace	Not given	No	X
5212747907			COVER, FR BUMPER RH	1	28.10	25.00	21.07	Replace	Replace	No	✓
5311247240			GRILLE, RADIATOR	0	165.00	25.00	0.00	Replace	Not given	No	X
5310147080			GRILLE SUB-ASSY	1	335.60	25.00	251.70	Replace	Replace	No	✓
5211447190			BRACKET, FR BUMPER	1	99.80	25.00	74.85	Replace	Replace S	No	✓
			NUMBER PLATE	1	35.00	0.00	35.00	Replace	Replace	No	✓
			NUMBER PLATE FRAME	1	25.00	0.00	25.00	Replace	Replace	No	✓
7531047060			EMBLEM ASSY FRONT	1	87.10	25.00	65.32	Replace	Replace	No	✓
5211647050			SUPPORT, FR BUMPER LH	1	82.30	25.00	61.73	Replace	Check	No	X
5211547050			SUPPORT, FR BUMPER RH	1	76.90	25.00	57.68	Replace	Check	No	X
5202147110			REINFORCEMENT FRONT UPPER	1	691.10	25.00	518.33	Replace	Check	No	X
5261147140			ABSORBER, FR BUMPER	1	70.30	25.00	52.73	Replace	Replace S	No	✓
5210347010			EXTENSION SUB-ASSY, LH	1	116.30	25.00	87.23	Replace	Check	No	X
5210247020			EXTENSION SUB-ASSY, RH	1	116.30	25.00	87.23	Replace	Check	No	X
5213247010			REINFORCEMENT FRONT LOWER	1	238.50	25.00	178.88	Replace	Check	No	X
5261847090			ABSORBER, FR BUMPER LOWER	1	117.00	25.00	87.75	Replace	Check	No	X
5320547900			SUPPORT S/A UPPER	1	364.90	25.00	273.68	Replace	Check	No	X

5651.50

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
8118547691			UNIT, HEADLAMP, LH	1	2,558.90	10.00	2,303.01	Replace	Check	No X
8114547691			UNIT, HEADLAMP, RH	1	2,558.90	10.00	2,303.01	Replace	Check	No X
8122047020			LAMP ASSY, FOG, LH	1	910.20	10.00	819.18	Replace	Check	No X
8121047020			LAMP ASSY, FOG, RH	1	910.20	10.00	819.18	Replace	Check	No X
8155147281			LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Replace	No /
TOTAL MATERIALS							11,563.71	2,638.42		
TOTAL MATERIALS(Discounted)							11,563.69	2,638.42		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
8155147281		LENS & BODY, REAR COMBINATION LAMP, RH	1	438.10	10.00	394.29	Replace	Replace	No
TOTAL SUPPLEMENTARY MATERIALS						394.29			

23732

2638.41 ✓
+ 1000.00 ✓
+ 890.00 ✓

4528.41 @ 6 days
confirmed.

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHF155K
 Ref. No : TAX/06/18/2005
 Reg. Date : 28/11/2017
 Vehicle Type : TAXI
 Make : TOYOTA PRIUS
 Model : PRIUS4
 Name of Driver : LAU WEI SUN LAWRENCE
 Type of Accident : CHAIN COLLISION
 Date / Time of Accident : 01/06/2018 04:30:00 PM
 Accident Reported Date / Time : 02/06/2018 12:00:00 AM
 Surveyor is Required? : Yes
 Survey by :
 Vehicle is Towed Back? : No
 Towed Back Date/Time :
 Replacement Vehicle issued? : No
 Accident Repair Job Card No : 000024096405
 Special Instruction to ARC, if any :
 SHB7935B (TRANSCAB) - AXA
 Prepared Date : 02/06/2018 11:13:14 AM



Sathya Sai

5/6/2018

sebastianyeang@lkkauto.com

- Part by Part repair
- Question mark item photo
- Photo before paint

5 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : JTDKB3FU303575335

Mileage :

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates**Quotation from ARC****Adjusted by Surveyor, if applicable**

Total Labour Charges : 1,859.00

0.00

Total Spray Painting Charges : 2,412.00

0.00

Total Material Charges : 14,736.01

14,736.01

Other Charges : 1,040.00

0.00

TOTAL : 20,047.01**0.00****Lum Sum Total : 0.00****0.00**

No. of Repair Days : 11.00

~~0.00~~ 5 days

Prepared / Adjusted By :

Arc / Surveyor Sign Off Date : 04/06/2018 11:03:25 AM

01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 04/06/2018 11:03:25 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount :

Prepared Date :

Section D - Details of Repair Estimates

Part 1 - Labour Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
TO REPAIR FRONT PORTION	845.00	0.00 400
Total Labour	1,859.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	378.00	0.00 200
TO RESPRAY FILLER RR BUMPER LH	180.00	0.00 ?
TO RESPRAY FILLER RR BUMPER RH	180.00	0.00 ?
TO RESPRAY REAR PANEL	180.00	0.00 ?
TO RESPRAY TAIL GATE	378.00	0.00 x
TO RESPRAY TAILGATE OUTSIDE GARNISH	378.00	0.00 x
TO RESPRAY REAR SPOILER	180.00	0.00 x
TO REPSRAY FRONT BUMPER	378.00	0.00 200
TO RESPRAY FRONT SUPPORT PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	2,412.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 50
TO APPLY RUST-PROOFING ON AFFECTED AREA	200.00	0.00 100
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 x
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 x
TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 x
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 x
Total Other Costs	1,040.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
5215947913			COVER, RR BUMPER ASSY ✓ OT	1	423.90	25.00	317.92	Replace	Replace	No
5202347030			REAR BUMPER REINFORCEMENT ?	1	318.80	25.00	239.10	Replace	Replace	No
5245347010			GUARD, RR BUMPER, LOWER ?	1	558.30	25.00	418.72	Replace	Replace	No
5216947020			COVER, GUARD RR BUMPER LOWER ✓ OT	1	14.80	25.00	11.10	Replace	Replace	No
5257647040			RETAINER, RR BUMPER, LH ?	1	111.50	25.00	83.62	Replace	Replace	No
5257547040			RETAINER, RR BUMPER, RH ?	1	112.70	25.00	84.52	Replace	Replace	No
5246247030			PAD, RR BUMPER, RH & LH, 1 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247020			PAD, RR BUMPER, RH & LH, 2 ?	2	3.80	25.00	5.70	Replace	Replace	No
5246247010			PAD, RR BUMPER, RH & LH, 3 ?	2	3.80	25.00	5.70	Replace	Replace	No
5219147030			SEAL, RR BUMPER ARM, RH & LH ?	2	11.00	25.00	16.50	Replace	Replace	No
5256647900			FILLER, RR BUMPER, LH ?	1	119.90	25.00	89.92	Replace	Replace	No
5256647900			FILLER, RR BUMPER, RH ?	1	119.90	25.00	89.92	Replace	Replace	No
			SENSOR REVERSE ✓ SC	1	180.00	0.00	180.00	Replace	Replace	No
			PIXEL STICKER ✓ NEC	2	60.00	0.00	120.00	Replace	Replace	No
5259247040			SEAL, RR BUMPER, LH X	1	85.20	25.00	63.90	Replace	Replace	No
5259147050			SEAL, RR BUMPER, RH X	1	85.20	25.00	63.90	Replace	Replace	No
5839947030			COVER, REAR FLOOR UNDER, LH X	1	234.30	25.00	175.72	Replace	Replace	No
7697147010C0			COVER, REAR UNDER, CENTER ?	1	106.90	25.00	80.17	Replace	Replace	No
5839847050			COVER, REAR FLOOR UNDER, RH X	1	169.50	25.00	127.12	Replace	Replace	No
5830747090			END PANEL SUB-ASSY, BODY LOWER BACK ?	1	629.80	25.00	472.35	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX X	1	37.00	0.00	37.00	Replace	Replace	No
6700547440			TAIL GATE PANEL SUB-ASSY, BACK DOOR X	1	929.60	25.00	697.20	Replace	Replace	No
7680147110A1			TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY X	1	891.20	25.00	668.40	Replace	Replace	No
5611750140			TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE X	2	27.90	25.00	41.85	Replace	Replace	No
7557547051			TAIL GATE MOULDING LOWER GLASS, BACK DOOR X	1	19.70	25.00	14.77	Replace	Replace	No
7544147090			NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR X	1	52.30	25.00	39.22	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommendation	Surveyor Approved	Photos Attached
7544247130			NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR X	1	52.30	25.00	39.22	Replace	Replace	No
7540348010			EMBLEM SUB-ASSY REAR X	1	46.30	25.00	34.72	Replace	Replace	No
	COMMON		SMRT LOGO X	1	7.80	0.00	7.80	Replace	Replace	No
			STICKER DECAL 6555 8888 X	1	21.60	0.00	21.60	Replace	Replace	No
6788147050			TAIL GATE WEATHERSTRIP, BACK DOOR X	1	360.70	25.00	270.52	Replace	Replace	No
6471847080C0			END PANEL, COVER, DECK TRIM SERVICE HOLE X	1	47.00	25.00	35.25	Replace	Replace	No
6471647130C0			END PANEL, COVER, DECK TRIM, REAR X	1	122.80	25.00	92.10	Replace	Replace	No
7608547916			SPOILER SUB-ASSY, REAR X	1	1,322.10	25.00	991.57	Replace	Replace	No
8156147151			LENS & BODY, REAR COMBINATION LAMP, LH ?	1	438.10	10.00	394.29	Replace	Replace	No
			NUMBER PLATE X BR	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME X	1	25.00	0.00	25.00	Replace	Replace	No
5211947962			COVER, FR BUMPER ✓ CUT	1	495.50	25.00	371.62	Replace	Replace	No
5212847906			COVER, FR BUMPER LH X	1	28.10	25.00	21.07	Replace	Replace	No
5212747907			COVER, FR BUMPER RH ✓ BR	1	28.10	25.00	21.07	Replace	Replace	No
5311247240			GRILLE, RADIATOR X BR	1	165.00	25.00	123.75	Replace	Replace	No
5310147080			GRILLE SUB-ASSY ✓ ✓ CR	1	335.60	25.00	251.70	Replace	Replace	No
5211447190			BRACKET, FR BUMPER ?	1	99.80	25.00	74.85	Replace	Replace	No
			NUMBER PLATE ✓ BR	1	35.00	0.00	35.00	Replace	Replace	No
			NUMBER PLATE FRAME ✓ BR	1	25.00	0.00	25.00	Replace	Replace	No
7531047060			EMBLEM ASSY FRONT ✓ CUT	1	87.10	25.00	65.32	Replace	Replace	No
5211647050			SUPPORT, FR BUMPER LH ?	1	82.30	25.00	61.72	Replace	Replace	No
5211547050			SUPPORT, FR BUMPER RH ?	1	76.90	25.00	57.67	Replace	Replace	No
5202147110			REINFORCEMENT, FRONT UPPER ?	1	691.10	25.00	518.32	Replace	Replace	No
5261147140			ABSORBER, FR BUMPER ?	1	70.30	25.00	52.72	Replace	Replace	No
5210347010			EXTENSION SUB-ASSY, LH ?	1	116.30	25.00	87.22	Replace	Replace	No
5210247020			EXTENSION SUB-ASSY, RH ?	1	116.30	25.00	87.22	Replace	Replace	No
5213247010			REINFORCEMENT, FRONT LOWER ?	1	238.50	25.00	178.87	Replace	Replace	No
5261847090			ABSORBER, FR BUMPER LOWER ?	1	117.00	25.00	87.75	Replace	Replace	No
5320547900			SUPPORT S/A UPPER ?	1	364.90	25.00	273.67	Replace	Replace	No

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
8118547691			UNIT, HEADLAMP , LH ?	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8114547691			UNIT, HEADLAMP , RH ?	1	2,558.90	10.00	2,303.01	Replace	Replace	No
8122047020			LAMP ASSY, FOG, LH ?	1	910.20	10.00	819.18	Replace	Replace	No
8121047020			LAMP ASSY, FOG, RH ?	1	910.20	10.00	819.18	Replace	Replace	No
TOTAL MATERIALS							14,736.15	14,736.01		
TOTAL MATERIALS(Discounted)							14,736.01	14,736.01		

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									

View Received Message

This mail is associated with :

***SHF155K (C0473814)**
[SHB7935B]

TP

SMRT TAXIS PTE LTD

Jun 1 2018 12:00AM

[TRANS-CAB SERVICES PTE LTD]

SMRT Automotive Services Pte Ltd

[Reply](#)[Reply All](#)[Mark as Unread](#)[Print Message](#)[Delete Message](#)[Forward](#)

From AXA Insurance Pte Ltd (HQ) (AXA_SG), sent on 29/11/2018 22:29 PM.

To LKK_HQ

Subject Alert - Adj Mandate Approved (S\$6239.23) - SHF155K - Claim Handler: Chan Kian Chuan

Approved:6239.23.

DOCUMENTS SUMMARY

There are no documents.

...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	04 Jun 2018		05 Jun 2018 09:37 Edit Adj Rpt	S\$4,528.41 Edit Estimates	S\$4,528.41 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[\[Created by insurer\]](#)

Insured:	TRANS-CAB SERVICES PTE LTD , Co. Reg. No.: 200303878K		
Main Claimant:	SMRT TAXIS PTE LTD , Co. Reg. No.: 198905369K		
Vehicle Reg. No.:	SHF155K	Date of Loss:	01/06/2018 00:00 - :59 [6 Months and 4 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / C0473814	Policy/Cover Note No.:	P1680520 (Third Party Only)
Vehicle Reg. No. (Insured):	SHB7935B	Policy No. (Claimant):	D-18090213MFSH
		Excess:	S\$5,000.00
Repairer:	SMRT Automotive Services Pte Ltd (Woodlands) 60 Woodlands Industrial Park E4, 757705 Woodlands - Tel: 68662628		
Handling Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288 ... [Handled by Chan Kian Chuan - 6880 4269]		
Claimant's Insurer:	MS First Capital Insurance Ltd (HQ) - Tel: 62222311		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sebastian Yeang Wai Keen] ... [Final Rpt due 14/06/2018]		
Driver/Custodian (Insured):	TAY HENG THIAM (66 / Male), NRIC: S0200427E, Tel: +6591993598		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AXA_SG (29/11/2018): **Alert - Adj Mandate Approved (S\$6239.23) - SHF155K - Claim Handler: Chan Kian Ch...**
- AXA_SG (05/06/2018): **New TP Assignment - C0473814/P1680520**

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date Priority Type Task Group Subject Handler Assigned By Completed On Created On Done?

No results.

Claim Documents

***SHF155K (C0473814)**
[SHB7935B]
TP
SMRT TAXIS PTE LTD
Jun 1 2018 12:00AM
[TRANS-CAB SERVICES PTE LTD]
SMRT Automotive Services Pte Ltd

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Letters/Correspondences			1 per page	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement – Payment Breakdown	 Edit	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 10:15	General View	 Load JPG	☒
2	06/06/18 10:15	General View	 Load JPG	☒
3	06/06/18 10:15	General View	 Load JPG	☒
4	06/06/18 10:15	General View	 Load JPG	☒
5	06/06/18 10:15	General View	 Load JPG	☒
6	06/06/18 10:15	General View	 Load JPG	☒
7	06/06/18 10:15	General View	 Load JPG	☒
8	06/06/18 10:15	General View	 Load JPG	☒
9	06/06/18 10:15	General View	 Load JPG	☒
10	06/06/18 10:15	General View	 Load JPG	☒
11	06/06/18 10:15	General View	 Load JPG	☒
12	06/06/18 10:15	General View	 Load JPG	☒
13	06/06/18 10:15	General View	 Load JPG	☒
14	06/06/18 10:15	General View	 Load JPG	☒
15	06/06/18 10:15	General View	 Load JPG	☒
16	06/06/18 10:15	General View	 Load JPG	☒
17	06/06/18 10:15	General View	 Load JPG	☒
18	06/06/18 10:15	General View	 Load JPG	☒
19	06/06/18 10:15	General View	 Load JPG	☒
20	06/06/18 10:15	General View	 Load JPG	☒
21	06/06/18 10:15	General View	 Load JPG	☒
22	06/06/18 10:15	General View	 Load JPG	☒
23	06/06/18 10:15	General View	 Load JPG	☒
24	06/06/18 10:15	General View	 Load JPG	☒
25	06/06/18 10:15	General View	 Load JPG	☒
26	06/06/18 10:15	General View	 Load JPG	☒
27	06/06/18 10:15	General View	 Load JPG	☒
28	06/06/18 10:15	General View	 Load JPG	☒
29	06/06/18 10:15	General View	 Load JPG	☒
30	06/06/18 10:15	General View	 Load JPG	☒
31	06/06/18 10:15	General View	 Load JPG	☒
32	06/06/18 10:15	General View	 Load JPG	☒

Letters/Correspondences			1 per page	
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
33	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
34	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
35	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
36	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
37	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
38	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
39	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
40	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
41	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
42	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
43	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
44	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
45	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
46	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
47	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
48	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
49	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
50	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
51	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
52	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
53	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
54	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
55	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
56	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
57	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
58	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
59	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
60	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
61	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
62	03/10/18 10:50	Reinspection Photo	 Load JPG	☒
63	03/10/18 10:50	Reinspection Photo	 Load JPG	☒

Documentation			1 per page	
No	Finalized On	AXA Insurance Pte Ltd (HQ)	Thumbnail	Print
1	04/06/18 12:15	EMAIL	 Load PDF	
2	04/06/18 12:15	ESTIMATE	 Load PDF	
3	04/06/18 12:15	GIA REPORT OF SHD8826R	 Load PDF	
4	04/06/18 12:15	GIA REPORT OF SHF155K (TP)	 Load PDF	
5	04/06/18 12:15	GIA REPORT OF SHF155K (TP) 1	 Load PDF	
6	04/06/18 12:15	GIA REPORT OF SHB7935B (INSD)	 Load PDF	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 15:21	Immediate Advice	 Load PDF	
2	06/06/18 17:51	TP ESTIMATE- MARKED	 Load PDF	
3	28/09/18 08:49	LETTER TO OI	 Load PDF	
4	28/09/18 08:49	RENTAL RECEIPT	 Load PDF	
5	20/12/18 11:33	LOD	 Load PDF	
6	20/12/18 11:33	AUTHORISATION TO ACT	 Load PDF	
7	20/12/18 11:33	DISCHARGE VOUCHER	 Load PDF	
8	20/12/18 11:33	WORKSHOP INVOICE	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SHB7935B (Insd veh)	Model:	TOYOTA PRIUS TAXI 1.8 (A)
	SHF155K (TP veh)		
Date of Accident:	01/06/2018		

Global Sum Settlement	:	[] Yes	[X] No
Repair Estimate	:	\$	23,732.00
Final Repair Cost	:	\$	4,528.41
Loss of Use	:	\$	475.00
Rental (if any)	:	\$	1,143.61
LTA / GIA Search Fee	:	\$	
Others:	:	\$	
	:	\$	
Final Settlement Sum	:	\$	6,147.02
Is Third Party Workshop GIA Registered? [] YES [X] NO (Kindly indicate below)			
A) For Non GIA Registered Workshop:		Agreed Liability _____ 100 _____ (%)	
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: _____	
BOLA Liability: _____ (%)		Assessed Liability (*): _____ 100 _____ (%)	
* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.			
Remarks _____			

Payment Instruction: Payee's Breakdown			
1)	SMRT TAXIS PTE LTD	:	\$ 6,147.02
2)		:	\$
3)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

20 Dec
2018

Date

Please attach all the supporting documents to the form.

(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/ Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/AXA18010165/VWB3S2
Date: 20/12/2018

REFERENCE

Handling Insurer: AXA Insurance Pte Ltd Policy No: P1680520
Claimant Vehicle No : SHF155K **Insured Vehicle No :** SHB7935B
 Date of Loss: 01/06/2018 Nature of Claim: TP Claim No: C0473814

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SHF155K**
 Make & Model: TOYOTA PRIUS TAXI, 1.8 (A) Engine No: 2ZRS108741
 Reg. Date: 28/11/2017 (Man. Year: 2017) Chassis No: JTDKB3FU303575335
 Colour: Maroon Odometer: 61071 km
 Engine Capacity: 1798 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Fair Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 195/65R15 Rear Tyre Size: 195/65R15
 Front Left Side: Yokohama 6 mm Rear Left Side: Yokohama 6 mm
 Front Right Side: Yokohama 6 mm Rear Right Side: Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	18,421.00	2,638.41	15,782.59	85.68
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,311.00	1,890.00	3,421.00	64.41
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	23,732.00	4,528.41	19,203.59	80.92
	+ Loss of Use (9.5 x S\$50.00/day) (S\$)	475.00		
	+ Car Rental (9.5 x S\$120.38/day) (S\$)	1,143.61		
	Nett Liability (S\$)	6,147.02		

INSPECTION

Date of Assignment: 05/06/2018
 Date Inspected: 05/06/2018 Inspected At: SMRT Automotive Services Pte Ltd (Woodlands)
 60 Woodlands Industrial Park E4
 Singapore 757705
 Estimated Period of Repair: 6.0 days

Adjuster: Sebastian Yeang Wai Keen

Manager: VIVIAN LAU PEI FENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 20 Dec 2018)
Parts:	144	TOYOTA PRIUS TAXI 1.8 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHF155K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*COVER, RR BUMPER ASSY (DISC 25%) (CONSISTENT)	Dented	423.90 F	*317.92 F
2	1		*REAR BUMPER REINFORCEMENT (DISC 25%) (CONSISTENT)	Dented	318.80 F	*239.10 F
3	1		*GUARD, RR BUMPER, LOWER (DISC 25%) (CONSISTENT)	Dented	558.30 F	*418.72 F
4	1		*COVER, GUARD RR BUMPER LOWER (DISC 25%) (CONSISTENT)	Dented	14.80 F	*11.10 F
5	1		*COVER, FR BUMPER (DISC 25%) (CONSISTENT)	Cut	495.50 F	*371.62 F
6	1		*COVER, FR BUMPER RH (DISC 25%) (CONSISTENT)	Broken	28.10 F	*21.07 F
7	1		*GRILLE SUB-ASSY (DISC 25%) (CONSISTENT)	Cracked	335.60 F	*251.70 F
8	1		*BRACKET, FR BUMPER (DISC 25%) (CONSISTENT)	Deformed	99.80 F	*74.85 F
9	1		*EMBLEM ASSY FRONT (DISC 25%) (CONSISTENT)	Cut	87.10 F	*65.32 F
10	1		*ABSORBER, FR BUMPER (DISC 25%) (CONSISTENT)	Cracked	70.30 F	*52.72 F
11	1		*LENS & BODY, REAR COMBINATION LAMP, RH (DISC 10%) (CONSISTENT)	Cracked	438.10 F	*394.29 F
12	1		*SENSOR REVERSE (SN) (CONSISTENT)	Short Circuit	180.00 F	*180.00 F
13	2		*PIXEL STICKER (SN) (CONSISTENT)	Necessary	120.00 F	*120.00 F
14	1		*NUMBER PLATE (SN) (CONSISTENT)	Cut	35.00 F	*35.00 F
15	1		*NUMBER PLATE FRAME (SN) (CONSISTENT)	Cracked	25.00 F	*25.00 F
16	1		*NUMBER PLATE (SN) (CONSISTENT)	Broken	35.00 F	*35.00 F
17	1		*NUMBER PLATE FRAME (SN) (CONSISTENT)	Broken	25.00 F	*25.00 F
18	1		*RETAINER, RR BUMPER, LH (CONSISTENT)	Not Necessary	111.50 F	*- F
19	1		*RETAINER, RR BUMPER, RH (CONSISTENT)	Not Necessary	112.70 F	*- F
20	2		*PAD, RR BUMPER, RH & LH, 1 (CONSISTENT)	Not Necessary	7.60 F	*- F
21	2		*PAD, RR BUMPER, RH & LH, 2 (CONSISTENT)	Not Necessary	7.60 F	*- F
22	2		*PAD, RR BUMPER, RH & LH, 3 (CONSISTENT)	Not Necessary	7.60 F	*- F
23	2		*SEAL, RR BUMPER ARM, RH & LH (CONSISTENT)	Not Necessary	22.00 F	*- F
24	1		*FILLER, RR BUMPER, LH (CONSISTENT)	Not Necessary	119.90 F	*- F
25	1		*FILLER, RR BUMPER, RH (CONSISTENT)	Not Necessary	119.90 F	*- F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
26	1		*SEAL, RR BUMPER, LH (CONSISTENT)	Not Necessary	85.20 F	*-F
27	1		*SEAL, RR BUMPER, RH (CONSISTENT)	Not Necessary	85.20 F	*-F
28	1		*COVER, REAR FLOOR UNDER, LH (CONSISTENT)	Not Necessary	234.30 F	*-F
29	1		*COVER, REAR UNDER, CENTER (CONSISTENT)	Not Necessary	106.90 F	*-F
30	1		*COVER, REAR FLOOR UNDER, RH (CONSISTENT)	Not Necessary	169.50 F	*-F
31	1		*END PANEL SUB-ASSY, BODY LOWER BACK (CONSISTENT)	Not Necessary	629.80 F	*-F
32	1		*SEALANT SIKAFLEX (CONSISTENT)	Not Necessary	37.00 F	*-F
33	1		*TAIL GATE PANEL SUB-ASSY, BACK DOOR (CONSISTENT)	Not Necessary	929.60 F	*-F
34	1		*TAIL GATE BACK DOOR OUTSIDE GARNISH SUB-ASSY (CONSISTENT)	Not Necessary	891.20 F	*-F
35	1		*TAIL GATE DAM, BACK DOOR GLASS UPPER ADHESIVE (CONSISTENT)	Not Necessary	27.90 F	*-F
36	1		*TAIL GATE MOULDING LOWER GLASS, BACK DOOR (CONSISTENT)	Not Necessary	19.70 F	*-F
37	1		*NAME PLATE (HYBRID), LUGGAGE COMPARTMENT DOOR (CONSISTENT)	Not Necessary	52.30 F	*-F
38	1		*NAME PLATE (PRIUS), LUGGAGE COMPARTMENT DOOR (CONSISTENT)	Not Necessary	52.30 F	*-F
39	1		*EMBLEM SUB-ASSY REAR (CONSISTENT)	Not Necessary	46.30 F	*-F
40	1		*SMRT LOGO (CONSISTENT)	Not Necessary	7.80 F	*-F
41	1		*STICKER DECAL 6555 8888 (CONSISTENT)	Not Necessary	21.60 F	*-F
42	1		*TAIL GATE WEATHERSTRIP, BACK DOOR (CONSISTENT)	Not Necessary	360.70 F	*-F
43	1		*END PANEL, COVER, DECK TRIM SERVICE HOLE (CONSISTENT)	Not Necessary	47.00 F	*-F
44	1		*END PANEL, COVER, DECK TRIM, REAR (CONSISTENT)	Not Necessary	122.80 F	*-F
45	1		*SPOILER SUB-ASSY, REAR (CONSISTENT)	Not Necessary	1,322.10 F	*-F
46	1		*LENS & BODY, REAR COMBINATION LAMP LH (CONSISTENT)	Not Necessary	438.10 F	*-F
47	1		*COVER, FR BUMPER LH (CONSISTENT)	Not Necessary	28.10 F	*-F
48	1		*GRILLE, RADIATOR (CONSISTENT)	Not Necessary	165.00 F	*-F
49	1		*SUPPORT, FR BUMPER LH (CONSISTENT)	Not Necessary	82.30 F	*-F
50	1		*SUPPORT, FR BUMPER RH (CONSISTENT)	Not Necessary	76.90 F	*-F
51	1		*REINFORCEMENT FRONT UPPER (CONSISTENT)	Not Necessary	691.10 F	*-F
52	1		*EXTENSION SUB-ASSY, LH (CONSISTENT)	Not Necessary	116.30 F	*-F
53	1		*EXTENSION SUB-ASSY, RH (CONSISTENT)	Not Necessary	116.30 F	*-F
54	1		*REINFORCEMENT FRONT LOWER (CONSISTENT)	Not Necessary	238.50 F	*-F
55	1		*ABSORBER, FR BUMPER LOWER (CONSISTENT)	Not Necessary	117.00 F	*-F
56	1		*SUPPORT S/A UPPER (CONSISTENT)	Not Necessary	364.90 F	*-F
57	1		*UNIT, HEADLAMP, LH (CONSISTENT)	Not Necessary	2,558.90 F	*-F
58	1		*UNIT, HEADLAMP, RH (CONSISTENT)	Not Necessary	2,558.90 F	*-F

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
59	1		*LAMP ASSY, FOG LH (CONSISTENT)	Not Necessary	910.20 F	*- F
60	1		*LAMP ASSY, FOG RH (CONSISTENT)	Not Necessary	910.20 F	*- F
F=Franchise part.						
				Total Parts (\$\$)	18,421.00	2,638.41

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING & BODYWORK.	New	1,859.00	1,000.00
2	SPRAY PAINT.	New	2,412.00	600.00
3	TO CHECK WIRING AND SYSTEM FUNCTION.	New	80.00	50.00
4	TO APPLY RUST-PROOFING ON AFFECTED AREA.	New	200.00	100.00
5	TO TEST AND REFIX REVERSE SENSOR SYSTEM.	New	120.00	60.00
6	TO TRANSFER REAR TAILGATE MECHANISM.	New	120.00	0.00
7	TO REMOVE AND REFIX REAR WINDSCREEN.	New	120.00	0.00
8	TO INSPECT RR LIGHTING, MECHANISMS & WATER TEST RR LIGHTING FOR LEAKAGE.	New	120.00	60.00
9	TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	New	120.00	0.00
10	TO REPLACE SUNDRY PARTS.	New	100.00	20.00
11	TO WASH AND VACUUM.	New	60.00	0.00
Gross Labour Cost (S\$)			5,311.00	1,890.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >