



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

TAX INVOICE

CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD #16-00
SPRINGLEAF TOWER
SINGAPORE 079909

INV No. AC2004955
INV Date 16/07/2020
Reference CC6/CTI18010171/Aea3n2
Code CTI



PROFESSIONAL SERVICE FEE

Vehicle No. GBF 1764S
Insured Veh. XD 6628U
Claim No. SNM18D02802C02/8
Policy No. DMCVSN1813761800
Accident Date 03/06/2018
Inspection Date 04/06/2018

Description	Total
Third Party Express Settlement	400.00
Subtotal	400.00
GST (7%)	28.00
Grand Total	428.00

We shall be glad if you could forward the payment at your early convenience.

Cheque should be crossed and made payable to **'LKK Auto Consultants Pte Ltd'**

LKK Auto Consultants Pte Ltd

HYN



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CC6/CTI18010171/Aea3n2

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 16-07-2020



Code : CTI

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	XD 6628U	Veh. Inspected	GBF 1764S
Policy No.	DMCVSN1813761800	Coverage (\$)	0.00
Claim No.	SNM18D02802C02/8	Excess (\$)	0.00
Assign From		Assign Date	04/06/2018

2. Vehicle Particulars & Condition

Make & Model	NISSAN NAVARA	c.c	2298
Engine No.	HIDDEN	Year of Reg.	2016
Chassis No.	MNTCB4D23Z0000086	Colour	WHITE
Odometer	38499	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	255/70 R16	DUNLOP	6 mm
L/H Front Tyre	255/70 R16	DUNLOP	6 mm
R/H Rear Tyre	255/70 R16	DUNLOP	6 mm
L/H Rear Tyre	255/70 R16	DUNLOP	6 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT PORTION.

DAMAGES SEE DETAILS.

5. General Information

Accident Date	03/06/2018	Inspection Date	04/06/2018
Survey held at	FLYING HIGH SPRAY PAINTING BLK 1 KAKI BUKIT AVE 6 #01-29 AUTOBAY SINGAPORE 417883		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
B) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	7 Working Days
-------------------------------------	----------------



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBF 1764S

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<u>REPLACEMENT OF PARTS</u>				
1	FRONT NUMBER PLATE GARNISH	NOT NECESSARY	77.30	-
1	FRONT BUMPER	DEFORMED	473.00	473.00
1	FRONT BUMPER CLIPS	NECESSARY	30.00	30.00
2	FRONT BUMPER SIDE HOLDER @\$26.30	NECESSARY	52.60	52.60
2	FRONT BUMPER FOG LAMP @\$321.60	NOT NECESSARY	643.20	-
2	FRONT BUMPER FOG LAMP COVER @\$108.60	NOT NECESSARY	217.20	-
3	FRONT BUMPER BRACKET @\$35.00	BENT	105.00	105.00
1	FRONT GRILLE C/W CHROME MOULDING	CRACKED	576.80	576.80
1	FRONT GRILLE LOGO	NECESSARY	118.10	118.10
1	FRONT SUPPORT PANEL	BUCKLED	1,193.40	1,193.40
2	HEADLAMP @\$494.60	CRACKED	989.20	989.20
1	BONNET	DISTORTED	731.50	731.50
1	BONNET LOCK	DAMAGED	105.80	105.80
1	BONNET WEATHERSTRIPE	CUT	31.60	31.60
2	BONNET HINGE @\$32.60	NOT NECESSARY	65.20	-
1	BONNET INSULATOR	NOT NECESSARY	104.70	-
1	BONNET INSULATOR CLIPS	NOT NECESSARY	30.00	-
2	FRONT FENDER @\$548.20	N/S BUCKLED	1,096.40	548.20
1	FRONT BRACE PANEL	BENT	48.20	48.20
1	POWER STEERING COOLER PIPE	BENT	291.50	291.50
1	AIR CON CONDENSER	BENT	760.60	760.60
2	AIR CON CONDENSER SIDE GARNISH @\$41.00	TORN	82.00	82.00
1	RADIATOR	BENT	712.40	712.40
1	RADIATOR FAN COWLING	CRACKED	130.70	130.70
1	RADIATOR FAN BLADE	NOT NECESSARY	190.70	-
1	RADIATOR TOP PANEL	BUCKLED	345.40	345.40
	LESS 10% DISCOUNT		-	-732.60
			9,202.50	6,593.40
<u>SPECIAL NETT ITEMS</u>				
1	FRONT NUMBER PLATE (SN)	NOT NECESSARY	30.00	-

Report Ref No. CC6/CTI18010171/Aea3n2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	OIL COOLER (SN) <u>LABOUR</u> PANEL BEATING. SPRAY PAINTING. WIRING. TO UNDERSEAL. TO REMOVE CONDENSER RADIATOR AND TO RE-GAS.	BENT	624.00	624.00
			654.00	624.00
			1,400.00	1,000.00
			1,400.00	1,000.00
			50.00	30.00
			150.00	30.00
			180.00	120.00
GRAND TOTAL			13,036.50	9,397.40
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				7,500.00

Report Ref No. CC6/CTI18010171/Aea3n2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.