

REC. BY:

REF:

CS/FCL18010179 / Aqbm2

Special Instruction:

Surveyor: Adrian

ASSIGNMENT (Office)

From (Person): CWS May Chua

of

FCL

Date/Time: 05062018 827am

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SMA 9826R

Insured:

SHC 3530G

at Workshop m/s

Hua Feng

Tel:

9271 2214

of

Blk 1 Kaki Bukit Ave 6 #01-107

Policy No:

Claim No:

D18001412 MFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

01062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'WPI

H.O.D. Endorsement:

Date/Time: 05062018

Person Contacted:

Chris

Vehicle: IN OUT

Date/Time

Action/Instruction (✓) Estimate

SMA 9826R - x

SHC 3530G - NS / INC 14012275 / STM3d1

DCA: 270614

06/6/18@ 9.45am informed May Chua, we are pending estimate from repairer.

18/7/18@ 1203pm revised to May Chua by email -

Us & Brov, 2 days. Used \$10523.39, 89%

REF:

As REG BY: Abrian Ling

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

2

days

Res.: Yes or No

Lum Sum:

%

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

SMA9826R Yr Regn: 2018 / May.

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Toyota Noah

C.C 1797

Colour:

White

A/C: Insured / Std / NI / NA

Sp. Reading:

541

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

ZWR800303745

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size:

F:

195/65R15

R:

195/65R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Front

Rear

R/Bal.

06

mm

R/Bal.

06

mm

L/Bal.

06

mm

L/Bal.

06

mm

D.O.A.

D.O.I.

24/06/18

05

Survey held at

Hua Feng

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

TP 1st Cap.

RECEIVED 20 JUL 2018

Date/Time, File Pass to?

☐

: Preli. Report

☐

: Final Report

1)

Date/Time, File Return to?

2)

Days Of Repair: 2

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp. (\$)

☐

: Interview (\$)

☐

: Tech. Invs (\$)

☐

: Weekend (\$)

Survey Fee:

Transportation:

S + RS. \$

Photos

Other:

TOTAL

Report Format:

7c

Lump Sum / B.I. (\$)

1300

1704 15

50

50

25

310

MOTOR SURVEY ASSIGNMENT

Date	04-06-2018	Our Ref No. D18004412MFSH
Accident Date	01-06-2018	Claim Type. Third Party
Insured Vehicle	SHC3530G	Third Party Vehicle. SMA9826R
Survey Location	1 KAKI BUKIT AVENUE 6 #01-107SYNERGY @ KB	
Contact Person.	CHRIS CHAN	
Contact No.	0/ 92712214	Fax No. 0
Survey Type	<i>Adm.</i>	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 18 July 2018 12:03 PM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004412MFSH/1
Attachments: CSFCI18010179Aqb.pdf

Dear May,

Enclosed herewith preliminary advice of SMA 9826R.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 June 2018 9:45 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004412MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SMA 9826R on 04/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 June 2018 10:33 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004412MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004412MFSH

Date: 18 July 2018

Our Ref: CS/FCI18010179/Aqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SMA 9826R

Please be informed that we had conducted the inspection of the abovementioned vehicle on 04/06/2018 at the premises of M/s HUA FENG, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>11,823.30</u>
Revised Estimate Amount	: S\$ <u>1,300.00 (Lump Sum)</u>
"Check" Items Amount	: S\$ <u>-</u>
Market Value	: S\$ <u>-</u>
LTA Reimbursement Value	: S\$ <u>-</u>
Nett Value	: S\$ <u>-</u>

Description of Damage:

The vehicle sustained damages
at the rear portion.



Yours faithfully

ADRIAN LING WAI PING
B.Eng, AMSOE, AMIRTE, AMSAE-A, M.MATAI
Licensed Appraiser

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 June 2018 9:45 AM
To: 'Claim Workflow System'; assignments
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004412MFSH/1

Dear May,

Please be informed that we have inspected the vehicle SMA 9826R on 04/06/2018.

We are pending for estimate from repairer.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 June 2018 10:33 AM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: MAYCHUA@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004412MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 5 June, 2018 8:27 AM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; MAYCHUA@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004412MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

[Back to OneMotoring](#)

Enquire PARF/COE Rebate for Registered Vehicle

Vehicle Owner Particulars

Owner ID Type: Singapore NRIC
Owner ID: 22491

Vehicle Details

Vehicle No.: SMA9826R
Vehicle to be Exported: Yes
Intended De-registration Date: 03 Jun 2018
Vehicle Make: TOYOTA
Vehicle Model: NOAH HYBRID 1.8X CVT
Primary Colour: White
Manufacturing Year: 2018
Engine No.: 2ZR0A99852
Chassis No.: ZWR800303745
Maximum Power Output: 100.0 kW (134 bhp)
Open Market Value: \$31,937.00
Original Registration Date: 10 May 2018
First Registration Date: 10 May 2018
Transfer Count: 0
Actual ARF Paid: \$26,712.00

Intended PARF Rebate Details

PARF Eligibility: Yes
PARF Eligibility Expiry Date: 09 May 2028
PARF Rebate Amount: \$20,034.00

Intended COE Rebate Details

COE Expiry Date: 09 May 2028
COE Category: E - Open - all except motorcycle
COE Period(Years): 10
OP Paid: \$38,801.00
COE Rebate Amount: \$31,040.00
Total Rebate Amount: \$51,074.00

The information contained herein is correct as at 03 Jun 2018

OK

LETTER OF UNDERTAKING

I/We, Low TEIK HANG, the owner of vehicle no. SMA 9826 R

My/Our Insurance is under M/s AXA Insurance Singapore Pte Ltd, I/we shall decide whether to claim under my/our Policy or against the Third Party and if the former shall submit such a claim to M/s AXA Insurance Singapore Pte Ltd with all relevant facts and documents within 14(fourteen) days of occurrence or discovery of damage.

My/Our Third Party claim is handle by my/our preferred workshop, unknown

Signed and Acknowledge by:

ST5822491 [Signature]
Nric no. and signature of policyholder

.....
Company Stamp

01 Jun 2018
Date



redefining insurance

AXA Insurance Pte Ltd
 1000 000 0000 (Toll-free Singapore)
 65 6555 5555 (Singapore)
 65 6555 5555
 1000 000 0000 (Toll-free Singapore)
 1000 000 0000

Certificate of Insurance

AXA Insurance Pte Ltd
 1000 000 0000

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

Policy details

AXA Insurance Pte Ltd	LOW CHIEF	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd
AXA Insurance Pte Ltd	Corporate	AXA Insurance Pte Ltd	AXA Insurance Pte Ltd

Persons or classes of persons entitled to drive*

AXA Insurance Pte Ltd
 AXA Insurance Pte Ltd

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

Limitation as to use*

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

- AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.
- AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.
- AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

Additional clauses & endorsements to your policy

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

AXA Insurance Pte Ltd

AXA Insurance Pte Ltd
 AXA Insurance Pte Ltd

Important note

AXA Insurance Pte Ltd, a company incorporated in Singapore, is the insurer of the vehicle described in the Certificate of Insurance. The vehicle is insured under the AXA Insurance Pte Ltd Motor Vehicle Insurance Policy.

AXA Insurance Pte Ltd
 1000 000 0000
 65 6555 5555
 Singapore 06000
 Singapore 06000

Page 1

Identification Card



Identification Card

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. 880729508



NAME
CHAN WAI LENG

名 易 榮

SEX
G-MALE

DATE OF BIRTH
02-03-1963

DATE OF EXPIRATION
04-03-2018

880729508



880729508

DATE OF ISSUE
01-03-2018

ADDRESS
APT 1001, 100 TANGKAP STREET, #2
100, 100
SINGAPORE 100001

REPUBLIC OF SINGAPORE
IDENTIFICATION NO. 875822491



LOW TALKING

与 德 德

1992

1510
1511

2008年11月11日

REPLY



PCN 576022-488



POSTAL ADDRESS

194-1-1-8-1-2

NOTED BY: TAPWES2105 01/02/05 33
 DISAPPEARANCE
 HP 1000 SPANORR 0000 05 02 0000 02 00000000

Identification Card



Sheet1
HUA FENG AUTOMOTIVE
ENGINEERING & RECONSTRUCTION
 BLOCK 1 KAKI BUKIT AVENUE 6 #01-107 AUTOBAY @ KB (S) 417883
 Tel : (65) 69664526 HP: 92712214 Fax: (65)67476918

TP 1st Cap
 Xiao Chen

04th JUNE 2018

BLOCK 1 KAKI BUKIT AVE 6
 #01-107 AUTOBAY @ KB
 Singapore 417883

Accident date: 01st JUNE 2018

Estimated repair cost for vehicle no: SMA9826R TOYOTA NOAH 1.8 '18

S/n	Qty	Items	U/price	Amount
1	1	Rear Boot Lid <i>Repr</i>		\$1,592.50 ⁺
2	2	Rear Boot Lid lock sensor <i>new</i>		\$0.00 ⁺
3	1	Rear Boot Lid Lock		\$390.00 ⁺
4	1	boot lid weatherstrip		\$311.70 ⁺
5	1	boot lid inner trim board clips		\$30.00 ⁺
6	1	Rear Boot Lid Inner Trim board <i>rel</i>		\$438.50 ⁺
7	2	rear number plate lamp	\$58.00	\$116.00 ⁺
8	1	Boot lid emblem logo		\$55.90 ⁺
9	2	Rear boot lid lamp	\$475.30	\$950.60 ⁺
10	2	tail lamp	\$381.90	\$763.80 ⁺
11	1	Rear Bumper <i>Del</i>		\$1,339.50 ⁺
12	2	Rear Bumper reflector <i>new</i>	\$86.00	\$172.00 ⁺
13	1	Rear bumper clips-set <i>new</i>		\$30.00 ⁺
14	1	Rear End Panel <i>Repr</i>		\$683.10 ⁺
15	1	Rear End Panel garnish		\$249.10 ⁺
16	1	rear end Panel garnish clips <i>new</i>		\$30.00 ⁺
17	1	Rear exhaust mounting		\$38.90 ⁺
18	1	Rear Exhaust pipe		\$1,091.70 ⁺
			Subtotal :-	\$8,283.30

S/n	Qty	Items/ s.nett	U/price	Amount
1	1	rear number plate		\$50.00 ⁺
2	1	rear number plate holder <i>new</i>		\$30.00 ⁺
3	1	rear end Panel sealant <i>new</i>		\$100.00 ⁺

4	1	reverse sensor (4 pieces)	<i>Heple</i>	\$380.00	*
5	1	rear camera	<i>nen</i>	\$580.00	*

Subtotal :- \$1,140.00

Labour charges

To Remove & refix rear cushion	\$150.00	*
To Remove & refix camera	\$100.00	*
Remove & refix rear exhaust	\$250.00	*
To Remove & refix reverse Sensor	\$100.00	50
To Check Wiring System	\$80.00	30
tuff Kote	\$120.00	*
Panel beating	\$800.00	200
Spray painting	\$800.00	400

Subtotal :- \$2,400.00

Total:- \$11,823.30

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

total: 1707.12

L/S: 1.3K

02 days

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD		Ref : CS/FCI18010179/Aqbn2		
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877		Date : 01-08-2018		
		Code : FCI2		
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHC 3530G	Veh. Inspected	SMA 9826R	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004412MFSH	Excess (\$)	0.00	
Assign From	MAY CHUA	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	TOYOTA NOAH	c.c	1797	
Engine No.	HIDDEN	Year of Reg.	2018	
Chassis No.	ZWR800303745	Colour	WHITE	
Odometer	541	Steering	IN ORDER	
Brakes	IN ORDER	Modification	SPORTS RIM	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Front Tyre	195/65 R15	YOKOHAMA	6 mm	
R/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
L/H Rear Tyre	195/65 R15	YOKOHAMA	6 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	01/06/2018	Inspection Date	05/06/2018	
Survey held at	HUA FENG AUTOMOTIVE ENGINEERING & RECONSTRUCTION BLK 1 KAKI BUKIT AVE 6 #01-107 AUTOBAY SINGAPORE 417883			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		2 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SMA 9826R

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	REAR BOOT LID	TO REPAIR SEE LABOUR	1,592.50	-
2	REAR BOOT LID LOCK SENSOR (NPA)	NOT NECESSARY	-	-
1	REAR BOOT LID LOCK	NOT NECESSARY	390.00	-
1	BOOT LID WEATHERSTRIP	NOT NECESSARY	311.70	-
1	BOOT LID INNER TRIM BOARD CLIPS	NOT NECESSARY	30.00	-
1	REAR BOOT LID INNER TRIM BOARD	NOT NECESSARY	438.50	-
2	REAR NUMBER PLATE LAMP @\$58.00	NOT NECESSARY	116.00	-
1	BOOT LID EMBLEM LOGO	NOT NECESSARY	55.90	-
2	REAR BOOT LID LAMP @\$475.30	NOT NECESSARY	950.60	-
2	TAIL LAMP @\$381.90	NOT NECESSARY	763.80	-
1	REAR BUMPER	DEFORMED	1,339.50	1,339.50
2	REAR BUMPER REFLECTOR @\$86.00	NOT NECESSARY	172.00	-
1	SET REAR BUMPER CLIPS	NECESSARY	30.00	30.00
1	REAR END PANEL	TO REPAIR SEE LABOUR	683.10	-
1	REAR END PANEL GARNISH	NOT NECESSARY	249.10	-
1	REAR END PANEL GARNISH CLIPS	NOT NECESSARY	30.00	-
1	REAR EXHAUST MOUNTING	NOT NECESSARY	38.90	-
1	REAR EXHAUST PIPE	NOT NECESSARY	1,091.70	-
	LESS 25% DISCOUNT		-	-342.38
			8,283.30	1,027.12
SPECIAL NETT ITEMS				
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	50.00	-
1	REAR NUMBER PLATE HOLDER (SN)	NOT NECESSARY	30.00	-
1	REAR END PANEL SEALANT (SN)	NOT NECESSARY	100.00	-
1	REVERSE SENSOR (4 PCS)(SN)	NOT NECESSARY	380.00	-
1	REAR CAMERA (SN)	NOT NECESSARY	580.00	-
			1,140.00	-
LABOUR				
	TO REMOVE & REFIX REAR CUSHION.	NOT NECESSARY	150.00	-

Report Ref No. CS/FCI18010179/Aqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REMOVE & REFIX CAMERA.	NOT NECESSARY	100.00	-
	TO REMOVE & REFIX REAR EXHAUST.	NOT NECESSARY	250.00	-
	TO REMOVE & REFIX REVERSE SENSOR.		100.00	50.00
	TO CHECK WIRING SYSTEM.		80.00	30.00
	TUFF KOTE.	NOT NECESSARY	120.00	-
	PANEL BEATING.INCLUSIVE OF THE REPAIR OF REAR BOOT LID AND REAR END PANEL.		800.00	200.00
	SPRAY PAINTING.		800.00	400.00
			2,400.00	680.00
GRAND TOTAL			11,823.30	1,707.12
RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)				1,300.00

Report Ref No. CS/FCI18010179/Aqbn2

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.