

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

ESTIMATE : ACCIDENT/BODY REPAIRS  
WORKSHOP : TOA PAYOH  
CONTACT NO : 64730333  
REFERENCE : INS/IC/CHI/0733/2018  
DATE : 13-APR-2018

AIG ASIA PACIFIC INSURANCE PTE LTD  
78 SHENTON WAY  
#07-16 AIG BUILDING  
S(079120)  
TEL : 91007211  
FAX :

OWNER'S NAME : JEREMY CHARLES ANTHONY  
ADDRESS : BLK 24 SIN MING ROAD  
#11-51  
S(570024)  
TELEPHONE NO : 9749 3570

TYPE OF CLAIM : THIRD PARTY CLAIM  
POLICY NO : 10653151  
VEHICLE NO : SBH0225C  
MODEL CODE : BL5CK9S  
MODEL/YEAR : LEGACY 2.0R AWD SEDAN AT  
ENGINE NO : EJ20C602020  
CHASSIS NO : JF1BL5KS56G019907  
MILEAGE : 1 KM  
DATE IN : 13/04/2018  
LIABILITY : 0.00  
EXCESS CLAUSE : 0.00  
ESTIMATE BY : KUAN WEI LOONG\*\*  
ACCIDENT DATE : 13/04/2018

Print Date : 13/04/2018  
Print Time : 16:07:34

MOTORIMAGE ENTERPRISES PTE. LTD.  
 19 LORONG 8, TOA PAYOH  
 SINGAPORE 319255

ESTIMATED LABOUR CHARGES FOR ACCIDENT VEHICLE REGN NO SBH0225C

S/NO	JOB CODE	NATURE OF JOB	ESTIMATED CHARGES	SURVEYOR'S RECOMMENDATION
1	TPCLAIM	CONDUCT BODYWORK REPAIR (THIRD PARTY CLAIM)		
2	ZZ/001	CONDUCT TP CLAIM AIG LOCATION:AMK AVE1 TWD BOUNDY RD DATE:07/04/2018 TIME:1315HRS		
3	ZZ/002	REPAIR/REPLACE REAR BUMPER AND REAR PANEL	1000.00	250
4	ZZ/003	RESPRAY REAR BUMPER AND REAR PANEL	600.00	200
5	ZZ/004	TO CONDUCT REAR LIGHTING TEST	28.00	X
6	ZZ/005	TO CONDUCT REAR PROTECTANT COATING	250.00	X
7	ZZ/006	TO SUPPLY/INSTALL REVERSE SENSOR-2 EYES	300.00	?
8	ZZ/007	SUNDRIES	100.00	20.
TOTAL LABOUR CHARGES			2278.00	

MOTORIMAGE ENTERPRISES PTE. LTD.  
 19 LORONG 8, TOA PAYOH  
 SINGAPORE 319255

MATERIAL LIST FOR ACCIDENT VEHICLE REGN NO SBH0225C

S/NO PARTS DESCRIPTION	PARTS NUMBER	DAMAGED PARTS & PRICES			S/LIST REMARKS
		NETT	LIST	S/NETT	
1 REAR END PANEL <i>X NN</i>	52401AG0019P				288.00
2 REAR BUMPER <i>- ee</i>	57704AG080				594.00
3 REAR RH CORNER BRACKET <i>X LNN</i>	57707AG360				32.40
4 REAR LH CORNER BRACKET <i>X</i>	57707AG370				32.40
5 REAR BUMPER LOWER RH/LH BRACKET <i>?</i>	57707AG480				14.40
6 REAR BUMPER BEAM INNER <i>?</i>	57711AG010				100.80
7 REAR BUMPER OUTER BEAM (WITH FOAM) <i>?</i>	57712AG170				302.40
8 REAR BUMPER BEAM RH BRACKET <i>X</i>	57714AG0009P				50.40
9 REAR BUMPER BEAM LH BRACKET <i>X</i>	57714AG0109P				50.40
10 REAR RH SIDE BRACKET <i>X</i>	57717AG020				46.80
11 REAR LH SIDE BRACKET <i>X</i>	57717AG030				46.80
SUB TOTAL		0.00	0.00	0.00	1558.80
LESS DISCOUNT ( S/LIST-30 % )		0.00	0.00	0.00	467.64
GRAND TOTAL		0.00	0.00	0.00	1091.16
OVERALL TOTAL		1091.16			

LEGEND: REMARKS( OK ) = APPROVED, REMARKS( X ) = NOT APPROVED

MOTORIMAGE ENTERPRISES PTE. LTD.  
19 LORONG 8, TOA PAYOH  
SINGAPORE 319255

SUMMARY OF ESTIMATE FOR VEHICLE REGN NO SBH0225C

TOTAL LABOUR CHARGES	2278.00
TOTAL SPARE PARTS CHARGES	1091.16
GRAND TOTAL	3369.16 *

\* All charges do2 not include GST.

SURVEYOR'S PARTICULARS

NAME	:	
SURVEYED DATE	:	
AUTHORIZED DATE	:	
EXCESS CLAUSE	:	0.00
LIABILITY	:	0.00
REMARKS	:	

Guo Qiang - 8288 0282  
05/6/18  
retail paint photos.  
3 Days.

PLS NOTE : This estimate is based on visual inspection of the affected vehicle. Should we require further labour charges & spare parts in the process of repairs, we shall inform you accordingly.

**LKK Auto Consultants** hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer  
Signature:  
Date: