

ASS. REC. BY:

REF:

CS/7CL18010201/Kgbnz

Special Instruction:

Surveyor:

Kenneth

ASSIGNMENT (Office)

From (Person):

CWS

Eileen Lee

of

FCL

Date/Time:

05062018 237pm

Estimated Cost:

Bill to:

OD ☒ TP ☐ WS ☐ TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SHD 36G

Insured:

SH 7518K

at Workshop m/s

Trans Cab

Tel:

6287 6666

of

No. 2 AMK St 63

Policy No:

Claim No:

D18004477mFSH

Sum Insured:

Excess:

Make of Veh:

D.O.A.

04062018

(Client's Record)

CA / REV / REP. / REV 24 HRS 'DS'

H.O.D. Endorsement:

Date/Time:

Person Contacted:

Vehicle ☒ IN ☐ OUT

Date/Time

Action/Instruction (☒) Estimate

SHD 36G - CC4 / AXA 18011181 / K1h63

DA: 02032018

SH 7518K - CC3 / AXA 11012224 / H1n1c3f1

DA: 22062011

06/6/18 @ 12.11pm revised to Eileen by email.

ASS. REC. BY:

REF:

FCL/

Kenneth

ASSIGNMENT

From:

Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured:


Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt:

Consistent? : Yes or No

GIA / PR Seen:

Consistent? : Yes or No

Est. Repairs:

04 days

Res.: Yes or No

Lum Sum:

20 %

3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date:

Person Contacted:

Vehicle: IN / OUT

Veh No:

S14D 366

Yr Regn:

03, 15

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make:

Perault Corbiere

c.c

189

Colour:

M. White IR

A/C: Insured / Std / NI / NA

Sp. Reading

442522

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

VF1ABL15AUC 281531

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modl: NII / S/Rim / STD A/Rim or

Tyre Size:

F:

215/60R16

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or

Giti

Front

R/Bal.

7

mm

Rear

R/Bal.

8

mm

L/Bal.

7

mm

L/Bal.

8

mm

D.O.A.

4/6/18

D.O.I.

5/6/18

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

6/6 PM 14:15 to 14:45

L189 852501 (Red & 44666.47, 85%)

RECEIVED 6 JUN 2018

Date/Time, File Pass to?



: Prell. Report



: Final Report

1) 06/6 14:15 to 14:45
Date/Time, File Return to?

2)

Days Of Repair:

4

Resurvey No. of Trip:

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Survey Fee:

Transportation:

S + RS \$

Fees

Others

TOTAL

40x15=600

170+600

50

17

837

Report Format:

7P

Lump Sum / I.B.I: (\$

5250



Auto
Consultants
Pte Ltd

51 UBI AVE 1, #01-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004477MFSH

Date: 06 June 2018

Our Ref: CS/FCI18010201/Kqb

The Motor Claims Department
First Capital Insurance Ltd

Dear Sir/Madam,


INITIAL INSPECTION REPORT OF VEHICLE NO. SHD 36G .

Please be informed that we had conducted the inspection of the abovementioned vehicle on 05/06/2018 at the premises of M/s TRANS CAB, and have the following to report:-

Workshop Estimate Amount	: S\$ <u>49,916.47</u> .
Revised Estimate Amount	: S\$ <u>5,250.00 (Lump Sum)</u> .
"Check" Items Amount	: S\$ <u>-</u> .
Market Value	: S\$ <u>-</u> .
LTA Reimbursement Value	: S\$ <u>-</u> .
Nett Value	: S\$ <u>-</u> .

Description of Damage:

The vehicle sustained damages at the rear portion.



Yours faithfully

KONG SENG CHEONG
Licensed Appraiser

MOTOR SURVEY ASSIGNMENT

Date	05-06-2018	Our Ref No. D18004477MFSH
Accident Date	04-06-2018	Claim Type. Third Party
Insured Vehicle	SH7518K	Third Party Vehicle. SHD36G
Survey Location	NO. 2 ANG MO KIO STREET 63	
Contact Person.	CANDY	
Contact No.	62876666/ 0	Fax No. 62571330
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TRANS-CAB AUTO SERVICES PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Shiau Chan (LKKAUTO)

From: Shiau Chan (LKKAUTO)
Sent: Wednesday, 6 June 2018 12:11 PM
To: 'Claim Workflow System'; assignments
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18004477MFSH/1
Attachments: CSFCI18010201Kqb.pdf

Dear Eileen,

Enclosed herewith preliminary advice of SHD 36G.

Best Regards,

Shiau Chan (Ms) | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: siewsc@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAUTO)
Sent: Tuesday, 5 June 2018 2:45 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18004477MFSH/1

Dear Sir / Madam,

Thank you for the assignment.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Tuesday, 5 June, 2018 2:37 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18004477MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department

MS First Capital Insurance Limited

[Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type:	Company
Owner ID:	3878K

Vehicle Details

Vehicle No.:	SHD36G
Vehicle to be Exported:	Yes
Intended De-registration Date:	04 Jun 2018
Vehicle Make:	RENAULT
Vehicle Model:	LATITUDE 2.0L DCI AUTO D/AB 4DR
Primary Colour:	Red
Manufacturing Year:	2015
Engine No.:	M9R8839C002655
Chassis No.:	VF1ABL15AUC281531
Maximum Power Output:	127.0 kW (170 bhp)
Open Market Value:	\$19,998.00
Original Registration Date:	23 Mar 2015
First Registration Date:	23 Mar 2015
Transfer Count:	0
Actual ARF Paid:	\$12,498.00

Intended PARF Rebate Details

PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	22 Mar 2023
PARF Rebate Amount:	\$9,373.00

Intended COE Rebate Details

COE Expiry Date:	22 Mar 2023
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	8
PQP Paid:	\$51,092.00
COE Rebate Amount:	\$30,644.00
Total Rebate Amount:	\$40,017.00

Message

Please note that the 8-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 04 Jun 2018

OK

Trans-cab Auto Services Pte Ltd

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 36G**AAD1806-028***Not Authored
61 Pm @ 5250h*

Vehicle No.:

Chassis No.:

Vehicle Make:

Vehicle Model:

Date of Accident :

Third Party Insurer :

SHD 36G

VF1ABL15AUC281531

RENAULT

LATITUDE

4.6.2018

FCIL**PART****LIST**

1	1 BUMPER COVER REAR	\$	<i>Bu</i> 1,108.46	—
2	1 BUMPER LOWER REAR	\$	<i>Red 10/11</i> 768.84	—
3	1 BUMPER BRACKET CTR REAR	\$	<i>DIT</i> 113.47	—
4	1 BUMEP R BRACKET SIDE RH REAR	\$	<i>Sen</i> 135.97	X
5	1 BUMEP R RETAINER RH REAR	\$	<i>Sen</i> 44.99	X
6	1 BUMPER REFLECTOR RH	\$	<i>Sen</i> 43.61	X
7	1 BUMEP R BRACKET SIDE LH REAR	\$	<i>Sen</i> 135.97	X
8	1 BUMEP R RETAINER LH REAR	\$	<i>Sen</i> 44.99	X
9	1 BUMPER REFLECTOR LH	\$	<i>CM</i> 43.61	—
10	1 BUMPER BEAM REAR	\$	<i>R</i> 777.52	—
11	1 BUMPER BEAM BRACKET LH REAR	\$	<i>DIT</i> 225.95	—
12	1 BUMPER BEAM BRACKET RH REAR	\$	<i>DIT</i> 225.95	—
13	1 BOOT REAR	\$	<i>R</i> 2,872.68	} X
14	1 BOOT FINISHER	\$	<i>Sen</i> 470.06	
15	1 BOOT WHEATERSTRIP	\$	<i>Sen</i> 323.05	
16	1 BOOT REFLECTOR LAMP LH	\$	<i>Sen</i> 493.35	
17	1 BOOT REFLECTOR LAMP RH	\$	<i>Sen</i> 493.35	
18	1 BOOT BADGE 'RENAULT'	\$	<i>Sen</i> 225.36	
19	1 BOOT BADGE	\$	<i>Sen</i> 225.36	
20	1 BOOT STRUT LH	\$	<i>Sen</i> 276.08	
21	1 BOOT STRUT RH	\$	<i>Sen</i> 276.08	
22	1 BOOT HINGE LH	\$	<i>R</i> 367.84	
23	1 BOOT HINGE RH	\$	<i>R</i> 367.84	
24	1 BOOT INNER TRIM	\$	<i>Sen</i> 586.45	
25	1 BOOT SWITCH	\$	<i>Sen</i> 168.13	
26	1 BOOT LOCK	\$	<i>R</i> 202.67	
27	1 BOOT LOCK CATCH	\$	<i>R</i> 74.40	
28	2 LICENCE PLATE LAMP	\$	<i>Sen</i> 50.52	
29	2 BOOT RUBBER PLUG	\$	<i>Sen</i> 221.81	

Trans-cab Auto Services Pte Ltd**AAD1806-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 36G

30	1 DOOR PANEL REAR LH	\$	<i>R</i> 2,844.66	
31	1 FENDER PANEL INNER TRIM REAR LH	\$	<i>Sn</i> 671.45	
32	1 FENDER PANEL REAR LH	\$	<i>R</i> 3,299.13	
33	1 WHEELARCH REAR LH	\$	<i>Sn</i> 543.47	
34	1 FENDER PANEL INNER TRIM REAR RH	\$	<i>Sn</i> 671.45	
35	1 FENDER PANEL REAR RH	\$	<i>R</i> 3,299.13	
36	1 WHEELARCH REAR RH	\$	<i>Sn</i> 543.47	
37	1 TAILLAMP RH	\$	<i>Sn</i> 552.55	
38	1 TAILLAMP PANEL RH	\$	<i>R</i> 986.70	
39	1 TAILLAMP LH	\$	<i>Sn</i> 552.55	
40	1 TAILLAMP PANEL LH	\$	<i>R</i> 986.70	
41	1 OUTER PANEL REAR (End Panel)	\$	<i>R</i> 1,471.77	✓
42	1 OUTER PANEL REAR (End Panel)TRIM	\$	<i>Adm</i> 404.56	✓
43	1 SPARE WHEEL PANEL (Luggage Floor Panel)	\$	<i>R</i> 2,189.88	X
44	1 SPARE WHEEL PANEL TRIM	\$	<i>Sn</i> 612.21	X
45	1 EXHAUST REAR	\$	<i>R</i> 7,489.05	X
46	1 EXHAUST CAP REAR	\$	<i>R</i> 230.49	X
47	1 FUEL FLAP L70Y	\$	<i>Sn</i> 343.57	X
TOTAL		\$	39,057.17	
10%		\$	3,905.72	
		\$	35,151.45	

Special Nett

1	1SET PARKING AID	\$	<i>Shay</i> 700.00	<i>Good</i>
2	1SET REAR BUMPER CLIP	\$	<i>na</i> 66.00	—
3	1SET BUMPER BRACKET CTR CLIP	\$	<i>na</i> 33.00	—
4	1SET BUMPER BRACKET SIDE CLIP RH RR	\$	<i>na</i> 10.00	X
5	1SET BUMPR RETAINER RH CLIP RR	\$	<i>na</i> 20.00	X
6	1SET BUMPR BRACKET SIDE CLIP LH RR	\$	<i>na</i> 10.00	X
7	1SET BUMPR RETAINER CLIP LH RR	\$	<i>na</i> 20.00	X
8	1SET BUMPER LOWER REAR RIVET	\$	<i>na</i> 22.00	X
9	1SET BUMPER LOWER REAR CLIP	\$	<i>na</i> 66.00	✓
10	1 EXHAUST MOUNTING REAR	\$	<i>Sn</i> 17.82	X
11	1SET BOOT FINISHER CLIP	\$	<i>na</i> 24.20	X
12	1 BOOT STICKER "Trans-cab"	\$	<i>na</i> 30.00	X
13	1 BOOT STICKER "6555-3333"	\$	<i>na</i> 30.00	X
14	1 BOOT INNER TRIM CLIP	\$	<i>na</i> 45.00	X
15	1SET FENDER WHEELARCH REAR RH CLIP	\$	<i>na</i> 35.00	X

Trans-cab Auto Services Pte Ltd

AAD1806-028

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 36G

16 1SET FENDER WHEELARCH REAR LH CLIP	\$	35.00	}
17 1 FENDER INNER TRIM CLIP LH	\$	28.00	
18 1 FENDER INNER TRIM CLIP LH	\$	28.00	
19 1 TAILLAMP CLIP RH	\$	5.00	
20 1 TAILLAMP CLIP LH	\$	5.00	
21 2 REAR WINDSCREEN SELANT	\$	80.00	
22 1 WINDSCREEN MOULDING	\$	100.00	
23 1 REAR WINDSCREEN INNER SPONGE SEAL	\$	100.00	
24 1 SPARE TYRE RIM (ROUE 7J 16H 2547)	\$	385.00	}
25 1 SPARE TYRE	\$	330.00	

TOTAL \$ 2,225.02**TOTAL PARTS \$ 37,376.47****LABOUR**

Putty And Spray Painting Of The Affected Portion.	\$	6,000.00	4800
Panel Beating, Knocking And Straightening The Necessary Portion, Remove And Renewal Of Parts, Adjust And Realign The Same	\$	4,200.00	6000
To Rust-Proofing Of The Affected Areas.	\$	170.00	300
To reinstall rear bumper parking sensor.	\$	170.00	600
To transfer of bootlid fittings, attachments and perform water seepage test.	\$	170.00	X
To repair and realign rear exhaust pipe.	\$	170.00	X
To drop rear exhaust box, renew the same, to repair and realign centre exhaust pipe.	\$	170.00	X
To transfer of rear end panel fittings, attachment and perform water seepage test.	\$	170.00	600

Trans-cab Auto Services Pte Ltd**AAD1806-028**

No. 2 Ang Mo Kio Street 63 Singapore 569111

Tel No. : 6287 6666 Fax No. : 6257 1330

CO./GST Reg. No. 201019626G

SHD 36GTo transfer of rear luggage floor panel fittings,
attachment and perform water seepage test.

\$ 170.00 X

To supply and re-do rear luggage floor panel
insulation padding.

\$ 380.00 X

To transfer of rear fender fittings, attachment and
perform water seepage test.

\$ 380.00 X

To transfer of rear windscreen fittings and conduct
water seepage test.

\$ 170.00 X

To check steering geometry and computer wheel
alignment

\$ 220.00 X

To transfer of rear door fittings, attachment and
perform water seepage test.

\$ 380.00 X

TOTAL \$ 12,540.00**Over All Total \$ 49,916.47**

50,296.45

(LUMP SUM)**Repair Days****20 DAYS**

4 days

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:




LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010201/Kqbn2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SH 7518K	Veh. Inspected	SHD 36G	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18004477MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	05/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	RENAULT LATITUDE (A)	c.c	1991	
Engine No.	HIDDEN	Year of Reg.	2015	
Chassis No.	VF1ABL15AUC281531	Colour	METALLIC WHITE / RED	
Odometer	442522	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	GOOD			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	215/60 R16	GITI	7 mm	
L/H Front Tyre	215/60 R16	GITI	7 mm	
R/H Rear Tyre	215/60 R16	GITI	8 mm	
L/H Rear Tyre	215/60 R16	GITI	8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE REAR PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	04/06/2018	Inspection Date	05/06/2018	
Survey held at	TRANS-CAB AUTO SERVICES PTE LTD NO.2 ANG MO KIO ST 63 SINGAPORE 569111			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		4 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 1 of 4

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SHD 36G

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	BUMPER COVER REAR	BUCKLED	1,108.46	1,108.46
1	BUMPER LOWER REAR	DENTED / DISTORTED	768.84	768.84
1	BUMPER BRACKET CTR REAR	DISTORTED	113.47	113.47
1	BUMPER BRACKET SIDE RH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER RH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR RH	SERVICEABLE	43.61	-
1	BUMPER BRACKET SIDE LH REAR	SERVICEABLE	135.97	-
1	BUMPER RETAINER LH REAR	SERVICEABLE	44.99	-
1	BUMPER REFLECTOR LH	CRACKED	43.61	43.61
1	BUMPER BEAM REAR	BENT	777.52	777.52
1	BUMPER BEAM BRACKET LH REAR	DISTORTED	225.95	225.95
1	BUMPER BEAM BRACKET RH REAR	DISTORTED	225.95	225.95
1	BOOT REAR	TO REPAIR SEE LABOUR	2,872.68	-
1	BOOT FINISHER	SERVICEABLE	470.06	-
1	BOOT WEATHERSTRIP	SERVICEABLE	323.05	-
1	BOOT REFLECTOR LAMP LH	SERVICEABLE	493.35	-
1	BOOT REFLECTOR LAMP RH	SERVICEABLE	493.35	-
1	BOOT BADGE "RENAULT"	NOT NECESSARY	225.36	-
1	BOOT BADGE	NOT NECESSARY	225.36	-
1	BOOT STRUT LH	SERVICEABLE	276.08	-
1	BOOT STRUT RH	SERVICEABLE	276.08	-
1	BOOT HINEG LH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT HINGE RH	TO REPAIR SEE LABOUR	367.84	-
1	BOOT INNER TRIM	SERVICEABLE	586.45	-
1	BOOT SWITCH	SERVICEABLE	168.13	-
1	BOOT LOCK	TO REPAIR SEE LABOUR	202.67	-
1	BOOT LOCK CATCH	TO REPAIR SEE LABOUR	74.40	-

Report Ref No. CS/FCI18010201/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No. 2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
2	LICENCE PLATE LAMP	SERVICEABLE	50.52	-
2	BOOT RUBBER PLUG	SERVICEABLE	221.81	-
1	DOOR PANEL REAR LH	TO REPAIR SEE LABOUR	2,844.66	-
1	FENDER PANEL INNER TRIM REAR LH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR LH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR LH	SERVICEABLE	543.47	-
1	FENDER PANEL INNER TRIM REAR RH	SERVICEABLE	671.45	-
1	FENDER PANEL REAR RH	TO REPAIR SEE LABOUR	3,299.13	-
1	WHEELARCH REAR RH	SERVICEABLE	543.47	-
1	TAILLAMP RH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL RH	TO REPAIR SEE LABOUR	986.70	-
1	TAILLAMP LH	SERVICEABLE	552.55	-
1	TAILLAMP PANEL LH	TO REPAIR SEE LABOUR	986.70	-
1	OUTER PANEL REAR (END PANEL)	BENT	1,471.77	1,471.77
1	OUTER PANEL REAR (END PANEL) TRIM	DENTED / DISTORTED	404.56	404.56
1	SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL)	TO REPAIR SEE LABOUR	2,189.88	-
1	SPARE WHEEL PANEL TRIM	SERVICEABLE	612.21	-
1	EXHAUST REAR	TO REPAIR SEE LABOUR	7,489.05	-
1	EXHAUST CAP REAR	TO REPAIR SEE LABOUR	230.49	-
1	FUEL FLAP L70Y	SERVICEABLE	343.57	-
	LESS 10% DISCOUNT		-3,905.72	-514.01
			35,151.43	4,626.12
	SPECIAL NETT ITEMS			
1	SET PARKING AID (SN)	SHORTED	700.00	600.00
1	SET REAR BUMPER CLIP (SN)	NECESSARY	66.00	66.00
1	SET BUMPER BRACKET CTR CLIP (SN)	NECESSARY	33.00	33.00
1	SET BUMPER BRACKET SIDE CLIP RH RR (SN)	NOT NECESSARY	10.00	-

Report Ref No. CS/FCI18010201/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	SET BUMPER RETAINER RH CLIP RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER BRACKET SIDE CLIP LH RR (SN)	NOT NECESSARY	10.00	-
1	SET BUMPER RETAINER CLIP LH RR (SN)	NOT NECESSARY	20.00	-
1	SET BUMPER LOWER REAR RIVET (SN)	NOT NECESSARY	22.00	-
1	SET BUMPER LOWER REAR CLIP (SN)	NECESSARY	66.00	66.00
1	EXHAUST MOUNTING REAR (SN)	SERVICEABLE	17.82	-
1	SET BOOT FINISHER CLIP (SN)	NOT NECESSARY	24.20	-
1	BOOT STICKER "TRANS-CAB" (SN)	NOT NECESSARY	30.00	-
1	BOOT STICKER "6555-3333" (SN)	NOT NECESSARY	30.00	-
1	BOOT INNER TRIM CLIP (SN)	NOT NECESSARY	45.00	-
1	SET FENDER WHEELARCH REAR RH CLIP (SN)	NOT NECESSARY	35.00	-
1	SET FENDER WHEELARCH REAR LH CLIP (SN)	NOT NECESSARY	35.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	FENDER INNER TRIM CLIP LH (SN)	NOT NECESSARY	28.00	-
1	TAILLAMP CLIP RH (SN)	NOT NECESSARY	5.00	-
1	TAILLAMP CLIP LH (SN)	NOT NECESSARY	5.00	-
2	REAR WINDSCREEN SEALANT (SN)	NOT NECESSARY	80.00	-
1	WINDSCREEN MOULDING (SN)	NOT NECESSARY	100.00	-
1	REAR WINDSCREEN INNER SPONGE SEAL (SN)	NOT NECESSARY	100.00	-
1	SPARE TYRE RIM (ROUE 7J 16H 2547)(SN)	SERVICEABLE	385.00	-
1	SPARE TYRE (SN)	SERVICEABLE	330.00	-
			2,225.02	765.00
	LABOUR			
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION.		6,000.00	440.00
	PANEL BEATING,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF BOOT REAR,BOOT HINGE LH,BOOT HINGE RH,BOOT LOCK,BOOT LOCK CATCH,DOOR PANEL REAR LH,FENDER PANEL REAR LH,FENDER PANEL REAR RH,TAILLAMP PANEL RH,TAILLAMP PANEL LH,SPARE WHEEL PANEL (LUGGAGE FLOOR PANEL),EXHAUST REAR AND EXHAUST CAP REAR.		4,200.00	600.00
	TO RUST-PROOFING OF THE AFFECTED AREAS.		170.00	30.00

Report Ref No. CS/FCI18010201/Kqbn2



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REINSTALL REAR BUMPER PARKING SENSOR.		170.00	60.00
	TO TRANSFER OF BOOTLID FITTINGS, ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO REPAIR AND REALIGN REAR EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO DROP REAR EXHAUST BOX, RENEW THE SAME, TO REPAIR AND REALIGN CENTRE EXHAUST PIPE.	NOT NECESSARY	170.00	-
	TO TRANSFER OF REAR END PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.		170.00	60.00
	TO TRANSFER OF REAR LUGGAGE FLOOR PANEL FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO SUPPLY AND RE-DO REAR LUGGAGE FLOOR PANEL INSULATION PADDING.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR FENDER FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
	TO TRANSFER OF REAR WINDSCREEN FITTINGS AND CONDUCT WATER SEEPAGE TEST.	NOT NECESSARY	170.00	-
	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT.	NOT NECESSARY	220.00	-
	TO TRANSFER OF REAR DOOR FITTINGS, ATTACHMENT AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	380.00	-
			12,920.00	1,190.00
	GRAND TOTAL		50,296.45	6,581.12
	RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)			5,250.00

Report Ref No. CS/FCI18010201/Kqbn2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.