

22/03/2002

A.S. REC. BY:

REF:

CS/CTZ18010218/Xtbez

Special Instruction:

Survivor:
Mummen

Sathya

ASSIGNMENT (Office)

From (Person):

Chong Boon Sen

of

CTL

Date/Time:

05062018 2:14pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

GBH 2090K

Insured:

YM 8234A

at Workshop m/s

William's Auto

Tel:

92636811

of

Blk 3 Yew Tee Ind Est 391-B

Policy No:

DMCVSN 3087911700

Claim No:

SNM18D02771C03

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

04062018

CA / REV / REP. / REV 24 HRS 'wp'

06062018 @ 11am

H.O.D. Endorsement:

Date/Time:

05062018 4pm

Person Contacted:

William

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	GBH 2090K - x
	YM 8234A - x

unconfirm at lump sum \$22007 (Red. 399655; 64%)

REF: CTI

ASSIGNMENT

From: Date: 06/06/18

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: GBH 2090 K
at Workshop n/s William's Auto
of Blk 3, Yew Tee Ind. Est 391-B

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS 'up

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: GBH 2090 K Yr Regn: Mar / 2018

Type: M.Car / M.Cycle / Bus / Van / Corr / Taxi / Prime Mover /

Truck / Trailer or

Make: Toyota Dyna C.C. 2482

Colour Blue A/C: Insured / Std / NI / NA

Sp. Reading 4568.8 T/Radio: Insured / Std / NI / NA

Eng/No: IKD 2789516

C/No: JTFAT35420K209991

Gen. Cond: Good / Fair / Poor / BurntSteering: In order / Jammed / Leaked / Burnt orBrake: In order / Jammed / Leaked / Burnt orModi: Til / S/Rim / STD A/Rim or

Tyre Size: F: 195/75 R15

R: 155 R15

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm R/Bal. 6 mm

L/Bal. 6 mm L/Bal. 6 mm

D.O.A. 4/6/2018 D.O.I. 6/6/2018

Survey held at William's Auto.

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

Sathya,

Pls see me.

RECEIVED 22 APR 2019

13/6.

Date/Time: File Pass to?

☐ : Preli. Report☐ : Final Report

Date/Time: File Return to?

B

Days Of Repair: 3

Resurvey No. of Trip: -

Survey Fee:

Transportation:

) \$ + RS \$

) Photos

) Others

TOTAL

Add Fee: ☐ : Site Insp (\$☐ : Interview (\$☐ : Tech. Invs (\$☐ : Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$

TP

22007

220

220

...CLAIM SUBFOLDER...(New Assignment)

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018		05 Jun 2018 14:14 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	HOCKLIM ENGINEERING PTE LTD	
Main Claimant:	SIN JOO HENG GAS SUPPLY PTE LTD	
Vehicle Reg. No.:	GBH2090K	Date of Loss: 04/06/2018 07:00 - :59
Claim Type:	TP / SNM18D02771C02	Policy/Cover Note No.: DMCVSN3087911700
Vehicle Reg. No. (Insured):	YM8234A	Policy No. (Claimant):
		Excess: S\$0.00
Repairer:	William's Auto Pte Ltd (HQ) BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE, 677965 Woodlands - Tel:	
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 14/06/2018]	
Adj Asg. Remarks:	Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS						View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Denise Tay (LKKAUTO)

From: William Auto <waplsp21@singnet.com.sg>
Sent: Monday, 20 August 2018 4:21 PM
To: Denise Tay (LKKAUTO)
Subject: WRONG LIST PRICE RE: GBH2090K

CORNER PANEL - 325/2
HEAD LAMP - 1,015.34
SIDE MIRROR - ELECTRICAL 845/2
PLEASE CHECK ON YOUR LIST PRICE ARE WRONG THANK YOU WILLIAM ANG

-----Original Message-----

From: Denise Tay (LKKAUTO) [mailto:denisetay@lkkauto.com]
Sent: Monday, 20 August, 2018 3:22 PM
To: William Auto <waplsp21@singnet.com.sg>
Subject: RE: GBH2090K

Dear William,

Can accept the finalize amount? Lump sum \$2100.

Best Regards,

Denise Tay | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email: denisetay@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: Sathya Sai (LKK Auto)
Sent: Thursday, 26 July 2018 11:36 AM
To: William Auto <waplsp21@singnet.com.sg>
Cc: SUR <sur@lkkauto.com>; CS A Team <cs-a@lkkauto.com>
Subject: RE: GBH2090K

Good Day,

Please refer to attachment for finalisation.

Thank you

Best Regards,

Sathya Sai | Assistant Automotive Assessor

LKK Auto Consultants

Phone: 9807 2012 | Email: SathyaSai@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

-----Original Message-----

From: William Auto [mailto:waplsp21@singnet.com.sg]

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	04/06/2018 10:39
Date Of Accident	04/06/2018 07:30
Exact Location Of Accident	AT BLK 2020 BUKIT BATOK IND PARK
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	GBH2090K
Insured/Policyholder	
Name Of Registered Owner	SIN JOO HENG GAS SUPPLY PTE. LTD.
Co Reg No	200416751E
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-97543575

Vehicle Particulars

Manufacturer	TOYOTA
Model	DYNA 150 5MT
Exact Purpose for which vehicle was being used at time of accident	COMMERCIAL

Are you claiming under your own insurance policy for repair to your vehicle? NO

If No, Please state action to be taken THIRD PARTY

Vehicle Category COMMERCIAL VEHICLE

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	5094993704
Cover Note Number	

Driver

Name of Driver	YEO KOK TONG
NRIC No	S1541060D
Date Of Birth	22/02/1962
Occupation	OUTDOOR
Date Of Driving Pass	16/04/1980
Driving Experience	38 YEARS AND 1 MONTH
Gender	MALE
Mobile Number	(LOCAL) +65-90698100
Fax Number	
Contact Number	
EEmail Address	NOEMAIL

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965
 TEL: 67636811 FAX: 67632166 Email: wapsp21@singnet.com.sg
 GST:M2-0032987-2 RCB NO:A03151/1978Z



M/S : CHINA TAIPING INSURANCE (S) PTE LTD
 3 ANSON ROAD
 #15-00 SPRINGLEAF TOWER
 SINGAPORE 079909
 TEL: 63896174 FAX: 62247175
 ATTN: Motor Claim Department \ MR TEO

Estimate No: EST1800839
Date: 04 Jun 2018
Policy No: 5094993704
Veh Reg No: GBH2090K
Make/Model: TOYOTA DYNA 150
 5MT
Chassis No: JTFAT35Y20K209991
Engine No: 1KD2789516
Reg. Date: 19/03/2018

Your Ref No: GBH2090K
 Claim Type: Third Party
 Accident Date: 04/06/2018
 TP Veh Reg No: YM8234A

Estimate Repair Cost to Vehicle No : GBH2090K

Description	U/Price	Quantity	Cost	Amount
			S\$	S\$
Special Net				
1 FRONT GRILLE CLIPS ✓ NEL		1 SET	95.00	95.00 20
2 FRONT DOOR SIDE LETTERING ✓ NEL	120	1 SET	180.00	180.00 120
				275.00
List Price				
3 FRONT GRILLE ✓ CRK		1 PC	393.20	393.20 ✓
4 FRONT GRILLE SEAL X NN		1 PC	69.70	69.70
5 FRONT CORNER PANEL - LH ✓ CUT		1 PC	396.45	✓ 396.45
6 FRONT PANEL LOGO ✓ NEL		1 PC	68.50	68.50 ✓
7 HEAD LAMP HID - LH ✓ SCR 1165		1 PC	1,389.40	1,389.40
8 FRONT SIDE MIRROR ASSY (ELECTRICAL) ✓ reform - photo 592		1 PC	1,589.10	1,589.10
				3,906.35
To Repair				
9 FRONT DOOR - LH R		1 PC	985.20	985.20 ✓ 120
				985.20
Labour				
10 LABOUR TO REMOVE NECESSARY DAMAGED PARTS ENABLE TO STRAIGHTEN PANEL, PANEL BEAT & REPAIR AFFECTED PANEL TO THE SAME.		1 JOB	400.00	400.00 250
11 TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS		1 JOB	600.00	600.00 400
12 WIRING JOB		1 JOB	30.00	30.00 500
				1,030.00

the Repairer of the following:
 • To resurvey before/after spray painting
 • To display damaged part(s) during resurvey
 • Parts prices are subject to confirmation
 • Third party survey is on a "Without Prejudice" basis
 • No illegal modification is allowed
 • Supplementary items must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date:

WILLIAM'S AUTO PTE LTD

BLK c3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE SINGAPORE 677965

TEL: 67636811 FAX: 67632166 Email: wapls21@singnet.com.sg

GST:M2-0032987-2 RCB NO:A03151/1978Z

M/S : CHINA TAIPING INSURANCE (S) PTE LTD
3 ANSON ROAD
#15-00 SPRINGLEAF TOWER
SINGAPORE 079909
TEL: 63896174 FAX: 62247175
ATTN: Motor Claim Department \ MR TEO

Your Ref No: GBH2090K
Claim Type: Third Party
Accident Date: 04/06/2018
TP Veh Reg No: YM8234A

Estimate No: EST1800839
Date: 04 Jun 2018
Policy No: 5094993704
Veh Reg No: GBH2090K
Make/Model: TOYOTA DYNA 150
5MT
Chassis No: JTFAT35Y20K209991
Engine No: 1KD2789516
Reg. Date: 19/03/2018

Estimate Repair Cost to Vehicle No : GBH2090K

Total	S\$ 6,196.55
Add GST @ 7%	433.76
Total Amount payable	S\$ 6,630.31

TOTAL: SINGAPORE DOLLAR SIX THOUSAND SIX HUNDRED THIRTY AND CENTS THIRTY ONE ONLY

For WILLIAM'S AUTO PTE LTD

AUTHORISED SIGNATURE

Sathya Sai
6/5/2018
98072012
- Lump Sum Repair
- photo after paint

[Handwritten signature]
2/6/18

3 days

<p>LKK Auto Consultants hence notify the Repairer of the following:</p> <ul style="list-style-type: none">• To resurvey before/after spray painting• To display damaged part(s) during resurvey• Parts prices are subject to confirmation• Third party survey is on a "Without Prejudice" basis• No illegal modification(s) is allowed• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company <p>Acknowledged by Repairer Signature: Date:</p>

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	05 Jun 2018		05 Jun 2018 14:14 Edit Adj Rpt	S\$2,200.00 Edit Estimates	S\$2,200.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: HOCKLIM ENGINEERING PTE LTD , Co. Reg. No.: -									
Main Claimant: SIN JOO HENG GAS SUPPLY PTE LTD									
Vehicle Reg. No.: GBH2090K		Date of Loss: 04/06/2018 07:00 - :59 [3 Months and 3 Days From LTA Reg Date (Man Yr)]							
Claim Type: TP / SNM18D02771C02		Policy/Cover Note No.: DMCVSN3087911700							
Vehicle Reg. No. (Insured): YM8234A		Policy No. (Claimant):							
		Excess: S\$0.00							
Repairer: William's Auto Pte Ltd (HQ) BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE, 677965 Woodlands - Tel:									
Handling Insurer: China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Chong Boon Sen]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Muhammad Nazril Bin Abdullah] ... [Final Rpt due 14/06/2018]									
Adj Asg. Remarks: Please survey third party vehicle & let us have your recommendation on estimated amount required to repair the vehicle if there is NO estimate provided during pre-repair inspection									
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*GBH2090K (SNM18D02771C02)
[YM8234A]
TP
SIN JOO HENG GAS SUPPLY PTE LTD
Jun 4 2018 7:00AM
[HOCKLIM ENGINEERING PTE LTD]
William's Auto Pte Ltd

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)						Thumbnail	Print	
1	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
2	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
3	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
4	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
5	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
6	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
7	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
8	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
9	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
10	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
11	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
12	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
13	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
14	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
15	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
16	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
17	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
18	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
19	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
20	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
21	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
22	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
23	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
24	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
25	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
26	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
27	06/06/18 17:56	Chassis Number						Load JPG	<input checked="" type="checkbox"/>	
28	06/06/18 17:56	Odometer Reading						Load JPG	<input checked="" type="checkbox"/>	
29	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
30	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
31	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
32	06/06/18 17:56	General View						Load JPG	<input checked="" type="checkbox"/>	
33	11/06/18 17:51	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
34	11/06/18 17:51	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
35	11/06/18 17:51	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
36	11/06/18 17:51	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	
37	11/06/18 17:51	Photo After Spray						Load JPG	<input checked="" type="checkbox"/>	

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
39	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
40	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
41	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
42	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
43	11/06/18 17:51	Photo After Spray	 Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	05/06/18 14:10	TP NOTIFICATION	 Load PDF	
2	05/06/18 14:12	TP REPORT	 Load PDF	

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ) <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
Show Remarks To: <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/CTI18010218/NTBE2

Date: 23/04/2019

REFERENCE

Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd.	Policy No:	DMCVSN3087911700
Claimant Vehicle No :	GBH2090K	Insured Vehicle No :	YM8234A
Date of Loss:	04/06/2018	Nature of Claim:	TP
		Claim No:	SNM18D02771C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	GBH2090K	Engine No:	1KD2789516
Make & Model:	TOYOTA DYNA 150, 3.0 D 5MT (M)	Chassis No:	JTFAT35Y20K209991
Reg. Date:	01/03/2018 (Man. Year: 2018)	Odometer:	4568 km
Colour:	Blue		
Engine Capacity:	2982 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/75 R15	Rear Tyre Size:	155 R15
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	5,166.55	2,101.36	3,065.19	59.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,030.00	680.00	350.00	33.98
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,196.55	2,781.36	3,415.19	55.11
Approved Total (Overridden) (S\$)		2,200.00		
(S\$)	6,196.55	2,200.00	3,996.55	64.50
+ GST 7.00/7.00% (S\$)	433.76	154.00	279.76	64.50
Nett Amount (S\$)	6,630.31	2,354.00	4,276.31	64.50

INSPECTION

Date of Assignment:	05/06/2018	
Date Inspected:	06/06/2018 Inspected At:	William's Auto Pte Ltd (HQ) BLK 3 WOODLANDS ROAD 391-B YEW TEE INDUSTRIAL ESTATE Singapore 677965
Estimated Period of Repair:	3.0 days	

Adjuster: Muhammad Nazril Bin Abdullah**Manager:** DENISE TAY KWEE CHENG

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	(Last Synchronised: 23 Apr 2019)	
Parts:	N/A	TOYOTA DYNA 150 3.0 D 5MT (M) (Model not available in database)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for GBH2090K)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SET FRONT GRILLE CLIPS	Necessary	95.00 FS	*20.00 FS
2	1		*SET FRONT DOOR SIDE LETTERING	Necessary	180.00 FS	*120.00 FS
3	1		*FRONT GRILLE	Cracked	393.20 F	*393.20 FL
4	1		*FRONT GRILLE SEAL	Not Necessary	69.70 F	*- FL
5	1		*FRONT CORNER PANEL - LH	Cut	396.45 F	*396.45 FL
6	1		*FRONT PANEL LOGO	Necessary	68.50 F	*68.50 FL
7	1		*HEAD LAMP HID - LH	Scratched	1,389.40 F	*1,165.00 FL
8	1		*FRONT SIDE MIRROR ASSY (ELECTRICAL)	Deformed	1,589.10 F	*592.00 FL
9	1		*FRONT DOOR - LH	Repair	985.20 F	*- FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	5,166.55	2,755.15
- List Item Discount on L Items 0.00/25.00% (S\$)	0.00	653.79

Total Parts (S\$)	5,166.55	2,101.36
--------------------------	-----------------	-----------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	LABOUR TO REMOVE NECESSARY DAMAGED PARTS ENABLE TO STRAIGHTEN PANEL, PANEL BEAT & REPAIR AFFECTED PANEL TO THE SAME	New	400.00	250.00
2	TO RESPRAY PAINTING ON REPLACEMENT PARTS AND OTHER AFFECTED AREAS	New	600.00	400.00
3	WIRING JOB	New	30.00	30.00
Gross Labour Cost (S\$)			1,030.00	680.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >