

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A

#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimmc@singnet.com.sg

GST Reg No: M9-0009639-E

TP INSURER: India International Insurance Pte Ltd (HQ)

SURVEYOR COPY

Singapore

Claimant Insurer: Tokio Marine Insurance Singapore Ltd

PARTICULARS OF CLAIM

Claim Type:	THIRD PARTY	Ref. No:	
Policy No:		Date of Loss:	04/06/2018
Vehicle Reg. No.:	SLX5479B	Driveable?	
Party At Fault:	UNKNOWN		
Driver (TP):	KUAH WEN GUI FRANCIS		
Make/Model:	TOYOTA SIENTA HYBRID, 1.5 X CVT (A)	Vehicle Reg. Date:	29/03/2018
Vehicle Colour:	BLUE		
Engine No:	1NZ8398109	Chassis No:	NHP1707110172
Odometer:	0 KM		
Paint Type:			
List Item Discount:	25.00 %		
Total Loss?	NO		
Est. Duration of Repair (day)	5		
Description of Accident/Loss	REFER TO THE SKETCH PLAN BY DRIVER		
Remarks:	CAR NOT IN - TO BE ARRANGE		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

Amount

Parts	1,056.27
Miscellaneous Items	10.00
Labour	1,640.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (\$)	2,706.27
+ GST 7.00% (\$)	189.44
Nett Amount (\$)	2,895.71

This claim is handled by: ZILA

Generated using Merimen e-Claims Internet Estimation & Adjusting System

REPAIR DETAILS**Reference****Part Source:** MRM-SG Version: 1.0 (Last Synchronised: 05 Jun 2018)**Parts:** M1-MPV TOYOTA SIENTA HYBRID 1.5 X CVT (A) (Catalogue:Merimen Singapore 1.0)**Labour:** Repairer's (Price-denominated Standard List)**Print Code:** Ah Lim Motor Company/SLX5479B/05/06/2018 16:36**Validity:** These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page**Further Info:** Items/values not in reference catalogue are prefixed with an asterisk *.**Estimates on Parts**

No.	Qty	Part No.	Particulars	%Disc	%Depr	Amount
1	1		*TAILAMP LH <i>X NN</i>	25.00	0.00	*311.69 FL
2	1		*REAR BUMPER <i>/ CWT</i>	25.00	0.00	*397.40 FL
3	1		*REAR BUMPER SIDE RETAINER LH <i>- MC</i>	25.00	0.00	*42.70 FL
4	10		*REAR BUMPER CLIPS <i>/ MC</i>	25.00	0.00	*38.90 FL
5	1		*REAR BUMPER SIDE GARNISH LH (BLACK) <i>/ CWT</i>	25.00	0.00	*151.60 FL
6	1		*REAR FENDER PROTECTOR LH <i>/ MC</i>	25.00	0.00	*61.70 FL
7	1		*REAR DOOR PROTECTOR (BLACK) LH <i>/ SIR</i>	25.00	0.00	*141.70 FL
8	1		*STEEL RIM COVER LHR <i>/ SGR</i>	0	0.00	*197.00 FS
9	1		*TYRE LHR - CHECK PRICE <i>X NN</i>	0	0.00	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$) **1,342.69**- List Item Discount on L Items (S\$) **286.42**Total Parts (S\$) **1,056.27**

Ah Lim Motor Company/SLX5479B/05/06/2018 16:36. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Estimates on Miscellaneous Items

No	Qty	Particulars	Amount
<u>Miscellaneous Items</u>			
1	1	OD/TP Case (Insurer)	10.00
Sub Total (S\$)			10.00

Estimates on Labour

No	Particulars	Lab.Type	Amount
<u>Labour Items</u>			
1	TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	40.00
2	TO CHECK AND RE-ADJUST WHEEL ALIGNMENT.	New	80.00
3	TO REMOVE AND REINSTALL CUSHIONS; SEATS; BACKREST; INNER TRIM; GARNISH; ROOF LINING OR UPHOLSTERY TO FACILITATE REPAIRS.	New	120.00
4	TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD. TO KNOCK & REPAIR REAR FENDR LH; REAR DOOR LH INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	700.00
5	TO SPRAY REAR BUMPER; REAR FENDER LH; REAR DOOR LH.	New	700.00
Gross Labour Cost (S\$)			1,640.00

Ah Lim Motor Company/SLX5479B/05/06/2018 16:36. Not valid without Reference section.

Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.

part by part.

before paint photos.

Gene Qicp - 82880282

07/6/18.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: