

Surveyor:

ASSIGNMENT

COB Sept 2021

From: Date:

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop m/s

of

Insured:

Policy No.

Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 12 days Res.: Yes or No

Lum Sum: 20 % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted:

Vehicle: IN / OUT

Veh No: SH 6383M

Yr Regn: Sept 2013

Type: M.Car / M.Cycle / Bus / Van / Lorry / (ax) / Prime Mover /

Truck / Trailer or

Make: Mercedes Benz E220 C.C. 2143

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 799595 T/Radio: Insured / Std / NI / NA

Eng/No: 65192431495533

C/No: WDD220022A758798

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In Order / Jammed / Leaked / Burnt or

Brake: In Order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 225/55 R16

R: ———

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Westlake

Front

Rear

R/Bal. S mm

R/Bal. S mm

L/Bal. S mm

L/Bal. S mm

D.O.A. 04/06/2018

D.O.I. 07/06/2018

Survey held at Churni AMK

Des. of Damages (Frt) (Rear) O/S / N/S / U/C / Rooftop or,

Front 7 Rear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

AXA SHB 7542 B

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation:

S + RS, SI

Photos

Others

TOTAL

Report Format :

Lump Sum / I.B.I. (\$))

Add Fee: ☐ : Site Insp (\$)☐ : Interview (\$)☐ : Tech. Invs (\$)☐ : Weekend (\$)