

Soon Hock
To Survey by ~~LA. Part~~ LKK

DATE : 4.06.2018

TEL : 6542 5119

FAX : 6542 6039


AXA

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Bumper Assy, Frt dented			\$ 1,890.50 ✓
	Bumper Reinforcement, Frt & b/t			\$ 1,158.00 ✓✓
	Bumper Bracket, Frt/LH/RH * Nm	S	95.00	\$ 190.00 ✗X
	Bumper Frame, Frt/Centre broken			\$ 198.00 ✓
	Bumper Sponge, Frt/Centre > SVC			\$ 285.00 ✗X
	Bumper Inner Clip, Frt n/c			\$ 22.00 ✓
	Head Lamp Assy (LH/RH) & mounting broken	S	2,380.00	\$ 4,760.00 ✗✓
	Head Lamp Bracket (LH/RH) rep	S	300.00	\$ 600.00 X
	Radiator Top Panel, Frt b/t			\$ 330.50 ✓
	Head Lamp Panel (LH/RH) cap b/t	S	480.00	\$ 960.00 ✗✓
	Radiator Grille broken			\$ 718.75 ✓
	Radiator Grille Adjuster Bracket & broken			\$ 685.70 ✓✓
	Bonnet Assy Replaced			\$ 2,850.60 ✓
	Bonnet Mercedes Star Logo n/c			\$ 56.70 ✓
	Bonnet Centre Lock b/t			\$ 95.00 ✓
	Bonnet Lock, Top b/t			\$ 94.00 ✓
	Bonnet Lock Lower SVC			\$ 92.00 X
	Bonnet Lock Brace Panel b/t			\$ 64.80 ✓
	Bonnet Air Inlet Grille broken			\$ 269.25 ✓
	Bonnet Stopper Spring (LH/RH) & Dam			\$ 770.00 ✓✓
	Radiator Assy & b/t			\$ 1,345.00 ✓✓
	Radiator Fan Blower Assy & start down			\$ 1,385.40 ✓✓
	Radiator Shroud & cable			\$ 1,225.60 ✓✓
	Radiator Air Baffle, Top broken			\$ 85.90 ✓
	Radiator Air Baffle, Lower nm			\$ 125.90 X
	Radiator Dowel Pin n/c			\$ 6.80 ✓
	Radiator Mounting Lower SVC			\$ 7.50 X
	Radiator Mounting Top SVC			\$ 10.85 X
	Aircon Condenser punctured			\$ 1,235.80 ✓
	Turbo Charger Air Cooler & b/t			\$ 1,053.80 ✓✓
	Turbo Charger Cooler Hose, RH nm			\$ 313.60 X
	Turbo Charger Cooler Hose, Top nm			\$ 92.50 X
	P/Steering Cooling Pipe b/t			\$ 556.80 ✓
	Front Head Rest, LH/RH rep	S	1,850.00	\$ 3,700.00 LR 300 -
	SUB TOTAL			\$ 27,236.25
	LESS 10%			\$ 2,723.63
	DISCOUNTED TOTAL			\$ 24,512.63

SH 6383M

Qty	Parts Description/ Labour	Type	Unit Price	Amount	
	Labour Charge				
	Panel Beating			\$ 1,000.00	700/-
	Spray Painting Charge			\$ 600.00	400/-
	Wiring Charge			\$ 50.00	30/-
	Towing Charges			\$ 50.00	NH
	Tuff Kote			\$ 50.00	NH
	Remove/Refix Aircon & Refill Gas			\$ 150.00	80/-
	TOTAL LABOUR			\$ 1,900.00	
	Boot Lid <i>Dented</i>			\$ 2,470.00	<i>Photo</i>
	Boot Lid Lamp (LH/RH) <i>crack</i>	\$	655.00	\$ 1,310.00	<i>photo</i>
	Boot Lid Rubber <i>deformed</i>			\$ 170.00	<i>✓</i>
	Boot Lid Moulding <i>crack</i>			\$ 110.00	<i>✓</i>
	Boot Lid Lock <i>bt</i>			\$ 275.00	<i>✓</i>
	Boot Lid Lock Lower Catch <i>bt</i>			\$ 35.00	<i>X</i>
	Boot Lid Lock Sticker <i>bt</i>			\$ 17.00	<i>✓</i>
	Boot Lid 'E220' Emblem <i>huc</i>			\$ 54.30	<i>✓</i>
	Boot Lid Star Logo <i>huc</i>			\$ 45.00	<i>✓</i>
	Boot Lid 'CDI' Emblem <i>huc</i>			\$ 54.30	<i>✓</i>
	Rear Bumper <i>distorted</i>			\$ 1,510.00	<i>✓</i>
	Rear Bumper Reinforcement <i>bt</i>			\$ 1,150.00	<i>✓</i>
	Rear Bumper Bracket Lower (LH/RH) <i>bt</i>	\$	135.00	\$ 270.00	<i>✓</i>
	Rear Bumper Bracket Top (LH/RH) <i>bt</i>	\$	125.00	\$ 250.00	<i>X</i>
	Rear Bumper Retainer Mounting (LH/RH) <i>svc</i>	\$	115.00	\$ 230.00	<i>X</i>
	Rear Bumper Towing Cover <i>distorted</i>			\$ 175.00	<i>✓</i>
	Taillamp (LH/RH) <i>crack / broken</i>	\$	1,280.00	\$ 2,560.00	<i>photo</i>
	Rear Panel End <i>Dented</i>			\$ 1,380.00	<i>photo</i>
	Rear Panel Inner Garnish <i>broken</i>			\$ 240.00	<i>✓</i>
	Rear Panel Inner Garnish Clip (10pcs) <i>huc</i>			\$ 40.00	<i>✓</i>
	Rear Exhaust Pipe Insulator <i>huc</i>			\$ 46.00	<i>X</i>
	Rear Exhaust Silencer <i>bt</i>			\$ 1,890.00	<i>photo</i>
	Rear Exhaust 'S' Shape Ring (1pc only) <i>huc</i>			\$ 16.00	<i>X</i>
	Rear Exhaust Mounting <i>huc</i>			\$ 21.85	<i>X</i>
	SUB TOTAL			\$ 14,319.45	
	LESS 10%			\$ 1,431.95	
	DISCOUNTED TOTAL			\$ 12,887.51	
	Rear Bumper Sensor <i>Dem</i>			\$ 388.00	<i>220/-</i>
	Rear Bumper Rubber Mat <i>huc</i>			\$ 50.00	<i>Nett</i>
				\$ 438.00	<i>Nett ✓</i>

SH 6383M

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Labour Charge			
	Panel Beating			\$ 1,000.00 800/-
	Spray Painting Charge			\$ 900.00 600/-
	Wiring Charge			\$ 50.00 30/-
	Tuff Kote			\$ 50.00 40/-
	Remove/Refix Reverse Sensor			\$ 120.00 40/-
	Remove/Refix Exhaust Pipe			\$ 150.00 60/-
	TOTAL LABOUR			\$ 2,270.00
	ESTIMATE TOTAL			\$ 42,008.13
	07/06/2018 @ 1500h Not Antenna L/Sun 12 Edgs.  LKlc Auto  Check Part prices			
LKlc Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				