



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 9687Y

| Qty | Description of Parts | Condition | Estimate By Workshop (\$) | Our Adjusted (\$) |
|-----|---|----------------------|---------------------------|-------------------|
| | <u>REPLACEMENT OF PARTS</u> | | | |
| 1 | REAR BUMPER (CONSISTENT) | * CHECK | 538.40 | - |
| 1 | REAR BUMPER LOWER SPOILER (CONSISTENT) | CRACKED | 525.40 | 525.40 |
| 2 | REAR BUMPER RETAINER @\$87.40 (CONSISTENT) | SERVICEABLE | 174.80 | - |
| 1 | REAR END PANEL (CONSISTENT) | TO REPAIR SEE LABOUR | 658.16 | - |
| 1 | REAR BOOT VIOS EMBLEM (CONSISTENT) | NECESSARY | 78.70 | 78.70 |
| 1 | REAR BOOT E SPORTS EMBLEM (CONSISTENT) | NECESSARY | 75.40 | 75.40 |
| | LESS 25% DISCOUNT | | -512.72 | -169.88 |
| | | | 1,538.14 | 509.62 |
| | <u>SPECIAL NETT ITEMS</u> | | | |
| 1 | SET REAR BUMPER REVERSE SENSOR (SN) (CONSISTENT) | SERVICEABLE | 200.00 | - |
| | | | 200.00 | - |
| | <u>LABOUR</u> | | | |
| | TO PUTTY & SPRAY PAINTING. | | 700.00 | 400.00 |
| | TO ANTI RUST. | NOT NECESSARY | 50.00 | - |
| | LABOUR CHARGES.INCLUSIVE OF THE REPAIR OF REAR END PANEL . | | 600.00 | 200.00 |
| | | | 1,350.00 | 600.00 |
| | GRAND TOTAL | | 3,088.14 | 1,109.62 |
| | RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION) (REPAIR COST NOT CONCLUDE) (EXCLUDE CHECK ITEMS S\$408.30 NETT) | | | 850.00 |

Report Ref No. CC4/ASM18010304/Kps3q2

KONG SENG CHEONG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.