

ASS. REC. BY:

REP:

03/1AIG18010309/G 24d3

Special Instruction:

Surveyor:

GQ

ASSIGNMENT (Office)

From (Person):

Chin Lee Ying

of

AIG

Date/Time:

5/6/18 @ 2.52pm

Estimated Cost:

Bill to:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

8KC 2713S

Insured:

SKQ 9091H

at Workshop m/s:

Apex Motoring (365)

Tel:

9169 0825

of

25 Kaki Bukit Rd 4 # 01-55 Synergy

Policy No:

2100398241

Claim No:

708837137786

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A:

02/06/2018

CA / REV / REP. / REV 24 HRS

(up)

07/06/2018 @ Morning

H.O.D. Endorsement:

Date/Time:

9.44am @ 6/6/18

Person Contacted:

Ms-Lim

Vehicle IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

356 Automotive < Insp.

8KC 2713S - CC6/AIG15002602/Kha3s2

DOA: 6/2/2015

SKQ 9091H - X

PRS
KAR.

REF: AIG

ASSIGNMENT

From

Date: 7/6/18

Estimated Cost:

OD / ☒ WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: SKC 27135

at Workshop m/s Apex Motoring @ 365 Automotive
of 25 Kaki Bkt Rd 4 # 01-55

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

Morning

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

\$36K

IDAC Accident Report: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: 2 days Res.: Yes or No

Lump Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS 'up

Vehicle: IN / OUT

Date:

Person Contacted:

Veh No: SKC27135

Yr Regn: 05 Aug 2011

Type: ☒ M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: M/T Lancer

C.C. 1499

Colour: Silver

A/C: Insured / Std / NI / NA

Sp. Reading: 105683

T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

3MYSRCY2ABU001780

Gen. Cond: ☒ Good / Fair / Poor / Burnt

Steering: ☒ In order / Jammed / Leaked / Burnt or

Brake: ☒ In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

215/50R17

R:

11

BS / ☒ DUM / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I.

07-06-18

Survey held at

w/s

4:10pm

Des. of Damages: ☒ Fr / Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

7/6/18

Submit DAR Report.

RECEIVED 05 JUL 2018

Date/Time: File Pass to?

☐

: Preli. Report

to

☐

: Final Report

Date/Time: File Return to?

to

Days Of Repair: 2

Resurvey No. of Trip:

Survey Fee:

Transportation

1) S + PS (\$) 2)

3) Photos

4) Other

TOTAL

Report Format: DAR.

Lump Sum / L.B.I. (\$) :

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech Invs (\$)

☐ Weekend (\$)



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

FWD SINGAPORE PTE LTD

Ref : CS3/FWD18010359/Gz4d3

6 TEMASEK BOULEVARD

#18-01 SUNTEC TOWER 4 SINGAPORE 038986

Date : 07-06-2018



Code : FWD

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SGJ 1532P	Veh. Inspected	SLV 5161C
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From	JOSEY LOH	Assign Date	07/06/2018

2. Vehicle Particulars & Condition

Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	06/06/2018	Inspection Date	07/06/2018
Survey held at	APEX MOTORING 25 KAKI BUKIT ROAD 4 #01-55 SYNERGY @ KB SINGAPORE 417800.		

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

**- FW: PRE-REPAIR INSPECTION - ACCIDENT INVOLVING OUR INSURED
VEHICLE SKQ9091H AND SKC2713S ON 02/06/2018**

From: Chin, Lee-Ying
To: assignments@lkkauto.com, Admin A
Cc: Fong, Andy-SY
Sent: Tuesday, 5 June, 2018 2:52:31 PM
Attachments:  SKQ9091H--PRI.TIF

Hi LKK,

Kindly assist to survey, vehicle in.

Thanks.

Best Regards
Lee Ying, Chin
AIG

Claims | AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way #08-16 Singapore 079120
Tel +(65) 6419 1947 | Fax +(65) 6835 7416
Lee-Ying.Chin@aig.com | www.aig.com.sg

IMPORTANT NOTICE:

The information in this email (and any attachments) is confidential. If you are not the intended recipient, you must not use or disseminate the information. If you have received this email in error, please immediately notify me by "Reply" command and permanently delete the original and any copies or printouts thereof. Although this email and any attachments are believed to be free of any virus or other defect that might affect any computer system into which it is received and opened, it is the responsibility of the recipient to ensure that it is virus free and no responsibility is accepted by American International Group, Inc. or its subsidiaries or affiliates either jointly or severally, for any loss or damage arising in any way from its use.



04th June 2018

AIG Asia Pacific Insurance Pte Ltd
AIG Building
78 Shenton Way #07-16
Singapore 079120
Fax : 6415 3727

Dear Sirs

ACCIDENT BETWEEN VEHICLE NO. SKC 2713 S AND VEHICEL NO. SKQ 9091 H ON 02/06/2018 @ 1700 Hrs

We are the appointed repair workshop of vehicle no. SKC 2713 S

We understand that you are the insurer of vehicle no. SKQ 9091 H

The owner of vehicle number SKC 2713 S has authorised us to carry out the repairs to his vehicle which was damaged by your insured's vehicle. The owner intends to make a claim against your insured and/or insured's authorised driver for the accident which is caused wholly and/or contributed by your insured and/or your insured's authorised driver's negligence.

We hereby give you notice of the accident and an opportunity to inspect the damaged to the vehicle prior to the commencement of the repairs.

The vehicle is now at our workshop awaiting for your inspection at the following address: 25 Kaki Bukit Road 4 #01-55 Synergy@KB Singapore 417800
Mobile No. 91690825 / peijie@expresscar.com.sg. Ms Lim

Yours faithfully



Condition (CON):
 (0) Asst (2) Dented (3) Discolored (4) Cracked (5) Cut (6) Scratched (7) Deformed
 (8) Seized (9) Buckled (10) Broken (11) Necessary (12) Missing (13) Torn
 (14) Unidentified (15) Not Working

MOTOR CAR (Frt)

ACTION (AC):

(1) Replace (✓) (2) Repair (X) (3) Check (?)
 (4) Not Consistent (NC)

Aug 2005

Vehicle No: SKC 27135

Front Portion

NAC	INC	Item	CON	AC	Qty
1001	991886	Frt Number Plate			
1002	991887	Frt Number Plate Base			
1003	991889	Frt Number Plate Garnish			
1004	991300	Frt Bumper	NEC	✓	
1005	992341	Frt Bumper Clips	NEC	✓	
1006	991325	Frt Bumper Bracket			
1007	991462	Frt Bumper Side Retainer			
1008	991433	Frt Bumper Reinforcement			
1009	991318	Frt Bumper Beam			
1010	991468	Frt Bumper Sponge			
1011	991427	Frt Bumper Protector			
1012	991420	Frt Bumper Pad			
1013	991363	Frt Bumper Grille <i>Wear and Tearing</i>	SCR	✓	
1014	991301	Frt Bumper Moulding			
1015	991407	Frt Bumper Lower Spoiler			
1016	991438	Frt Bumper Sensor			
1017	995100	Frt LH Bumper Fog Lamp Cover			
1018	991355	Frt RH Bumper Fog Lamp Cover			
1019	995079	Frt LH Bumper Fog Lamp			
1020	995080	Frt RH Bumper Fog Lamp			
1021	991793	Frt Grille	SCR	✓	
1022	991328	Frt Grille Emblem	NEC	✓	
1023	991799	Frt Grille Chrome Moulding Lower	SCR	✓	
1024	991222	Frt Apron Panel			
1025	992013	Frt Support Panel			
1026	992025	Frt Support Panel Top Garnish Cover			
1027	992416	Horn			
1028	991277	Frt Brace Panel			
1029	995153	Frt LH Headlamp Assy	SCR	✓	
1030	991821	Frt RH Headlamp Assy			
1031	995088	Frt LH Side Lamp			
1032	995089	Frt RH Side Lamp			
1033	990248	Bonnet			
1034	991328	Bonnet Emblem			
1035	990287	Bonnet Lock			
1036	990285	Bonnet Insulator			
1037	990273	Bonnet Hinge			
1038	990261	Bonnet Damper			
1039	990305	Bonnet Rubber			
1040	990252	Bonnet Cable			
1041	990311	Bonnet Stand			
1042	990119	Air Con Condenser			
1043	990122	Air Con Fan Assy			
1044	990134	Air Con Suction Pipe (Low Pressure)			
1045	990118	Air Con Suction Hose			
1046	990133	Air Con Discharge Pipe (High Pressure)			
1047	990114	Air Con Discharge Hose			
1048	990149	Air Con Liquid Pipe			
1049	995066	Air Con Receiver Drier			
1050	990111	Air Con Compressor Assy			
1051	995294	Air Con Belt			
1052	995074	Radiator			
1053	992738	Radiator Cowling			
1054	992742	Radiator Fan Assy			
1055	992745	Radiator Fan Clutch			
1056	992758	Radiator Hose Top			
1057	992757	Radiator Hose Bottom			
1058	992741	Radiator Expansion Tank			
1059	990151	Air Duct			
1060	990070	Air Cleaner Assy			
1061	990056	Air Cleaner Hose			
1062	990089	Air Cleaner Resonator			
1063	991712	Frt Exhaust Manifold			
1064	991713	Frt Exhaust Manifold Cover			
1065	991054	Frt Exhaust Manifold Sensor (Oxygen)			
1066	991714	Front Exhaust Pipe			
1067	990219	Battery			
1068	990224	Battery Cover			
1069	990223	Battery Bracket			
1070	990229	Battery Tray			

NAC	INC	Item	CON	AC	Qty
1071	992205	Fuse Box			
1072	994011	Relay Box			
1073	995053	Wiper Washer Tank			
1074	995052	Wiper Washer Tank Motor			
1075	990159	Alternator Assy			
1076	990160	Alternator Belt			
1077	992688	Power Steering Pump			
1078	992669	Power Steering Belt			
1079	994431	Power Steering Cooler Pipe			
1080	992692	Power Steering Hose			
1081	990010	ABS Pump Control Unit			
1082	990427	Brake Master Pump Assy			
1083	990403	Brake Booster Pump Assy			
1084	991005	Engine Top Cover			
1085	991011	Engine Under Cover			
1086	990946	Engine Mounting			
1087	990949	Engine Mounting Frt			
1088	990950	Engine Mounting LH			
1089	990952	Engine Mounting RH			
1090	990951	Engine Mounting Rear			
1091	992234	Gear Box Mounting			
1092	991520	Frt LH Chassis Member			
1093	991520	Frt RH Chassis Member			
1094	990728	Frt Vertical Cross Member			
1095	991863	Frt Lower Cross Member			
1096	995070	Frt LH Fender			
1097	995072	Frt LH Fender Inner Panel			
1098	995147	Frt LH Fender Lamp			
1099	995148	Frt LH Fender Protector			
1100	991740	Frt LH Fender Inner Shield			
1101	995179	Frt LH Mudflap			
1102	995170	Frt LH Wheel Rim			
1103	994025	Frt LH Rim Cover			
1104	995065	Frt LH Tyre			
1105	995071	Frt RH Fender			
1106	991739	Frt RH Fender Inner Panel			
1107	991744	Frt RH Fender Lamp			
1108	991752	Frt RH Fender Protector			
1109	991740	Frt RH Fender Inner Shield			
1110	991884	Frt RH Mudflap			
1111	992087	Frt RH Wheel Rim			
1112	994025	Frt RH Rim Cover			
1113	995065	Frt RH Tyre			
1114	992093	Frt Windscreen Glass			
1115	992117	Frt Windscreen Rubber			
1116	992108	Frt Windscreen Moulding			
1117	992098	Frt Windscreen Sealant			
1118	991019	ERP Bracket			
1119	991020	ERP Unit			
1120	992140	Frt Wiper Arm			
1121	992142	Frt Wiper Blade			
1122	995045	Wiper Panel Garnish			
1123	991126	Firewall Panel			
1124	990753	Dashboard Assy			
1125	992282	Glove Box Cover			
1126	992281	Glove Box Compartment			
1127	994483	Steering Wheel Airbag			
1128	994485	Steering Wheel Airbag Sensor			
1129	996749	Dashboard Airbag			
1130	990750	Dashboard Airbag Sensor			
1131	990029	Airbag Control Unit			
1132	990864	Frt Driver Seat			
1133	991922	Frt RH Seat Belt Assy			
1134	991899	Frt Passenger Seat			
1135	995182	Frt LH Seat Belt Assy			
1136	990247	Sticker			

No of Items: _____

Assessor: _____

original copy

...CLAIM SUBFOLDER...(Pending for Survey Report)

PRI

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 Edit Reg		05 Jun 2018 00:00 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	Lim Khim Hwa, ID: S0292883C		
Main Claimant:	-		
Vehicle Reg. No.:	SKC2713S	Date of Loss:	02/06/2018 17:00 - :59 [85 Months and 28 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 7088371377SG	Policy/Cover Note No.:	2100398241
Vehicle Reg. No. (Insured):	SKQ9091H	Policy No. (Claimant):	
		Excess:	
Repairer:	Apex Motoring () 25 Kaki Bukit Road 4, #01-55 Synergy @ KB, 417800 Kaki Bukit - Tel:		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Loh, Chee-Heng] Chee-Heng.Loh@aig.com		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by XING GUO QIANG] ... [Final Rpt due 21/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG (12/06/2018): No OI GIA Report
- AIG_SG (12/06/2018): Request To Upload TP GIA Report

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SKC2713S (7088371377SG)**
[SKQ9091H]

TP

Jun 2 2018 5:00PM

[Lim Khim Hwa]

Apex Motoring

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser	
Photos/Images			3 per page	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 10:57	General View	 Load JPG	☒
2	12/06/18 10:57	General View	 Load JPG	☒
3	12/06/18 10:57	General View	 Load JPG	☒
4	12/06/18 10:57	General View	 Load JPG	☒
5	12/06/18 10:57	General View	 Load JPG	☒
6	12/06/18 10:57	General View	 Load JPG	☒
7	12/06/18 10:57	General View	 Load JPG	☒
8	12/06/18 10:57	General View	 Load JPG	☒
9	12/06/18 10:57	General View	 Load JPG	☒
10	12/06/18 10:57	General View	 Load JPG	☒
11	12/06/18 10:57	General View	 Load JPG	☒
12	12/06/18 10:57	General View	 Load JPG	☒
13	12/06/18 10:57	General View	 Load JPG	☒
14	12/06/18 10:57	General View	 Load JPG	☒
15	12/06/18 10:57	General View	 Load JPG	☒
16	12/06/18 10:57	General View	 Load JPG	☒
17	12/06/18 10:57	General View	 Load JPG	☒
18	06/07/18 09:09	Reinspection Photo	 Load JPG	☒
19	06/07/18 09:09	Reinspection Photo	 Load JPG	☒
20	06/07/18 09:09	Reinspection Photo	 Load JPG	☒
21	06/07/18 09:09	Reinspection Photo	 Load JPG	☒
22	06/07/18 09:09	Reinspection Photo	 Load JPG	☒

Documents Checklist

DOCUMENTS CHECKLIST	Reset Save Print
There are no document checklists configured.	
Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)	
Show Remarks To: ☐ Handling Insurer Note: Remarks are private unless you show it to other parties.	

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/AIG18010309/GZ4D3S2

Date: 06/07/2018

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd.

Policy No: 2100398241

Claimant Vehicle No : SKC2713S

Insured Vehicle No : SKQ9091H

Date of Loss: 02/06/2018

Nature of Claim: TP

Claim No: 7088371377SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKC2713S

Make & Model: MITSUBISHI LANCER, 1.5 (A)

Engine No: HIDDEN

Reg. Date: 05/04/2011 (Man. Year: 2011)

Chassis No: JMYSRCY2ABU001780

Colour: Silver

Odometer: 105683 km

Engine Capacity: 1499 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Good	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:	

CONDITION OF TYRES

Front Tyre Size: 215/50ZR17

Rear Tyre Size: 215/50ZR17

Front Left Side: Dunlop 6 mm

Rear Left Side: Dunlop 6 mm

Front Right Side: Dunlop 6 mm

Rear Right Side: Dunlop 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 05/06/2018

Date Inspected: 07/06/2018 Inspected At:

Apex Motoring
25 Kaki Bukit Road 4, #01-55 Synergy @ KB
Singapore 417800

Estimated Period of Repair: 2.0 days

Adjuster: XING GUO QIANG

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRT BUMPER	Deformed	0.00 F	*- F
2	1		*FRT BUMPER GRILLE	Scratched	0.00 F	*- F
3	1		*FRT GRILLE	Scratched	0.00 F	*- F
4	1		*FRT GRILLE EMBLEM	Necessary	0.00 F	*- F
5	1		*FRT LH HEADLAMP ASSY	Scratched	0.00 F	*- F
6	1		*FRT BUMPER CLIPS	Necessary	0.00 F	*- F
Total Parts (S\$)					0.00	0.00

F=Franchise part.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >