

SMRT Accident Vehicle Repair Estimates

Section A - To be completed by claims Advisor/Duty officer at Accident Reporting Centre

Reg. No : SHB5946H
Ref. No : TAX/05/18/2143
Reg. Date : 31/01/2013
Vehicle Type : TAXI
Make : SSANGYONG
Model : RODIUS-SV270
Name of Driver : HO WEI SENG
Type of Accident : HEAD TO REAR
Date / Time of Accident : 31/05/2018 07:13:00 AM
Accident Reported Date / Time : 01/06/2018 12:00:00 AM
Surveyor is Required? : Yes
Survey by :
Vehicle is Towed Back? : Yes
Towed Back Date/Time : 04/06/2018
Replacement Vehicle issued? : No
Accident Repair Job Card No : 000024096386
Special Instruction to ARC, if any :
TOWED \$40 / SLE7496M (AIG) - LKK
Prepared Date : 01/06/2018 03:17:06 PM



Sathya Sai

5/6/2018

sebastianyeang@lkkauto.com

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

Section B - To be Completed by Service Advisor, Accident Repair Centre

Chassis No : KPTV0B1FSCP066731

Mileage

0

Work Shop :

Repair Completed Date / Time :

Summary of Repair Estimates

	Quotation from ARC	Adjusted by Surveyor, if applicable
Total Labour Charges	: 1,014.00	0.00
Total Spray Painting Charges	: 1,306.00	0.00
Total Material Charges	: 3,770.63	3,770.63
Other Charges	: 896.00	0.00
TOTAL	: 6,986.63	0.00
Lum Sum Total	: 7,000.00	0.00
No. of Repair Days	: 6.00	0.00 3 days
Prepared / Adjusted By	:	
Arc / Surveyor Sing Off Date	: 05/06/2018 10:24:25 AM	01/01/1900 12:00:00 AM



Prepared / Adjusted Date :

Remarks :

Prepared Date : 05/06/2018 08:43:17 AM

Section C - To be Completed by Admin Assistant, Accident Repair Centre, Upon Completion of Repair

Quotation No :

Invoice No :

Quotation Date :

Invoice Date :

Invoice Amount : 0.00

Prepared Date : 6/5/2018 10:24:36 AM

Section D - Details of Repair Estimates**Part 1 - Labour Works**

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPAIR REAR PORTION	1,014.00	0.00 600
Total Labour	1,014.00	0.00

Part 2 - Spray Painting & Panel Beating Related Works

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TO REPSRAY REAR BUMPER	473.00	0.00 300
TO RESPRAY BUMPER BEAM	180.00	0.00 ?
TO RESPRAY TAIL GATE	473.00	0.00 300
TO RESPRAY REAR PANEL	180.00	0.00 ?
Total Spray Painting & Panel Beating	1,306.00	0.00

Part 3 - Other Costs - Accident and Accident Repair Related Expenses

Job Scope	Quotation from ARC	Adjusted by Surveyor, if applicable
TOWING CHARGE	56.00	0.00 50
TO CHECK WIRING AND SYSTEM FUNCTION	80.00	0.00 30
TO TRANSFER REAR TAILGATE MECHANISM	120.00	0.00 60
TO REMOVE AND REFIX REAR WINDSCREEN	120.00	0.00 60
TO TEST AND REFIX REVERSE SENSOR SYSTEM	120.00	0.00 60
TO REMOVE AND INSTALL LUGGAGE COMPARTMENT TRIM TO FACILITATE REPAIR.	120.00	0.00 60
TO REMOVE AND REFIT WIRE HARDESS	120.00	0.00 50
TO REPLACE SUNDRY PARTS	100.00	0.00 20
TO WASH AND VACUUM	60.00	0.00 X
Total Other Costs	896.00	0.00

Part 4 - Spare Parts / Material Usage

Part Number	Portion	Stock No	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Recommended	Surveyor Approved	Photos Attached
7881A21000	REAR		Rear Bumper Assy ✓DMG	1	925.27	10.00	832.74	Replace	Replace	No
	COMMO N		REAR BUMPER CLIP ✓NEC	10	4.25	10.00	38.25	Replace	Replace	No
8390121100	BODY		LAMP ASSY, REFLEX REFLECTOR LH ✓SCR	1	10.52	10.00	9.47	Replace	Replace	No
8390221100	BODY		LAMP ASSY, REFLEX REFLECTOR RH ?	1	10.52	10.00	9.47	Replace	Replace	No
	REAR		REVERSE SENSOR ✓ms	1	165.10	10.00	148.59	Replace	Replace	No
7882121000	BODY		ABSORBER ENERGY RR BUMPER ?	1	111.73	10.00	100.56	Replace	Replace	No
7883021000	COMMO N		BEAM ASSY-IMPACT RR BUMPER ?	1	513.97	10.00	462.57	Replace	Replace	No
6401121000	REAR		REAR TAILGATE ASSY ✓DT	1	1,355.08	10.00	1,219.57	Replace	Replace	No
	REAR		REAR NUMBER PLATE ✓DT	1	15.00	0.00	15.00	Replace	Replace	No
	REAR		REAR NUMBER PLATE FRAME ✓DT	1	35.00	0.00	35.00	Replace	Replace	No
8379021001	REAR		LAMP ASSY-LICENSE PLATE ✓DMG	2	49.25	10.00	88.65	Replace	Replace	No
7141021000	BODY		LATCH ASSY, T/GATE ✓DMG	1	59.98	10.00	53.98	Replace	Replace	No
7141521000	BODY		STRIKER ASSY, T/GATE ✓NEC	1	9.89	10.00	8.90	Replace	Replace	No
7145021001	REAR		WEATHER STRIP T/GATE OPENING ?	1	97.67	10.00	87.90	Replace	Replace	No
6617403093	REAR		Handle assy-T/gate O/S ✓	1	14.16	10.00	12.74	Replace	Replace	No
7381021002ABU	Body		Trim assy-T/gate lwr ?	1	199.92	10.00	179.93	Replace	Replace	No
7963021002	REAR		Garnish assy-T/gate ctr ?	1	300.19	10.00	270.17	Replace	Replace	No
8837021100	BODY		ACTUATOR ASSY, DR LOCK T/GATE ?	1	74.55	10.00	67.09	Replace	Replace	No
8360121201	REAR		COMBI LAMP ASYS-RR T/GATE LH ✓CRK1	1	288.57	10.00	259.71	Replace	Replace	No
8360221201	REAR		COMBI LAMP ASYS-RR T/GATE RH ✓CRK	1	288.57	10.00	259.71	Replace	Replace	No
			EMBLEM REAR ✓NEC	1	48.94	10.00	44.05	Replace	Replace	No
	COMMO N		SMRT LOGO ✓NEC	1	7.80	0.00	7.80	Replace	Replace	No
	COMMO N		STICKER PRESTIGE ✓NEC	1	60.00	0.00	60.00	Replace	Replace	No
7934021001	BODY		RUBBERSEAL GLASS RR QTR X	2	11.04	10.00	19.87	Replace	Replace	No
	COMMO N		SEALANT W/SCREEN X	2	37.00	0.00	74.00	Replace	Replace	No
			PANEL END INNER ?	1	239.33	10.00	215.40	Replace	Replace	No
			PANEL END OUTER ?	1	105.74	10.00	95.17	Replace	Replace	No
	COMMO N	4006314	SEALANT SIKAFLEX ?	1	37.00	0.00	37.00	Replace	Replace	No
TOTAL MATERIALS								4,713.30	4,713.29	
TOTAL MATERIALS(Discounted)								3,770.63	3,770.63	

Added Spare Parts / Material Usage After Surveyor Signed off

Part Number	Portion •	Part Name	Qty	List Price (\$)	Discount (%)	Final Price (\$)	ARC Check	Surveyor Check	LT Check
TOTAL SUPPLEMENTARY MATERIALS									