

Caligha CC 6 / III180 10314, Ueas Yu

Surveyor:

MAREWS

DOI:

Type

Date / Time:

6/6/18

Registered in Merimen:

6/6/18

Pre-assign / CCU / FTE



Insured Vehicle No.:

SKW 8906H

Name of Insured:

TAN Hock Guan

Insured Tel No.:

HP:

Excess Sec II :S\$

D.O.A:

4/6/18

Is driver the owner?

(YES / NO)

Nature of Accident:

Claim No.:

m2018/2490

Policy No.:

M493797

Make / Model:

7. Altis

Place of Accident:

Slip Rd of S'gwan North Ave

If NO, Driver Name / Age:

Driver Tel No.:

(V/L: YES / NO)

OI GIA REPORT: YES / NO ; TP GIA REPORT: YES / NO

Insured Liability:

%

Final ? Yes / No

SKM 4018A



INSRS:

WSP:

Tel:

Liability:

RMKS:

Hup Motor



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:



INSRS:

WSP:

Tel:

Liability:

RMKS:

Date/ Time

13/6/18

SKM 4018A, x; SKW 8906H - x

STAGE

DATE / PIC

Non-Reporting ltr (1st):

Non-Reporting ltr (2nd):

Non-Reporting ltr (Final):

Notification ltr (if non-pickup):

Call OI:

After call ltr to OI:

Documentation Check List: Handler Typist

Notification ltr (if non-pickup)

After call ltr to OI:

Authorisation To Act:

Release Voucher:

Final Repair Bill:

Car Rental Invoice:

Towing Invoice:

LTA / GIA:

Medical Bill:

PIR:

Mandate/Reject Instruction:

LOD

Payment Breakdown Form:

Post-Repair Photos:

Others:

18.6.18

FILE PASS TO TYPYST TO PREPARE REPORT.

RECEIVED 05 JUL 2018

RECEIVED 18 JUN 2018

PRELIMINARY ADVICE Date/Time: - Sent By: -

FINALIZATION

Date/Time: 1.6.18

Confirm with: DAVID

Confirm by: MAREWS

Repair Cost:

45

S\$ 4,650

( 6

days) Reduction:

38

%

Email ☒Call ☐

FINAL SETTLEMENT

Date/Time: 2.7.18

Confirm with: DAVID

Email ☒Call ☐

Final Liability:

% 100

(Agreed / Assessed) BOLA S/N No.:

31

Repair Cost:

S\$ 4,650.00

p1 REAR END TO TP

Loss of Rental (LOR):

S\$ 900.00

( 6

days) x +180

Loss of Use (LOU):

S\$ -

(\$

x

days)

Loss of Income (LOI):

S\$ -

(\$

x

days)

LOR only ☒LOU only ☐LOR + LOU ☐LOR + LOI ☐

[Tick only one]

GIA/LTA Search

S\$ -

Medical:

S\$ -

Disbursement:

S\$ -

(e.g. Tow/ Independent)

Legal Cost:

S\$ -

Total:

S\$ 5,550.00

Global Sum S\$:

FINAL PAYMENT

Date/Time: 2.7.18

Confirm with: DAVID

Email ☒Call ☐

Payee 1:

S\$ 5,550.00

Name 1:

HUP MOTOR TRADING &amp; SERVICE

Payee 2: (Strike if N.A.)

S\$

Name 2:

Payee 3: (Strike if N.A.)

S\$

Name 3:

1) Claim status: Normal/Reject/Private Settle

2) Report Format:

TP

3) Survey fee:

+350

COPY SENT 5/7/18

(06/11/13) waf

ASS. REC. BY: Morcas

REF:

111/  
ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No:

at Workshop mls

of \_\_\_\_\_

Insured:

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_ Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Report Consistent? : Yes or No

GIA / PR Seen Consistent? : Yes or No

Est Repairs: 6 days Res: Yes or NoLum Sum: 20 % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

L7A 72871

Vehicle: IN / OUT

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Veh No: SKM 4018A Yr Regn: 2 14Type: M/Car / M/Cycle / Bus / Van / Lorry / Taxi / Private Mover /

Truck / Trailer or

Make:

Colour:

Sp. Reading

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / BurntSteering: Good / Jammed / Leaked / Burnt orBrake: Good / Jammed / Leaked / Burnt orMod: Nil / STD A/Rim or

Tyre Size:

F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front:

R/Bal:

L/Bal:

D.O.A.

Survey held at

Des. of Damages: Front / Rear / O/S / N/S / U/C / Rooftop orRear

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

7/6/18 Confirmed N/S & 4650 with Damd.RED: 2,860.40 38%

Date/Time, File Pass to?

☐

: Preli. Report

1:

☐

: Final Report

Date/Time, File Return to?

2:

Days Of Repair: \_\_\_\_\_

Resurvey No. of Trip: \_\_\_\_\_

Add Fee:

☐

: Site Insp

☐

: Interview

☐

: Tech. Invs

☐

: Weekend

Survey Fee:

Transportation:

Photos

Others

TOTAL

Report Format: \_\_\_\_\_

Lump Sum / I.B.I: (\$ \_\_\_\_\_)





## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

INDIA INTERNATIONAL INSURANCE PL

Ref : CC6/III18010314/Uea3

64 CECIL STREET  
#05-02 IOB BUILDING SINGAPORE 049711

Date : 06-06-2018



Code : III2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKW 8906H	Veh. Inspected	SKM 4018A
Policy No.		Coverage (\$)	0.00
Claim No.		Excess (\$)	0.00
Assign From		Assign Date	06/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

### 4. Description of Damages

--

### 5. General Information

Accident Date	04/06/2018	Inspection Date	07/06/2018
Survey held at	HUP MOTOR TRADING & SERVICE BLK 9004 TAMPINES ST 93 #01-120 SINGAPORE 528838		

### 5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0075 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2910/06/18

Your Ref:

MUSTAFA BIN HASSAN ALKHATIB  
BLK 396, #11-293  
TAMPINES AVE 7, S (520396)

LKK Auto Consultants hence notify

the following:

- To resurvey price after spray painting
- To survey damaged parts during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

5th June 2018

Estimate cost of repair to TOYOTA ESTIMA AERAS 2.4 (A) S/Wagon - SKM 4018 A

1 pc rear bumper	20/22	\$ 571.40	==
6 pcs rear bumper top clips	6 \$ 3.80	22.80	==
8 pcs rear bumper low clips	8 \$ 3.80	30.40	==
2 pcs rear bumper o/s & n/s side retainer (Long)	2 \$ 51.90	103.80	14C
2 pcs rear bumper o/s & n/s side retainer (Short)	2 \$ 36.40	72.80	14C
1 pc rear bumper sponge damper	1 \$ 65.70	65.70	X
2 set rear bumper reverse sensor	2 \$ 280.00	560.00	2505.2
1 pc rear bumper o/s reflector	1 \$ 52.30	52.30	X
1 pc tail gate door	2.5/20	1,490.10	==
1 pc tail gate door inner lock	1 \$ 389.20	389.20	==
1 pc tail gate door lock stricker	1 \$ 35.30	35.30	X
1 pc tail gate door 'ESTIMA' emblem	1 \$ 44.20	44.20	==
1 pc tail gate door 'AERAS' emblem	1 \$ 51.50	51.50	==
1 pc tail gate door logo emblem	1 \$ 66.70	66.70	==
1 pc tail gate door windscreen glass moulding	1 \$ 91.10	91.10	==
1 pc tail gate door windscreen glass inner seal	1 \$ 68.00	68.00	305.2
1 pc tail gate door windscreen glass sealant	1 \$ 60.00	60.00	405.2
1 pc tail gate door weatherstrip	1 \$ 325.70	325.70	==
12 pcs tail gate door inner trim board clips	12 \$ 4.20	50.40	==
1 pc rear end panel	1 \$ 625.50	625.50	==
1 pc rear end panel top garnish	1 \$ 260.50	260.50	==
6 pcs rear end panel top garnish clips	6 \$ 6.80	40.80	==
1 pc rear lower garnish	1 \$ 175.70	175.70	==
		\$ 5,253.90	
	Less 25%	\$ 1,313.48	
		\$ 3,940.42	

4324.3

3243.22

To wiring check up & transfer affected wiring system. 60.00 20

To remove & refix rear windscreen glass & necessary parts. 150.00 120

To transfer tail gate door inner trim board, hinge, shock absorber, garnish, wiper motor, arm, third brake light, inner lock & necessary parts into new door. 150.00 60

To remove & refix carpet, floor mat, garnish, floor board cover, spare tyre, carrier & necessary parts. 120.00 80

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel, rear end panel & necessary parts, to weld, renew & align above parts. 1,350.00 800

To putty & respray painting on all affected accident parts. 1,650.00 1100

To respray Tuff-Kote on all affected accident parts. 90.00 80

HUP MOTOR TRADING & SERVICE

\$ 7,510.42

=====



# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE Email : hupmotor@gmail.com

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 WEB SITE: <http://hupmotor.com.sg> Reg. No. 378091/00W

Our Ref: TP 2910/06/18 Your Ref: Date: 13rd June 2018



The Claim's Manager  
Motor Claims Dept.  
INDIA INTERNATIONAL INSURANCE PTE LTD  
64, Cecil Street, #05-00, IOB Bldg  
Singapore 049711

Dear Sirs,

RE : ACCIDENT ON 04/06/18 ALONG SLIP RD OF SERANGOON NORTH AVE 1  
INVOLVING : SKM 4018 A & YOUR INSURED : SKW 8906 H

We act for Mustaffa Bin Hassan Alkhatib., NRIC No : S1589394Z  
Who is the registered owner of Veh. No : SKW 4018 A Which was involved  
in the above accident with Veh. No : SKW 8906 H Which we understand  
is insured with you.

Your appointed surveyor had surveyed our client's damaged vehicle and  
we had repaired the vehicle.

The accident was clearly caused by your insured's negligence, I am,  
therefore, seeking compensation from you for my financial losses as  
itemised below : -

Cost of repair	\$ 4,650.00
Car rental for 6 days ( 1 day X \$ 150.00 )	900.00
LTA Search Fee & GIA-RMC Search Fee	0.00 (Insured)
Survey Fee	0.00
	<hr/>
	\$ 5,550.00
	=====

We have enclosed copies of relevant documents to support my client's  
claim, There was no receipt enclosed, as my client's did not pay us  
any single amount.

Your prompt settlement of our claim would be much appreciated.

Yours faithfully,

HUP MOTOR TRADING & SERVICE

Mr David Ang B. Y.

Encl : Final Bill, Car Rental Bill, ~~LTA Search Fee~~, Owner Authorisation  
Letter, ~~GIA Report, Survey Report & Ins. Cert.~~

Remark : Kindly acknowledge receipt.

 TO : INDIA INTERNATIONAL INSURANCE PTE LTD

## AUTHORIZATION TO ACT

I, MUSTAFA BIN HASSAN ALKHATIB ("the third party claimant") NRIC : S1589394Z

of BLK 396, #11-293, Tampines Avenue 7 S (520396) (address),

owner of SKM 4018 A (vehicle no.) hereby authorize

Hup Motor Trading & Service,

("The workshop") to act for me with respect to my claim for

repair costs and/or rental and/or loss of use ("claim") for my

Vehicle No. SKM 4018 A that was damaged pursuant to the

accident which occurred on 04/06/18 (date) along Slip Rd Of

Serangoon North Ave 1 into Ang Mo Kio Ave 3 (location)

involving Vehicle No/s SKM 8906 H

("The accident").

I further authorize the workshop to settle my above mentioned claim in a manner that they deem fit and the workshop is further authorized to receive payment further to settlement of my claim with payment cheque/s being made in favour of the workshop.

I further acknowledge that any settlement the workshop may reach on my behalf is on a without prejudice and without admission of liability basis insofar as the driver/owner/insurers of the other vehicle/s is concerned.

Dated this 13rd day of June (month) 20 18 (year)

  
S1589394Z

Owner of SKM 4018 A  
Signed by "the third party claimant"

**HUP MOTOR TRADING & SERVICE**

  
Signed by "the workshop"

Signature: \_\_\_\_\_ CKS  
Signed by appointed Surveyor

Name: LKK AUTO CONSULTANTS PTE LTD \_\_\_\_\_

NRIC: 199607198R \_\_\_\_\_

Address: 51 UBI AVE 1, PAYA UBI INDUSTRIAL PARK  
#02-25 SINGAPORE 408933 \_\_\_\_\_

Nationality: \_\_\_\_\_

Occupation: \_\_\_\_\_



# 哈 汽 車 貿 易 服 務

## HUP MOTOR TRADING & SERVICE

Blk 9004 Tampines Street 93 #01-120 Singapore 528838 Tel: 6784 0039 Fax: 6784 0076 Email: hupmotor@gmail.com Reg. No. 378091/00W

Our Ref: TF 2910/06/18 Your Ref: \_\_\_\_\_ Date: 13rd June 2018

MUSTAFA BIN HASSAN ALKHATIB  
Blk 396, Tampines Avenue 7  
#11-293, Singapore 520396

### Cost of repair to TOYOTA ESTIMA AERAS 2.4 (A) S/Wagon - SKM 4018 A

To supply rear bumper, clips, side retainer, reverse sensor, tail gate door, lock, emblems, rear windscreen glass moulding, dam rubber, sealant, weatherstrip, trim board clips, rear end panel, top garnish, clips & necessary parts.

To remove & refix rear windscreen glass, tail gate door inner trim board cover, wiper motor, hinge, garnish, shock absorber, third brake light & necessary parts, including wiring check up for affected wiring system.

Labour charge to remove & cut out damaged parts, to jack, straighten & knocking out rear floor board panel & necessary parts, to weld, renew & align above parts.

To putty & respray painting on all affected accident parts, including respray Tuff-Kote on all affected accident parts.

Lump Sum Repair : \$ 4,650.00  
\*\*\*\*\*

Dollars : Four Thousand Six Hundred And Fifty Only.

HUP MOTOR TRADING & SERVICE







# 萬豐利汽車服務

## BAN HONG LEE MOTOR SERVICES

Blk 5033, Ang Mo Kio Industrial Park 2 #01-279 (off Ang Mo Kio Ave. 3)  
Singapore 569536 Tel: 6482 5577 (3 Lines) Fax: 6482 5000  
Reg. No: 263102/00M

TOWING SERVICE: 6858 4067 (After 10.30pm)

Truck Rental  
Motor Repair  
Motor Insurance Claims  
Insurance Agent  
Dealer in Used Car  
Authorised Carpool Service Centre

总甲及罗理出租  
汽车修理  
保险赔偿  
代理保险  
买卖汽车  
维修服务中心



TOTAL  
DEFENCE  
AWARDS  
1999

SKM4018A

### 车辆出租合同 VEHICLE RENTAL AGREEMENT

Date: 7/6/18  
Owner: BAN HONG LEE MOTOR SERVICES ("the owner")  
Hirer: MUSTAFFA BIN HANAN AKKHYATIB (OWNER OF SKM4018A)  
Address: BUK 396 #11-293 TANJUNGPAGAR AVENUE 7. S (520396)  
NRIC / Co. Reg. No: S1589394Z  
Tel: \_\_\_\_\_ Fax: \_\_\_\_\_ H/P: 96197162

Owner and Hirer have agreed to enter into this Vehicle Rental Agreement for the motor vehicle described below and upon the terms and conditions contained on both sides of this document. Hirer acknowledges having read and understood all the terms and conditions and signifies acceptance upon signing.

Vehicle Reg. No: SKU4167F TOYOTA WISH 2.0		Agreement No.: 138897	
Driver's Particulars		Odometer: _____	
Name: MUSTAFFA BIN HANAN AKKHYATIB		Date & Time Out: 7/6/18 (10:00 AM)	
Address: AS ABN25		Date & Time In: 13/6/18 (10:00 AM)	
I/C No: S1589394Z	Dr/Licence No: S1589394Z	Hour @\$ _____	
Date of Issue: 11/8/03	Occupation: DIRECTOR	6 Days @\$ 150.00	\$ 900.00
Y00: 17/8/03		Wks @\$ _____	
Date of Birth: 27/8/1963	Tools: No Spare Tyre: one set	Mths @\$ _____	

#### Third Party Claim

In respect of each third party insurance claim arising from the date of hire to date of return of the vehicle (both dates inclusive). Hirer unconditionally agrees to pay Owner S\$ 5000 comprising excess payable and compensation to Owner for impact of claim on future motor insurance premiums.

#### Own Vehicle Damage

Hirer is responsible for the first \$ 4000 excess for collision/damage to first party, (i.e.) BAN HONG LEE MOTOR SERVICES (including windscreen) plus loss of earning while damaged vehicle is under repair.

#### Authorised Driver

Hirer shall pay additional excess of S\$1500 if the Authorised Driver is below the age of 25 or is above 65 years old or has less than 2 years driving experience.

#### Driver Not Cover By Insurance

General Exception: Insurance policy does not cover against any driver aged below 22 and/or above 70 years old and/or with driving experience of 1 year and below.

Deposit (Refundable): \_\_\_\_\_

Sub-Total: \$ 900.00

Balance To Pay: \$ 900.00

PETROL/DIESEL AT YOUR OWN EXPENSE  
FOR LOCAL USE ONLY

BAN HONG LEE MOTOR SERVICES

Authorised Signature

Hirer's Signature

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

Direct Settlement

## CLAIM SUBFOLDER TRACKING



































Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018 <a href="#">Edit Reg</a>		07 Jun 2018 00:00 <a href="#">Edit Adj Rpt</a>	<b>\$54,650.00</b> <a href="#">Edit Estimates</a>	<b>\$54,650.00</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b> <span style="float: right;">[Created by adjuster]</span>									
Insured:	<b>TAN HOCK GUAN</b> , ID: S2154277F								
Main Claimant:	<b>MUSTAFA BIN HASSAM ALKHATIB</b> , ID: S1589394Z								
Vehicle Reg. No.:	<b>SKM4018A</b>	Date of Loss:	04/06/2018 13:00 - :59 [51 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>TP / MC2018/2490</b>	Policy/Cover Note No.:	M493797 (Comprehensive)						
Vehicle Reg. No. (Insured):	<b>SKW8906H</b>	Policy No. (Claimant):	5064269151-04						
		Excess:							
Repairer:	<b>Hup Motor Trading &amp; Service (HQ)</b> Blk 9004 Tampines Street 93, #01-120, 528838 Tampines - Tel: 67840039/98154655								
Handling Insurer:	<b>India International Insurance Pte Ltd (HQ)</b> - Tel: 63476100 ... [Handled by <b>Lalitha Krishnan</b> - 6347 6139]								
Claimant's Insurer:	<b>NTUC Income Insurance Co-operative Ltd (HQ)</b> - Tel:								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MARCUS CHUA</b> ] ... [Final Rpt due 18/06/2018]								
<b>ASSOCIATED MAIL RECEIVED</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Compose Case Mail</a></span>									
<ul style="list-style-type: none"> <li>III_SG (21/06/2018): Alert - Adj Mandate Approved (\$5550.00) - SKM4018A - Claim Handler: Lalitha Kri...</li> <li>III_SG (07/06/2018): Alert - Adj Mandate Approved (\$0.00) - SKM4018A - Claim Handler: Lalitha Krishn...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b> <span style="float: right;"><a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a></span>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

**\*SKM4018A (MC2018/2490)**  
**[SKW8906H]**  
**TP**  
**MUSTAFA BIN HASSAM ALKHATIB**  
**Jun 4 2018 1:00PM**  
**[TAN HOCK GUAN]**  
**Hup Motor Trading & Service**

Upload Documents			Upload Photos		Compose New Letter		View		View in Browser	
Photos/Images							3 per page		<input checked="" type="checkbox"/>	
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	12/06/18 11:32	Odometer Reading		Load JPG	<input checked="" type="checkbox"/>					
2	12/06/18 11:32	Chassis Number		Load JPG	<input checked="" type="checkbox"/>					
3	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
4	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
5	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
6	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
7	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
8	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
9	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
10	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
11	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
12	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
13	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
14	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
15	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
16	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
17	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
18	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
19	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
20	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
21	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
22	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
23	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
24	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
25	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
26	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
27	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
28	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
29	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
30	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
31	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
32	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
33	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
34	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
35	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
36	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					
37	12/06/18 11:32	General View		Load JPG	<input checked="" type="checkbox"/>					

Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
38	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
39	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
40	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
41	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
42	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
43	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
44	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
45	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
46	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
47	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
48	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
49	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
50	12/06/18 11:32	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	06/06/18 16:44	TP ESTIMATE + TP GIA REPORT	Load PDF	
2	12/06/18 13:28	TP ESTIMATE - MARKED	Load PDF	
3	19/06/18 16:24	WORKSHOP INVOICE	Load PDF	
4	19/06/18 16:24	RENTAL RECEIPT	Load PDF	
5	19/06/18 16:24	LOD	Load PDF	
6	06/07/18 15:17	DISCHARGE VOUCHER	Load PDF	
7	06/07/18 15:17	AUTHORISATION TO ACT FORM	Load PDF	
No	Finalized On	India International Insurance Pte Ltd (HQ)	Thumbnail	Print
1	07/06/18 08:45	Singapore Accident Statement	Load PDF	

## Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; margin-top: 5px;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			



# LKK Auto Consultants Pte Ltd (Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC6/III18010314/JEA3Q2

Date: 06/07/2018

### REFERENCE

Handling Insurer: India International Insurance Pte Ltd

Policy No:

M493797

Claimant Vehicle No : SKM4018A

Insured Vehicle No :

SKW8906H

Date of Loss: 04/06/2018

Nature of Claim:

TP

Claim No: MC2018/2490

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SKM4018A

Make &amp; Model: TOYOTA ESTIMA, 2.4 AERAS (A)

Engine No: 2AZJ026875

Reg. Date: 26/02/2014 (Man. Year: 2013)

Chassis No: ACR500168750

Colour: Black

Odometer: 92329 km

Engine Capacity: 2362 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable):

Yes

Footbrake (Serviceable):

Yes

Handbrake (Serviceable):

Yes

Engine Modification:

No

Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 225/50 R18

Rear Tyre Size:

225/50 R18

Front Left Side: Yokohama 6 mm

Rear Left Side:

Yokohama 6 mm

Front Right Side: Yokohama 6 mm

Rear Right Side:

Yokohama 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	3,940.42	3,563.22	377.20	9.57
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,570.00	2,260.00	1,310.00	36.69
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>7,510.42</b>	<b>5,823.22</b>	<b>1,687.20</b>	<b>22.46</b>
<b>Approved Total (Overridden) (S\$)</b>		<b>4,650.00</b>		
<b>Nett Amount (S\$)</b>	<b>7,510.42</b>	<b>4,650.00</b>	<b>2,860.42</b>	<b>38.09</b>
<b>+ Car Rental (6.0 x S\$150.00/day) (S\$)</b>		900.00		
<b>Nett Liability (S\$)</b>		<b>5,550.00</b>		

### INSPECTION

Date of Assignment: 07/06/2018

Date Inspected: 07/06/2018 Inspected At:

Hup Motor Trading & Service (HQ)  
Blk 9004 Tampines Street 93, #01-120  
Singapore 528838

Estimated Period of Repair: 6.0 days

**Adjuster:** MARCUS CHUA

**Manager:** Asher Sng Rong Yi

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*



## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 19 Jun 2018)
<b>Parts:</b>	M1-MPV	TOYOTA ESTIMA 2.4 AERAS (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SKM4018A)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Dented / Deformed	571.40 FL	*571.40 FL
2	6		*REAR BUMPER TOP CLIPS	Necessary	22.80 FL	*22.80 FL
3	8		*REAR BUMPER LOW CLIPS	Necessary	30.40 FL	*30.40 FL
4	1		*REAR BUMPER O/S & N/S SIDE RETAINER (LONG)	O/S Bent	103.80 FL	*51.90 FL
5	1		*REAR BUMPER O/S & N/S SIDE RETAINER (SHORT)	O/S Bent	72.80 FL	*36.40 FL
6	1		*REAR BUMPER SPONGE DAMPER	Not Necessary	65.70 FL	*- FL
7	2		*SET REAR BUMPER REVERSE SENSOR	Shorted	420.00 FS	*250.00 FS
8	1		*REAR BUMPER O/S REFLECTER	Not Necessary	52.30 FL	*- FL
9	1		*TAIL GATE DOOR	Badly Dented	1,490.10 FL	*1,490.10 FL
10	1		*TAIL GATE DOOR INNER LOCK	Dented	389.20 FL	*389.20 FL
11	1		*TAIL GATE DOOR LOCK STRICKER	Not Necessary	35.30 FL	*- FL
12	1		*TAIL GATE DOOR ESTIMA EMBLEM	Necessary	44.20 FL	*44.20 FL
13	1		*TAIL GATE DOOR AERAS EMBLEM	Necessary	51.50 FL	*51.50 FL
14	1		*TAIL GATE DOOR LOGO EMBLEM	Necessary	66.70 FL	*66.70 FL
15	1		*TAIL GATE DOOR WINDSCREEN GLASS MOULDING	Necessary	91.10 FL	*91.10 FL
16	1		*TAIL GATE DOOR WINDSCREEN GLASS INNER SEAL	Necessary	51.00 FS	*30.00 FS
17	1		*TAIL GATE DOOR WINDSCREEN GLASS SEALANT	Necessary	45.00 FS	*40.00 FS
18	1		*TAIL GATE DOOR WEATHERSTRIP	Twisted	325.70 FL	*325.70 FL
19	12		*TAIL GATE DOOR INNER TRIM BOARD CLIPS	Necessary	50.40 FL	*50.40 FL
20	1		*REAR END PANEL	Badly Dented	625.50 FL	*625.50 FL
21	1		*REAR END PANEL TOP GARNISH	Twisted / Cracked	260.50 FL	*260.50 FL
22	6		*REAR END PANEL TOP GARNISH CLIPS	Necessary	40.80 FL	*40.80 FL
23	1		*REAR LOWER GARNISH	Deformed / Cracked	175.70 FL	*175.70 FL

F=Franchise part. S=SpcNett. L=ListItemDisc.

<b>Sub Total (\$\$)</b>	<b>5,081.90</b>	<b>4,644.30</b>
<b>- List Item Discount on L Items 25.00/25.00% (\$\$)</b>	<b>1,141.48</b>	<b>1,081.08</b>
<b>Total Parts (\$\$)</b>	<b>3,940.42</b>	<b>3,563.22</b>

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO WIRING CHECK UP & TRANSFER AFFECTED WIRING SYSTEM	New	60.00	20.00
2	TO REMOVE & REFIX REAR WINDSCREEN GLASS & NECESSARY PARTS	New	150.00	120.00
3	TO TRANSFER TAIL GATE DOOR INNER TRIM BOARD ,HINGE ,SHOCK ABSORBER ,GARNISH ,WIPER MOTOR ,ARM ,THIRD BRAKE LIGHT ,INNER LOCK & NECESSARY PARTS INTO NEW DOOR	New	150.00	60.00
4	TO REMOVE & REFIX CARPET ,FLOOR MAT ,GARNISH ,FLOOR BOARD COVER ,SPARE TYRE ,CARRIER & NECESSARY PARTS	New	120.00	80.00
5	LABOUR CHARGE TO REMOVE & CUT OUT DAMAGED PARTS ,TO JACK ,STRAIGHTEN & KNOCKING OUT REAR FLOOR BOARD PANEL ,REAR END PANEL & NECESSARY PARTS ,TO WELD ,RENEW & ALIGN ABOVE PARTS	New	1,350.00	800.00
6	TO PUTTY & RESPRAY PAINTING ON ALL AFFECTED ACCIDENT PARTS	New	1,650.00	1,100.00
7	TO RESPRAY TUFF-KOTE ON ALL AFFECTED ACCIDENT PARTS	New	90.00	80.00
<b>Gross Labour Cost (\$\$)</b>			<b>3,570.00</b>	<b>2,260.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >