

ASS. REC. BY:

REF: CS/MSG18010331/KSD3

Special Instruction:

Surveyor
Mehmen

Kenneth

ASSIGNMENT (Office)

From (Person):

Lionel Tan

of

M81G

Date/Time: 6/6/18 @ 4:35pm

Estimated Cost:

Bill to:

OD ☒ TP WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SKT 8695G

Insured:

8KB 1301J

at Workshop m/s

Cheng Hoo Motor

Tel:

6755 6142

of

Bik 1017 # 01-374/382 Yishun Ind. park A

Policy No:

A28750097AVW

Claim No:

560348

Sum Insured:

Excess:

Make of Veh:

D.O.A. 01/06/2018

(Client's Record)

CA / REV / REP. / REV 24 HRS

lup

H.O.D. Endorsement:

Date/Time:

5:43pm @ 6/6/18

Person Contacted:

june

Vehicle IN/OUT

Date/Time

Action/Instruction (→ Estimate

SKT 8695G - CC4/AIG 17013747/K263s2

D.O.A. 15/7/17

8KB 1301J - CC6/AXA 13021458/M1m3w2

D.O.A. 13/11/13

5:43pm 6/6/18

eferdon say she will call Kenneth and arrange.

08/06/18

@ 14:48 p.m. revised IA to Lionel Tan Tian Pei via merimer.

ASS. REC. BY:

REF: *MS6-1*

ASSIGNMENT

From: _____

Date: _____

Estimated Cost: _____

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: _____

at Workshop n/s _____

of _____

Insured: _____

Policy No. _____

Claims No. _____


Sum Insured: _____

Excess: _____

(Client's Record)

Make of Veh: _____

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value: _____

IDAC Accident Rpt: _____ Consistent? : Yes or No

GIA / PR Seen: _____ Consistent? : Yes or No

Est. Repairs: *10* days Res.: Yes or NoLum Sum: *20* % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: _____

Person Contacted: _____

Vehicle: IN / OUT

Veh No: *SICT 86856*Yr Regn: *07, 05*

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or _____

Make: *Honda*C.C. *1339*Colour: *M. Black*

A/C: Insured / Std / NI / NA

Sp. Reading *227369*

T/Radio: Insured / Std / NI / NA

Eng/No: _____

C/No: *JHMGD185055244850*Gen. Cond: *Good* / Fair / Poor / BurntSteering: *Inorder* / Jammed / Leaked / Burnt orBrake: *Inorder* / Jammed / Leaked / Burnt or

Mod: Nil / S/Rlm / STD A/Rlm or

Tyre Size: F: *185/55R15*

R: _____

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /
TOYO / YOKO or *Falken*

Front

Rear

R/Bal. *6* mmR/Bal. *6* mmL/Bal. *6* mmL/Bal. *6* mmD.O.A. *1/6/18*D.O.A. *7/6/18*

Survey held at _____

Des. of Damages: Frt / *Rear* / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time

Action / Instruction

*8/6 File pass to Kenneth**3/7 L1Rp 848001 Confirm Turn**07/09/18 Confirmed 215 & 4,800/- @ 10 days with Kenneth.**(\$ 1,496.66 Red - 24%)**Parts Pricas checked by Kenneth*

RECEIVED 07 SEP 2018

Date/Time, File Pass to?

07/09/18

: Prell. Report



: Final Report

1) *Spot*

Date/Time, File Return to?

Days Of Repair: *10*Resurvey No. of Trip: *1*

Survey Fee:

Transportation:

S + R.S. \$

Fees

Others

TOTAL

Add Fee:



: Site Insp (\$



: Interview (\$



: Tech Invs (\$



: Weekend (\$

Report Format :

Lump Sum / I.B.I. (\$) *4,800.00 1/5*

150
10
160

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Adj Auth'd	Status
Main	05 Jun 2018		06 Jun 2018 16:35 Assign				New Assignment Cancel Case

Main	Reference	Claim Details	Documents	Show All
------	-----------	---------------	-----------	--------------------------

CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	CHONG CHIAN HUEI, ID: S7914566A, Tel: +6597889980, Email: CEDRICCHC@GMAIL.COM			
Main Claimant:	DANIEL LONG @ LONG JITAI, ID: S7929025D			
Vehicle Reg. No.:	SKT8695G	Date of Loss:	01/06/2018 09:00 - :59 [154 Months and 10 Days From LTA Reg Date (Man Yr)]	
Claim Type:	TP / 560348	Policy/Cover Note No.:	A28750097AVW (Comprehensive) Coverage: 23/05/2018 - 22/05/2019	
Vehicle Reg. No. (Insured):	SKB1301J	Policy No. (Claimant):		
		Excess:	S\$1,500.00	
Repairer:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A, 768761 Yishun - Tel: 6755 6142			
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Lionel Tan Tian Pei - 6643 1307]			
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 07/06/2018]			
Driver/Custodian (Insured):	CHONG CHIAN HUEI (39 / Male), NRIC: S7914566A, Tel: +6597889980			
Adj Asg. Remarks:	on WP. SJE - AGREED Please appoint MR KENNETH KONG from LKK AUTO CONSULTANTS to conduct the survey . Kindly contact Ms June Phua @ 6755 6142 to arrange survey. Liability : CLEAR			

ASSOCIATED MAIL RECEIVED

[View All](#)
[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

MSIG INSURANCE (SINGAPORE) PTE LTD

Ref : CS/MSG18010331/sd3

16 RAFFLES QUAY
#24-01 HONG LEONG BLDG SINGAPORE 048581

Date : 06-06-2018



Code : MSG

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SKB 1301J	Veh. Inspected	SKT 8695G
Policy No.	A28750097AVW	Coverage (\$)	0.00
Claim No.	560348	Excess (\$)	0.00
Assign From	MERIMEN (LIONEL TAN)	Assign Date	06/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--	--

5. General Information

Accident Date	01/06/2018	Inspection Date
Survey held at	CHENG HOE MOTOR PL BLK 1019 YISHUN IND. PARK A #01-374/382 SINGAPORE 768761	

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Lionel Tan Tian Pei

Date: 08 Jun 2018

Preliminary Advice

Insured Vehicle No	: SKB1301J	Accident Date	: 01/06/2018
TP Vehicle No	: SKT8695G	Assignment Date	: 06/06/2018
Make	: HONDA JAZZ	Est. Duration of Repair	: 10 days
Date of Inspection	: 07/06/2018		
Inspection At	: Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	6,296.66
Revised Amount	:S\$	6,027.53
Check Items (Estimated)	:S\$	0.00
Total	:S\$	6,027.53

Lump Sum Repair	:S\$
-----------------	------

Total Loss Consideration

New for Old Value	:S\$
Pre-Accident Value	:S\$
COE / PARF Rebate	:S\$
Salvage Value	:S\$
Margin for Repair	:S\$

Remarks

- () The vehicle is economical/not economical for repair.
- (X) The above survey was conducted on a 'without prejudice' basis.

[> Back to OneMotoring](#)**Enquire PARF/COE Rebate for Registered Vehicle****Vehicle Owner Particulars**

Owner ID Type: Singapore NRIC
Owner ID: 9025D

Vehicle Details

Vehicle No.: SKT8695G
Vehicle to be Exported: No
Intended De-registration Date: 05 Jun 2018
Vehicle Make: HONDA
Vehicle Model: JAZZ 1.4A
Primary Colour: Black
Manufacturing Year: 2005
Engine No.: L13A52001539
Chassis No.: JHMGD18505S244850
Maximum Power Output: 60.0 kW (80 bhp)
Open Market Value: \$16,345.00
Original Registration Date: 22 Jul 2005
First Registration Date: 22 Jul 2005
Transfer Count: 4
Actual ARF Paid: \$17,980.00

Paid \$8990 - forfeited ★

Intended PARF Rebate Details

PARF Eligibility: Forfeited
PARF Eligibility Expiry Date: -
PARF Rebate Amount: \$0.00

Intended COE Rebate Details

COE Expiry Date: 21 Jul 2020
COE Category: A - Car (1600cc & below)
COE Period(Years): 5
PQP Paid: \$33,128.00
COE Rebate Amount: \$14,088.00
Total Rebate Amount: \$14,088.00

Message

Please note that the 5-year COE for this vehicle cannot be further renewed. The vehicle must be de-registered upon COE expiry or when the vehicle reaches its statutory lifespan (if applicable), whichever is earlier.

The information contained herein is correct as at 05 Jun 2018

OK

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY
#24-01 HONG LEONG BUILDING
SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 01/06/2018

TP Veh Reg No: SKB1301J

Estimate No: ES1890619/WS

Date: 06 Jun 2018

Policy No: 5078196027-01

Veh Reg No: SKT8695G

Make/Model: HONDA HONDA JAZZ
1.4A

Chassis No: JHMGD18505S244850

Engine No: L13A52001539

Reg. Date: 22/07/2005

Estimate Repair Cost to Vehicle No :SKT8695G

Description	U/Price	Quantity	List Price	Amount
			SS	SS
List Price				
1 REAR BUMPER	470.13	1 PC	470.13	✓
2 REAR BUMPER LH SIDE RETAINER	14.70	1 PC	14.70	✓
3 REAR BUMPER CLIPS	3.70	6 PC	22.20	✓
4 TAILGATE	849.20	1 PC	849.20	✓
5 TAILGATE EMBLEM 'JAZZ'	34.20	1 PC	34.20	✓
6 TAILGATE INNER LOCK	109.40	1 PCS	109.40	✓
7 TAILGATE INNER RUBBER	97.10	1 PC	97.10	501a
8 REAR WINDSCREEN MOULDING	38.90	1 PCS	38.90	✓
9 LH TAIL LAMP	222.80	1 PCS	222.80	✓
10 REAR PANEL	302.90	1 PC	302.90	✓
11 REAR PANEL INTER TOP GARNISH	63.40	1 PCS	63.40	✓
12 REAR SPARE TYRE TOP BOARD	245.90	1 PC	245.90	✓
13 REAR FENDER INNER GARNISH	168.80	2 PC	337.60	✓
14 REAR SPARE TYRE COMPARTMENT TOP SPONGE	737.40	1 PC	737.40	✓
			3,545.83	
		Less 20%	709.17	2,836.66
Special Net				
15 REAR WINDSCREEN GUM	40.00	1 PC	40.00	✓
16 REVERSE SENSOR	200.00	1 PC	200.00	✓
17 REAR SPARE TYRE PANEL TOP COAT	80.00	1 PCS	80.00	600a
			320.00	320.00
Labour				
18 TOWING	50.00	1 LA	50.00	✓
19 REMOVE AND REFIX REAR WINDSCREEN GLASS	120.00	1 LA	120.00	✓
20 REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE, REAR WIPER ASSY, TO STRAIGHTEN REAR LH CHASSISS. TO CUTTING, WELDING AND RENEW REAR SPARE TYRE COMPARTMENT, KNOCK AND REPAIR REAR FENDER AND REALIGN THE SAME	1,300.00	1 LA	1,300.00	1200

Cheng Hoe Motor Pte Ltd

Blk 1019, Yishun Industrial Park A #01-374/382, Singapore 768761
TEL: 67556142 (YIS) FAX: 67557719 (YIS) Email: chmotor@singnet.com.sg
GST:201001158E RCB NO:201001158E

M/S : MSIG INSURANCE (S) PTE LTD (SGX)

16 RAFFLES QUAY

#24-01 HONG LEONG BUILDING

SINGAPORE 048581

TEL: 68277660

FAX: 62257402

ATTN: Motor Claim Department

WS Ref: TP-MSIG

Claim Type: Third Party

Accident Date: 01/06/2018

TP Veh Reg No: SKB1301J

Estimate No: ES1890619/WS

Date: 06 Jun 2018

Policy No: 5078196027-01

Veh Reg No: SKT8695G

Make/Model: HONDA HONDA JAZZ
1.4A

Chassis No: JHMGD18505S244850

Engine No: L13A52001539

Reg. Date: 22/07/2005

Estimate Repair Cost to Vehicle No :SKT8695G

Description	U/Price	Quantity	List Price	Amount
			<u>S\$</u>	<u>S\$</u>
21 PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, TAILGATE, REAR PANEL AND REAR AFFECTED AREA	1,200.00	1 LA	1,200.00	1100
22 REMOVE AND REFIX REAR UNDER CARRAIGE INORDER TO FACILITATE ON REPAIRS	200.00	1 LA	200.00	180
23 RUSTPROOFING	90.00	1 LA	90.00	✓
24 TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	60.00	1 PC	60.00	✓
25 REMOVE AND REFIX SEAT, CARPET, TOP ROOF LINING ETC	120.00	1 LA	120.00	✓
			3,140.00	3,140.00
			Total	S\$ 6,296.66
			Add GST @ 7%	440.77
			Total Amount Payable	S\$ 6,737.43

For Cheng Hoe Motor Pte Ltd


AUTHORISED SIGNATURE

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and
is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature: _____

Date: _____

張建福 (機件) 拖車服務
TEO KIAN HOCK (CHEE CHEN) TOWING SERVICES

Mailing Address: 40 Cactus Road, Singapore 809597

Tel: 6858 4067 Fax: 6854 0407

廿四小時服務 24 HOURS SERVICE

Reg. No. 413736/00L

CASH SALE / WORK ORDER

No. 0603

Date: 5/6/18

寶號

Messrs: 清河

車號

Vehicle No: SKT 8695 G

車型

Model No:

由

From: A'Port Rd T. P

到

To: w'lands

時間 (日/夜)

Time (day/night):

其他

Others:

CASH \$: 50

CHEQUE:

經手人

Authorised by: [Signature]

收貨人

Received by: [Signature]

注意: 本公司對所托之車輛, 在進行中如有任何損失或破壞, 一概由車主自行負責。

NOTE: Vehicle is towed at owner's risk. The Company accepts no responsibility for damages or other misdemeanour to your vehicle whilst being towed.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010331/KSD3N2

Date: 07/09/2018

REFERENCE

Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd.	Policy No:	A28750097AVW
Claimant Vehicle No :	SKT8695G	Insured Vehicle No :	SKB1301J
Date of Loss:	01/06/2018	Nature of Claim:	TP
		Claim No:	560348

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SKT8695G	Engine No:	L13A52001539
Make & Model:	HONDA JAZZ, 1.4 (A)	Chassis No:	JHMGD18505S244850
Reg. Date:	22/07/2005 (Man. Year: 2005)	Odometer:	227369 km
Colour:	Metallic Black		
Engine Capacity:	1339 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	185/55R15	Rear Tyre Size:	185/55R15
Front Left Side:	Falken 6 mm	Rear Left Side:	Falken 6 mm
Front Right Side:	Falken 6 mm	Rear Right Side:	Falken 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS

	Repairer's	Adjuster's	Difference	Diff %
Parts	3,156.66	3,107.53	49.13	1.56
Miscellaneous Items	0.00	0.00	0.00	
Labour	3,140.00	2,920.00	220.00	7.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	6,296.66	6,027.53	269.13	4.27
Approved Total (Overridden) (S\$)		4,800.00		
(S\$)	6,296.66	4,800.00	1,496.66	23.77
+ GST 7.00/7.00% (S\$)	440.77	336.00	104.77	23.77
Nett Amount (S\$)	6,737.43	5,136.00	1,601.43	23.77

INSPECTION

Date of Assignment:	06/06/2018	
Date Inspected:	07/06/2018 Inspected At:	Cheng Hoe Motor Pte Ltd (Yishun) Blk 1019 #01-374/382, Yishun Industrial Park A Singapore 768761
Estimated Period of Repair:	10.0 days	

Adjuster: KENNETH KONG

Manager: Hiew May Fung

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our

knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source:	MRM-SG	Version: 1.0 (Last Synchronised: 07 Sep 2018)
Parts:	144	HONDA JAZZ 1.4 (A) (Catalogue:Merimen Singapore 1.0)
Labour:	Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SKT8695G)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*REAR BUMPER	Buckled	470.13 FL	*470.13 FL
2	1		*REAR BUMPER LH SIDE RETAINER	Distorted	14.70 FL	*14.70 FL
3	6		*REAR BUMPER CLIPS	Necessary	22.20 FL	*22.20 FL
4	1		*TAILGATE	Bent	849.20 FL	*849.20 FL
5	1		*TAILGATE EMBLEM JAZZ	Necessary	34.20 FL	*34.20 FL
6	1		*TAILGATE INNER LOCK	Dented	109.40 FL	*109.40 FL
7	1		*REAR WINDSCREEN MOULDING	Necessary	38.90 FL	*38.90 FL
8	1		*LH TAIL LAMP	Mtg Cracked	222.80 FL	*222.80 FL
9	1		*REAR PANEL	Bent	302.90 FL	*302.90 FL
10	1		*REAR PANEL INNER TOP GARNISH	Dented	63.40 FL	*63.40 FL
11	1		*REAR SPARE TYRE TOP BOARD	Deformed	245.90 FL	*245.90 FL
12	2		*REAR FENDER INNER GARNISH	Deformed/Cracked	337.60 FL	*337.60 FL
13	1		*REAR SPARE TYRE COMPARTMENT	Buckled/Bent	737.40 FL	*737.40 FL
14	1		*TAILGATE INNER RUBBER (50%)	Dented/Cut	77.68 FS	*48.55 FS
15	1		*REAR WINDSCREEN GUM	Necessary	40.00 FS	*40.00 FS
16	1		*REVERSE SENSOR	Shorted	200.00 FS	*200.00 FS
17	1		*REAR SPARE TRYE PANEL TOP COAT	Necessary	80.00 FS	*60.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (S\$)	3,846.41	3,797.28
- List Item Discount on L Items 20.00/20.00% (S\$)	689.75	689.75
Total Parts (S\$)	3,156.66	3,107.53

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOWING	New	50.00	50.00
2	REMOVE AND REFIX REAR WINDSCREEN GLASS	New	120.00	120.00
3	REMOVE AND REFIX REAR BUMPER ASSY, TAIL LAMPS, TAILGATE, REAR WIPER ASSY, TO STRAIGHTEN REAR LH CHASSISS. TO CUTTING, WELDING AND RENEW REAR SPARE TYRE COMPARTMENT, KNOCK AND REPAIR REAR FENDER AND REALIGN THE SAME	New	1,300.00	1,200.00
4	PUTTY AND RESPRAY ON REAR SPARE TYRE COMPARTMENT, REAR FENDERS, REAR BUMPER, TAILGATE, REAR PANEL AND REAR AFFECTED AREA	New	1,200.00	1,100.00
5	REMOVE AND REFIX REAR UNDER CARRIAGE IN ORDER TO FACILITATE ON REPAIRS	New	200.00	180.00
6	RUSTPROOFING	New	90.00	90.00
7	TO CONDUCT COMPUTERIZED WHEEL ALIGNMENT	New	60.00	60.00
8	REMOVE AND REFIX SEAT, CARPET, TOP ROOF LINING ETC	New	120.00	120.00
Gross Labour Cost (S\$)			3,140.00	2,920.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >