

AH LIM MOTOR COMPANY

10 ANG MO KIO INDUSTRIAL PARK 2A
#01-09 AMK AUTOPOINT Singapore 568047

Tel: 6483 1244 Fax: 6483 6170 Email: ahlimme@singnet.com.sg
GST Reg No: M9-0009639-E

SURVEYOR COPY

INSURER: FWD Singapore Pte. Ltd. (HQ)

PARTICULARS OF CLAIM

Claim Type:	OD (OWN DAMAGE)	Ref. No:	OD/FWD
Policy No:	PNPV2018-00005678	Date of Loss:	04/06/2018
Vehicle Reg. No.:	SLB6838H	Driveable?	
Driver Age/Info:	41 / MALE	Party At Fault:	UNKNOWN
TP Injury Involved?	NO	Third Party Involved?	YES
Insured/Claimant:	TAY RAY	Contact No:	+6588182937
Driver:	TAY RAY		
Make/Model:	TOYOTA WISH, 1.8 (A)	Vehicle Reg. Date:	28/04/2006
Vehicle Colour:	SILVER		
Engine No:	1ZZ2552422	Chassis No:	ZNE100303182
Odometer:	0 KM		
Paint Type:			
Total Loss?	NO		
Est. Duration of Repair (day)	15		
Description of Accident/Loss	REFER TO THE ATTACHED SKETCH PLAN BY DRIVER.		
Remarks:	CAR IS IN OUR WORKSHOP (TOW IN). KINDLY ARRANGE SURVEY TODAY.		
Present Location:	AH LIM MOTOR COMPANY (AMK)		

COST OF CLAIMS

	Amount
Parts	5,521.00
Miscellaneous Items	0.00
Labour	1,840.00
Paintwork Labour	0.00
Towing	0.00
Gross Total (S\$)	7,361.00
+ GST 7.00% (S\$)	515.27
Nett Amount (S\$)	7,876.27

This claim is handled by: EILEEN CHUA

These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Items/values not in reference catalogue are prefixed with an asterisk *.

on Parts

No. Particulars	%Disc	%Depr	Amount
*FRONT BONNET / <i>MC</i>	0.00	0.00	*170.00 F
*FRONT BONNET HINGE LH & RH / <i>BT</i>	0.00	0.00	*50.00 F
*FRONT BONNET INSULATOR / <i>EL</i>	0.00	0.00	*120.00 F
*FRONT BONNET INSULATOR CLIPS X 10 / <i>MC</i>	0.00	0.00	*15.00 F
*FRONT BONNET CHROME MOULDING / <i>EL</i>	0.00	0.00	*90.00 F
*FRONT BONNET RUBBER FRONT / <i>MC</i>	0.00	0.00	*28.00 F
*FRONT BONNET RUBBER CENTER - CHECK PRICE / <i>MC</i>	0.00	0.00	* F
*FRONT BONNET INNER LOCK / <i>BT</i>	0.00	0.00	*40.00 F
*FRONT BONNET LOCK CABLE / <i>?</i>	0.00	0.00	*35.00 F
*HEADLAMP LH & RH / <i>CMA</i>	0.00	0.00	*640.00 F
*HEADLAMP CLIPS X 4 / <i>MC</i>	0.00	0.00	*6.00 F
*FRONT GRILLE / <i>P.S</i>	0.00	0.00	*55.00 F
*FRONT GRILLE CLIPS X 6 / <i>MC</i>	0.00	0.00	*9.00 F
*FRONT GRILLE CLIPS SIDE (BIG) X 2 / <i>MC</i>	0.00	0.00	*16.00 F
*FRONT BUMPER / <i>EL</i>	0.00	0.00	*175.00 F
*FRONT BUMPER SIDE RETAINER LH & RH / <i>MC</i>	0.00	0.00	*56.00 F
*FRONT BUMPER CLIPS X 15 / <i>MC</i>	0.00	0.00	*15.00 F
*FRONT BUMPER LOWER AIR GRILLE / <i>EL</i>	0.00	0.00	*48.00 F
*FRONT BUMPER REINFORCEMENT / <i>BT</i>	0.00	0.00	*90.00 F
*FRONT BUMPER REINFORCEMENT BRACKET LH & RH / <i>?</i>	0.00	0.00	*60.00 F
*FRONT BUMPER SPONGE / <i>EL</i>	0.00	0.00	*48.00 F
*FRONT FENDER LH & RH / <i>x repair</i>	0.00	0.00	*370.00 F
*FRONT FENDER COWLING LH & RH / <i>LH - CMA, RH - x repair</i>	0.00	0.00	*130.00 F
*FRONT FENDER COWLING CLIPS X 16 / <i>MC</i>	0.00	0.00	*24.00 F
*RADIATOR SUPPORT PANEL / <i>BT</i>	0.00	0.00	*280.00 F
*RADIATOR SUPPORT PANEL TOP GARNISH / <i>M's</i>	0.00	0.00	*75.00 F
*RADIATOR SUPPORT PANEL TOP GARNISH CLIPS X 8 / <i>MC</i>	0.00	0.00	*16.00 F
*AIR CON CONDENSER / <i>BT</i>	0.00	0.00	*480.00 F
*AIR CON CONDENSER PIPE (FROM COND TO COMP) / <i>?</i>	0.00	0.00	*190.00 F
*AIR CON CONDENSER PIPE (FROM COND TO VALVE) / <i>?</i>	0.00	0.00	*240.00 F
*AIR CON CONDENSER TOP BRACKET LH & RH / <i>BT</i>	0.00	0.00	*70.00 F
*AIR CON CONDENSER BOTTOM BUSH LH & RH / <i>BT</i>	0.00	0.00	*50.00 F
*RADIATOR / <i>BT</i>	0.00	0.00	*480.00 F
*RADIATOR FAN MOTOR / <i>?</i>	0.00	0.00	*100.00 F
*RADIATOR FAN BLADE / <i>?</i>	0.00	0.00	*40.00 F
*RADIATOR FAN COWLING / <i>CMA</i>	0.00	0.00	*75.00 F
*RADIATOR TOP BRACKET LH & RH / <i>BT</i>	0.00	0.00	*56.00 F
*RADIATOR TOP BUSH LH & RH / <i>BT</i>	0.00	0.00	*30.00 F
*RADIATOR BOTTOM BUSH LH & RH / <i>BT</i>	0.00	0.00	*56.00 F
*RADIATOR TOP HOSE / <i>?</i>	0.00	0.00	*22.00 F
*RADIATOR BOTTOM HOSE / <i>?</i>	0.00	0.00	*28.00 F
*RADIATOR AIR GUIDE LH & RH / <i>EL</i>	0.00	0.00	*80.00 F

Qty	Part No.	Particulars	%Disc	%Depr	Amount
2		*HORN X 2	0.00	0.00	*80.00F
1		*BRACE PANEL / BT	0.00	0.00	*38.00F
2		*HEADLAMP SUPPORT PANEL LH & RH /	0.00	0.00	*110.00F
1		*BATTERY TRAY ?	0.00	0.00	*40.00F
1		*AIR FILTER BOX HOUSING ?	0.00	0.00	*350.00F
1		*NUMBER PLATE /	0	0.00	*35.00FS
1		*COOLANT /	0	0.00	*30.00FS
1		*BATTERY / (40%)	0	0.00	*180.00FS
Total Parts (S\$)					5,521.00

Ah Lim Motor Company/SLB6838H/07/06/2018 11:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

Items on Miscellaneous Items

There are no new miscellaneous items selected.

Items on Labour

Particulars	Lab.Type	Amount
TO DISCONNECT AND CHECK ELECTRICAL WIRING; WIRE SOCKETS AND ETC. TO REMOVE AND REINSTALL DAMAGED ELECTRICAL UNITS; TEST AND RECTIFY FOR PROPER FUNCTIONING.	New	30 40.00
TO REMOVE AND REPLACE A/C CONDENSER AND PIPES; RADIATOR AND HOSES; VACUUM A/C SYSTEM AS WELL AS REFILL A/C GAS.	New	/ 100.00
TO DISMANTLE ALL DAMAGED PARTS. TO CUT & WELD RADIATOR SUPPORT PANEL. TO KNOCK & REPAIR FRONT DOOR RH; INNER PANELS AND AFFECTED AREAS. TO REFIT LISTED PARTS BACK SAME.	New	700 800.00
TO SPRAY FRONT BONNET; FRONT BUMPER; FRONT FENDER LH & RH; RADIATOR SUPPORT PANEL	New	800 900.00
Gross Labour Cost (S\$)		1,840.00

Ah Lim Motor Company/SLB6838H/07/06/2018 11:04. Not valid without Reference section.
Generated using Merimen e-Claims IEAS

< END OF ESTIMATES >

5 Days.
part by part.
before paint photos.

Emo Q: ap - 8288 02 82

07/6/18

Excess \$600

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date: