

TPA16

Vic

SJX1034B.

Suzuki Swift.

JS AIZC21S0056/575.

Rear Number Plate.	crushed	30(SN) ✓
Rear Number Plate Lamp x02	damaged	41.8 x 2 = 83.60 ✓
Rear Bumper	Distorted	605 ✓
Rear Bumper Clips	new	30 ✓
Rear Bumper Side Holder x02	new	35.1 x 2 = 70.20 ✓
Rear Bumper Impact Bracket x02	new	47.2 x 2 = 94.40 ✓
Reverse Sensor	damaged	280(SN) - 200(SN)
Rear End Panel	Distorted	305 ✓
Rear End Panel Top Garnish.	behind	73.40 ✓
Rear End Panel Air Vent.	new	30.40 x 289.70.
Taillamp x02	LH ut	289.7 x 1 = 579.40
Tailgate	distorted	580.20 ✓
Tailgate Lock	damaged	149.50 ✓
Tailgate Weatherstripe.	ut	76.60 ✓
Tailgate Inner Trim Board	new	172.20 x
Tailgate Inner Trim Board Clips.	new	30 x
Tailgate Glass Moulding.	} new	100.20 ✓
Tailgate Glass Sealant.		60(SN) ✓

SJX1034B.

Suzuki Logo.	} <i>Mr</i>	25.30 ✓
Swift Welding.		25.90 ✓
Spore Tyre Panel	<i>Buckled</i>	589.30 ✓
Spore Tyre Insulation Pads.	<i>Mr</i>	280 (sw) 220 (sw)
Spore Tyre Panel Top Cover	<i>del</i>	220.60 ✓
Rees Exhaust Pipe.	<i>Best</i>	579.30 ✓
Rees Exhaust Manthng.	<i>Mr</i>	28 X
	<i>SW 1490</i>	
	3888.40	
	3312.64	

Panel Beating.	1500 1200
Spray Painting.	1200 800
Wiring.	50 30
To undress	150 60
To remove reverse sensor	100 50
To remove exhaust pipe.	150 50
To transfer tailgate fittings.	150 80
To remove tailgate gl(s)	180 120

Total: 6193.64
 L/S: 4.9K
 OT Pays.

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
 Signature:
 Date: