



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

SLX 7271 U

Parts	(a) Cost / List Price Items	\$	4,130.90
	Plus/Less 20%	\$	826.18
	Total of Cost / List	\$	3,304.72
	(b) Nett Price Items		
	Less		
	Total of Nett Item		
	(c) Special Nett Items	\$	250.00
Total Parts Cost		\$	3,554.72
Labour		\$	2,830.00
Total		\$	6,384.72

Not authorized
1.B.1
Runny B4 palm

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during survey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kenrick
Company : LKK
Survey conducted on : 11/6/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is ~~authorized~~ / is not authorized until further notice.

(b) Recommended Days of Repair : 03 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Pc Date: 11/6/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **SLX 7271 U**
Make & Model : **HONDA SHUTTLE**
Chassis No : **GP71104082**

Submit By : **Carmen Lim**
Year Manufacture : **2016**
Engine No. :

Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	Rear windscreen moulding <i>me</i>	1	\$20.00		✓
2	Rear windscreen sealant <i>me</i>	1	\$50.00	S.N	✓
3	Reverse sensor	1	\$200.00	S.N	?
4	Rear bumper	1	\$1,150.60		?
5	Rear bumper clip	10	\$40.00		?
6	Rear bumper side retainer LH <i>sm</i>	1	\$26.50		X
7	Rear bumper side retainer RH <i>sm</i>	1	\$26.50		X
8	Rear bumper sponge <i>sm</i>	1	\$89.50		X
9	Tail door <i>B</i>	1	\$1,193.00		✓
10	Tail door lock <i>K</i>	1	\$157.70		X
11	Tail door emblem <i>me</i>	1	\$38.00		✓
12	Wording "HYBRID" <i>me</i>	1	\$66.20		✓
13	Wording "SHUTTLE" <i>me</i>	1	\$55.00		✓
14	Tail door chrome <i>sm</i>	1	\$383.10		X
15	Tail end panel <i>K</i>	1	\$560.80		X
16	Tail end panel garnish <i>sm</i>	1	\$155.50		X
17	Tail end panel garnish clip <i>me</i>	8			✓
18	Boot weatherstrip <i>sm</i>	1	\$168.50		X
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **SLX 7271 U** Submit By : **Carmen Lim**
Make & Model : **HONDA SHUTTLE** Year of Manufacture : **2016**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$1,000.00	400
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (REAR BUMPER, TAILDOOR, END PANEL)	\$1,000.00	440
3	To check wiring	\$50.00	15
4	To tuff coat	\$150.00	30
5	To remove & refit spare tyre, spare tyre board, carpet trim to assist work load. <i>na</i>	\$150.00	X
6	To remove & refit rear windscreen.	\$120.00	120
7	To remove & refit reverse sensor	\$120.00	50
8	To transfer boot mechanism to new boot	\$120.00	60
9	To conduct water leakage tests to ensure proper air and sealing <i>na</i>	\$120.00	X

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.