

51 UBI AVE 1, #01/02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL: (065) 6256 3561 FAX: (065) 6256 4315

Your Ref: C0441359

Date: 21st June 2018

Our Ref: CS3/AXA17012835/Brbs2-1

M/s AXA Insurance Pte Ltd

8 Shenton Way #24-01 AXA Tower Singapore 068811 (The Motor Claims Department)

Attn: Wancong

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: SLC 9547Y INSURED VEHICLE: FBJ 9689C ACCIDENT DATE: 14/06/2017

We thank you for your instruction on 07/06/2018.

We acknowledge receipt of the following documents:-

- a) Automobile Inspection Report of SLC 9547Y from M/s PAR Automotive Consultancy.
- b) Final Repair Bill of SLC 9547Y TwinCar Automotive Pte Ltd.
- c) Singapore Accident Statement of Vehicles SLC 9547Y and FBJ 9689C.
- d) Colour damaged vehicle photographs of SLC 9547Y.

Pre-Repair Inspection Date: 04/07/2017 at M/s Twincar Automotive Pte Ltd, 2 Kaki Bukit Ave 2 #01-17 Kaki Bukit Autohub Singapore 417921.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

Information Recorded: -

Registration Number

: SLC 9547Y

Make & Model

: Mazda 3 1.5L

Year of Registration

: 2016

Chassis Number

: JM6BM44A8G0342724

Engine Capacity

: 1496 cc

- We recommend that the repairs of the entire damage require about <u>5 (Five)</u> working days to complete.
- We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.