



**Catherine Chong (LKK Auto)**

---

**From:** Michelle Liew on behalf of Angeline Rajoo <michelleliew@tkqp.com.sg>  
**Sent:** Thursday, 31 May, 2018 3:53 PM  
**To:** LKK (assignments@lkkauto.com)  
**Cc:** Angeline Rajoo  
**Subject:** SJE report - MC Suit 3074/2017 - LKK Ref: New Matter II TKQP Ref: TWK/AR/0322.17/ntuc/ml/PD  
**Attachments:** 20180531112315497.pdf; 20180531111904606.pdf; 20180531111812473.pdf  
**Importance:** High

**LKK Auto Consultants Pte Ltd**  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Dear Sirs

**MC SUIT NO. 3074 OF 2017 - CLAIMANT: CHING JEN HAUR**  
**ACCIDENT INVOLVING SJT 330Z & XD 7061Y ON 19.09.16 AT THE JUNCTION OF MARYMOUNT ROAD AND SIN MING AVENUE**

Please find enclosed herewith our letter of 30 May 2018 for your urgent attention.

Please retrieve the survey reports and photos at the link below:-

<https://tkqp.sharepoint.com/:b:/g/insurancelitigation/EVly7e5OpSZAiNpUJBFHk4BBBozIWsdL48U7mQdwcIXRlw?e=Eb4s4i>

We look forward to receiving your report as soon as possible.

Best Regards

Michelle Liew  
Secretary  
For and on behalf of Ms Angeline Rajoo

---

**TKQP**

**Tan Kok Quan Partnership**  
**Advocates & Solicitors, Singapore**  
1 Wallich Street #07-02 Guoco Tower Singapore 078881  
T (65) 6225 9333  
D (65) 6496 9569  
F (65) 6225 0111  
E [michelleliew@tkqp.com.sg](mailto:michelleliew@tkqp.com.sg)  
W [www.tkqp.com.sg](http://www.tkqp.com.sg)

This email is intended solely for the abovenamed addressee(s). It may contain confidential and/or legally privileged information. If this email has reached you in error, please delete it immediately and inform us of the error. Thank you for your co-operation.

Internet communications cannot be guaranteed to be secured or error-free as information can be intercepted, corrupted, lost, or it may arrive late or contain viruses. The sender therefore does not accept liability for any errors or omissions in the contents of this message which arise as a result of Internet transmission.

# TKQP

Advocates & Solicitors

Celine

Your Ref : New Matter  
Our Ref : TWK/AR/0322.17/ntuc/ml/PD

Service of Court  
Documents by Fax  
Is Not Accepted

Direct Line : 6496 9525  
Direct Fax : 6227 6116  
Writer's E-mail : angeline@tkqp.com.sg  
Secretary's DID : 6496 9569  
To Fax No: 6256 4315

Date: 5 June 2018

**BY FAX & POST**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933


Dear Sirs

**MC SUIT NO. 3074 OF 2017 - CLAIMANT: CHING JEN HAUR  
ACCIDENT INVOLVING SJT 330Z & XD 7061Y ON 19.09.16 AT THE JUNCTION OF  
MARYMOUNT ROAD AND SIN MING AVENUE**

We refer to our earlier email of 31 May 2018 and our letter dated 30 May 2018.

Please be advised that we appoint Kenneth Kong from LKK Auto Consultants Pte Ltd as parties Single Joint Expert. As such, please inform Kenneth Kong to arrange for the re-inspection.

Yours faithfully

  
**ANGELINE RAJOO**

cc **M/s Cheonghoh Law Corporation**  
Ref: LCH.my/SMTB-60699.16

**BY FAX (6337 3700) ONLY**

Page 1 of 1

This fax is for the addressee only and may contain confidential information and/or may be subject to legal privilege. If it has reached you in error, please inform us immediately by telephone, reversing the charges if necessary.

## Denise Tay (LKKAuto)

---

**From:** Vincent Seah Yong Kuan <vincent.seah@cyclecarriage.com.sg>  
**Sent:** Tuesday, 31 July 2018 10:53 AM  
**To:** Denise Tay (LKKAuto)  
**Subject:** RE: Can help me check part price

Morning Denise

Kindly refer below

Vincent Seah  
Cycle & Carriage Ind. Pte Limited  
Body Care & Repair - Pandan Loop Service Center  
188 Pandan Loop Singapore 128378  
Tel : 83320062 ( H/P ) DID: 6771 4401  
Fax.: 6872 1272

---

**From:** Denise Tay (LKKAuto) [mailto:denisetay@lkkauto.com]  
**Sent:** Tuesday, 31 July 2018 9:57 AM  
**To:** Vincent Seah Yong Kuan <vincent.seah@cyclecarriage.com.sg>  
**Subject:** Can help me check part price

Hi Vincent,

Able to help me check part price please

SJT 330Z

WDD2120362A982182

Front bumper \$1440.44  
Front headlamp L/H \$5023.11  
Front Knuckle arm L/H & RH \$1242.56- each  
Front side mirror assy L/H \$949.95  
Front axle Frame \$2372.02  
Front steering rack & pinion assy \$8267.96

Thanks a million

Best Regards,

**Denise Tay** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [denisetay@lkkauto.com](mailto:denisetay@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

## **Cheonghoh Law Corporation**

(Incorporated with limited liability) Blk 53 Chin Swee Road #03-05 Singapore 160053  
Co. Reg No.201108070G Tel: 63378700 Fax: 63373700 E-mail: mail@cheonghoh.sg

---

In reply, please quote our Reference Number

Our Ref: LCH.my/SMTB-80899.16  
Your Ref: To be advised

30 July 2018

**BY EMAIL ONLY**

LKK Auto Consultants Pte Ltd  
51 Ubi Avenue 1  
Paya Ubi Industrial Park #02-25  
Singapore 408933  
Attn: Mr Kenneth Kong

No of pages: 1

Dear Sirs

**ACCIDENT INVOLVING SJT 330 Z AND XD 7061 Y ON 19 SEPTEMBER 2016 AT/ALONG MARYMOUNT ROAD BEFORE JUNCTION WITH SIN MING AVENUE - MC/MC 3074/2017**

We refer to the above matter.

Kindly be informed that court had appointed your Kenneth Kong as the Single Joint Expert pursuant to O.108 r.5(3) (1) of the Rules of Court and resurvey was carried on 12 June 2018.

Kindly make needful preparation of the SJE report and let us have your report **before next CDR on 27 August 2018.**

Yours faithfully



Lee Cheong Hoh  
Advocates & Solicitors  
CHEONGHOH LAW CORPORATION

# TKQP

Advocates & Solicitors

Your Ref : New Matter  
Our Ref : TWK/AR/0322.17/ntuc/ml/PD  
Direct Line : 6496 9525  
Direct Fax : 6227 6116  
Writer's E-mail : angeline@tkqp.com.sg  
Secretary's DID : 6496 9569  
To Fax No: 6256 4315

Service of Court  
Documents by Fax  
Is Not Accepted

Date: 30 May 2018

**BY FAX & EMAIL**

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Dear Sirs

**MC SUIT NO. 3074 OF 2017 – CLAIMANT: CHING JEN HAUR  
ACCIDENT INVOLVING SJT 330Z & XD 7061Y ON 19.09.16 AT THE JUNCTION OF  
MARYMOUNT ROAD AND SIN MING AVENUE**

We act for NTUC Income Co-operative Limited, the insurers of motor vehicle no. motor vehicle no. XD 7061Y. M/s Cheonghoh Law Corporation act for Plaintiff's the owner of motor vehicle mo. SJT 330Z.

Both our clients have agreed to appoint your goodself as single joint expert to conduct a physical re-inspection of Plaintiff's motor vehicle no. SJT 330Z.

For purposes of the appointment, we enclose the following:-

- 1) Plaintiff's repair bill from T & B Motor Repairs Services Pte Ltd
- 2) Plaintiff's survey report and photos from Pro-option Services
- 3) Plaintiff's re-inspection report and photos from FormTeam Consultancy Pte Ltd
- 4) Plaintiff's GIA report and photos
- 5) Defendant's GIA report and photos

For purposes of re-inspection, please liaise directly with Mr Tay of T & B Motor Repairs Services Pte Ltd at telephone number 6458 0296.

Yours faithfully

  
**ANGELINE RAJOO**

Enc. (By Email Only)

cc **M/s Cheonghoh Law Corporation**  
Ref: LCH.my/SMTB-60699.16

**BY FAX (6337 3700) ONLY**

Page 1 of 1

This fax is for the addressee only and may contain confidential information and/or may be subject to legal privilege. If it has reached you in error, please inform us immediately by telephone, reversing the charges if necessary.

Tan Kok Quan Partnership

1 Wallich Street #07-02 Guoco Tower Singapore 078881 T (65) 6225 9333 F (65) 6225 0111 UEN: 53130809W

[www.tkqp.com.sg](http://www.tkqp.com.sg)

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	20/09/2016 11:15
Date Of Accident	19/09/2016 08:40
Exact Location Of Accident	MARYMOUNT ROAD / SIN MING AVE TRAFFIC JUNCTION
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SJT330Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	CHING JEN HAUR (CHEN ZHENHAO)
NRIC No	S7813492E
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-97430160
Alternative Phone No	Others-97523330
<b>Vehicle Particulars</b>	
Manufacturer	MERCEDES-BENZ
Model	E250 CGI SE AUTO
Exact Purpose for which vehicle was being used at time of accident	PRIVATE USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Private Car
<b>Insurance Company</b>	
Name of Insurance Company	MSIG Insurance (Singapore) Pte. Ltd.
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	B 27802515 QMX
Cover Note Number	
<b>Driver</b>	
Name of Driver	CHING JEN HAUR (CHEN ZHENHAO)
NRIC No	S7813492E
Date Of Birth	12/05/1978
Occupation	Indoor
Date Of Driving Pass	10/06/1998
Driving Experience	18 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-97430160
Fax Number	
Contact Number	Others-97523330
Email Address	NOEMAIL

Address BLK 411B FERNSVALE ROAD  
 #16-68  
 Postcode 792411  
 Was driver an employee of the Insured's Company No  
 If No, Relationship of the Driver with the Insured Owner  
 Vehicle Registration Number of Driver's Own Vehicle -  
 -  
 -  
 Insurance Company of Driver's Own Vehicle -  
 -  
 -

**General Information of the Accident**

Type Of Accident Unknown - VEH B CUT INTO MY LANE & HIT MY VEH  
 Weather Conditions Clear  
 Road Surface Dry

**Other Information**

Was any foreign vehicle involved in this accident? No  
 Was any body injured in the Accident? No  
 Was any other material or property damaged? Yes  
 Was there any video captured by Car Camera? Yes  
 Number of Passengers (Including Driver) 1 + 1

**Details of Police Action**

Was the accident reported to the police? No  
 If Yes, Please state which Police Station  
 Was notice of intended Prosecution given? No  
 If Yes, against whom?

**Circumstances of Accident**

REFER ATTACHED  
 Are accident photos available for attachment? Yes

**DETAILS OF OTHER VEHICLE PROPERTY 1**

Vehicle Registration Number XD7061Y  
 Vehicle Make/Model/Colour  
 Details Of Properties RIGHT SIDE REAR  
 Name of Driver LIM TONG TECK  
 NRIC/Passport Number S0216135D  
 Contact Number 97599186

Address  
 Postcode  
 Insurance Company Name  
 Nature Of Damage  
 No. Of Passenger (Including Driver)

**Details of Witness**

Name  
 Phone Number  
 Email Address

**SKETCH PLAN**

**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the Insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that :

(a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

(i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;

(ii) investigating the accident and/or my claims;

(iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;

(iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or

(v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and


(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

**Sketch Plan**



Sketch Plan #2 Pg.1

Describe Circumstances of the Accident

On 19-9-2016 at about 8.40 am. I was "very honest" and  
Turning to the right to Simmy Ave. There was a Loony XD 3061 Y  
on my left turning right at the same time and try to cut into  
my lane, hit on my vehicle SSF 3302 front left side and force  
my vehicle slide to the right and hit on the kerb.

Declaration

We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time



Driver's Signature (If driver is not the policyholder) / Date & Time



Witnessed by Reporting Centre Personnel

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore(GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	19/09/2016 16:50
Date Of Accident	19/09/2016 08:30
Exact Location Of Accident	MARYMOUNT ROAD TURNING RIGHT TO SIN MING ROAD
Country/State of Loss	Singapore

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	XD7061Y
<b>Insured/Policyholder</b>	
Name Of Registered Owner	YUAN JI ENTERPRISES PTE LTD
Co Reg No	199404390C
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	Office-98429137

### Vehicle Particulars

Manufacturer	MITSUBISHI
Model	FV51JJD4RDEA-12.9 D (M)
Exact Purpose for which vehicle was being used at time of accident	WORK USE
Are you claiming under your own insurance policy for repair to your vehicle?	No
If No, Please state action to be taken	Third Party
Vehicle Category	Goods Vehicle

### Insurance Company

Name of Insurance Company	NTUC Income Insurance Co-operative Ltd
Type Of Coverage	Comprehensive
Fleet Policy	No
Policy Number	5070783331-01
Cover Note Number	

### Driver

Name of Driver	LIM TONG TECK
NRIC No	S0216135D
Date Of Birth	25/10/1954
Occupation	Outdoor
Date Of Driving Pass	29/05/1982
Driving Experience	34 Years And 3 Months
Gender	Male
Mobile Number	(Local) +65-97599186
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address BLK 587 #09-44  
WOODLANDS DRIVE 16

Postcode 730587

Was driver an employee of the Insured's Company Yes

If No, Relationship of the Driver with the Insured

Vehicle Registration Number of Driver's Own Vehicle -  
-  
-

Insurance Company of Driver's Own Vehicle -  
-  
-

#### General Information of the Accident

Type Of Accident Unknown - REFER TO SKETCH PLAN

Weather Conditions Clear

Road Surface Dry

#### Other Information

Was any foreign vehicle involved in this accident? No

Was any body injured in the Accident? No

Was any other material or property damaged? Yes

I have been approached by unknown person(s) soliciting/offering accident claims assistance. No

Number of Passengers (Including Driver) 1

#### Details of Police Action

Was the accident reported to the police? No

If Yes, Please state which Police Station

Was notice of intended Prosecution given? No

If Yes, against whom?

#### Circumstances of Accident

REFER TO ATTACHMENT

#### Attachment(s)

Are accident photos available for attachment? Yes

Was there any video captured by Car Camera? No

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number SJT330Z

Vehicle Make/Model/Colour MERCEDES

Details Of Properties

Name of Driver CHING JEN HAUR

NRIC/Passport Number S7813492E

Contact Number

Address

Postcode

Insurance Company Name

Nature Of Damage

No. Of Passenger (Including Driver)

#### Details of Witness

Name

Phone Number

Email Address

Sketch Plan

SKETCH PLAN

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repealate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)

I understand, acknowledge, agree and consent that :

(a) My insurer , my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this (form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' law yers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :

- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.

(collectively the "Purposes")

(b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' law yers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and

(c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their law yers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.



Policyholder's Signature / Date & Time


Sketch Plan

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

Refer To Drawing Sketch

Sketch Plan #2



Sketch Plan #3

Describe Circumstances of the Accident

On 19/9/16, around 8:30 am, I was driving along Marymount Rd towards Sin Ming Rd, <sup>7 Ave</sup> while I already turning half into right to Sin Ming Rd, traffic light already turn yellow from green, suddenly a Mercedes (SJT 330 Z) drove so fast from behind, he wanted to turn right into Sin Ming Rd also, then his car hit onto my truck (XD10611) right side portion.

Declaration

I/We declare the foregoing particulars are true in every respect.



Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Centre Personnel

# PRO-OPTION SERVICES

Mailing address: Blk 189B Rivervale Drive, #04-1004, Singapore 542189

Tel: 6315 1239, Fax: 6315 3298, Mobile: 9061 0543

Ching Jen Haur (Chen Zhenhao)  
Blk 411B Rivervale Road  
#16-68  
Singapore 792411


Invoice no:	POS0422/16
Date:	12 December 2016
Report no:	422M0916.TB
Vehicle :	SJT330Z

## INVOICE

No	Item Description	Qty	Unit Price	Total Amount(\$)
01	Being charges for the inspection of the accident vehicle, transport and photographs.			1,540.00
<i>SGD(\$): One thousand five hundred and forty only</i>			<b>Payable Amount:</b>	<b>1,540.00</b>

*"Cheque should be crossed and made payable to "Pro-Option Services"*

PRO-OPTION SERVICES

  
.....  
Authorised Signature

## 8 ASSESSMENT OF DAMAGE AND COSTS

Report no: 422M0916.TB  
 Vehicle no: SJT330Z

### A SPARE PARTS

Description	Qty	Assessed Condition	Repairer's Amount	Revised Amount
Front bumper <i>1440-44</i>	1	grazed/torn/deformed	1,550.00	1,550.00
Front bumper lower side chrome L/H	1	grazed	75.00	75.00
Front bumper lower centre chrome	1	to reuse	122.00	0.00 <i>NH</i>
Front bumper lower side chrome R/H	1	to reuse	75.00	0.00 <i>NH</i>
Front lower arm ball joint LH	1	bent	142.00	142.00
Front bumper lower centre grille	1	to reuse	37.00	0.00 <i>NH</i>
Front bumper towing cover	1	to reuse	30.00	0.00 <i>NH</i>
Front bumper seal	4	necessary	12.00	12.00
Front bumper parking sensor	6	to reuse	1,530.00	0.00 <i>NH</i>
Front radar sensor bracket	1	to reuse	16.00	0.00 <i>NH</i>
Front bumper side bracket LH	1	necessary	9.00	9.00
Front bumper side bracket RH	1	necessary	9.00	9.00
Front bumper blind rivet	14	necessary	84.00	84.00
Sheet metal screw	10	necessary	60.00	60.00
Front lower arm ball joint RH	1	bent	142.00	142.00
Front bumper lower cover	1	to reuse	216.50	0.00 <i>NH</i>
Front number plate garnish	1	to reuse	163.00	0.00 <i>NH</i>
Front bumper side cover garnish L/H	1	to reuse	48.00	0.00 <i>NH</i>
Front bumper side cover grille LH	1	to reuse	38.00	0.00 <i>NH</i>
Front bumper side cover garnish moulding L/H	1	to reuse	96.00	0.00 <i>NH</i>
Front bumper side cover garnish RH	1	to reuse	48.00	0.00 <i>NH</i>
Front bumper side cover grille RH	1	to reuse	38.00	0.00 <i>NH</i>
Front radar sensor	1	to reuse	600.00	0.00 <i>NH</i>
Front bumper cable set	1	to reuse	98.00	0.00 <i>NH</i>
Front bumper lower basic mounting	1	bent/deformed	122.00	122.00
Front bumper pressure sensor	1	to reuse	100.00	0.00 <i>NH</i>
Front bumper centre basic mounting	1	bent/deformed	215.00	215.00
Front bumper impact absorber	1	deformed	290.00	290.00
Front bumper basic mounting LH	1	bent/distorted	120.00	120.00
Front bumper basic mounting RH	1	bent/distorted	120.00	120.00
Wiper washer tank	1	squashed/deformed	135.00	135.00
Front bumper reinforcement	1	bent <i>no damage photo</i>	580.00	580.00 <i>X NH</i>
Front bumper sponge	1	to reuse	120.00	0.00 <i>NH</i>
Front grille assy	1	to repair	1,850.00	0.00
Front grille logo	1	to repair	130.00	0.00
Front fender LH	1	dented/grazed/bent	992.00	992.00
Front fender inner shield LH	1	bent/deformed	158.00	158.00
Front fender side lower moulding LH	1	necessary	42.00	42.00
Front headlamp L/H	1	grazed/cracked	4,815.00	4,815.00
Front headlamp panel L/H	1	bent	241.00	241.00
Front headlamp lower panel L/H	1	bent	32.00	32.00
Front headlamp RH	1	to reuse	4,815.00	0.00 <i>NH</i>
Front grille top weatherstrip	1	to reuse	248.00	0.00 <i>NH</i>
Radiator top support panel	1	to repair	142.00	0.00
Radiator top support panel garnish	1	to reuse	130.00	0.00 <i>NH</i>
Radiator side garnish LH	1	bent/deformed	38.00	38.00
Radiator side garnish RH	1	bent/deformed	38.00	38.00
Front shock absorber LH	1	bent	820.00	820.00

Report no: 422M0916.TB  
 Vehicle no: SJT330Z

Front shock absorber RH	1 bent		820.00	820.00	
Front shock absorber mounting LH	1 bent		190.00	190.00	
Front shock absorber mounting RH	1 bent		190.00	190.00	
Front lower arm LH	1 bent		495.00	495.00	
Front struct arm L/H	1 bent		620.00	620.00	
Front knuckle arm L/H	1 bent		1,240.00	1,240.00	
Front knuckle arm screw	10 necessary		100.00	100.00	
Front steering rack & pinion assy	1 bent/notchy	NIT →	7,940.00	7,940.00	X NH
Front struct arm R/H	1 bent		620.00	620.00	
Front knuckle arm R/H	1 bent		1,240.00	1,240.00	
Front wheel bearing hub assy LH	1 rattled/noisy		680.00	680.00	
Front wheel bearing hub assy RH	1 rattled/noisy		680.00	680.00	
Front side mirror assy L/H	1 abraded/jammed	Repair	2,300.00	2,300.00	X repair
Front lower arm RH	1 bent		495.00	495.00	
Front bumper parking sensor	6 2 no grazed/shorted		1,530.00	510.00	
Front bumper parking sensor stopper	6 necessary		36.00	36.00	
Front axle frame	1 bent/distorted	NIT	2,290.00	2,290.00	X NH
Engine mounting LH	1 to reuse		315.00	0.00	NH
Engine mounting RH	1 to reuse		315.00	0.00	X NH
Rocker garnish clip	15 necessary		90.00	90.00	
Lock clip	10 necessary		50.00	50.00	
Fender rear inner garnish LH	1 to reuse		165.00	0.00	NH
Fender inner shield clip	15 necessary		90.00	90.00	
	Subtotal of the above		44,022.50	31,517.00	
	Discount 10% / 10%		4,402.25	3,151.70	
	Subtotal 1:		39,620.25	28,365.30	
Sport rim (set)	1 front body abraded		4,600.00	4,600.00	3000 IN
Front tyre 245/35-19 (Pirelli Pzero)	2 to reuse		1,000.00	0.00	NH
	Subtotal 2:		5,600.00	4,600.00	
	Total cost of parts:		45,220.25	32,965.30	

## B LABOUR

Remove and refit aircon system and vacuum, top up compressor oil & aircon gas.		~	480.00	240.00	X
Computer wheel alignment.			180.00	120.00	
Computer tyre high speed balancing.			160.00	160.00	50%
Spray anti-rust undercoat.			280.00	120.00	40%
Remove & refit radiator and top/lower hose and top up coolant, bleed air bubble from cooling system and turbo intercooler and engine oil cooler.		~	800.00	240.00	X
Check wiring, computer diagnose, online programming, reset, erase fault code.			800.00	450.00	30%
Remove & refit front bumper parking sensor.			180.00	120.00	80%

Report no: 422M0916.TB  
Vehicle no: SJT330Z

Spray paint on front bonnet, front fender left & right, front wheel arc panel left & right, front support panel and front bumper.

2,500.00 1,500.00 *800*

Remover & refit front undercarriage parts.

1,500.00 1,200.00 *360*

Labour to repair/adjust/welding/panel beating wheel arc panels, front support panel and chassis. *600*

2,200.00 1,000.00 *600*

Total cost of labour:

9,080.00 5,150.00

Total cost of repair:

54,300.25 38,115.30

**9 CONCLUSION**

Report no: 422M0916.TB  
Vehicle no: SJT330Z

The actual damage sustained by the vehicle was carefully inspected and assessed during the inspection and the assessment is appended in para. 8 of this report. The degree of damage sustained by individual part(s) is/are carefully assessed before the part(s) is/are recommended to be either replaced or repaired.

The revised or adjusted cost of repairs to restore the vehicle is **\$38,115.30.**


However, after considering the age and condition of the vehicle and the availability of good second hand parts in the market, the repairs are therefore recommended to be undertaken on a contract lump sum basis of **\$30,500.00** and the estimated number of days for the repairs would **Fourteen (14)** working days.

The above recommendations in my view are fair and reasonable for the restoration of the vehicle to its pre-accident condition.

*Note: By accepting to carry out the repairs on a contract lump sum basis, the repairer has the discretion to replace the damaged part(s) with used, reconditioned or new part(s), or to repair the part(s) to a roadworthy condition.*

We have not authorised any repairs and would like to revert the recommendations for your consideration and decision.

Yours faithfully



.....  
Liaw Leong San  
Licensed Automotive Appraiser

**ntuc**  
**income**

Your Ref: LCH.my/SMTB-60699.16  
Our Ref: MT/CA/TP/096/0915886-001/RD/AY

20 Sep 2016

CHEONGHOH LAW CORPORATION  
BLK 53 #03-05  
CHIN SWEE ROAD  
SINGAPORE 160053

BY FAX & POST

Dear Sir/Madam

**CLAIM NUMBER: MT/0915886-001**  
**ACCIDENT INVOLVING XD7061Y / SJT3302 on 19 Sept 2016**

We refer to your letter of 20 Sep 2016.

We regret we do not agree to the list of surveyors nominated by you. This being the case, we shall proceed to appoint FormTeam Consultancy Pte Ltd to be our surveyor for this matter. May we highlight to you that that pre-repair survey as per NIMA protocol includes survey of the vehicle when its damaged parts are being dismantled before repairs. Please provide a list of items that were damaged and required to be replaced or repaired to facilitate an effective survey.

In addition, please note our intention to conduct a post-repair survey before the vehicle has been returned to your client. Please co-ordinate with our surveyor immediately after the repair is completed.

If you have any queries, please contact Rajeswary Doralsamy at 6430 7934 or email us at [motor@income.com.sg](mailto:motor@income.com.sg).

Yours sincerely



Jenny Pe  
Senior Claims Manager  
Motor Insurance

# FormTeam Consultancy Pte Ltd

No.33, Ubi Ave 3  
#02-15, Vertex  
Singapore 408668

Tel : (65) 6509 1788  
Fax : (65) 6509 6221

Email: [motorsurvey@fta.com.sg](mailto:motorsurvey@fta.com.sg)

Co.Reg No: 200819280D

GST Reg No: 200819280D

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg

Your Reference: MT/CA/TP/036/0915886-001/RD/DT

Date : 08-Feb-2017

Motor Claims Department  
NTUC Income Insurance Co-Operative Limited  
73 Bras Basah Road  
#05-01 NTUC Trade Union House  
Singapore 189556

Attention : Ms Rajeswary

Dear Sir/Mdm,

## **RE-INSPECTION OF VEHICLE NO . SJT 330Z**

Pursuant to your instructions on 21 Dec 2016 , we have conducted a reinspection of the above vehicle at 20 Sin Ming Road #01-28 S 575678 on 23 Jan 2017.

We recommend a repair cost of **\$17,300.00** (see report) based on lump sum repair and the estimated duration of repairs would take **06 days** .

We also enclosed our note of charges for your consideration.

Thank you for this assignment.

Your faithfully

**FormTeam Consultancy Pte Ltd**  
Adjusters & Surveyors (Licensed Appraiser)



Axel Lee  
Automobile Appraiser

(Email : [axellee@fta.com.sg](mailto:axellee@fta.com.sg))

Encl. Re-inspection Report

# FormTeam Consultancy Pte Ltd

## AUTOMOBILE ASSESSMENT REPORT

PAGE : 1

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg  
 Your Reference : MT/CA/TP/036/0915886-001/RD/DT

Date : 08-Feb-2017

Attention : Ms Rajeswary

TO : Motor Claims Department  
 NTUC Income Insurance Co-Operative Limited  
 73 Bras Basah Road  
 #05-01 NTUC Trade Union House  
 Singapore: 189556

Dear Sir/Madam,

Vehicle No : SJT 330Z  
 Model : Mercedes Benz E250  
 Mileage : 45481 km  
 Chassis No : WDD2120362A982182  
 Workshop : M/S T & B Motor Repairs Services Pte Ltd

Pursuant to your instructions on **21 Dec 2016**, we have conducted a reinspection of the above vehicle at **20 Sin Ming Road #01-28 S'575678** on **23 Jan 2017**.

We are pleased to submit hereunder our adjustment which we trust should serve your purpose: -

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
<b><u>PARTS REPLACEMENT-LIST ITEMS</u></b>					
1	Front Bumper	Grazed/Torn/ Deformed		1,550.00	1,550.00
1	Frt Bumper Lower Side Chrome LH	Grazed		75.00	75.00
1	Frt Bumper Lower Centre Chrome	To Reuse		-	-
1	Frt Bumper Lower Side Chrome RH	To Reuse		-	-
1	Front Lower Arm Ball Joint LH	Bent		142.00	142.00
1	Front Bumper Lower Centre Grille	To Reuse		-	-
1	Front Bumper Towing Cover	To Reuse		-	-
4	Front Bumper Seal	Necessary		12.00	12.00
6	Front Bumper Parking Sensor	To Reuse		-	-
1	Front Radar Sensor Bracket	To Reuse		-	-
1	Front Bumper Side Bracket LH	Necessary		9.00	9.00
1	Front Bumper Side Bracket RH	Necessary		9.00	9.00
14	Front Bumper Blind Rivet	Necessary		84.00	84.00
10	Sheet Metal Screw	Necessary		60.00	60.00
1	Front Lower Arm Ball Joint RH	Bent		142.00	142.00
1	Front Bumper Lower Cover	To Reuse		-	-

# FormTeam Consultancy Pte Ltd

PAGE : 2

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg

Your Reference : MT/CA/TP/036/0915886-001/RD/DT

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Front Number Plate Garnish	To Reuse		-	-
1	Frt Bumper Side Cover Garnish LH	To Reuse		-	-
1	Front Bumper Side Cover Grille LH	To Reuse		-	-
1	Front Bumper Side Cover Garnish Moulding LH	To Reuse		-	-
1	Frt Bumper Side Cover Garnish RH	To Reuse		-	-
1	Front Bumper Side Cover Grille RH	To Reuse		-	-
1	Front Radar Sensor	To Reuse		-	-
1	Front Bumper Cable Set	To Reuse		-	-
1	Front Bumper Lower Basic Mounting	Bent/Deformed		122.00	122.00
1	Front Bumper Pressure Sensor	To Reuse		-	-
1	Front Bumper Centre Basic Mounting	Bent/Deformed		215.00	215.00
1	Front Bumper Impact Absorber	Deformed		290.00	290.00
1	Front Bumper Basic Mounting LH	Bent/Distorted		120.00	120.00
1	Front Bumper Basic Mounting RH	Bent/Distorted		120.00	120.00
1	Wiper Washer Tank	No Photo Show		135.00	-
1	Front Bumper Reinforcement	Damage		580.00	-
1	Front Bumper Sponge	To Reuse		-	-
1	Front Grille Assy	To Repair		-	-
1	Front Grille Logo	To Repair		-	-
1	Front Fender LH	Dented/Grazed/ Bent		992.00	992.00
1	Front Fender Inner Shield LH	Bent/Deformed		158.00	158.00
1	Frt Fender Side Lower Moulding LH	Necessary		42.00	42.00
1	Front Headlamp LH	Grazed/Cracked		4,815.00	4,815.00
1	Front Headlamp Panel LH	Bent		241.00	241.00
1	Front Headlamp Lower Panel LH	Bent		32.00	32.00
1	Front Headlamp RH	To Reuse		-	-
1	Front Grille Top Weatherstrip	To Reuse		-	-
1	Radiator Top Support Panel	To Repair		-	-
1	Radiator Top Support Panel Garnish	To Reuse		-	-
1	Radiator Side Garnish LH	Bent/Deformed		38.00	38.00
1	Radiator Side Garnish RH	Bent/Deformed		38.00	38.00

# FormTeam Consultancy Pte Ltd

PAGE : 3

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg

Your Reference : MT/CA/TP/036/0915886-001/RD/DT

QTY	DESCRIPTION	CONDITION	REMARKS	SUBMITTED	REVISED
1	Front Shock Absorber LH	Bent		820.00	820.00
1	Front Shock Absorber RH	Bent		820.00	820.00
1	Front Shock Absorber Mounting LH	Bent		190.00	190.00
1	Front Shock Absorber Mounting RH	Bent		190.00	190.00
1	Front Lower Arm LH	Bent		495.00	495.00
1	Front Struct Arm LH	Bent		620.00	620.00
1	Front Knuckle Arm LH	Bent		1,240.00	1,240.00
10	Front Knuckle Arm Screw	Necessary		100.00	100.00
1	Front Steering Rack & Pinion Assy	Not Consistent		7,940.00	-
1	Front Struct Arm RH	Bent		620.00	620.00
1	Front Knuckle Arm RH	Bent		1,240.00	1,240.00
1	Front Wheel Bearing Hub Assy LH	Rattled/Noisy		680.00	680.00
1	Front Wheel Bearing Hub Assy RH	Rattled/Noisy		680.00	680.00
1	Front Side Mirror Assy LH	No Photo Show		2,300.00	-
1	Front Lower Arm RH	Damage		495.00	495.00
6	Front Bumper Parking Sensor	Bent		510.00	510.00
6	Front Bumper Parking Sensor	2 No Grazed/		36.00	36.00
6	Front Bumper Parking Sensor	Shorted			
6	Front Bumper Parking Sensor	Necessary			
1	Front Axle Frame	Not Consistent		2,290.00	-
1	Engine Mounting LH	To Reuse		-	-
1	Engine Mounting RH	To Reuse		-	-
15	Rocker Garnish Clip	Necessary		90.00	90.00
10	Lock Clip	Necessary		50.00	50.00
1	Fender Rear Inner Garnish LH	To Reuse		-	-
15	Fender Inner Shield Clip	Necessary		90.00	90.00
	<b>List Items Sub-Total</b>			<b>31,517.00</b>	<b>18,272.00</b>
	<b>Original Less 10%</b>			<b>3,151.70</b>	<b>1,827.20</b>
	<b>Revised Less 10%</b>				
	<b>Discounted Sub-Total</b>			<b>28,365.30</b>	<b>16,444.80</b>
	<b><u>PARTS REPLACEMENT</u></b>				
	<b><u>SPECIAL NETT ITEMS</u></b>				
1	Sport Rim (Set)	Frnt Badly Abraded		4,600.00	3,000.00
2	Front Tyre 245/35-19 (Pirelli Pzero)	To Reuse		-	-
	<b>Special Nett Sub-Total</b>			<b>4,600.00</b>	<b>3,000.00</b>
	<b>Total Parts Amount</b>			<b>32,965.30</b>	<b>19,444.80</b>

# FormTeam Consultancy Pte Ltd

PAGE : 4

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg

Your Reference: MT/CA/TP/036/0915886-001/RD/DT

QTY	DESCRIPTION	SUBMITTED	REVISED
<b>LABOUR &amp; MISC</b>			
1	Remove and refit aircon system and vacuum, top up compressor oil & aircon gas.	240.00	-
2	Computer wheel alignment.	120.00	120.00
3	Computer tyre high speed balancing.	160.00	-
4	Spray anti-rust undercoat.	120.00	40.00
5	Remove & refit radiator and top/lower hose and top up coolant, bleed air bubble from cooling system and turbo intercooler and engine oil cooler.	240.00	-
6	Check wiring, computer diagnose, online programming, reset, erase fault code.	450.00	300.00
7	Remove & refit front bumper parking sensor.	120.00	80.00
8	Spray paint on front bonnet, front fender left & right, front wheel arc panel left & right, front support panel and front bumper.	1,500.00	800.00
9	Remove and refit front undercarriage parts.	1,200.00	250.00
10	Labour to repair/adjust/welding/panel beating wheel arc panels, front support panel and chassis.(including all repair parts)	1,000.00	600.00
<b>Total Labour Amount</b>		<b>5,150.00</b>	<b>2,190.00</b>
<b>Total Parts and Labour</b>		<b>38,115.30</b>	<b>21,634.80</b>

# FormTeam Consultancy Pte Ltd

PAGE : 5

Our Reference : RRN16-093690/PRS/AL/RI/AL/cg

Your Reference: MT/CA/TP/036/0915886-001/RD/DT

QTY	DESCRIPTION	SUBMITTED	REVISED
	Our Recommended Repair Cost (see remarks)	\$30,500.00	\$17,300.00


**REMARKS :**

Our recommended Lump Sum Repair Cost is **\$17,300.00** (instead of the submitted repair cost of **\$30,500.00** .In normal circumstances, repairs to the vehicle would take approximately **06 days** to complete. Please find enclosed our note of charges for your kind attention.

**Disclaimer**

This report is intended for the exclusive use of the addressee solely in relation to the loss occurrence in which the assessed vehicle is involved. No liability or responsibility whatsoever shall be held by **FormTeam Consultancy Pte Ltd** for any reliance on this report by any third party, unless with the permission of the addressee.

Yours faithfully,  
**FormTeam Consultancy Pte Ltd**



Frankie Pang  
AMSAE(AUST), AMIRTE, AMSOE,  
MASPACI, MSAAA  
Licensed Appraiser



Axel Lee  
Automobile Appraiser



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
TAN KOK QUAN PARTNERSHIP		Ref : CS/LAW18010454/Ktbs2	
1 WALLICH STREET #07-02 GUOCO TOWERSINGAPORE 078881		Date : 07-08-2018	
		Code : L021	
1. Policy Particulars :- THIRD PARTY CLAIM (RESURVEY INSPECTION)			
Insured Veh.	XD 7061Y	Veh. Inspected	SJT 330Z
Policy No.	LCH.my/SMTB-60699.16	Coverage (\$)	0.00
Claim No.	TWK/AR/0322.17/ntuc/ml/PD	Excess (\$)	0.00
Assign From	MICHELLE LIEW	Assign Date	31/05/2018
2. Vehicle Particulars & Condition			
Make & Model	MERCEDES BENZ E250 (A)	c.c	1991
Engine No.	HIDDEN	Year of Reg.	2014
Chassis No.	WDD2120362A982182	Colour	METALLIC BLACK
Odometer	69939	Steering	IN ORDER
Brakes	IN ORDER	Modification	SPORTS RIM
General	GOOD		
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre	245/35ZR19	PIRELLI	8 mm
L/H Front Tyre	245/35ZR19	PIRELLI	8 mm
R/H Rear Tyre	275/30R19	PIRELLI	9 mm
L/H Rear Tyre	275/30R19	PIRELLI	9 mm
4. Description of Damages			
THE VEHICLE COMMENCED ITS REPAIR AT THE TIME OF INSPECTION. REPAIR CONDITION SEE DETAILS.			
5. General Information			
Accident Date	19/09/2016	Inspection Date	12/06/2018
Survey held at	160 SIN MING DRIVE #08-03		
Repairer	T & B MOTOR REPAIRS SERVICES PTE LTD		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			
5b. Estimate Days of Repair			
ESTIMATED NORMAL PERIOD FOR REPAIR:		7 Working Days	



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 4

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SJT 330Z

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	REPLACED	1,550.00	1,440.44
1	FRONT BUMPER LOWER SIDE CHROME L/H	REPLACED	75.00	75.00
1	FRONT BUMPER LOWER CENTRE CHROME	NOT CHANGED	122.00	-
1	FRONT BUMPER LOWER SIDE CHROME R/H	NOT CHANGED	75.00	-
1	FRONT LOWER ARM BALL JOINT LH	REPLACED	142.00	142.00
1	FRONT BUMPER LOWER CENTRE GRILLE	NOT CHANGED	37.00	-
1	FRONT BUMPER TOWING COVER	NOT CHANGED	30.00	-
4	FRONT BUMPER SEAL	REPLACED	12.00	12.00
6	FRONT BUMPER PARKING SENSOR	NOT CHANGED	1,530.00	-
1	FRONT RADAR SENSOR BRACKET	NOT CHANGED	16.00	-
1	FRONT BUMPER SIDE BRACKET LH	REPLACED	9.00	9.00
1	FRONT BUMPER SIDE BRACKET RH	REPLACED	9.00	9.00
14	FRONT BUMPER BLIND RIVET	REPLACED	84.00	84.00
10	SHEET METAL SCREW	REPLACED	60.00	60.00
1	FRONT LOWER ARM BALL JOINT RH	REPLACED	142.00	142.00
1	FRONT BUMPER LOWER COVER	NOT CHANGED	216.50	-
1	FRONT NUMBER PLATE GARNISH	NOT CHANGED	163.00	-
1	FRONT BUMPER SIDE COVER GARNISH L/H	NOT CHANGED	48.00	-
1	FRONT BUMPER SIDE COVER GRILLE LH	NOT CHANGED	38.00	-
1	FRONT BUMPER SIDE COVER GARNISH MOULDING L/H	NOT CHANGED	96.00	-
1	FRONT BUMPER SIDE COVER GARNISH RH	NOT CHANGED	48.00	-
1	FRONT BUMPER SIDE COVER GRILLE RH	NOT CHANGED	38.00	-
1	FRONT RADAR SENSOR	NOT CHANGED	600.00	-
1	SET FRONT BUMPER CABLE	NOT CHANGED	98.00	-
1	FRON BUMPER LOWER BASIC MOUNTING	REPLACED	122.00	122.00
1	FRONT BUMPER PRESSURE SENSOR	NOT CHANGED	100.00	-
1	FRONT BUMPER CENTRE BASIC MOUNTING	REPLACED	215.00	215.00
1	FRONT BUMPER IMPACT ABSORBER	REPLACED	290.00	290.00
1	FRONT BUMPER BASIC MOUNTING LH	REPLACED	120.00	120.00
1	FRONT BUMPER BASIC MOUNTING RH	REPLACED	120.00	120.00
1	WIPER WASHER TANK	REPLACED	135.00	135.00

Report Ref No. CS/LAW18010454/Ktbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT BUMPER REINFORCEMENT	NOT CHANGED	580.00	-
1	FRONT BUMPER SPONGE	NOT CHANGED	120.00	-
1	FRONT GRILLE ASSY	REPAIRED SEE LABOUR	1,850.00	-
1	FRONT GRILLE LOGO	REPAIRED SEE LABOUR	130.00	-
1	FRONT FENDER LH	REPLACED	992.00	992.00
1	FRONT FENDER INNER SHIELD LH	REPLACED	158.00	158.00
1	FRONT FENDER SIDE LOWER MOULDING LH	REPLACED	42.00	42.00
1	FRONT HEADLAMP L/H	REPLACED	4,815.00	4,815.00
1	FRONT HEADLAMP PANEL L/H	REPLACED	241.00	241.00
1	FRONT HEADLAMP LOWER PANEL L/H	REPLACED	32.00	32.00
1	FRONT HEADLAMP RH	NOT CHANGED	4,815.00	-
1	FRONT GRILLE TOP WEATHERSTRIP	NOT CHANGED	248.00	-
1	RADIATOR TOP SUPPORT PANEL	REPAIRED SEE LABOUR	142.00	-
1	RADIATOR TOP SUPPORT PANEL GARNISH	NOT CHANGED	130.00	-
1	RADIATOR SIDE GARNISH LH	REPLACED	38.00	38.00
1	RADIATOR SIDE GARNISH RH	REPLACED	38.00	38.00
1	FRONT SHOCK ABSORBER LH	REPLACED	820.00	820.00
1	FRONT SHOCK ABSORBER RH	REPLACED	820.00	820.00
1	FRONT SHOCK ABSORBER MOUNTING LH	REPLACED	190.00	190.00
1	FRONT SHOCK ABSORBER MOUNTING RH	REPLACED	190.00	190.00
1	FRONT LOWER ARM LH	REPLACED	495.00	495.00
1	FRONT STRUCT ARM L/H	REPLACED	620.00	620.00
1	FRONT KNUCKLE ARM L/H	REPLACED	1,240.00	1,240.00
10	FRONT KNUCKLE ARM SCREW	REPLACED	100.00	100.00
1	FRONT STEERING RACK & PINION ASSY	NOT CHANGED	7,940.00	-
1	FRONT STRUCT ARM R/H	REPLACED	620.00	620.00
1	FRONT KNUCKLE ARM R/H	REPLACED	1,240.00	1,240.00
1	FRONT WHEEL BEARING HUB ASSY LH	REPLACED	680.00	680.00
1	FRONT WHEEL BEARING HUB ASSY RH	REPLACED	680.00	680.00
1	FRONT SIDE MIRROR ASSY L/H	REPAIRED SEE LABOUR	2,300.00	-

Report Ref No. CS/LAW18010454/Ktbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FRONT LOWER ARM RH	REPLACED	495.00	495.00
6	FRONT BUMPER PARKING SENSOR	REPLACED 2PCS ONLY	1,530.00	510.00
6	FRONT BUMPER PARKING SENSOR STOPPER	REPLACED	36.00	36.00
1	FRONT AXLE FRAME	NOT CHANGED	2,290.00	-
1	ENGINE MOUNTING LH	NOT CHANGED	315.00	-
1	ENGINE MOUNTING RH	NOT CHANGED	315.00	-
15	ROCKER GARNISH CLIP	REPLACED	90.00	90.00
10	LOCK CLIP	REPLACED	50.00	50.00
1	FENDER REAR INNER GARNISH LH	NOT CHANGED	165.00	-
15	FENDER INNER SHIELD CLIP	REPLACED	90.00	90.00
	LESS 10% DISCOUNT		-4,402.25	-1,829.74
			39,620.25	16,467.70
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET SPORT RIM (SN)	FRONT REPLACED	4,600.00	3,000.00
2	FRONT TYRE 245/35-19 (PIRELLI PZERO) (SN)	NOT CHANGED	1,000.00	-
			5,600.00	3,000.00
	<b><u>LABOUR</u></b>			
	REMOVE AND REFIT AIRCON SYSTEM AND VACUUM, TOP UP COMPRESSOR OIL & AIRCON GAS.	NOT NECESSARY	480.00	-
	COMPUTER WHEEL ALIGNMENT.		180.00	120.00
	COMPUTER TYRE HIGH SPEED BALANCING.		160.00	50.00
	SPRAY ANTI-RUST UNDERCOAT.		280.00	40.00
	REMOVE & REFIT RADIATOR AND TOP / LOWER HOSE AND TOP UP COOLANT, BLEED AIR BUBBLE FROM COOLING SYSTEM AND TURBO INTERCOOLER AND ENGINE OIL COOLER.	NOT NECESSARY	800.00	-
	CHECK WIRING, COMPUTER DIAGNOSE, ONLINE PROGRAMMING, RESET, ERASE FAULT CODE.		800.00	300.00
	REMOVE & REFIT FRONT BUMPER PARKING SENSOR.		180.00	80.00
	SPRAY PAINT ON FRONT BONNET, FRONT FENDER LEFT & RIGHT, FRONT WHEEL ARC PANEL LEFT & RIGHT, FRONT SUPPORT PANEL AND FRONT BUMPER.		2,500.00	800.00
	REMOVE & REFIT FRONT UNDERCARRIAGE PARTS.		1,500.00	360.00

Report Ref No. CS/LAW18010454/Ktbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 4 of 4

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LABOUR TO REPAIR / ADJUST / WELDING / PANEL BEATING WHEEL ARC PANELS, FRONT SUPPORT PANEL AND CHASSIS. INCLUSIVE OF THE REPAIR OF FRONT GRILLE ASSY, FRONT GRILLE LOGO, RADIATOR TOP SUPPORT PANEL AND FRONT SIDE MIRROR ASSY L/H.		2,200.00	600.00
			9,080.00	2,350.00
<b>GRAND TOTAL</b>			<b>54,300.25</b>	<b>21,817.70</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>17,450.00</b>

Report Ref No. CS/LAW18010454/Ktbs2

KONG SENG CHEONG

Licensed Appraiser

K.K.LAU CPT(RET)

BEng(Hons), B.Bus, MBA, PEng, PE,  
MInstAEA, MASME, MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.