

23/09/2003

A/C REC. BY:

REF:

CS/MSG18010456/Tird30

Special instruction:

Surveyor:

Taufik

ASSIGNMENT (Office)

From (Person):

Kwok Woon Choo

of

MSG

Date/Time:

8/6/18 @ 10:50am

Estimated Cost:

Bill to:

☒

OD/TP/WS/TP RES/OD RES/EVA/INV/MV7CS

To Inspect Vehicle No:

SLQ 1334Z

Insured:

at Workshop m/s

Performance Motor

Tel:

9116 5600

of

303 Alexandra Road

Policy No:

28985545

Claim No:

Sum Insured:

Excess:

\$1,000.00

Make of Veh:

D.O.A.

06/06/18

(Client's Record)

CA / ☒

REV

/ REP. / REV 24 HRS

H.O.D. Endorsement:

Date/Time:

11:07am @ 8/6/18

Person Contacted:

Kevin

Vehicle:

☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SLQ 1334Z - X
11/6/18	Event thru mainmen
13/6/18	Authorise repair; inform Kevin to proceed for repair
13/11/18	Mandate for final figure + supp
13/11/18	Confirm with Caroline & 12.11.18 @ 6 days (Ref: 265640 171.)

REF: mslg

ASSIGNMENT

From: Tan Kah Date: 2017 June

Estimated Cost: OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To inspect Vehicle No: 3LQ1534Z Yr Regn: 2017 June

at Workshop n/s

at

Insured

Policy No

Claims No

Sum Insured \$1000 Excess

(Client's Record)

Make of Veh

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

Bal. or Market Value: 9119K

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repair: days Res. Yes or No

Lum Sum: \$ 3 Val. Yes or No

CA / REV / REP. / 24 HRS

Date: Person Contacted: Vehicle: IN / OUT

Date / Time Action / Instruction

Type: M Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: BMW 216D

Colour: Blue A/C Insured / Std / NI / NA

Sp Reading: 14305 T/Radio: Insured / Std / NI / NA

Eng/No

C/No: WBA2E520205446378

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Mod: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/55R17

R: ~

BS / DUN / EXNOVA / SY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front: 6 mm Rear: 6 mm

R/Bal: 6 mm L/Bal: 6 mm

D.O.A: 8/6/18 01630

Survey held at: PML

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

Frt N/S

The UIC / Chassis frame / Body Structure affected due to collision

RECEIVED 14 NOV 2018

14/11/2018

Days Of Repair: 6

Resurvey No. of Trip: 1

Survey Fee: 200

Dispendary: 10

Report Format: OD

Lump Sum / LB: 13,011.65

Add Fee: ☐ Site Insp: \$ ☐ Interview: \$ ☐ Tech Insp: \$ ☐ Drawing: \$

Preli. Report: ☐ Final Report: ☒

File Pass: 14/11/2018

File Return: 14/11/2018



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
MSIG INSURANCE (SINGAPORE) PTE LTD			Ref : CS/MSG18010456/T1rd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581			Date : 08-06-2018	
			Code : MSG	
<b>1. Policy Particulars :- OWN DAMAGE</b>				
Insured Veh.		Veh. Inspected		SLQ 1334Z
Policy No. 28988545		Coverage (\$)		0.00
Claim No.		Excess (\$)		1,000.00
Assign From MERIMEN ( KWOK WOON CHOO)		Assign Date		08/06/2018
<b>2. Vehicle Particulars &amp; Condition</b>				
Make & Model		c.c		0
Engine No. HIDDEN		Year of Reg.		
Chassis No.		Colour		
Odometer -		Steering		
Brakes		Modification		
General				
<b>3. Conditions of Tyres</b>				
		Size	Make	Balance
	R/H Front Tyre			mm
	L/H Front Tyre			mm
	R/H Rear Tyre			mm
	L/H Rear Tyre			mm
<b>4. Description of Damages</b>				
<b>5. General Information</b>				
Accident Date 06/06/2018		Inspection Date 08/06/2018		
Survey held at		PERFORMANCE MOTORS LTD 303 ALEXANDRA ROAD SINGAPORE 159941		
<b>5a. Remarks</b>				
A)THE MARKET VALUE IS S\$------(EST. AVERAGE) B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE AUTHORISED REPAIRS.				

## ...CLAIM SUBFOLDER...(New Assignment)

### CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018		08 Jun 2018 10:50 <a href="#">Assign</a>				<b>New Assignment</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	<a href="#">Show All</a>
------	-----------	---------------	-----------	--------------------------

#### CLAIM SUBFOLDER DETAILS [Created by insurer]

Insured:	SIME DARBY SERVICES PTE LTD, Co. Reg. No.: S197501065W		
Vehicle Reg. No.:	SLQ1334Z	Date of Loss:	06/06/2018 19:00 - :59 [17 Months and 5 Days From LTA Reg Date (Man Yr)]
Claim Type:	OD	Policy/Cover Note No.:	28986545 (Comprehensive) Coverage: 28/06/2017 - 27/06/2018
		Excess:	S\$1,000.00
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Kwok Woon Choo - 6643 1330]		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/06/2018]		
Driver/Custodian:	GOH HONG MING DESMOND (32 / Male), NRIC: S8533799H, Tel: +6596639961		
Adj Asg. Remarks:	SURVEY TODAY AND REVERT - WORKSHOP REQUEST TO SURVEY BY TODAY		

#### ASSOCIATED MAIL RECEIVED [View All](#) [Compose Case Mail](#)

There are no mail for this case.

#### ALL ASSOCIATED TASKS [View All](#) [Search Tasks](#) [Create New Task](#) [Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

## Woon Choo Kwok

---

**From:** Koh Lay Hoon  
**Sent:** Friday, June 08, 2018 9:29 AM  
**To:** Woon Choo Kwok  
**Subject:** FW: OD Claim : SLQ1334Z D.O.A : 06/06/18  
**Attachments:** SKM\_558e18060808580.pdf

---

**From:** Kevin Leong Wai Kit [mailto:kevin.leong.waikit@sime-darby.com.sg]  
**Sent:** Friday, June 08, 2018 9:17 AM  
**To:** Claims <claims@sg.msig-asia.com>  
**Subject:** OD Claim : SLQ1334Z D.O.A : 06/06/18

Dear All,

Kindly refer to above attach for OD Claim : SLQ1334Z  
Please arrange for survey by today.  
Car is in workshop.

Thank you

Regards,

**Kevin Leong**

Customer Service Advisor | Body and Paint  
Performance Motors Limited  
303 Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Hp (+65) 9116 5600 | Fax (+65) 6479 4601  
[Kevin.leong.waikit@sime-darby.com.sg](mailto:Kevin.leong.waikit@sime-darby.com.sg)



"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."

---

#### CONFIDENTIALITY NOTICE

This e-mail (including any attachments) may contain information that is privileged or confidential. The sending of this e-mail to any person other than the intended recipient is not a waiver of the privilege or confidentiality that attaches to it. If you are not the intended recipient, please notify the sender immediately, delete the email and do not copy, distribute or disclose its contents.

# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 11 Jun 2018

## Preliminary Advice

Vehicle No	: SLQ1334Z	Accident Date	: 06/06/2018
Make	: BMW 216i	Policy No.	: 28986545
Assignment Date	: 08/06/2018	Excess	: S\$1,000.00
Date of Inspection	: 08/06/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

### Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	13,833.40
Revised Amount	:S\$	10,789.30
Check Items (Estimated)	:S\$	1,226.05
Total	:S\$	12,015.35

Lump Sum Repair	:S\$	
-----------------	------	--

### **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	119,000.00
COE / PARF Rebate	:S\$	66,709.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,291.00

### Remarks

- ( X ) The vehicle is economical for repair.
- ( ) The above survey was conducted on a 'without prejudice' basis.

## Print Received Message

This mail is associated with :

**\*SLQ1334Z (560680)**  
OD  
Jun 6 2018 7:00PM  
[SIME DARBY SERVICES PTE LTD]  
Performance Motors Limited

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 13/06/2018 10:40 AM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$10789.30) - SLQ1334Z - Claim Handler: Kwok Woon Choo

Approved:10789.30:a if c; check items to be confirmed

**Janice Lee (LKKAuto)**

---

**From:** Janice Lee (LKKAuto)  
**Sent:** Wednesday, June 13, 2018 10:48 AM  
**To:** 'kevin.leong.waikit@simeдарby.com.sg'  
**Cc:** SUR  
**Subject:** SLQ 1334Z

Dear Sir,

As instructed by our client, please proceed to repair the insured vehicle **SLQ 1334Z (excess \$1,000/-)**.

If there are any check items or supplementary items please inform our office's Assignment Team at Tel: 6741 8434 to arrange our surveyor for inspection.

All supplementary items and unconfirm items are subjected to further approval from insurance company before completion of the repair.

\*Our client reserve their right **not to pay** if there is no valid approval obtained before repair.

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)



# LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

From: LKK Auto Consultants Pte Ltd  
51 Ubi Ave 1 #01-25  
Paya Ubi Industrial Park  
Singapore 408933

Attn: Kwok Woon Choo

Date: 13 Nov 2018

## Preliminary Advice

Vehicle No	: SLQ1334Z	Accident Date	: 06/06/2018
Make	: BMW 216I	Policy No.	: 28986545
Assignment Date	: 08/06/2018	Excess	: S\$1,000.00
Date of Inspection	: 08/06/2018	Est. Duration of Repair	: 7.00
Inspection At	: PERFORMANCE MOTORS LIMITED (ALEXANDRA) 303 ALEXANDRA ROAD, SIME DARBY PERFORMANCE CENTRE SINGAPORE 159941		

## Point of Impact / General Description of Damages

The vehicle sustained impact / damages front n/s portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	15,668.05	(Include Supplementary \$1,834.65)
Revised Amount	:S\$	13,011.65	(Include supplementary + check item)
Check Items (Estimated)	:S\$	0.00	
Total	:S\$	13,011.65	
Lump Sum Repair	:S\$		

## **Total Loss Consideration**

New for Old Value	:S\$	
Pre-Accident Value	:S\$	119,000.00
COE / PARF Rebate	:S\$	66,709.00
Salvage Value	:S\$	
Margin for Repair	:S\$	52,291.00

## Remarks

( X ) The vehicle is economical for repair. The repair cost include supplementary \$1,834.65 and check item.

( ) The above survey was conducted on a 'without prejudice' basis.

## Print Received Message

This mail is associated with :

**\*SLQ1334Z (560680)**

OD

Jun 6 2018 7:00PM

[SIME DARBY SERVICES PTE LTD]

Performance Motors Limited

**From** MSIG Insurance (Singapore) Pte. Ltd. (MSIG\_SG), sent on 13/11/2018 16:24 PM.  
**To** LKK\_HQ  
**Subject** Alert - Adj Mandate Approved (S\$13011.65) - SLQ1334Z - Claim Handler: Kwok Woon Choo

Approved:13011.65:a if c

[> Back to OneMotoring](#)

## Enquire PARF/COE Rebate for Registered Vehicle

<b>Vehicle Owner Particulars</b>	
Owner ID Type:	Company
Owner ID:	1065W
<b>Vehicle Details</b>	
Vehicle No.:	SLQ1334Z
Vehicle to be Exported:	No
Intended De-registration Date:	11 Jun 2018
Vehicle Make:	B.M.W.
Vehicle Model:	216D GRAN TOURER LED NAV 7 SEATER
Primary Colour:	Blue
Manufacturing Year:	2017
Engine No.:	34989986837C15A
Chassis No.:	WBA2E320205H46378
Maximum Power Output:	85.0 kW (113 bhp)
Open Market Value:	\$32,369.00
Original Registration Date:	28 Jun 2017
First Registration Date:	28 Jun 2017
Transfer Count:	0
Actual ARF Paid:	\$27,317.00
<b>Intended PARF Rebate Details</b>	
PARF Eligibility:	Yes
PARF Eligibility Expiry Date:	27 Jun 2027
PARF Rebate Amount:	\$20,487.00
<b>Intended COE Rebate Details</b>	
COE Expiry Date:	27 Jun 2027
COE Category:	A - Car up to 1600cc & 97kW (130bhp)
COE Period(Years):	10
QP Paid:	\$51,106.00
COE Rebate Amount:	\$46,222.00
<b>Total Rebate Amount:</b>	<b>\$66,709.00</b>

The information contained herein is correct as at 11 Jun 2018

OK

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT	
Date Of Report	07/06/2018 15:27
Date Of Accident	06/06/2018 19:20
Exact Location Of Accident	413A COMMONWEALTH AVE WEST MULTI STOREY
Country/State of Loss	SINGAPORE
DETAILS OF OWN VEHICLE	
Vehicle Registration Number	SLQ1334Z
<b>Insured/Policyholder</b>	
Name Of Registered Owner	SIME DARBY SERVICES PTE LTD
Co Reg No	S197501065W
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-96639961
<b>Vehicle Particulars</b>	
Manufacturer	BMW
Model	216D
Exact Purpose for which vehicle was being used at time of accident	NORMAL USAGE
Are you claiming under your own insurance policy for repair to your vehicle?	YES
If No, Please state action to be taken	
Vehicle Category	PRIVATE CAR
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	
Cover Note Number	
<b>Driver</b>	
Name of Driver	GOH HONG MING DESMOND
NRIC No	S8533799H
Date Of Birth	11/10/1985
Occupation	INDOOR
Date Of Driving Pass	19/12/2006
Driving Experience	11 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96639961
Fax Number	
Contact Number	
Email Address	GHMD13@GMAIL.COM

Address	37 JURONG EAST AVE 1 #12-03
Postcode	609775
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

REFER TO ATTACH.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	GY4410J
Vehicle Make/Model/Colour	NISSAN DARK BLUE
Details Of Properties	
Vehicle Category	COMMERCIAL VEHICLE
Name of Driver	MR LIU
NRIC/Passport Number	
Contact Number	96456717
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	
No. Of Passenger (Including Driver)	

**SKETCH PLAN**


**IMPORTANT NOTICE**

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to regulate policy liability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:


- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of :
  - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
  - (ii) investigating the accident and/or my claims;
  - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
  - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
  - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims (collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
  - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
  - (ii) for complying with requirements under any regulations, laws or court orders.

  
 Policyholder's Signature:  
 Date & Time: 17 JUNE 2018,  
 09.50 AM

  
 Driver's Signature  
 (If driver is not the policyholder)  
 Date & Time:

  
 Reporting Centre Personnel's Signature  
 Name:  
 NRIC/FIN No.:

**SKETCH PLAN**



**DESCRIBE CIRCUMSTANCES OF THE ACCIDENT**

On 6 June 2018 at about 7.20pm, I was driving into the A13A Commonwealth Ave West multi-storey carpark. The vehicle (GY4410J) suddenly stopped while turning, and I accidentally knocked into the rear-right of his vehicle.

**DECLARATION**

I/We declare the foregoing particulars are true in every respect.

Policyholder's Signature  
Date & Time:


&

Driver's Signature  
(If driver is not the policyholder)  
Date & Time:

Reporting Centre Personnel's Signature  
Name:  
NRIC/FIN No.:

GIARMC SketchPlanForm\_V3

413A Commonwealth Ave West Multi-story Car park





## Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559M GST Reg. No M2-0020081-X



101, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel: 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax: 64747770

280, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel: 62190888 (AfterSales)  
Fax: 63449777

311, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel: 63190828 (AfterSales)  
63190833/930 (Motorrad)  
Fax: 64796603 (AfterSales)  
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## ESTIMATE

Estimate No. : b1 47211  
Date Estimated : 07/06/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1 of 5

- ESTIMATE REPAIR FOR -  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
Singapore 159942

- ACCOUNT - 66  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1334Z	5H46378	28/06/2017	216d G TOURER	0

## DESCRIPTION

To replace front bumper, front left side panel, bonnet,  
LH headlight bracket & all attachments cause by accident.

2550 3,825.00

Painting on front bumper, front left side panel & bonnet

241 2898 3,221.00

To check electrical wiring systems at the front section  
for proper function.

150 177.00

To replace left headlight including program and conduct  
tests for proper function.

451 531.00

To carry out body cavity preservation.  
(Per panel).

600 118.00

Sundries.

? 150.00

Total Labour 1: 8,022.00

## DESCRIPTION

FRT LH FENDER  
LH EXTENSION WHEEL HOUSING STRUT  
BONNET  
FRT IMPACT ABSORBER  
FRT RH SIDE PANEL TOP MOUNTING  
GRILLE BUMPER MIDDLE OPEN (PDC)  
LH FINISHER (LUXURY LINE)  
LH SUPPORT FOG LAMP (GESCHLOSSEN)  
FRT BUMPER PANEL PRIMED (PMA)  
GRILLE SIDE OPEN LH (LUXURY LINE+PD)  
FRT BUMPER TOP CARRIER  
GROMMET  
LH SUPPORT HEADLIGHT ARM  
AIR DUCT  
PLAQUE 82MM  
FRT ENGINE HOOD SEALING  
LH GASKET HEADLIGHT AND HOOD

QTY PRIC

1 573.30  
1 135.80  
1 953.80  
1 47.80  
1 8.85  
1 95.05  
1 52.55  
1 50.95  
1 842.00  
1 95.85  
1 368.90  
1 0.75  
1 124.85  
1 190.50  
1 69.50  
1 23.20  
1 19.70

VALUE

bl 573.30  
de 135.80  
bl 953.80  
nn 47.80  
nn 8.85  
nn 95.05  
nn 52.55  
nn 50.95  
de 842.00  
nn 95.85  
nn 368.90  
nn 0.75  
bl 124.85  
nn 190.50  
nn 69.50  
nn 23.20  
nn 19.70



303, Alexandra Road  
Sime Darby Performance Centre  
Singapore 159941  
Tel. 63190100 (Sales & Admin)  
63190111 (AfterSales)  
Fax. 64747770

288, Kampong Arang Road  
East Coast Centre  
Singapore 438180  
Tel. 63190888 (AfterSales)  
Fax. 63449777

315, Alexandra Road  
Sime Darby Business Centre  
Singapore 159944  
Tel. 63190528 (AfterSales)  
63190633/530 (Motorrad)  
Fax. 64794601 (AfterSales)  
64794624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

## E S T I M A T E

Estimate No. : b1 47211  
Date Estimated : 07/06/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 2 of 5

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1334Z	5H46378	28/06/2017	216d G TOURER	0

## DESCRIPTION

LH HEADLIGHT LED TECHNOLOGY  
DECOUPING RING PDC TORQUE CONVERTER

QTY	PRIC	VALUE
1	2,137.85	2,137.85
4	5.05	20.20

Total Parts : 5,811.40

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

8/6/18 @ 16.50  
Tougher  
b 92445344  
Not Authorise

41,000  
higher

Sanjib @ Interview on  
6-7 days

Signature  
13/6/18

Labour 1	:	8,022.00
Parts	:	15668.45 5,811.40
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	968.34
Grand Total	:	14,801.74

\*\* THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY\*\*

\*\* PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE \*\*

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



## SUPPLEMENTARY

Estimate No. : b1 47211  
Date Estimated : 07/06/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

**REPAIR FOR -**  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
  
Singapore 159942

**- ACCOUNT - 66**  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1334Z	5H46378	28/06/2017	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
-------------	----------------	---------	------

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# BONNET LH HINGE *	107.00	1.00		107.00 <i>ht</i>
# MODEL DESIGNATION LETTERING SIDE (L *	45.20	1.00		45.20 <i>ah</i>
# FRT LH FENDER SEALING *	23.70	1.00		23.70 <i>mt</i>
# LH LED MODULE CORNERING LIGHT *	786.65	1.00		786.65 <i>hs</i>
# CONTROL UNIT FRT LIGHT ELECTRONIC *	872.10	1.00		872.10 <i>hs</i>

Total Labour :	
Total Parts :	1,834.65
Total Labour & Parts :	1,834.65

# Performance Motors Limited

A member of the Sime Darby Group  
Co. Reg. No. 19740155AW. GST Reg. No. M2-0020081-X



## FINAL REPORT

Estimate No. : b1 47211  
Date Estimated : 07/06/2018  
Prepared By : Kevin Leong Wai Kit

Page No. : 1

**REPAIR FOR -**  
Sime Darby Services Private Limited  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
Singapore 159942

**- ACCOUNT - 66**  
MSIG Insurance (S) Pte Ltd  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1334Z	5H46378	28/06/2017	216d G TOURER	0
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT	
* To replace front bumper and attachments, front LH fender and attachments, bonnet and attachments, LH extension wheel housing strut, LH support headlight arm include knocking out dents caused by the accident	2550.00		2,550.00	
To spray paint front bumper, front LH fender and bonnet	2899.00		2,899.00	
To check electrical wiring systems at the front section for proper function.	150.00		150.00	
To replace LH LED technology headlight include programming and conducting tests for proper function	451.00		451.00	
To carry out body cavity preservation. (Per panel).	100.00		100.00	
Sundries.	150.00		150.00	

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	573.30	1.00		573.30
# BONNET LH HINGE *	107.00	1.00		107.00
LH EXTENSION WHEEL HOUSING STRUT	135.80	1.00		135.80
BONNET	953.80	1.00		953.80
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
# MODEL DESIGNATION LETTERING SIDE (L. *	45.20	1.00		45.20
LH SUPPORT HEADLIGHT ARM	124.85	1.00		124.85
PLAQUE 82MM	69.50	1.00		69.50
# FRT LH FENDER SEALING *	23.70	1.00		23.70
LH GASKET HEADLIGHT AND HOOD	19.70	1.00		19.70
# LH LED MODULE CORNERING LIGHT *	786.65	1.00		786.65
LH HEADLIGHT LED TECHNOLOGY	2,137.85	1.00		2,137.85
# CONTROL UNIT FRT LIGHT ELECTRONIC *	872.10	1.00		872.10
DECOUPING RING PDC TORQUE CONVERTER	5.05	4.00		20.20

### # SUPPLEMENTARY ITEMS

Total Labour :	6,300.00
Total Parts :	6,711.65
Total Labour & Parts :	13,011.65
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	12,011.65
GST @7%:	840.82
Grand Total :	12,852.47

**Janice Leé (LKKAUTO)**

---

**From:** PBSP <pml-pbsp@simedarby.com.sg>  
**Sent:** Tuesday, September 11, 2018 2:13 PM  
**To:** Taufikh (LKKAUTO); SUR  
**Subject:** FINAL REPORT / SLQ1334Z  
**Attachments:** Final Report SLQ1334Z\_2.pdf; Final Report SLQ1334Z.pdf

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,300.00  
Total Parts : 6,711.65  
Total Labour & Parts : 13,011.65

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies of the Message. Sime Darby disclaims all liability for any error, loss or damage arising from the Message being infected by computer virus or other malicious software. Any views and/or opinions expressed in the Message are solely those of the author's and do not necessarily represent those of Sime Darby's."



## FINAL REPORT

Estimate No. : b1 47211  
Date Estimated : 07/06/2018  
Prepared By : Kevin Leong Wai Kit

Page No. :

**REPAIR FOR -**  
**Sime Darby Services Private Limited**  
305 Alexandra Road  
#02-01 Vantage Automotive Centre  
  
Singapore 159942

**- ACCOUNT - 66**  
**MSIG Insurance (S) Pte Ltd**  
4 Shenton Way  
#21-01 SGX Centre 2  
Singapore 068807

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SLQ1334Z	5H46378	28/06/2017	216d G TOURER	0

DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT
* To replace front bumper and attachments, front LH fender and attachments, bonnet and attachments, LH extension wheel housing strut, LH support headlight arm include knocking out dents caused by the accident	2550.00		2,550.00
To spray paint front bumper, front LH fender and bonnet	2899.00		2,899.00
To check electrical wiring systems at the front section for proper function.	150.00		150.00
To replace LH LED technology headlight include programming and conducting tests for proper function	451.00		451.00
To carry out body cavity preservation. (Per panel).	100.00		100.00
Sundries,	150.00		150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
FRT LH FENDER	573.30	1.00		573.30
# BONNET LH HINGE *	107.00	1.00		107.00
LH EXTENSION WHEEL HOUSING STRUT	135.80	1.00		135.80
BONNET	953.80	1.00		953.80
FRT BUMPER PANEL PRIMED (PMA)	842.00	1.00		842.00
# MODEL DESIGNATION LETTERING SIDE (L *	45.20	1.00		45.20
LH SUPPORT HEADLIGHT ARM	124.85	1.00		124.85
PLAQUE 82MM	69.50	1.00		69.50
# FRT LH FENDER SEALING *	23.70	1.00		23.70
LH GASKET HEADLIGHT AND HOOD	19.70	1.00		19.70
# LH LED MODULE CORNERING LIGHT *	786.65	1.00		786.65
LH HEADLIGHT LED TECHNOLOGY	2,137.85	1.00		2,137.85
# CONTROL UNIT FRT LIGHT ELECTRONIC *	872.10	1.00		872.10
DECOUPLING RING PDC TORQUE CONVERTER	5.05	4.00		20.20

### # SUPPLEMENTARY ITEMS

Total Labour :	6,300.00
Total Parts :	6,711.65
Total Labour & Parts :	13,011.65
Deduction for Excess :	1,000.00
Total Repair Costs less Excess:	12,011.65
GST @7%:	840.82
<b>Grand Total :</b>	<b>12,852.47</b>

## Janice Lee (LKKAUTO)

---

**From:** Janice Lee (LKKAUTO)  
**Sent:** Tuesday, November 13, 2018 5:38 PM  
**To:** PBSP; Taufikh (LKKAUTO); SUR  
**Subject:** RE: FINAL REPORT / SLQ1334Z

Dear Caroline,

Confirm \$13,011.65 @ 6 days

Thank you.

Best Regards,

**Jannice Lee (Ms)** | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [janicelee@lkkauto.com](mailto:janicelee@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** PBSP [mailto:[pml-pbsp@simedarby.com.sg](mailto:pml-pbsp@simedarby.com.sg)]  
**Sent:** Tuesday, September 11, 2018 2:13 PM  
**To:** Taufikh (LKKAUTO) <[Taufikh@lkkauto.com](mailto:Taufikh@lkkauto.com)>; SUR <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** FINAL REPORT / SLQ1334Z

Dear Taufikh

We refer to the above and attached Final Report.

Please confirm COR as follows:

Total Labour : 6,300.00  
Total Parts : 6,711.65  
Total Labour & Parts : 13,011.65

Thank you.

Regards,  
Caroline  
C/o Performance Motors Limited - Body and Paint  
303 Alexandra Road Singapore 159941  
DID: 6319 0174 Fax: 6479 4601

"This electronic mail content and any accompanying attachments ("the Message") is intended only for the named addressee ("the Recipient") and may contain information that is confidential, privileged and/or proprietary to the Sime Darby group of companies ("Sime Darby") and/or protected under applicable laws. If you are not the intended Recipient, you are strictly prohibited from using, disseminating, forwarding and/or printing the Message. Please notify the sender immediately by return e-mail and permanently delete all copies

## ...CLAIM SUBFOLDER...(Pending for Survey Report)

## CLAIM SUBFOLDER TRACKING


















Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	07 Jun 2018		08 Jun 2018 10:50 <a href="#">Edit Adj Rpt</a>	<b>S\$13,011.65</b> <a href="#">Edit Estimates</a>	<b>S\$13,011.65</b> <a href="#">View Rpt</a>		<b>Pending for Survey Report</b> <a href="#">Cancel Case</a>

Main	Reference	Claim Details	Documents	Show All					
<b>CLAIM SUBFOLDER DETAILS</b>		<b>[Created by insurer]</b>							
Insured:	<b>SIME DARBY SERVICES PTE LTD</b> , Co. Reg. No.: S197501065W								
Vehicle Reg. No.:	<b>SLQ1334Z</b>	Date of Loss:	06/06/2018 19:00 - :59 [11 Months and 9 Days From LTA Reg Date (Man Yr)]						
Claim Type:	<b>OD / 560680</b>	Policy/Cover Note No.:	28986545 (Comprehensive) Coverage: 28/06/2017 - 27/06/2018						
		Excess:	S\$1,000.00						
Repairer:	<b>Performance Motors Limited (Alexandra)</b> 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174								
Handling Insurer:	<b>MSIG Insurance (Singapore) Pte. Ltd. (HQ)</b> - Tel: +65 6827 7888 ... [Handled by <b>Kwok Woon Choo</b> - 6643 1330]								
Adjuster:	<b>LKK Auto Consultants Pte Ltd (HQ)</b> - Tel: 6256-3561 ... [Handled by <b>MOHD TAUFIKH BIN HAMID</b> ] ... [Final Rpt due 08/07/2018]								
Driver/Custodian:	GOH HONG MING DESMOND (32 / Male), NRIC: S8533799H, Tel: +6596639961								
Adj Asp. Remarks:	SURVEY TODAY AND REVERT - WORKSHOP REQUEST TO SURVEY BY TODAY								
<b>ASSOCIATED MAIL RECEIVED</b>		<a href="#">View All</a> <a href="#">Compose Case Mail</a>							
<ul style="list-style-type: none"> <li>MSIG_SG (13/11/2018): Alert - Adj Mandate Approved (S\$13011.65) - SLQ1334Z - Claim Handler: Kwok Woon ...</li> <li>MSIG_SG (13/06/2018): Alert - Adj Mandate Approved (S\$10789.30) - SLQ1334Z - Claim Handler: Kwok Woon ...</li> </ul>									
<b>ALL ASSOCIATED TASKS</b>		<a href="#">View All</a> <a href="#">Search Tasks</a> <a href="#">Create New Task</a> <a href="#">Complete</a>							
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									



## Claim Documents

\*SLQ1334Z (560680)  
OD  
Jun 6 2018 7:00PM  
[SIME DARBY SERVICES PTE LTD]  
Performance Motors Limited

<a href="#">Upload Documents</a>   <a href="#">Upload Photos</a>   <a href="#">Compose New Letter</a>			<b>View</b> <a href="#">View in Browser</a>	
<b>Assessment Reports</b>			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	07/06/18 17:05	<b>Accident Statement</b>	 Load HTM	<input type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 14:11	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
2	13/11/18 14:50	<b>Adjuster Immediate Advice</b>	 Load HTM	<input type="checkbox"/>
<b>Photos/Images</b>			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	07/06/18 17:03	<b>Accident Photo</b> [Linked Accident Report Documents]	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
2	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
3	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
4	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
5	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
6	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
7	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
8	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
9	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
10	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
11	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
12	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
13	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
14	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
15	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
16	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>
17	11/06/18 14:22	<b>General View</b>	 Load JPG <input checked="" type="checkbox"/>	<input checked="" type="checkbox"/>

Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
18	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
19	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
20	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
21	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
22	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
23	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
24	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
25	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
26	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
27	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
28	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
29	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
30	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
31	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
32	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
33	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
34	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
35	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
36	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
37	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
38	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
39	11/06/18 14:22	General View		<input checked="" type="checkbox"/>
40	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
41	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
42	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
43	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
44	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
45	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
46	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
47	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
48	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
49	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
50	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
51	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
52	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
53	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
54	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
55	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
56	13/11/18 14:52	Reinspection Photo		<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	08/06/18 10:44	E-MAIL FR PML		
2	08/06/18 10:45	OD ESTIMATE + GIA REPORT + DRIVER NRIC + DL + CI.		
No	Finalized On	Performance Motors Limited (Alexandra)	Thumbnail	Print
1	07/06/18 17:02	Sketch Plan <small>[Linked Accident Report Documents]</small>		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	11/06/18 14:20	SLQ 1334Z ESTIMATE		
2	13/11/18 14:52	SLQ 1334Z SUPPLEMENTARY		
3	13/11/18 14:52	SLQ 1334Z EST + SUPP		

## Linked Accident Report Documents

				View	View in Browser
<b>Assessment Reports</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	07/06/18 17:05	Accident Statement		Load HTM	
<b>Photos/Images</b>				3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
2	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
3	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
4	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
5	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
6	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
7	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
8	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
9	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
10	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
11	07/06/18 17:03	Accident Photo		Load JPG	<input checked="" type="checkbox"/>
<b>Documentation</b>				1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Performance Motors Limited (Alexandra)		Thumbnail	Print
1	07/06/18 17:02	Sketch Plan		Load TIF	

## Documents Checklist

<b>DOCUMENTS CHECKLIST</b>	Reset	Save	Print
There are no document checklists configured.			
<b>Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)</b> <div style="border: 1px solid black; height: 40px; width: 100%;"></div>			
<b>Show Remarks To:</b> <input type="checkbox"/> Handling Insurer <small>Note: Remarks are private unless you show it to other parties.</small>			

# LKK Auto Consultants Pte Ltd

(Co. Reg. No: 199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

## VEHICLE DAMAGE INSPECTION REPORT

MSIG Insurance (Singapore) Pte. Ltd.  
4 Shenton Way, #21-01 SGX Centre 2  
Singapore 068807

Our File No: CS/MSG18010456/T1RD3E2

Date: 26/11/2018

### REFERENCE

Insured/Claimant: SIME DARBY SERVICES PTE LTD

Policy No: 28986545

Date of Loss: 06/06/2018

Nature of Claim: OD Claim No: 560680

### DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SLQ1334Z

Make &amp; Model: BMW 216i, 1.5 (A)

Engine No: 34989986B37C15A

Reg. Date: 28/06/2017 (Man. Year: 2017)

Chassis No: WBA2E320205H46378

Colour: Blue

Odometer: 14305 km

Engine Capacity: 1496 cc

Market Value/New Car Price: S\$119,000.00

Sum Insured (S\$): Market Value/New Car Price

### CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Steering (Serviceable): Yes Footbrake (Serviceable): Yes

Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

### CONDITION OF TYRES

Front Tyre Size: 205/55 R17

Rear Tyre Size: 205/55 R17

Front Left Side: Goodyear 6 mm

Rear Left Side: Goodyear 6 mm

Front Right Side: Goodyear 6 mm

Rear Right Side: Goodyear 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	7,796.05	6,861.65	934.40	11.99
Miscellaneous Items	0.00	0.00	0.00	
Labour	7,872.00	6,150.00	1,722.00	21.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
<b>Calculated Gross Total (S\$)</b>	<b>15,668.05</b>	<b>13,011.65</b>	<b>2,656.40</b>	<b>16.95</b>
<b>- Excess (S\$)</b>	<b>1,000.00</b>	<b>1,000.00</b>	<b>0.00</b>	<b>0.00</b>
<b>(S\$)</b>	<b>14,668.05</b>	<b>12,011.65</b>	<b>2,656.40</b>	<b>18.11</b>
<b>+ GST 7.00/7.00% (S\$)</b>	<b>1,026.76</b>	<b>840.82</b>	<b>185.94</b>	<b>18.11</b>
<b>Nett Amount (S\$)</b>	<b>15,694.81</b>	<b>12,852.47</b>	<b>2,842.34</b>	<b>18.11</b>

### INSPECTION

Date of Assignment: 08/06/2018

Date Inspected: 08/06/2018 Inspected At:

Performance Motors Limited (Alexandra)  
303 Alexandra Road, Sime Darby  
Performance Centre  
Singapore 159941

Estimated Period of Repair: 6.0 days

**Adjuster:** MOHD TAUFIKH BIN HAMID

**Manager:** Janice Lee Si Hua

*NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.*

## REPAIR DETAILS

## Reference

<b>Part Source:</b>	MRM-SG	Version: 1.0 (Last Synchronised: 26 Nov 2018)
<b>Parts:</b>	M1-MPV	BMW 216I 1.5 (A) (Catalogue:Merimen Singapore 1.0)
<b>Labour:</b>	Repairer's	(Price-denominated Standard List)
<b>Print Code:</b>	(Unsubmitted, no print-code for SLQ1334Z)	
<b>Validity:</b>	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
<b>Further Info:</b>	Items/values not in reference catalogue are prefixed with an asterisk *.	

## Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS
2	1		*FRT LH FENDER	Bent	573.30 FS	*573.30 FS
3	1		*LH EXTENSION WHEEL HOUSING STRUT	Deformed	135.80 FS	*135.80 FS
4	1		*BONNET	Bent	953.80 FS	*953.80 FS
5	1		*FRT IMPACT ABSORBER	Not Necessary	47.80 FS	*- FS
6	1		*FRT RH SIDE PANEL TOP MOUNTING	Not Necessary	8.85 FS	*- FS
7	1		*GRILLE BUMPER MIDDLE OPEN (PDC)	Not Necessary	95.05 FS	*- FS
8	1		*LH FINISHER (LUXURY LINE)	Not Necessary	52.55 FS	*- FS
9	1		*LH SUPPORT FOG LAMP (GESCHLOSSEN)	Not Necessary	50.95 FS	*- FS
10	1		*FRT BUMPER PANEL PRIMED (PMA)	Deformed	842.00 FS	*842.00 FS
11	1		*GRILLE SIDE OPEN LH (LUXURY LINE+PD	Not Necessary	95.85 FS	*- FS
12	1		*FRT BUMPER TOP CARRIER	Not Necessary	368.90 FS	*- FS
13	1		*GROMMET	Not Necessary	0.75 FS	*- FS
14	1		*LH SUPPORT HEADLIGHT ARM	Bent	124.85 FS	*124.85 FS
15	1		*AIR DUCT	Not Necessary	190.50 FS	*- FS
16	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
17	1		*FRT ENGINE HOOD SEALING	Not Necessary	23.20 FS	*- FS
18	1		*LH GASKET HEADLIGHT AND HOOD	Cut	19.70 FS	*19.70 FS
19	1		*LH HEADLIGHT LED TECHNOLOGY	Cracked	2,137.85 FS	*2,137.85 FS
20	4		*DECOUPING RING PDC TORQUE CONVERTER	Necessary	20.20 FS	*20.20 FS
21	1		*BONNET LH HINGE	Bent	107.00 FS	*107.00 FS
22	1		*MODEL DESIGNATION LETTERING SIDE (L	Necessary	45.20 FS	*45.20 FS
23	1		*FRT LH FENDER SEALING	Necessary	23.70 FS	*23.70 FS
24	1		*LH LED MODULE CORNERING LIGHT	Distorted	786.65 FS	*786.65 FS
25	1		*CONTROL UNIT FRT LIGHT ELECTRONIC	Distorted	872.10 FS	*872.10 FS
Total Parts (S\$)					7,796.05	6,861.65

F=Franchise part. S=SpcNett.

Report was unsubmitted during this print-out.

## Recommended Miscellaneous Items

There are no new miscellaneous items selected.

## Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<b>Labour Items</b>				
1	TO REPLACE FRONT BUMPER, FRONT LEFT SIDE PANEL, BONNET, LH HEADLIGHT BRACKET & ALL ATTACHMENTS CAUSE BY ACCIDENT	New	3,825.00	2,550.00
2	PAINTING ON FRONT BUMPER, FRONT LEFT SIDE PANEL & BONNET	New	3,221.00	2,899.00
3	TO CHECK ELECTRICAL WIRING SYSTEMS AT THE FRONT SECTION FOR PROPER FUNCTION	New	177.00	150.00
4	TO REPLACE LEFT HEADLIGHT INCLUDING PROGRAM AND CONDUCT TESTS FOR PROPER FUNCTION	New	531.00	451.00
5	TO CARRY OUT BODY CAVITY PRESERVATION (PER PANEL)	New	118.00	100.00
Gross Labour Cost (S\$)			<b>7,872.00</b>	<b>6,150.00</b>

Report was unsubmitted during this print-out.

< END OF ESTIMATES >