

22/03/2003

ASS. REC. BY:

REF: CS/MSG18010460 / T1vd3et Special Instruction:

Surveyor:
Merimen

Tautikh

ASSIGNMENT (Office)

From (Person):

Chhia Nyuk pui

of

MSG

Date/Time:

8/6/18 @ 9.25am

Estimated Cost:

Bill to:

OD

 TP

WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No.:

SHD 1128T

Insured:

SBK 1655Y

at Workshop m/s

Komoco Motors

Tel:

65446676

of

253 Alexandra Rd

Policy No.:

29070686 QMX

Claim No.:

560603

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS

up?

H.O.D. Endorsement:

Date/Time:

10:00am @ 8/6/18

Person Contacted:

vincent

Vehicle IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	SHD 1128T - CC3 / MSG 15008388 / Hlvbk3 DOA: 18/5/2015 SBK 1655Y - X.
11/6/18	Send preli revised by merimen
3/7/18	Final fig \$ 1430.73 confirmed by email (Ref 610.16, 309)

Tayfun

REF: MSIG

ASSIGNMENT

From: Date: 8/6/2018

Estimated Cost:

OD TP WS TP RES OD RES EVA INV MV

To Inspect Vehicle No: SHD 1128T
at Workshop m/s Komoco Motors
of 253 Alexandra Road

Insured:

Policy No.

Claims No.

Sum Insured:

Excess:

(Client's Record)

Make of Veh:

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.

N/S	O/S

Bal. or Market Value:

IDAC Accident Rpt: Consistent?: Yes or No

GLA / PR Seen: Consistent?: Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS (up)

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SHD/1128T Yr Regn: 2016 Sep

Type: M.Car / M.Cycle / Bus / Van / Lorry Taxi / Prime Mover /

Truck / Trailer or

Make: Hyundai 130 C.C. 1582

Colour: Sil/hec A/C: Insured / Std / NI / NA

Sp. Reading: 105020 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No:

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F:

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

D.O.I. 8/6/18 @ 1130

Survey held at

Des. of Damages: Frt / Rear / O/S / N/S / UIC / Rooftop or

The UIC / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED @ 3 JUL 2018

Date/Time: File Pass to?

: Preli. Report
 : Final Report

Days Of Repair: 3

Resurvey No. of Trip: 1

Survey Fee:

Date/Time: File Return to?

Transportation:

3/7 - typist

Add Fee: : Site Insp (\$

) \$ + RD \$

Interview (\$

) Photos

Tech. Invs (\$

) Others

Weekend (\$

)

Report Format: merimen

Lump Sum / I.B.I: (\$ 1432.73

TOTAL

150
10
160



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile			
MSIG INSURANCE (SINGAPORE) PTE LTD		Ref : CS/MSG18010460/T1vd3	
16 RAFFLES QUAY #24-01 HONG LEONG BLDG SINGAPORE 048581		Date : 08-06-2018	
		Code : MSG	
1. Policy Particulars :- THIRD PARTY CLAIM			
Insured Veh.	SBK 1655Y	Veh. Inspected	SHD 1128
Policy No.	29070686QMX	Coverage (\$)	0.00
Claim No.	560603	Excess (\$)	0.00
Assign From	MERIMEN (CHHIA NYUK PUI)	Assign Date	08/06/2018
2. Vehicle Particulars & Condition			
Make & Model		c.c	0
Engine No.	HIDDEN	Year of Reg.	
Chassis No.		Colour	
Odometer	-	Steering	
Brakes		Modification	
General			
3. Conditions of Tyres			
	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm
4. Description of Damages			
5. General Information			
Accident Date	07/06/2018	Inspection Date	08/06/2018
Survey held at	KOMOCO MOTORCYCLES PTE LTD 253 ALEXANDRA ROAD #01-04 SINGAPORE 159936		
5a. Remarks			
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.			

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2018		08 Jun 2018 09:25 <input type="button" value="Assign"/>				New Assignment <input type="button" value="Cancel Case"/>

Main	Reference	Claim Details	Documents	<input type="button" value="Show All"/>					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured: LING HANG LIANG , ID: S0643608J, Tel: +6597260240									
Main Claimant: PREMIER TAXI PTE LTD , Co. Reg. No.: 200304975H									
Vehicle Reg. No.:	SHD1128T	Date of Loss:	07/06/2018 00:00 - :59 [20 Months and 17 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / 560603	Policy/Cover Note No.:	29070686QMX (Comprehensive) Coverage: 03/02/2018 - 02/02/2019						
Vehicle Reg. No. (Insured):	SBK1655Y	Policy No. (Claimant):							
		Excess:							
Repairer: Komoco Motors - (alexandra) (HQ) 253 Alexandra Road, 159936 Alexandra - Tel:									
Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]									
Adjuster: LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Imm.Advice due 09/06/2018]									
Driver/Customer (Insured):	LING HANG LIANG (72 / Male), NRIC: S0643608J, Tel: +6597260240								
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP nominated LKK to survey, please arrange. Liability clear.								
ASSOCIATED MAIL RECEIVED <input type="button" value="View All"/> <input type="button" value="Compose Case Mail"/>									
There are no mail for this case.									
ALL ASSOCIATED TASKS <input type="button" value="View All"/> <input type="button" value="Search Tasks"/> <input type="button" value="Create New Task"/> <input type="button" value="Complete"/>									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Tuesday, 3 July 2018 10:19 AM
To: 'Goh Wee Dek'; Taufikh (LKKAuto)
Cc: SUR; Gary Shi
Subject: RE: SHD1128T- FINALIZE (AUDATEX)

Dear Mr Goh,

Noted with thanks.

Final invoice and all supporting documents sent over to MSIG

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]
Sent: Tuesday, 3 July 2018 10:10 AM
To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Gary Shi <gary.shi@premiertaxi.com>
Subject: RE: SHD1128T- FINALIZE (AUDATEX)

Dear Veron

Ok confirmed. Thanks

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]
Sent: Tuesday, 3 July, 2018 9:16 AM
To: Goh Wee Dek; Taufikh (LKKAuto)
Cc: SUR; Gary Shi
Subject: RE: SHD1128T- FINALIZE (AUDATEX)

Dear Mr Goh,

WITHOUT PREJUDICE

Finalize amount \$1432.73 before GST @ 3 working days.

Kindly confirmed.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]

Sent: Monday, 2 July 2018 5:22 PM

To: Veron Chen (LKKAuto) <veronchen@lkkauto.com>; Taufikh (LKKAuto) <Taufikh@lkkauto.com>

Cc: SUR <sur@lkkauto.com>; Gary Shi <gary.shi@premiertaxi.com>

Subject: RE: SHD1128T- FINALIZE (AUDATEX)

Dear Veron/Taufikh

Attach

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.SG

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

From: Veron Chen (LKKAuto) [mailto:veronchen@lkkauto.com]

Sent: Monday, 2 July, 2018 11:30 AM

To: Goh Wee Dek; Taufikh (LKKAuto)

Cc: SUR; Gary Shi

Subject: RE: SHD1128T- FINALIZE (AUDATEX)

Dear Mr Goh,

Please forward us a copy of finalize.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Goh Wee Dek [mailto:weedek.goh@premiertaxi.com]
Sent: Monday, 2 July 2018 9:08 AM
To: Taufikh (LKKAuto) <Taufikh@lkkauto.com>
Cc: SUR <sur@lkkauto.com>; Gary Shi <gary.shi@premiertaxi.com>
Subject: SHD1128T- FINALIZE (AUDATEX)

Dear Taufikh

Please confirm PxP \$1,314.02

No check items.

Regards

Goh Wee Dek
Assistant Claims Manager
Premier Automotive Services Pte Ltd

Address: 23 Changi South Ave 2, #01-02 Singapore 486443
Tel: 6214 8880 Ext 068 | DID: 6544 6682 | Fax: 6214 1511
Visit us at: www.premiertaxi.com.sg

Confidentiality Notice | This e-mail message, including any attachments, is for the sole use of the intended recipient(s) and may contain confidential or proprietary information. Any unauthorized review, use, disclosure or distribution is prohibited. If you are not the intended recipient, immediately contact the sender by reply e-mail and destroy all copies of the original message.

 Please Consider Your Environmental Responsibility Before Printing This E-mail. SAVE OUR TREES and REDUCE POLLUTION

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

To: MSIG Insurance (Singapore) Pte. Ltd.
4 Shenton Way
#21-01 SGX Centre 2
Singapore 068807

From: LKK Auto Consultants Pte Ltd
51 Ubi Ave 1 #01-25
Paya Ubi Industrial Park
Singapore 408933

Attn: Chhia Nyuk Pui

Date: 11 Jun 2018

Preliminary Advice

Insured Vehicle No	: SBK1655Y		
TP Vehicle No	: SHD1128T	Accident Date	: 07/06/2018
Make	: HYUNDAI I40	Assignment Date	: 08/06/2018
Date of Inspection	: 08/06/2018	Est. Duration of Repair	: 3.00
Inspection At	: KOMOCO MOTORS - (ALEXANDRA) (HQ) 253 ALEXANDRA ROAD SINGAPORE 159936		

Point of Impact / General Description of Damages

The vehicle sustained impact / damages rear portion and parts claimed are consistent to the accident.

Repairer's Estimate (Gross)	:S\$	2,042.89
Revised Amount	:S\$	1,432.72
Check Items (Estimated)	:S\$	530.17
Total	:S\$	1,962.89

Lump Sum Repair	:S\$	
-----------------	------	--

Total Loss Consideration

New for Old Value	:S\$	
Pre-Accident Value	:S\$	
COE / PARF Rebate	:S\$	
Salvage Value	:S\$	
Margin for Repair	:S\$	

Remarks

The vehicle is economical/not economical for repair.

The above survey was conducted on a 'without prejudice' basis.

SINGAPORE ACCIDENT STATEMENT

IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any wilful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

ACCIDENT STATEMENT

Date Of Report	07/06/2018 11:11
Date Of Accident	07/06/2018 07:20
Exact Location Of Accident	THOMSON ROAD // MARYMOUNT ROAD
Country/State of Loss	SINGAPORE

DETAILS OF OWN VEHICLE

Vehicle Registration Number	SHD1128T
Insured/Policyholder	
Name Of Registered Owner	PREMIER TAXIS PTE LTD
Co Reg No	200304975H
Email Address	NOEMAIL
Mobile Phone No	
Alternative Phone No	OFFICE-62148880

Vehicle Particulars

Manufacturer	HYUNDAI
Model	I30 (FD)-1.6 DOHC (A)
Exact Purpose for which vehicle was being used at time of accident	HIRED & REWARDS
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	TAXI

Insurance Company

Name of Insurance Company	NTUC INCOME INSURANCE CO-OPERATIVE LTD
Type Of Coverage	THIRD PARTY
Fleet Policy	YES
Policy Number	5095103893
Cover Note Number	

Driver

Name of Driver	TAN ZHI HAO DARRICK
NRIC No	S7925706J
Date Of Birth	15/08/1979
Occupation	OUTDOOR
Date Of Driving Pass	26/07/2005
Driving Experience	12 YEARS AND 10 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-93828250
Fax Number	
Contact Number	
E-Mail Address	NOEMAIL

Address	BLK 381 #12-394 CLEMENTI AVE 5
Postcode	120381
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

General Information of the Accident

Type Of Accident	COLLISION - HEAD TO REAR
Weather Conditions	CLEAR
Road Surface	DRY

Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	2
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	1

Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

Circumstances of Accident

VEH. A - NO PAX VEH. B - 1 PAX

Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	NO
Was there any audio recorded?	NO

DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SBK1655Y
Vehicle Make/Model/Colour	HONDA CIVIC
Details Of Properties	VEH. C
Vehicle Category	PRIVATE CAR
Name of Driver	LING HANG LIANG
NRIC/Passport Number	S0643608J
Contact Number	97260240
Address	
Postcode	
Insurance Company Name	
Nature Of Damage	DAMAGED ON THE FRONT PORTION
No. Of Passenger (Including Driver)	2

SKETCH PLAN

IMPORTANT NOTICE

1. Please report **correctly** the details of the accident to speed up the claims process.
2. This Form must be **completed by the Policyholder and/or the Authorised Driver**.
3. Information provided must be as **truthful and accurate as possible**. Any wilful misrepresentation or withholding of material facts may allow insurance companies to **repudiate policy liability**.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. **Any false reporting may be referred to the Police for investigation.**
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available upon application by interested parties.
7. By the lodgment of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.
8. **Consent under the Personal Data Protection Act (PDPA)**

I understand, acknowledge, agree and consent that:

- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this [form] and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all insurer(s) who have insured vehicle(s) involved in this accident (all insurer(s) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"), the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police), for the purpose(s) of:
 - (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
 - (ii) investigating the accident and/or my claims;
 - (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
 - (iv) administering my claims (including the mailing of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages); and/or
 - (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.(collectively the "Purposes")
- (b) all insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents(including their lawyers/law firms), which may be sited outside of Singapore, for one or more of the above Purposes.
- (d) my Personal Information will also be collected and used to compile claims history for the purpose of fraud detection, investigation and management in present and all future claims.
- (e) the information so collected under (d) above may be shared / disclosed:
 - (i) to all insurers and/or any other third parties that assist in evaluating, investigating, controlling or managing fraud, regulators, law enforcement and government agencies as reasonably required for the purposes stated, or
 - (ii) for complying with requirements under any regulations, laws or court orders.



Policyholder's Signature
Date & Time:

[Signature] SHD1128T
S792C706J

Driver's Signature
(If driver is not the policyholder)
Date & Time:

07 JUN 2018

[Signature]

Reporting Centre Personnel's Signature
Name:
NRIC/FIN No.:

Describe Circumstance of the Accident.

ON 07/06/2018 AT ABOUT 0720 HRS, I WAS DRIVING MY TAXI (SHD 1128 T) TRAVELLING ALONG THOMSON ROAD TOWARDS THE TRAFFIC LIGHT JUNCTION OF MARYMOUNT ROAD, IN THE LEFT LANE.

I SLOWED DOWN MY TAXI TO A STOP – AS TRAFFIC LIGHT WAS AMBER.

WHILE STATONARY, SUDDENLY I FELT AN IMPACT FROM THE REAR.


WHEN INSPECTED, I DISCOVERED THAT VEHICLE B (SBK 1655 Y – HONDA CIVIC) WHICH WAS BEHIND ME, HAD COLLIDED ONTO THE REAR OF MY TAXI.

DUE TO THE IMPACT, MY TAXI HAD DAMAGES ON THE REAR & REAR RIGHT PORTION. VEHICLE B HAD DAMAGES ON THE FRONT PORTION.

NO INJURY INVOLVED.

NO PASSENGERS ONBOARD MY TAXI & VEHICLE B HAD A PASSENGER ONBOARD.

*VIDEO FOOTAGE CAPTURED.



[Handwritten Signature] 572757065

Driver's Signature & NRIC Number
@ 11:20:08 AM

(attended by)

[Handwritten Signature]

Sketch Plan Pg. 4

PREMIER TAXIS	TRIKER / RELTEF / SUPER RELIEF
VEHICLE NO.	SFD128T
CONTACT NO.	9382 8250
NEW MAILING ADDRESS (if any)	

REPUBLIC OF SINGAPORE
IDENTITY CARD NO. S7925706J




Name: TAN ZHI HAO DARRICK
Race: 陈治豪
CHINESE
Date of Birth: 15-08-1979 Sex: M
Country of Birth: SINGAPORE

REPUBLIC OF SINGAPORE DRIVING LICENCE

License Number: S7925706J
Name: TAN ZHI HAO DARRICK
Birth Date: 15 Aug 1979
Issue Date: 12 Sep 2009






IRIS No: S7925706J
Date of Issue: 24-08-2009
Address: APT BLK 381 CLEMENTI AVENUE 5 #12-394 SINGAPORE 120381

4450441 YOU ARE LICENSED TO DRIVE VEHICLES IN THE FOLLOWING CLASSES

CLASS	DESCRIPTION	PASS DATE
Class 2B	Motorcycles <= 200 cc	30 Apr 2003
Class 2A	Motorcycles between 201 cc and 400 cc	15 Jun 2004
Class 3	Motor Cars <= 3000kg with <= 7 passengers, exclusive of the driver, and other motor vehicles <= 2500kg	26 Jul 2005
Class 4	*Motor vehicles which are constructed to carry load or passengers and the unladen weight > 2500kg *Motor vehicles which are not constructed to carry load and the unladen weight < 7250kg	04 Dec 2007

NP 428A



Land Transport Authority

VOCATIONAL LICENCE
Licence No: S7925706J
Name: TAN ZHI HAO DARRICK
Issue Date: 3/5/2016
Please visit www.lta.gov.sg to check the status of this vocational licence



SHD1128T

PREMIER AUTOMOTIVE SERVICES PTE LTD

**23 Changi South Ave 2
#01-02, Singapore 486443**

Assessment Number: MSIG0017

Version: PREMIERA/1

Assessor Report

Printed: 07/06/2018

LKK Auto Consultants hereby notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature: TBA
Date:

Summary Information

Claim

Claim Reference: SHD1128T
 Policy Number:
 Date of Decision: 07/06/2018
 Repairer:
 Estimated Repair Time (Working Days): 0.0

Insured:
 Third Party:
 Able to Authorise Repairs: TBA
 Repairs Authorised? TBA

Insured's Liability

Excess: TBA
 Customer Contribution: \$0.00 (excl GST)

Vehicle Details

Vehicle

Registration: SHD1128T
 Manufacturer: HYUNDAI
 Registration Month: September
 Odometer: Not Known
 Build Date:
 Model Specs FROM 09/2016
 5-DOOR (HATCHBACK)
 PAINTING OFF VEHICLE
 BASECOAT CLEAR

VIN/Chassis Number:
 Model: i30
 Registration Year: 2016
 Colour:

Taufik 7749574
 WP
 8/7/18 @ 11:30
 Roxbury before paint -
 sun@lkkauto.com
 3 days
 13/6/18

Vehicle Condition

Vehicle Status

Date of Incident: 07/06/2018
 Pre-Accident Condition:
 Pre-Accident Damage:
 Steering Rim Ply:
 Brake Pedal Travel:
 Vehicle Status:
 Damage Severity:
 Market Value: Unknown
 Salvage Value: Unknown
 Date of Inspection: 07/06/2018
 Place of Inspection:

Tyres Condition:

Tread Depth LHF: Tread Depth RHF:
 Tread Depth LHR: Tread Depth RHR:

Repair Information

LABOUR		Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR Price/Dent = \$50.00/HR	
Repair / Guide Number	Repair Details	WU	Cost Price (\$)
86520R00	RENEW REAR BUMPER INCLUDES: BOTH OUTER REAR LAMPS, REINFORCED BUMPER AND REQUIRED TRIMS	4.0	20.00
2931	ASSEMBLE ATTACHED PARTS RENEW IF NECESSARY REPAIR BOOTLID/TAILGATE	20.0*	100.00
LABOUR COST			
Total Work Units		24.0	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0017

Version: PREMIERA/1

Assessor Report

Printed: 07/06/2018

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.4HRS	\$120.00
Paint Labour	4.3HRS	\$215.00
Total Labour	6.7HRS	\$335.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	
LABOUR COST - PAINT			
	TIME(PAINT)	29.0	
	Preparation Main Work Metal	9.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	43.0	
	Total Paintwork Labour	4.3HRS	\$215.00
MATERIAL COST - PAINT			Cost Price
	New Part Painting - Plastic K1R		\$65.44
	Repair Painting		\$26.16
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$118.70
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$118.70

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3406	1	R/R FOG LAMP	92406A5000	SHO.90	0%	107.50*
2626	1	R/R OUT BUMPER BRKT	86614A6000		0%	52.20*
2583	1	REAR BUMPER	86611A6000	86611	0%	811.11*
2640	1	REAR BUMPER SUPPORT	86631A6000		0%	815.64*
f: OEM Parts			Sub Total			\$1,786.45
g: Original			Deduction from RRP	(35 %)		-\$625.26
h: Secondhand			Total Parts			\$1,161.19
p: Parallel						
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	200 yw ✓ \$280.00
TAILGATE STICKER SPECIALIST		net ✓ \$100.00
REAR BUMPER CLIPS SPECIALIST	0% 48	net ✓ \$48.00
	Total Extras	\$428.00

Final Calculation

Total Parts	\$1,161.19
Labour	

PREMIER AUTOMOTIVE SERVICES PTE LTD

23 Changi South Ave 2

#01-02, Singapore 486443

Assessment Number: MSIG0017

Version: PREMIERA/1

Assessor Report

Printed: 07/06/2018

Total Panel/Mechanical	\$120.00	
Total Paintwork	\$215.00	
Total Labour		\$335.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$428.00	
Total of Additional Costs		\$428.00
Total Paint/Material Costs		\$118.70
Grand Total Excludes GST		\$2,042.89
GST @ 7 %		\$143.00
Grand Total Includes GST		\$2,185.89

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Preli Revised

Claim Reference: SHD1128T
Assessment Number: MSIG0017
Version: PREMIERA/1
Date Calculated: 11/06/2018 05:29

Full Report - V1
Registration: SHD1128T
Printed: 11/06/2018 12:29

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	07/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SHD1128T	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	i30
Sub Model:	BASE MODEL
Model Sheet Number:	3080 01
Registration:	SHD1128T
Registration Month:	September
Registration Year:	2016
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 09/2016	5-DOOR (HATCHBACK)
PAINTING OFF VEHICLE	BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	07/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$335.00
Total Paint/Material	\$118.70
Total Parts	\$1,161.19
Total of Additional Costs	\$348.00
Excess:	TBA
Grand Total Exc GST:	\$1,962.89
7 % GST:	\$137.40
Grand Total Inc GST:	\$2,100.29

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
Price/Dent = \$50.00/HR

Repair /

Guide Number	Repair Details	WU	Cost Price (\$)
86520R00	RENEW REAR BUMPER INCLUDES: BOTH OUTER REAR LAMPS, REINF BUMPER AND REQUIRED TRIMS	4.0	20.00
2931	ASSEMBLE ATTACHED PARTS RENEW IF NECESS REPAIR BOOTLID/TAILGATE	20.0*	100.00
LABOUR COST			
Total Work Units		24.0	
Corrosion Protection External Labour		0.0HRS	0.00
Corrosion Protection Internal Labour		0.0HRS	0.00
Sub Total		2.4HRS	\$120.00
Paint Labour		4.3HRS	\$215.00
Total Labour		6.7HRS	\$335.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	
LABOUR COST - PAINT			
TIME(PAINT)		29.0	
Preparation Main Work Metal		9.0	
Preparation Comp. Work Plastic		5.0	
Preparation Work Multi Layer Paint		0.0	
Total Work Units (10WU/HR)		43.0	
Total Paintwork Labour		4.3HRS	\$215.00

MATERIAL COST - PAINT

	Cost Price
New Part Painting - Plastic K1R	\$65.44
Repair Painting	\$26.16
Material-Const Main Work Metal	\$18.10
Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$118.70
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$118.70

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3406	1	R/R FOG LAMP	92406A5000		0%	107.50*
2626	1	R/R OUT BUMPER BRKT	86614A6000		0%	52.20*
2583	1	REAR BUMPER	86611A6000		0%	811.11*
2640	1	REAR BUMPER SUPPORT	86631A6000		0%	815.64*
f: OEM Parts			Sub Total			\$1,786.45
g: Original			Deduction from RRP (35 %)			-\$625.26
h: Secondhand			Total Parts			\$1,161.19
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$200.00
TAILGATE STICKER SPECIALIST		\$100.00
REAR BUMPER CLIPS SPECIALIST	0%	\$48.00
Total Extras		\$348.00

Final Calculation

Total Parts	\$1,161.19
Labour	
Total Panel/Mechanical	\$120.00
Total Paintwork	\$215.00
Total Labour	\$335.00
Additional Costs	
Corr Prot Materials External	\$0.00
Corr Prot Materials Internal	\$0.00
Cost of Specialist	\$348.00
Total of Additional Costs	\$348.00
Total Paint/Material Costs	\$118.70
Grand Total Excludes GST	\$1,962.89
GST @ 7 %	\$137.40
Grand Total Includes GST	\$2,100.29

Assessment Notes

5111 1/1

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0017
Version: PREMIERA/1

Assessor Report
Printed: 07/06/2018

Summary Information

Claim		
Claim Reference:	SHD1128T	Insured:
Policy Number:		Third Party:
Date of Decision:	07/06/2018	Able to Authorise Repairs:
Repairer:		Repairs Authorised?
Estimated Repair Time (Working Days):	0.0	TBA

Insured's Liability

Excess:	TBA
Customer Contribution:	\$0.00 (excl GST)

Vehicle Details

Vehicle			
Registration:	SHD1128T	VIN/Chassis Number:	
Manufacturer:	HYUNDAI	Model:	30
Registration Month:	September	Registration Year:	2016
Odometer:	Not Known	Colour:	
Build Date:			
Model Specs	FROM 09/2016 5-DOOR (HATCHBACK) PAINTING OFF VEHICLE BASECOAT CLEAR		

*Tan Jiah 974852
WP
8/7/16 @ 11:30
Examined before print
sent to Hilda.com
2/2/18*

Vehicle Condition

Vehicle Status			
Date of Incident:	07/06/2018	Market Value:	Unknown
Pre-Accident Condition:		Salvage Value:	Unknown
Pre-Accident Damage:		Date of Inspection:	07/06/2018
Steering Rim Ply:		Place of Inspection:	
Brake Pedal Travel:			
Vehicle Status:			
Damage Severity:			

Tyres Condition:			
Tread Depth LHF:		Tread Depth RHF:	
Tread Depth LHR:		Tread Depth RHR:	

Repair Information

LABOUR		Time Basis 10 WU = 1 HR.	Price/CL 1 = \$50.00/HR
			Price/Dent = \$50.00/HR
Repair / Guide Number	Repair Details	WU	Cost Price (\$)
86520R00	RENEW REAR BUMPER INCLUDES: BOTH OUTER REAR LAMPS, REINFORCED BUMPER AND REQUIRED TRIMS	4.0	20.00
2931	ASSEMBLE ATTACHED PARTS RENEW IF NECESSARY REPAIR BOOTLID/TAILGATE	20.0*	100.00
	LABOUR COST		
	Total Work Units	24.0	

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0017
 Version: PREMIERA/1

Assessor Report
 Printed: 07/06/2018

Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.4HRS	\$120.00
Paint Labour	4.3HRS	\$215.00
Total Labour	6.7HRS	\$335.00

PAINT WORK		Time Basis 10 WU = 1 HR. Price = \$50.00/HR	
Guide Number	Description	WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	
	LABOUR COST - PAINT		
	TIME(PAINT)	29.0	
	Preparation Main Work Metal	9.0	
	Preparation Comp. Work Plastic	5.0	
	Preparation Work Multi Layer Paint	0.0	
	Total Work Units (10WU/HR)	43.0	
	Total Paintwork Labour	4.3HRS	\$215.00
	MATERIAL COST - PAINT		Cost Price
	New Part Painting - Plastic K1R		\$65.44
	Repair Painting		\$26.16
	Material-Const Main Work Metal		\$18.10
	Material-Const Comp. Work Plastic		\$9.00
	Total Excluding Pearlescent Uplift		\$118.70
	Pearlescent Uplift @ 0.0%		\$0.00
	Total Paint Material Cost		\$118.70

PARTS

				Price Valid: 01/06/2015		
Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
1405	1	R/R FOG LAMP	92406A5000	970.01	0%	107.50 ✓
2626	1	R/R OUT BUMPER BRKT	86514A5000	- 35	0%	52.20 ✓
2583	1	REAR BUMPER	86511A5000	631.02	0%	811.11 ✓
2640	1	REAR BUMPER SUPPORT	86531A5000		0%	815.64 X
f: OEM Parts			Sub Total			\$1,786.45
g: Original			Deduction from RRP (35%)			-\$625.26
h: Secondhand			Total Parts			\$1,161.19
p: Parallel						
x: Exchange						

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$280.00 ✓
TAILGATE STICKER SPECIALIST	0%	\$100.00 ✓
REAR BUMPER CLIPS SPECIALIST	0%	\$48.00 ✓
Total Extras		\$428.00

Final Calculation

Total Parts	\$1,161.19
Labour	

PREMIER AUTOMOTIVE SERVICES PTE LTD
23 Changi South Ave 2
#01-02, Singapore 486443

Assessment Number: MSIG0017
Version: PREMIERA/1

Assessor Report
Printed: 07/06/2018

Total Panel/Mechanical	\$120.00	
Total Paintwork	\$215.00	
Total Labour		\$335.00 ✓
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$428.00	
Total of Additional Costs		\$428.00
Total Paint/Material Costs		\$118.70
Grand Total Excludes GST		\$2,042.89
GST @ 7 %		\$143.00
Grand Total Includes GST		\$2,185.89

Assessment Notes

51 Ubi Avenue 1, #01-25
Paya Ubi Industrial Park
Singapore
408933

Finalised

Claim Reference: SHD1128T
Assessment Number: MSIG0017
Version: LKKAUTOC/3
Date Calculated: 03/07/2018 02:05

Full Report - V1
Registration: SHD1128T
Printed: 03/07/2018 09:05

Summary Information

Claim

Location:	Singapore (SG)	Currency:	SGD
Printed by:	LKK AUTO	Date of Incident:	07/06/2018
Authorisation Status:	Interim	Able to Authorise Repairs:	TBA
Work Provider:	MSIG Insurance (Singapore) Pte	Repairs Authorised:	TBA
Claim Reference:	SHD1128T	Estimated Repair Time:	
Policy Number:		Quote Due Date:	
Other Reference:	LKK	Actual Repair Days:	
Third Party:		Parts Ordered Date:	
Insured Amount:		Hire Car Start:	
Under Warranty:		Hire Car End:	
Warranty Expired:		Vehicle Collected:	

Vehicle Details

Vehicle

Manufacturer:	HYUNDAI
Model:	i30
Sub Model:	BASE MODEL
Model Sheet Number:	3080 01
Registration:	SHD1128T
Registration Month:	September
Registration Year:	2016
VIN Number:	
Odometer:	Not Known
Colour:	
Engine Number:	
Fuel Level:	%



Model Specs

FROM 09/2016	5-DOOR (HATCHBACK)
PAINTING OFF VEHICLE	BASECOAT CLEAR

Vehicle Condition

Vehicle Status

Pre-Accident Condition:	Severity of Impact:	
Steering:	Vehicle Status on Inspection:	
Brakes Pedal Travel:	Date of Inspection:	07/06/2018
Place of Inspection:		
Pre-Accident Damage:		
Tyres Condition:	Tread Depth RHF:	
Tread Depth LHF:	Tread Depth RHR:	
Tread Depth LHR:	Direction of Impact:	
Damage Areas:		



Addresses

Cost Summary

Total Labour	\$335.00
Total Paint/Material	\$118.70
Total Parts	\$631.03
Total of Additional Costs	\$348.00
Excess:	TBA
Grand Total Exc GST:	\$1,432.73
7 % GST:	\$100.29
Grand Total Inc GST:	\$1,533.02

Repair Information

LABOUR

Time Basis 10 WU = 1 HR. Price/CL 1 = \$50.00/HR
 Price/Dent = \$50.00/HR

Repair /

Guide Number Repair Details

		WU	Cost Price (\$)
NN	REAR BUMPER R&R / NEW PARTS	4.0*	20.00
2931	REPAIR BOOTLID/TAILGATE	20.0*	100.00

LABOUR COST

Total Work Units	24.0	
Corrosion Protection External Labour	0.0HRS	0.00
Corrosion Protection Internal Labour	0.0HRS	0.00
Sub Total	2.4HRS	\$120.00
Paint Labour	4.3HRS	\$215.00
Total Labour	6.7HRS	\$335.00

PAINT WORK

Time Basis 10 WU = 1 HR. Price = \$50.00/HR

Guide Number Description

		WU	Cost Price (\$)
	- PAINTING OFF VEHICLE		
	- BASECOAT CLEAR		
2583	REAR BUMPER NEW PART PAINT K1R	13.0	
2931	BOOTLID/TAILGATE REPAIR PAINTING <50%	16.0	

LABOUR COST - PAINT

TIME(PAINT)	29.0	
Preparation Main Work Metal	9.0	
Preparation Comp. Work Plastic	5.0	
Preparation Work Multi Layer Paint	0.0	
Total Work Units (10WU/HR)	43.0	
Total Paintwork Labour	4.3HRS	\$215.00

MATERIAL COST - PAINT

New Part Painting - Plastic K1R	\$65.44
Repair Painting	\$26.16
Material-Const Main Work Metal	\$18.10

Material-Const Comp. Work Plastic	\$9.00
Total Excluding Pearlescent Uplift	\$118.70
Pearlescent Uplift @ 0.0%	\$0.00
Total Paint Material Cost	\$118.70

PARTS

Guide No.	Qty	Description	Part Number	Supplier	Bet.	Price (\$)
3406	1	R/R FOG LAMP	92406A5000		0%	107.50*
2626	1	R/R OUT BUMPER BRKT	86614A6000		0%	52.20*
2583	1	REAR BUMPER	86611A6000		0%	811.11*
f: OEM Parts					Sub Total	\$970.81
g: Original					Deduction from RRP (35 %)	-\$339.78
h: Secondhand					Total Parts	\$631.03
p: Parallel						
x: Exchange						

Price Valid: 01/06/2015

NB - COLOUR CODED ITEMS/TRIM - PART NUMBERS MAY DIFFER

Extras

Description	Betterment	Price
REVERSE SENSOR SPECIALIST	0%	\$200.00
TAILGATE STICKER SPECIALIST		\$100.00
REAR BUMPER CLIPS SPECIALIST	0%	\$48.00
Total Extras		\$348.00

Final Calculation

Total Parts		\$631.03
Labour		
Total Panel/Mechanical	\$120.00	
Total Paintwork	\$215.00	
Total Labour		\$335.00
Additional Costs		
Corr Prot Materials External	\$0.00	
Corr Prot Materials Internal	\$0.00	
Cost of Specialist	\$348.00	
Total of Additional Costs		\$348.00
Total Paint/Material Costs		\$118.70
Total of Additional Costs		\$1,432.73
Grand Total Excludes GST		\$100.29
GST @ 7 %		\$1,533.02
Grand Total Includes GST		\$1,533.02

Assessment Notes

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	07 Jun 2018		08 Jun 2018 09:25 Edit Adj Rpt	S\$1,432.73 Edit Estimates	S\$1,432.73 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All
----------------------	---------------------------	-------------------------------	---------------------------	--------------------------

CLAIM SUBFOLDER DETAILS		[Created by insurer]
Insured:	LING HANG LIANG, ID: S0643608J, Tel: +6597260240	
Main Claimant:	PREMIER TAXI PTE LTD, Co. Reg. No.: 200304975H	
Vehicle Reg. No.:	SHD1128T	Date of Loss: 07/06/2018 00:00 - :59 [20 Months and 17 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 560603	Policy/Cover Note No.: 29070686QMX (Comprehensive) Coverage: 03/02/2018 - 02/02/2019
Vehicle Reg. No. (Insured):	SBK1655Y	Policy No. (Claimant):
		Excess:
Repairer:	Komoco Motors - (alexandra) (HQ) 253 Alexandra Road, 159936 Alexandra - Tel:	
Handling Insurer:	MSIG Insurance (Singapore) Pte. Ltd. (HQ) - Tel: +65 6827 7888 ... [Handled by Chhia Nyuk Pui - 6594 2521]	
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 08/07/2018]	
Driver/Custodian (Insured):	LING HANG LIANG (72 / Male), NRIC: S0643608J, Tel: +6597260240	
Adj Asg. Remarks:	on WP. Third Party Pre-Repair Survey. TP nominated LKK to survey, please arrange. Liability clear.	

ASSOCIATED MAIL RECEIVED	View All	Compose Case Mail
There are no mail for this case.		

ALL ASSOCIATED TASKS										View All	Search Tasks	Create New Task	Complete
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?				
No results.													

Claim Documents

***SHD1128T (560603)**
[SBK1655Y]
TP
PREMIER TAXI PTE LTD
Jun 7 2018 12:00AM
[LING HANG LIANG]
Komoco Motors - (alexandra)

Upload Documents			Upload Photos			Compose New Letter			View	View in Browser
Assessment Reports									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/06/18 12:42	Adjuster Immediate Advice		Load HTM						
Photos/Images									3 per page	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)		Thumbnail	Print					
1	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
2	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
3	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
4	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
5	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
6	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
7	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
8	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
9	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
10	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
11	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
12	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
13	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
14	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
15	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
16	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
17	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
18	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
19	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
20	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
21	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
22	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
23	11/06/18 09:52	General View		Load JPG	<input checked="" type="checkbox"/>					
24	02/07/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
25	02/07/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
26	02/07/18 11:13	Reinspection Photo		Load JPG	<input checked="" type="checkbox"/>					
Documentation									1 per page	<input checked="" type="checkbox"/>
No	Finalized On	MSIG Insurance (Singapore) Pte. Ltd. (HQ)		Thumbnail	Print					
1	07/06/18 16:24	E-FILE REPORT (SHD1128T)		Load PDF						
2	07/06/18 16:32	E-FILE REPORT (SBK1655Y)		Load PDF						
3	07/06/18 16:33	TP PRI & ACCDT REPORT		Load PDF						
4	07/06/18 17:06	EMAIL TP ON OUR AGREED COMMON NOMINATED SJE - LKK		Load PDF						

Documents Checklist

DOCUMENTS CHECKLIST	Reset	Save	Print
There are no document checklists configured.			

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)
<div style="border: 1px solid black; height: 40px; width: 100%;"></div>
Show Remarks To: <input type="checkbox"/> Handling Insurer
<small>Note: Remarks are private unless you show it to other parties.</small>

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS/MSG18010460/T1VD3E2

Date: 10/07/2018

REFERENCE

Handling Insurer: MSIG Insurance (Singapore) Pte. Ltd.	Policy No: 29070686QMX
Claimant Vehicle No : SHD1128T	Insured Vehicle No : SBK1655Y
Date of Loss: 07/06/2018	Nature of Claim: TP
	Claim No: 560603

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: SHD1128T			
Make & Model: HYUNDAI I30 GDH, 1.6 D TCI 5DR DCT (M)	Engine No: D4FBGZ105473		
Reg. Date: 21/09/2016 (Man. Year: 2016)	Chassis No: TMAD281UVHJ121486		
Colour: Silver	Odometer: 105020 km		
Engine Capacity: 1582 cc			
Market Value/New Car Price: N/A			
Sum Insured (S\$): Market Value/New Car Price			

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	Maxxis 6 mm	Rear Left Side:	Maxxis 6 mm
Front Right Side:	Maxxis 6 mm	Rear Right Side:	Maxxis 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	1,589.19	979.03	610.16	38.39
Miscellaneous Items	0.00	0.00	0.00	
Labour	453.70	453.70	0.00	0.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	2,042.89	1,432.73	610.16	29.87
+ GST 7.00/7.00% (S\$)	143.00	100.29	42.71	29.87
Nett Amount (S\$)	2,185.89	1,533.02	652.87	29.87

INSPECTION

Date of Assignment:	08/06/2018		
Date Inspected:	08/06/2018	Inspected At:	Komoco Motors - (alexandra) (HQ) 253 Alexandra Road Singapore 159936

Estimated Period of Repair: 3.0 days

Adjuster: MOHD TAUFIKH BIN HAMID**Manager:** VERON CHEN

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference	
Part Source:	(Last Synchronised: 09 Jul 2018)
Parts:	N/A HYUNDAI I30 GDH 1.6 D TCI 5DR DCT (M) (Model not available in database)
Labour:	Repairer's (Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SHD1128T)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount	
1	1		*R/R FOG LAMP	Cracked	107.50 FL	*107.50 FL	
2	1		*R/R OUT BUMPER BRKT	Deformed	52.20 FL	*52.20 FL	
3	1		*REAR BUMPER	Deformed	811.11 FL	*811.11 FL	
4	1		*REAR BUMPER SUPPORT	Serviceable	815.64 FL	*- FL	
5	1		*REVERSE SENSOR	Not Working	280.00 FS	*200.00 FS	
6	1		*TAILGATE STICKER	Necessary	100.00 FS	*100.00 FS	
7	1		*REAR BUMPER CLIPS	Necessary	48.00 FS	*48.00 FS	
					Sub Total (S\$)	2,214.45	1,318.81
					- List Item Discount on L Items 35.00/35.00% (S\$)	625.26	339.78
					Total Parts (S\$)	1,589.19	979.03

F=Franchise part. S=SpcNett. L=ListItemDisc.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TOTAL PANEL / MECHANICAL	New	120.00	120.00
2	TOTAL PAINTWORK	New	215.00	215.00
3	TOTAL PAINT / MATERIAL COSTS	New	118.70	118.70
			Gross Labour Cost (S\$)	453.70
				453.70

Report was unsubmitted during this print-out.

< END OF ESTIMATES >