

源摩哆廠 GUAN MOTOR WORKS

Business Regn. No: 08102600E

176 Sin Ming Drive #02-03 Sin Ming Autocare Singapore 575721 Tel: 6453 6111 Fax: 6453 8292 H/P: 9742 6003

CHUA HUP KIAT ELECTRICAL & AIR CONDITIONING ENGINE

07-06-2018

REPAIR ESTIMATE FOR TOYOTA HIACE – GT 7227 D

1 pc.	Tail gate	<i>Pullway</i> 1,185.00	✓
1 pc.	Tail gate inner lock	<i>R</i> 209.00	X
1 pc.	LH Rear lamp assy	<i>CMA</i> 298.40	✓
1 pc.	Rear bumper fascia	<i>Bu</i> 354.50	✓
1 pc.	Rear bumper beam	<i>DII</i> 232.00	✓
1 pc.	Rear end panel - outer	<i>Bu</i> 377.90	✓
1 pc.	Rear end panel - inner	402.20	?
		\$ 3,059.00	
Less 25%		764.75	
		\$ 2,294.25	

1.	Check electrical wirings	40.00	<i>201</i>
2.	Repair damages & renew parts	700.00	<i>6001</i>
3.	Spray paint on affected portions	800.00	<i>4501</i>
		\$ 3,834.25	

Not Authorized
L1 Lng 8?
Resurvey After Paint
3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date: