COMFORTDELGRO ENGINEERING PTE LTD

REPAIR ESTIMATE*

VEHICLE NO: SHA 7419E

4XA

DATE 6/7/2018 12:06

MAKE

: · HVIINDAI i40

Fauzy

Qty	: HYUNDAI i40 Parts Description/ Labour	Type	Unit Price		Amount
χ.,	Rocker Panel Outer Garnish (RH)			\$	483.60
				\$	150.70
	Kear Wheel Hup-Cap (Kir)				
	Peur Bunger SUB TOTAL			\$	634.30
	per ly fee at x 1900 SUBTOTAL LESS 20%			\$	126.86
	Rear Wheel Hup-Cap (RH) Rew Bunger & regult Per RH Fee do x regult SUB TOTAL LESS 20% DISCOUNTED TOTAL			\$	507.44
	DISCOUNTED TOTAL				307.44
	Rear Bumper Rubber Mat			\$	50.00
	Rear Door Comfortdelgro & Apps Sticker (LH/Rff)	. /		\$	80.00
	The Deer commence of the production (2015)				
				\$	130.00
	Labour Charge				200
	Panel Beating (Repair Rear RH Fender / Door)			\$	500.00
	Spray Painting Charge			\$	500.00 1,000.00 120.00
	Remove/Refix Reverse Sensor			\$	120.00
	Rear Wheel Alignment			\$	120.00
	TOTAL LABOUR			\$	1,740.00
	ESTIMATE TOTAL		- notify	\$	2,377.44
	ESTIMATE TOTAL LKK Auto the Repa To resure To displat Parts po To displat No illes Supply is sub	Consultants h	euce non.	\ 	2,377.44
	Vala ///(C) the Repa	Consultants rer of the folk ey before/after st y damaged park	pray painting	V	
	o To resurv	y damaged pant y damaged pant ices are subject adv survey is of	oray painting oray during resurvey oconfirmation oray(thout Prejudice" basis	1	
	Malifel 1503 kg. Parts P			Λ	
	o Third D	arty survey is on gal modification(s) mentary item(s)	is allowed must be resurveyed <u>and</u> oval from Insurance Company	11	
	2 PS	ementary item(s)	must be resurveyed and must be resurveyed company and from Insurance Company		
	is su	ject to Illian of	iraf	1	
	US , Ackno	wiledged by Rep	31161		
	Sign	ature.			
	Affe Report plas Sign Date	:			
	////				
	This is an initial estimate based on a visual inspection of th	e above veh	icle The final renair	nuant	um will
	be prepared after the vehicle is surveyed by a motor Survey				