

ASS. REC. BY:

REF: es/FCI18010503/ R1 v d3 | n2
Special Instruction:Surveyor: RCSU ASSIGNMENT (Office)CWS
From (Person): Eileen Lee of FCI Date/Time: 8/6/18 @ 2:59pm

Estimated Cost: Bill to:

OD ☒ TP / WS / TP RES / OD RES / EVA / INV / MV / CSTo Inspect Vehicle No: XE 1648P Insured: SHA 1618Lat Workshop m/s Tan chong Industrial Tel: 9787 9034of 23 jalan BurohPolicy No: Claim No: D18003874MF84

Sum Insured: Excess:

Make of Veh: D.O.A. 12/05/2018
(Client's Record) 11/06/2018CA / REV / REP. / REV 24 HRS ^{up} H.O.D. Endorsement:Date/Time: 3:21pm @ 8/6/18 Person Contacted: Alfred Vehicle ☒ IN / OUT

Date/Time	Action/Instruction (✓) Estimate
	<u>XE 1648P-X</u>
	<u>SHA 1618 L-CC3/EQ/7023567/K1wb3q2</u> D.O.A: <u>8/12/2017</u>
<u>14/6/18</u>	<u>Email preli revised to FCI</u>
<u>13/7/18</u>	<u>@ 306pm Alfred will email us finalise</u>
<u>13/7/18</u>	<u>Final fig \$ 9247.87 confirmed by email (Ref 1782.59, 16/7)</u>

Rasul

REF: FCL

ASSIGNMENT

From: Date: 11.06.2018

Estimated Cost:

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: XE 1648P

at Workshop m/s Tan Chong

of 23 Jin Buroh

Insured:

Policy No:

Claims No:

Sum Insured:

Excess:

(Client's Record)

Make of Veh: Alfred - 9787 9034

(Policy Condition)

Remark: The veh had commenced its repair at the time of inspection.



Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val: Yes or No

CA / REV / REP. / 24 HRS

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: XE 1648P Yr Regn: 2016 / APR

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: 110 trucks 6KBSSE C.C. 10837

Colour: GREEN A/C: Insured / Std / NI / NA

Sp. Reading: 114415 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JNCMIF1A364007210

Gen. Cond: Good / Fair / Poor / Burnt

Steering: In order / Jammed / Leaked / Burnt or

Brake: In order / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 11R22.5

R:

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or FIRENZA

Front

Rear

R/Bal. 8 mm R/Bal. 8/8 mm

L/Bal. 8 mm L/Bal. 8/8 mm

D.O.A. 12/05/18 D.O.I. 12/06/18

Survey held at TAN CHONG

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S & REAR O/S

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 17 JUL 2018

Signature
16/7/2018

Date/Time, File Pass to?

☐

: Preli. Report

1)

☐

: Final Report

Date/Time, File Return to?

2)

16/7- typist

Report Format: CWS

Lump Sum / L.B.I. (\$) 9247.87

Days Of Repair: 6

Resurvey No. of Trip: 1

Add Fee: ☐ Site Insp (\$)

☐ Interview (\$)

☐ Tech. Invs (\$)

☐ Weekend (\$)

Survey Fee:

Transportation

1 S + RS \$

Photos

Other's

TOTAL

170+15

50

50

109

394



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010503/R1vd3	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 08-06-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1618L	Veh. Inspected	XE 1648P	
Policy No.		Coverage (\$)	0.00	
Claim No.	D18003874MFSH	Excess (\$)	0.00	
Assign From	CWS (EILEEN LEE)	Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model		c.c	0	
Engine No.	HIDDEN	Year of Reg.		
Chassis No.		Colour		
Odometer	-	Steering		
Brakes		Modification		
General				
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre			mm	
L/H Front Tyre			mm	
R/H Rear Tyre			mm	
L/H Rear Tyre			mm	
4. Description of Damages				
5. General Information				
Accident Date	12/05/2018	Inspection Date		
Survey held at	TAN CHONG IND MACHINERY PTE LTD 23 JALAN BUROH SINGAPORE 619479			
5a. Remarks				
A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				



Auto
Consultants
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your ref: D18003874MFSH
Our Ref: CS/FCI18010503/R1vd3

Date : 14/6/2018

The Motor Claims Department
M/s FIRST CAPITAL INSURANCE LTD

Dear Sir/Madam,

PRELIMINARY ADVICE OF VEHICLE NO. XE 1648P


We thank you for your instruction on 8/6/2018

Please be informed that we had conducted the inspection of the above mentioned
12/6/2018 at the premises of M/s TAN CHONG IND MACHINERY PTE LTD
and have the following to report:-

Workshop Estimate Amount	: S\$10,555.29
Revised Estimate Amount	: S\$8,772.70
"Check" Items Amount	: S\$
Market Value	: S\$
LTA Reimbursement Value	: S\$
Nett Value	: S\$

Description of Damage:

The vehicle sustained damages at the
front n/s portion and front o/s portion



Comments/Present Status:
Damages Consistent

Yours faithfully,

MOHAMMED RASUL
Automotive Assessor

MOTOR SURVEY ASSIGNMENT

Date	15-05-2018	Our Ref No. D18003874MFSH
Accident Date	12-05-2018	Claim Type. Third Party
Insured Vehicle	SHA1618L	Third Party Vehicle. XE1648P
Survey Location	23 JALAN BUROH	
Contact Person.	ALFRED LEE	
Contact No.	67038755/ 97879034	Fax No. 62665862
Survey Type	WITHOUT PREJUDICE: LIABILITY UNCLEAR:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

FOR DIRECT SETTLEMENT

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

THIRD PARTY SURVEY REQUEST

Cc : Workshop	TAN CHONG INDUSTRIAL MACHINERY PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	EILEEN LEE	

IMPORTANT NOTE

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/240359)



PRI Documents



Close



PRI Header Details

Claim No	D18003874MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & TAN CHOI PTE LTD
Workshop Name	TAN CHONG INDUSTRIAL MACHINERY PTE LTD (Contact Person : ALFRED LEE)	Survey Location & Contact Details	23 JALAN BUROH Mobile: 97879034 , Phone: 67038755 , Fax: 6266586; EmailId: ALFRED_LEE@TANCHONG.COM		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: LIABILITY UNCLEAR:		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHA1618L	TP Vehicle No	XE1648P
PRI Recieved Date	07-06-2018 12:10:32 PM	Surveyor Appointed Date	08-06-2018 02:58:41 PM	Surveyor Accept Date	08-06-2018 0

Survey Report Upload

Surveyor Inspection Date *:		Surveyor Report Date	08-06-2018	Upload Survey Report *:	Choose File
------------------------------------	----------------------	-----------------------------	------------	--------------------------------	--

Vehicle Particulars

Make	Please Select Make	Model	Please Select Model	Year	Select Year
Chasis No		Engine No		Mileage	
Color		Cubic Capacity			

Multiple Documents Upload

File Name

Action

Surveyor Job Remarks

Remarks

Veron Chen (LKKAUTO)

From: Veron Chen (LKKAUTO)
Sent: Friday, 13 July 2018 3:38 PM
To: 'Alfred Lee'; SUR
Subject: RE: Finalise repair cost for XE1648P.

Dear Alfred,

WITHOUT PREJUDICE

Confirmed amount \$9247.87 before GST @ 6 working days.

Final invoice and all supporting documents sent over to First Capital Ins Ltd.

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Alfred Lee [mailto:alfred_lee@tanchong.com]
Sent: Friday, 13 July 2018 3:15 PM
To: SUR <sur@lkkauto.com>
Subject: Finalise repair cost for XE1648P.

Dear Yvonne,

As spoken over the phone, Kindly refer to the attached for the finalise repair cost for XE1648P. Please contact me at 97879034 for any questions.

Regards,

Alfred Lee

Tan Chong Industrial Machinery Pte Ltd

*DID : 6703 8755

Veron Chen (LKKAuto)

From: Veron Chen (LKKAuto)
Sent: Thursday, 14 June 2018 2:46 PM
To: 'Claim Workflow System'
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR
Subject: RE: SURVEY ASSESSMENT - D18003874MFSH/1, XE 1648P
Attachments: XE 1648P PRELI ADVISED.pdf

Dear Sir/Madam,

Enclosed preliminary revised of vehicle XE 1648P
Date of survey: 12/6/2018
Number of days :6 days

Best Regards,

Veron Chen | Case Handler

LKK Auto Consultants Pte Ltd

Phone: 6256-3561 | email :sur@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Admin-D (LKKAuto)
Sent: Friday, 8 June 2018 3:28 PM
To: 'Claim Workflow System' <cwsmotorclaims@msfirstcapital.com.sg>; assignments <assignments@lkkauto.com>
Cc: EILEENLEE@MSFIRSTCAPITAL.COM.SG; SUR <sur@lkkauto.com>
Subject: RE: SURVEY ASSESSMENT - D18003874MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

LKK Auto Consultants Pte Ltd

Phone: 6841-1972 | email: assignments@lkkauto.com | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Claim Workflow System [<mailto:cwsmotorclaims@msfirstcapital.com.sg>]
Sent: Friday, 8 June 2018 2:58 PM
To: ASSIGNMENTS@LKKAUTO.COM
Cc: CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG; EILEENLEE@MSFIRSTCAPITAL.COM.SG
Subject: PRI: SURVEY ASSESSMENT - D18003874MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,
Admin Team
Claim Workflow System
Motor Claims Department
MS First Capital Insurance Limited
Tel : 6507 3848
Fax : 6507 3849

PS: This is a system generated mail. Please do not reply to this mail.

> [Back to OneMotoring](#)

Enquire Transfer Fee

Vehicle Details			
Vehicle No. :	XE1648P		
Vehicle Type :	B36 - Goods (Open) Prime Mover		
Vehicle Attachment 1 :	No Attachment		
Vehicle Scheme :	Normal		
Vehicle Make :	UD TRUCKS		
Vehicle Model :	GKB5ELDHNT ESCOT V		
Chassis No. :	JNCM1F1A3GU007210		
Propellant :	Diesel		
Engine No. :	GH11735168		
Engine Capacity :	10837 cc		
Maximum Power Output :	-		
Maximum Laden Weight :	55000 kg		
Unladen Weight :	6780 kg		
Year Of Manufacture :	2016		
Original Registration Date :	21 Apr 2016		
Lifespan Expiry Date :	20 Apr 2036		
COE Category :	C - Goods Vehicle & Bus		
PQP Paid :	\$4,600.00		
COE Expiry Date :	20 Apr 2026		
Road Tax Expiry Date :	20 Oct 2018		
Inspection Due Date :	20 Apr 2019		
Intended Transfer Date :	13 Jun 2018		
CO2 Emission :	-		
CO Emission :	-		
HC Emission :	-		
NOx Emission :	-		
PM Emission :	-		
Late renewal fee(s) will be imposed if road tax / lay up has expired. Please use Enquire Road Tax Payable for fee(s) payable.			
Road tax, including Over Payment (if any), of a vehicle will follow the vehicle to the new registered owner when its ownership is being transferred.			
Amount Payable			
	Amount Before GST (S\$)	GST Amount (S\$)	Amount After GST (S\$)
Transfer Fee :	25.00	-	25.00
Total Amount Payable :			25.00
Message			
This vehicle has a road tax Over Payment of \$1,696.00. This Over Payment may be used to offset Road Tax payable and Transfer Fees respectively, where applicable.			

You may print this page for reference.

OK

Print

TAN CHONG INDUSTRIAL MACHINERY PTE LTD

23 JALAN BURUH

SINGAPORE 619479

TEL:67038755 FAX:62665862

LKK Auto Consultants hence notify
the Repairer of the following:

- To resurvey before/after spray painting
- ~~04 Jun-18~~ aged part(s) during resurvey
- Parts prices are subject to confirmation
- ~~AL/1648-010/0618~~ Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

From ALFRED LEE

Date

To FIRST CAPITAL INSURANCE LIMITED

Our ref

Attn MOTOR CLAIM DEPT

Tel
Fax

VEH NO : XE1648P

Model :

Acknowledged by Repairer

Signature: GKB5ELDHNT

Date:

GH11735168

Chassis : JNCM1F1A3GU007210

Eng No :

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :

Claim type: DIRECT SETTLEMENT

Description	Qty	Unit Price		Amount
LH CORNER LWR GRANISH	1	\$ 122.66	NETT	\$ 122.66 DE ✓
LH BUMPER GRILLE (OUTER)	1	\$ 95.65	25%	\$ 71.74 CR ✓
LH HEADLAMP ASSY	1	\$ 924.80	NETT	\$ 924.80 BRO ✓
LH FOG LAMP ASSY	1	\$ 252.19	NETT	\$ 252.19 BRO ✓
LH SIGNAL LAMP	1	\$ 44.40	NETT	\$ 44.40 BRO ✓
LH BUMPER SIDE	1	\$ 39.07	NETT	\$ 39.07 DE ✓
BUMPER CENTER	1	\$ 779.22	NETT	\$ 779.22 BT ✓
BUMPER REINFORCEMENT	1	\$ 996.71	25%	\$ 747.53 BT ✓
LH BUMPER ASSY	1	\$ 649.35	NETT	\$ 649.35 BT ✓
LH LOWER STEEL STEP	1	\$ 142.08	NETT	\$ 142.08 CR Repair ✓
LH CORNER PANEL	1	\$ 327.86	25%	\$ 245.90 CR ✓
RH BUMPER ASSY	1	\$ 649.35	NETT	\$ 649.35 BT ✓
RH HEADLAMP ASSY	1	\$ 924.80	NETT	\$ 924.80 CR ✓
RH FOG LAMP ASSY	1	\$ 252.19	NETT	\$ 252.19 CR ✓
RH SIGNAL LAMP	1	\$ 44.40	NETT	\$ 44.40 CR ✓
RH BUMPER STEP LH	1	\$ 42.62	NETT	\$ 42.62 DE ✓
FRONT PANEL ASSY	1	\$ 820.51	NETT	\$ 820.51 Repair ✓
LID GRILLE	1	\$ 452.88	NETT	\$ 452.88 CR ✓
LOWER GRILLE	1	\$ 399.60	NETT	\$ 399.60 CR ✓

Estimated parts cost \$ 7,605.29

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

TO REPLACE RH BUMPER ASSY, CENTER BUMPER, REINFORCEMENT, RH LOWER STEP GRANISH, STEEL STEP HEADLAMP ASSY, FOG LAMPS, SIGNAL LAMPS. TO JACK AND REALIGN CABIN ALIGNMENT. TO REPLACE TILT BRACKET, LH AND RH ASSY TO JACK AND REALIGN RH STEP PANEL AND STEP HANGER.

Estimated labour cost

EST. LABOUR & PARTS COST

\$

550.00

450 ✓

\$

2,400.00

(5 DAYS)

1680 ✓

\$

2,950.00

\$

10,555.29

11,030.46

1. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only.

Thank you and regards

ALFRED LEE
Marketing Executive
Service Department

DID : 67038755
HP: 97879034



TAN CHONG INDUSTRIAL MACHINERY PTE LTD
23 JALAN BUROH
SINGAPORE 619479
TEL: 67038755 FAX: 62665862

From ALFRED LEE
To FIRST CAPITAL INSURANCE LIMITED
Attn MOTOR CLAIM DEPT

Date 04-Jun-18
Our ref AL/1648-010/0618
Tel
Fax

VEH NO : XE1648P

Model : GKB5ELDHNT

Chassis : JNCM1F1A3GU007210

Eng No : GH11735168

1. The above vehicle was inspected by TCIM and append here under is the estimated repair cost :
Claim type: DIRECT SETTLEMENT

Description	Qty	Unit Price		Amount
LH CORNER LWR GRANISH	1	\$ 122.66	NETT	\$ 122.66 DE
LH BUMPER GRILLE (OUTER)	1	\$ 95.65	25%	\$ 71.74 CA
LH HEADLAMP ASSY	1	\$ 924.80	NETT	\$ 924.80 BRO
LH FOG LAMP ASSY	1	\$ 252.19	NETT	\$ 252.19 BRO
LH SIGNAL LAMP	1	\$ 44.40	NETT	\$ 44.40 BRO
LH BUMPER SIDE	1	\$ 39.07	NETT	\$ 39.07 DE
BUMPER CENTER	1	\$ 779.22	NETT	\$ 779.22 BT
BUMPER REINFORCEMENT	1	\$ 996.71	25%	\$ 747.53 BT
LH BUMPER ASSY	1	\$ 649.35	NETT	\$ 649.35 BT
LH LOWER-STEEL STEP	1	\$ 142.08	NETT	\$ 142.08 CA Repair
LH CORNER PANEL	1	\$ 327.86	25%	\$ 245.90 CA
RH BUMPER ASSY	1	\$ 649.35	NETT	\$ 649.35 BT
RH HEADLAMP ASSY	1	\$ 924.80	NETT	\$ 924.80 CA
RH FOG LAMP ASSY	1	\$ 252.19	NETT	\$ 252.19 CA
RH SIGNAL LAMP	1	\$ 44.40	NETT	\$ 44.40 CA
RH BUMPER STEP LH	1	\$ 42.62	NETT	\$ 42.62 DE
FRONT-PANEL ASSY	1	\$ 820.51	NETT	\$ 820.51 Repair
LID GRILLE	1	\$ 452.88	NETT	\$ 452.88 CA
LOWER GRILLE	1	\$ 399.60	NETT	\$ 399.60 CA

Estimated parts cost

\$ 7,605.29

Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

TO REPLACE RH BUMPER ASSY, CENTER BUMPER, REINFORCEMENT, RH LOWER STEP GRANISH, STEEL STEP HEADLAMP ASSY, FOG LAMPS, SIGNAL LAMPS.
TO JACK AND REALIGN CABIN ALIGNMENT.
TO REPLACE TILT BRACKET, LH AND RH ASSY
TO JACK AND REALIGN RH STEP PANEL AND STEP HANGER.

Estimated labour cost

\$ 2,950.00

EST. LABOUR & PARTS COST


\$ 10,555.29

1. All prices quoted are subjected to 7% GST. The above quotation is based on initial visual inspection only.

Thank you and regards

ALFRED LEE
Marketing Executive
Service Department

DID : 67038755
HP: 97879034





TAN CHONG INDUSTRIAL MACHINERY PTE LTD
23 JALAN BUROH
SINGAPORE 619479
TEL:6622287 FAX:62665862

From ALFRED LEE Date 14-Jun-18
To FIRST CAPITAL INSURANCE LIMITED Our ref AL/1648-011/0618
Attn MOTOR CLAIM DEPT Tel
Fax

VEH NO : XE1648P

Model : GKB5ELDHNT

Chassis : JNCM1F1A3GU007210

Eng No : GH11735168

SUPPLEMENTRY REPAIRS

Description	Qty	Unit Price		Amount
LH STEP COVER - UPPER	1	\$ 321.56	25%	\$ 241.17 <i>Ch</i>
STEP COVER LOWER	1	\$ 294.00	25%	\$ 220.50 <i>Ch</i>
COVER	1	\$ 18.00	NETT	\$ 13.50 <i>Ch</i>

Estimated parts cost \$ 475.17

Labour cost

TO REPLACE ABOVE MENTION ITEMS

Estimated labour cost

FOC

EST. LABOUR & PARTS COST


\$ 475.17

1. All prices quoted are subjected to 7% GST.

Thank you and regards

ALFRED LEE
Marketing Executive
Service Department

DID : 67038755
HP: 97879034



**TAN CHONG INDUSTRIAL MACHINERY PTE LTD**

23 JALAN BUROH

SINGAPORE 619479

TEL: 67038755 FAX: 62665862

From **ALFRED LEE**Date **28-Jun-18**To **FIRST CAPITAL INSURANCE LIMITED**Our ref **AL/1648-011/0618**Attn **MOTOR CLAIM DEPT**Tel
Fax

VEH NO : XE1648P

Model : **GKB5ELDHNT**

Chassis : JNCM1F1A3GU007210

Eng No : **GH11735168**

We are please to finalise the repair cost as follows

Claim type: **DIRECT SETTLEMENT**

Description	Qty	Unit Price	Amount
LH CORNER LWR GRANISH	1	\$ 122.66	NETT \$ 122.66
LH BUMPER GRILLE (OUTER)	1	\$ 95.65	25% \$ 71.74
LH HEADLAMP ASSY	1	\$ 924.80	NETT \$ 924.80
LH FOG LAMP ASSY	1	\$ 252.19	NETT \$ 252.19
LH SIGNAL LAMP	1	\$ 44.40	NETT \$ 44.40
LH BUMPER SIDE	1	\$ 39.07	NETT \$ 39.07
BUMPER CENTER	1	\$ 779.22	NETT \$ 779.22
BUMPER REINFORCEMENT	1	\$ 996.71	25% \$ 747.53
LH BUMPER ASSY	1	\$ 649.35	NETT \$ 649.35
LH CORNER PANEL	1	\$ 327.86	25% \$ 245.90
RH BUMPER ASSY	1	\$ 649.35	NETT \$ 649.35
RH HEADLAMP ASSY	1	\$ 924.80	NETT \$ 924.80
RH FOG LAMP ASSY	1	\$ 252.19	NETT \$ 252.19
RH SIGNAL LAMP	1	\$ 44.40	NETT \$ 44.40
LH BUMPER STEP	1	\$ 42.62	NETT \$ 42.62
LID GRILLE	1	\$ 452.88	NETT \$ 452.88
LOWER GRILLE	1	\$ 399.60	NETT \$ 399.60

Estimated parts cost \$ 6,642.70Labour cost

To putty/primer application and spray painting including touch-up affected areas with polyurethane paint.

\$ 450.00

TO REPLACE RH BUMPER ASSY, CENTER BUMPER, REINFORCEMENT, RH LOWER STEP GRANISH, STEEL STEP HEADLAMP ASSY, FOG LAMPS, SIGNAL LAMPS.
TO JACK AND REALIGN CABIN ALIGNMENT.
TO REPLACE TILT BRACKET, LH AND RH ASSY
TO JACK AND REALIGN RH STEP PANEL AND STEP HANGER.

\$ 1,680.00

Estimated labour cost \$ 2,130.00SUPPLEMENTRY REPAIRS

Description	Qty	Unit Price	Amount
RH STEP COVER - UPPER	1	\$ 321.56	25% \$ 241.17
STEP COVER LOWER	1	\$ 294.00	25% \$ 220.50
COVER	1	\$ 18.00	NETT \$ 13.50

Estimated parts cost \$ 475.17**EST. LABOUR & PARTS COST**\$ 9,247.87

1. All prices quoted are subjected to 7% GST.

Thank you and regards

ALFRED LEE
Marketing Executive
Service DepartmentDID : 67038755
HP: 97879034

claiming L.O.U 6 days: \$150 x 6 = \$900/-



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile				
FIRST CAPITAL INSURANCE LTD			Ref : CS/FCI18010503/R1vd3n2	
36 ROBINSON ROAD #16-01 CITY HOUSESINGAPORE 068877			Date : 18-07-2018	
			Code : FCI2	
1. Policy Particulars :- THIRD PARTY CLAIM				
Insured Veh.	SHA 1618L	Veh. Inspected	XE 1648P	
Policy No.	D-18088936MFSH	Coverage (\$)	0.00	
Claim No.	D18003874MFSH	Excess (\$)	0.00	
Assign From	EILEEN	Assign Date	08/06/2018	
2. Vehicle Particulars & Condition				
Make & Model	UD TRUCKS GKB5E	c.c	10837	
Engine No.	HIDDEN	Year of Reg.	2016	
Chassis No.	JNCM1F1A3GU007210	Colour	GREEN	
Odometer	114415	Steering	IN ORDER	
Brakes	IN ORDER	Modification	NIL	
General	FAIR			
3. Conditions of Tyres				
	Size	Make	Balance	
R/H Front Tyre	11 R22.5	FIRENZA	8 mm	
L/H Front Tyre	11 R22.5	FIRENZA	8 mm	
R/H Rear Tyre	11 R22.5 (D)	FIRENZA	8/8 mm	
L/H Rear Tyre	11 R22.5 (D)	FIRENZA	8/8 mm	
4. Description of Damages				
THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND FRONT O/S PORTION. DAMAGES SEE DETAILS.				
5. General Information				
Accident Date	12/05/2018	Inspection Date	12/06/2018	
Survey held at	TAN CHONG IND MACHINERY PTE LTD 23 JALAN BUROH SINGAPORE 619479			
5a. Remarks				
A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.				
5b. Estimate Days of Repair				
ESTIMATED NORMAL PERIOD FOR REPAIR:		6 Working Days		



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. XE 1648P

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
REPLACEMENT OF PARTS				
1	LH CORNER LWR GARNISH (SN)	DEFORMED	122.66	122.66
1	LH BUMPER GRILLE (OUTER)(SN)	CRACKED	71.74	71.74
1	LH HEADLAMP ASSY (SN)	BROKEN	924.80	924.80
1	LH FOG LAMP ASSY (SN)	BROKEN	252.19	252.19
1	LH SIGNAL LAMP (SN)	BROKEN	44.40	44.40
1	LH BUMPER SIDE (SN)	DEFORMED	39.07	39.07
1	BUMPER CENTER (SN)	BENT	779.22	779.22
1	BUMPER REINFORCEMENT (SN)	BENT	747.53	747.53
1	LH BUMPER ASSY (SN)	BENT	649.35	649.35
1	LH LOWER STEEL STEP (SN)	TO REPAIR SEE LABOUR	142.08	-
1	LH CORNER PANEL (SN)	CRACKED	245.90	245.90
1	RH BUMPER ASSY (SN)	BENT	649.35	649.35
1	RH HEADLAMP ASSY (SN)	CRACKED	924.80	924.80
1	RH FOG LAMP ASSY (SN)	CRACKED	252.19	252.19
1	RH SIGNAL LAMP (SN)	CRACKED	44.40	44.40
1	RH BUMPER STEP LH (SN)	DEFORMED	42.62	42.62
1	FRONT PANEL ASSY (SN)	TO REPAIR SEE LABOUR	820.51	-
1	LID GRILLE (SN)	CRACKED	452.88	452.88
1	LOWER GRILLE (SN)	CRACKED	399.60	399.60
1	LH STEP COVER-UPPER (ADDITIONAL)(SN)	CRACKED	241.17	241.17
1	STEP COVER LOWER (ADDITIONAL)(SN)	CRACKED	220.50	220.50
1	COVER (ADDITIONAL)(SN)	CRACKED	13.50	13.50
			8,080.46	7,117.87
LABOUR				
TO PUTTY/PRIMER APPLICATION AND SPRAY PAINTING INCLUDING TOUCH-UP AFFECTED AREAS WITH POLYURETHANE PAINT.			550.00	450.00



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.: 2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO REPLACE RH BUMPER ASSY,CENTER BUMPER,REINFORCEMENT,RH LOWER STEP GARNISH,STEEL STEP HEADLAMP ASSY,FOG LAMPS,SIGNAL LAMPS,TO JACK AND REALIGN CABIN ALIGNMENT.TO REPLACE TILT BRACKET,LH AND RH ASSY.TO JACK AND REALIGN RH STEP PANEL AND STEP HANGER.INCLUSIVE OF THE REPAIR OF LH LOWER STEEL STEP AND FRONT PANEL ASSY.		2,400.00	1,680.00
			2,950.00	2,130.00
	GRAND TOTAL		11,030.46	9,247.87
	RECOMMENDED COST OF REPAIRS			9,247.87

Report Ref No. CS/FCI18010503/R1vd3n2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.