

22/03/2002

ASS. REC. BY:

REF:

CS/FCI18010570/Ned3

Special Instruction:

Surveyor

CWS

ASSIGNMENT (Office)

From (Person): May chua

of

FCI

Date/Time:

11/6/18 @ 8:38am

Estimated Cost:

Bill to:

OD / ~~TP~~ WS / TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLR 5043G

Insured:

SHC 8390K

at Workshop m/s

N-51 Automotive

Tel:

68420051

of

2 Kaki Bkt Ave 2 # 01-18

Policy No:

Claim No:

D18004607MFSH

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

07/06/2018

CA / REV / REP. / REV 24 HRS <sup>1wp</sup>

H.O.D. Endorsement:

Date/Time:

9:22am @ 11/6/18

Person Contacted:

Vehicle ~~IN~~ OUT

Date/Time	Action/Instruction	(4) Estimate
	SLR 5043G -X	
	SHC 8390K - CS3 / FCI15019816 / Tlgbd1	DOA: 18/11/2015
12/05/18	@ 09:58 a.m. revised PA to May chua via email.	
	Confirmed 2/5 \$5,600/- @ 5 days with Naz & Adrian,	
	Adrian on Behalf marking estimate & finalize with Yong (Repairer).	
	( \$ 4 700 on 01/11/18 )	

## ASSIGNMENT

From: \_\_\_\_\_ Date: \_\_\_\_\_

Estimated Cost: \_\_\_\_\_

OD / TP / WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: \_\_\_\_\_

at Workshop no: \_\_\_\_\_

of \_\_\_\_\_

Insured: \_\_\_\_\_

Policy No. \_\_\_\_\_

Claims No. \_\_\_\_\_

Sum Insured: \_\_\_\_\_

Excess: \_\_\_\_\_

(Client's Record)

Make of Veh: \_\_\_\_\_

(Policy Condition)

Remark: The veh had commenced its  
repair at the time of inspection.

N/S	O/S

Bal. or Market Value: \_\_\_\_\_

IDAC Accident Rpt: \_\_\_\_\_ Consistent? : Yes or No

GIA / PR Seen: \_\_\_\_\_ Consistent? : Yes or No

Est. Repairs: \_\_\_\_\_ days Res.: Yes or No

Lum Sum: \_\_\_\_\_ % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS

Date: \_\_\_\_\_ Person Contacted: \_\_\_\_\_

Vehicle: IN / OUT

Veh No: SLR 50436

Page: 17 AUG 2017

Type: M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: HONDA VEZEL

Colour: BROWN

Sp. Reading: \_\_\_\_\_

Eng No: \_\_\_\_\_

C.No: RU3 1234471

Gen. Cond: Good / Fair / Poor / Burnt

Steering: Inorder / Jammed / Leaked / Burnt or

Brake: Inorder / Jammed / Leaked / Burnt or

Modi: Nil / S/Rim / STD A/Rim or

Tyre Size: F: 215/60 R16

R: 11

BS / DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /  
TOYO / YOKO or

Front

Rear

R/Bal. 6 mm

R/Bal. 6 mm

L/Bal. 6 mm

L/Bal. 6 mm

D.O.A. \_\_\_\_\_

D.O.I. 11/6/18

Survey held at NSI

Des. of Damages: Frt / Rear / O/S / N/S / U/C / Rooftop or

FRONT N/S, N/S FRONT

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

RECEIVED 12 SEP 2010

Date/Time File Pass to:

12/09/18

Type: \_\_\_\_\_

Date/Time File Return to:

☐

: Preli. Report

☒

: Final Report

Days Of Repair: 5

Resurvey No. of Trip: 1

Add Fee:

☐

: Site Insp : \$

☐

: Inter. S : \$

☐

: Tech. S : \$

☐

: Measure S : \$

Survey Fee

Transducer

S-P-S

Photo

Chart

170

50

50

60

330

Report Format:

Lump Sum / I.B. : \$ 5,600/- 4/5

84820051

**MOTOR SURVEY ASSIGNMENT**

Date	08-06-2018	Our Ref No. D18004607MFSH
Accident Date	07-06-2018	Claim Type. Third Party
Insured Vehicle	SHC8390K	Third Party Vehicle. SLR5043G
Survey Location	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB	
Contact Person.	MELODY CHIN	
Contact No.	68420051/ 0	Fax No. 67410510
Survey Type	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM TO BE AGREED:	
Appointed Surveyor	LKK AUTO CONSULTANTS PTE LTD	
Contact Person	NA	Fax No. 68416315
Contact Number.	NA	

**FOR DIRECT SETTLEMENT**

Please submit to us the Tax Invoice together with letter of claim for Rental OR Loss of use (based on NIMA Benchmark rates) together with your survey report.

**THIRD PARTY SURVEY REQUEST**

Cc : Workshop	N-51 AUTOMOTIVE PTE LTD	Attention. NIL
Cc : TP Solicitor	NA	TP Solicitor Fax No. NA
Officer Incharge	MAY CHUA	

**IMPORTANT NOTE**

Kindly submit the survey report via CWS within 14 days for survey assignment and 7 days for re-inspection.  
This is a computer generated letter, no signature required.

Job Sheet (/ClaimWS/Surveyor/JobSheet/241285)



PRI Documents



Close



## PRI Header Details

Claim No	D18004607MFSH	Policy No	D-18088936MFSH	Claimant S.No & Name	1 & N-51 AUT
Workshop Name	N-51 AUTOMOTIVE PTE LTD (Contact Person : MELODY CHIN)	Survey Location & Contact Details	2 KAKI BUKIT AVENUE 2 #01-18 KAKI BUKIT AUTOHUB Mobile: 0 , Phone: 68420051 , Fax: 67410510 EmailId: HUIXIN@N51.COM.SG		
Our Surveyor	LKK AUTO CONSULTANTS PTE LTD	Instructions To Surveyor	WITHOUT PREJUDICE: WE ADMIT LIABILITY QUANTUM		
Insured Name	COMFORT TRANSPORTATION PTE LTD	Insured Vehicle No	SHC8390K	TP Vehicle No	SLR5043G
PRI Recieved Date	08-06-2018 07:37:11 PM	Surveyor Appointed Date	11-06-2018 08:36:48 AM	Surveyor Accept Date	11-06-2018 1

## Survey Report Upload

Surveyor Inspection Date *:	<input type="text"/>	Surveyor Report Date	11-06-2018	Upload Survey Report *:	<input type="button" value="Choose File"/>
-----------------------------	----------------------	----------------------	------------	-------------------------	--

## Vehicle Particulars

Make	<input type="text" value="Please Select Make"/>	Model	<input type="text" value="Please Select Model"/>	Year	<input type="text" value="Select Year"/>
Chasis No	<input type="text"/>	Engine No	<input type="text"/>	Mileage	<input type="text"/>
Color	<input type="text"/>	Cubic Capacity	<input type="text"/>		

## Multiple Documents Upload

File Name

Action

## Surveyor Job Remarks

Remarks

## Shirley Hiew (LKK Auto)

---

**From:** Shirley Hiew (LKK Auto) <ShirleyHiew@lkkauto.com>  
**Sent:** Wednesday, 12 September 2018 9:58 AM  
**To:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; 'Claim Workflow System'  
**Cc:** "SUR"; 'Nivitha (LKK Auto)'; ASSIGNMENTS@LKKAUTO.COM  
**Subject:** RE: SURVEY ASSESSMENT - D18004607MFSH/1  
**Attachments:** SLR 5043G - Preli Advise.pdf

Dear May,

Enclosed herewith preliminary advice of SLR 5043G.

Thank you.

Best Regards,

Shirley Hiew | Case Handler

**LKK Auto Consultants Pte Ltd**

Phone: 6256-3561 | email: [Sur@lkkauto.com](mailto:Sur@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Nivitha (LKK Auto) [mailto:[admin-d@lkkauto.com](mailto:admin-d@lkkauto.com)]  
**Sent:** Monday, 11 June 2018 10:00 AM  
**To:** 'Claim Workflow System' <[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)>; ASSIGNMENTS@LKKAUTO.COM  
**Cc:** MAYCHUA@MSFIRSTCAPITAL.COM.SG; "SUR" <[sur@lkkauto.com](mailto:sur@lkkauto.com)>  
**Subject:** RE: SURVEY ASSESSMENT - D18004607MFSH/1

Dear Sir/Mdm,

Thank you for the assignment.

BEST REGARDS,

G.Nivitha | Admin

**LKK Auto Consultants Pte Ltd**

Phone: 6841-1972 | email: [assignments@lkkauto.com](mailto:assignments@lkkauto.com) | fax: 6256-4315

Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

---

**From:** Claim Workflow System [mailto:[cwsmotorclaims@msfirstcapital.com.sg](mailto:cwsmotorclaims@msfirstcapital.com.sg)]  
**Sent:** Monday, 11 June 2018 8:37 AM  
**To:** [ASSIGNMENTS@LKKAUTO.COM](mailto:ASSIGNMENTS@LKKAUTO.COM)  
**Cc:** [CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG](mailto:CWSMOTORCLAIMS@MSFIRSTCAPITAL.COM.SG); [MAYCHUA@MSFIRSTCAPITAL.COM.SG](mailto:MAYCHUA@MSFIRSTCAPITAL.COM.SG)  
**Subject:** PRI: SURVEY ASSESSMENT - D18004607MFSH/1

Dear Sir/Mdm,

We refer to the above reference.

Please find attached the necessary documents for survey.

Kindly submit your report via CWS within the next 14 days.

Best Regards,

Admin Team

Claim Workflow System

Motor Claims Department  
MS First Capital Insurance Limited  
Tel : 6507 3848  
Fax : 6507 3849

**PS: This is a system generated mail. Please do not reply to this mail.**



Auto  
Consultants  
Pte Ltd

Company Registration No. 199607198R

51 UBI AVE 1, #02-25 PAYA UBI INDUSTRIAL PARK, SINGAPORE 408933 TEL : (065) 62563561 FAX : (065) 62564315

Your Ref: D18004607MFSH

Date: 12 September 2018

Our Ref: CS/FCI18010570/Nsd3

The Motor Claims Department  
First Capital Insurance Ltd

Dear Sir/Madam,


**INITIAL INSPECTION REPORT OF VEHICLE NO. SLR 5043G .**

Please be informed that we had conducted the inspection of the abovementioned vehicle on 11/06/2018 at the premises of M/s N-51 Automotive Pte Ltd and have the following to report:-

Workshop Estimate Amount	: S\$ <u>10,350.00</u> .
Revised Estimate Amount (Lump Sum)	: S\$ <u>5,600.00</u> .
"Check" Items Amount	: S\$ _____ .
Market Value	: S\$ _____ .
LTA Reimbursement Value	: S\$ _____ .
Nett Value	: S\$ _____ .

**Description of Damage:**

The vehicle sustained damages at the front n/s & n/s front portion.



**Comments/ Present Status:**

Damages Consistent.

Repair days: 5 Days

Yours faithfully,  
Muhammad Nazril  
Automotive Assessor

## SINGAPORE ACCIDENT STATEMENT

### IMPORTANT NOTICE

1. Please report correctly the details of the accident to speed up the claims process.
2. This Form must be completed by the Policyholder and/or the Authorised Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy ability.
4. The issue and acceptance of this Form by insurance companies is not an admission of policy liability on the part of the insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. This report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will, for a fee, be made available upon application by interested parties.
7. By the lodgement of this report to the insurers, you hereby consent to the archiving of this report at the centre and to copies of the report being made available aforesaid.

### ACCIDENT STATEMENT

Date Of Report	08/06/2018 15:31
Date Of Accident	07/06/2018 14:55
Exact Location Of Accident	JUNC OF YISHUN AVE 7 AND AVE 8
Country/State of Loss	SINGAPORE

### DETAILS OF OWN VEHICLE

Vehicle Registration Number	SLR5043G
<b>Insured/Policyholder</b>	
Name Of Registered Owner	GRAB RENTALS PTE LTD
Co Reg No	201617200G
Email Address	NOEMAIL
Mobile Phone No	(LOCAL) +65-96603709
Alternative Phone No	OFFICE-96603709
<b>Vehicle Particulars</b>	
Manufacturer	HONDA
Model	VEZEL
Exact Purpose for which vehicle was being used at time of accident	HIRE AND REWARD
Are you claiming under your own insurance policy for repair to your vehicle?	NO
If No, Please state action to be taken	THIRD PARTY
Vehicle Category	PRIVATE HIRE
<b>Insurance Company</b>	
Name of Insurance Company	MSIG INSURANCE (SINGAPORE) PTE. LTD.
Type Of Coverage	COMPREHENSIVE
Fleet Policy	NO
Policy Number	A29069766MKF
Cover Note Number	
<b>Driver</b>	
Name of Driver	SALLEH BIN AMIR
NRIC No	S1161792A
Date Of Birth	30/07/1956
Occupation	OUTDOOR
Date Of Driving Pass	09/12/1980
Driving Experience	37 YEARS AND 5 MONTHS
Gender	MALE
Mobile Number	(LOCAL) +65-96603709
Fax Number	
Contact Number	
Email Address	NOEMAIL

Address	NA
Postcode	
Was driver an employee of the Insured's Company	NO
If No, Relationship of the Driver with the Insured	OTHER - HIRER
Vehicle Registration Number of Driver's Own Vehicle	-
	-
Insurance Company of Driver's Own Vehicle	-
	-
	-

#### General Information of the Accident

Type Of Accident	SIDE SWIPE
Weather Conditions	CLEAR
Road Surface	DRY

#### Other Information

Was any foreign vehicle involved in this accident?	NO
Number of vehicles involved in the accident	
Was any body injured in the Accident?	NO
Was any injured conveyed to hospital by ambulance?	NO
Was any other material or property damaged?	YES
I have been approached by unknown person(s) soliciting/offering accident claims assistance.	NO
Number of Passengers (Including Driver)	3
Passenger 1	NAME: : P1 GENDER: : MALE
Passenger 2	NAME: : P2 GENDER: : FEMALE

#### Details of Police Action

Was the accident reported to the police?	NO
If Yes, Please state which Police Station	
Was notice of intended Prosecution given?	NO
If Yes, against whom?	

#### Circumstances of Accident

ON THE DATE AND TIME MENTIONED, I WAS DRIVING AT THE SAID LOCATION, AND WHEN WAS MAKING A RIGHT TURN IN TO YISHUN AVE 8. ON THE EXTREME RIGHT LANE, VEHICLE B, COMING FROM MY LEFT, CUT IN TO MY PATH AND COLLIDED ON TO THE POINT LEFT PORTION OF MY VEHICLE. THIS INCIDENT WAS CAPTURED BY THE IN-CAR VIDEO WATCH WAS SUBMITTED TO THE N51 WORKSHOP. THE DRIVER OF VEHICLE B, DID NOT GIVE HIS PARTICULARS AND I WAS ADVISED BY HIM TO LODGE A REPORT. STATEMENT WAS READ TO ME AND I ACKNOWLEDGE IT. Upon collision, vehicle was pushed and the right rear wheel went up the curb.

#### Attachment(s)

Are accident photos available for attachment?	YES
Was there any video captured by Car Camera?	YES
Remarks/ Reasons:	YES-RETRIEVING
Was there any audio recorded?	NO

#### DETAILS OF OTHER VEHICLE PROPERTY 1

Vehicle Registration Number	SHC8390K
Vehicle Make/Model/Colour	HYUNDAI/I40/BLUE
Details Of Properties	
Vehicle Category	TAXI
Name of Driver	UNKNOWN DRIVER
NRIC/Passport Number	

1

### Sketch Plan

1. You must correctly state the details of the accident to speed up the claims process.
2. Your form must be completed by the Policyholder and/or the Authorized Driver.
3. Information provided must be as truthful and accurate as possible. Any willful misrepresentation or withholding of material facts may allow insurance companies to repudiate policy liability.
4. The issue and acceptance of this form by insurance companies is not an admission of policy liability on the part of insurance companies.
5. Any false reporting may be referred to the Police for investigation.
6. The report will be forwarded by the insurers of the GIA Records Management Centre established by the General Insurance Association of Singapore (GIA) for archiving and that copies of this report will for a fee be made available application by a identified parties.
7. By the submission of this report to the insurers, you hereby consent to the archiving of this report and to copies of the report being made available aforesaid.
8. Consent under the Personal Data Protection Act (PDPA)
- (I understand, acknowledge, agree and consent that:
- (a) My insurer, my workshop and the General Insurance Association of Singapore ("GIA") may/are permitted to collect, use, disclose and/or process my personal data/personal information set out in this form) and any other personal information provided by me or possessed by my insurer (collectively the "Personal Information") and disclose and transfer such Personal Information to all Insurers) who have insured vehicle(s) involved in this accident (all Insurers) who have insured vehicle(s) involved in this accident shall be collectively referred to as the "Insurers"; the Insurers' lawyers/law firms, the Monetary Authority of Singapore and any relevant government agency/authority (such as the police, for the purpose(s) of:
- (i) processing, handling and/or dealing with my claims including the settlement of the claims and any necessary investigations relating to the claims;
- (ii) investigating the accident and/or my claims;
- (iii) carrying out and/or dealing with my instructions or responding to any enquiries by me;
- (iv) administering my claims (including the making of correspondence, statements, invoices, reports or notices to me, which could involve disclosure of certain personal data about me to bring about delivery of the same as well as on the external cover of envelopes/mail packages) and/or
- (v) complying with applicable law in administering, processing, handling and/or dealing with my claims.
- (collectively the "Purposes")
- (b) all Insurer(s) who have insured vehicle(s) involved in this accident and the Insurers' lawyers/law firms, may/are permitted to collect, use, disclose and/or process my Personal Information for one or more of the above Purposes; and
- (c) my Personal Information may/can be disclosed by any of the Insurers and/or GIA to their third party service providers or agents (including their lawyers/law firms), which may be situated outside of Singapore, for one or more of the above Purposes.


VARIFIED BY  
MARS AGENT  
HASHIM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date &amp; Time \_\_\_\_\_

Witnessed by Reporting Centre  
Personnel:                     

### Sketch Plan



## Describe Circumstances of the Accident

ON THE DATE & TIME MENTIONED I WAS DRIVING AT THE SHIP JUNCTION, AND WHEN I WAS MAKING A RIGHT TURN INTO YUSMIN AVE 8, ON THE EXTREME RIGHT LANE, VEHICLE B, COMING FROM MY LEFT, CUT INTO MY PATH AND COLLIDED ON TO THE FRONT LEFT PORTION OF MY VEHICLE. THIS INCIDENT WAS CAPTURED BY THE IN-CAR VIDEO WHICH WAS SUBMITTED TO THE NSI WORKSHOP. THE DRIVER OF VEHICLE B, DID NOT GIVE HIS PARTICULARS & I WAS ASKED BY HIM TO LOGIC. A REPORT.

STATEMENT WAS READ TO ME & I ACKNOWLEDGED IT.

slw  
X

## Declaration:

I/We declare the foregoing particulars are true in every respect.

X slw

VARIFIED BY  
MARS AGENT  
HASHIM

Policyholder's Signature / Date & Time

Driver's Signature (if driver is not the policyholder) / Date & Time

Witnessed by Reporting Officer  
Personal


Elizabeth Lee

---

**From:** Chin Hui Xin <huixin@n51.com.sg>  
**Sent:** Monday, 11 June 2018 5:18 PM  
**To:** group@ajaxmars.com  
**Subject:** Fwd: SLR5043G ACCIENT ON 07/06/2018 @ 14:55HRS ALONG JUNC OF YISHUN AVE 7 AND AVE 8  
**Attachments:** WhatsApp Image 2018-06-08 at 4.44.48 PM.jpeg; WhatsApp Image 2018-06-08 at 4.44.49 PM (1).jpeg; WhatsApp Image 2018-06-08 at 4.44.49 PM.jpeg

Upon collision, vehicle was pushed and the right rear wheel went up the curb.

Regards,  
Melody Chin  
N-51 Automotive Pte Ltd  
Office : 6842 0051  
Fax : 6741 0510  
[www.n51.com.sg](http://www.n51.com.sg)



----- Forwarded message -----

**From:** Chin Hui Xin <huixin@n51.com.sg>  
**Date:** Fri, Jun 8, 2018 at 5:13 PM  
**Subject:** Fwd: SLR5043G ACCIENT ON 07/06/2018 @ 14:55HRS ALONG JUNC OF YISHUN AVE 7 AND AVE 8  
**To:** [group@ajaxmars.com](mailto:group@ajaxmars.com)

Upon collision, vehicle was pushed and the right rear wheel went up the curb.

Regards,  
Melody Chin  
N-51 Automotive Pte Ltd  
Office : 6842 0051

Kaki Bukit AutoHub  
 2 Kaki Bukit Ave 2  
 #01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
 Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
 E-Mail : sales@n51.com.sg  
 Company Reg. No. : 200616038C  
 GST Registration No. : 200616038C

Naz. Lik

Attn: Yang, Huixin

TP 1st Cop

Shirley

GRAB RENTALS PTE LTD  
 18 SIN MING LANE #01-08 MIDVIEW CITY  
 SINGAPORE 573960

Contact : 66550005 96603709

## ESTIMATE

Repair Code : CLM14576

Date in : 07/06/2018

Vehicle Num. : SLR5043G

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31234471/LEB5934485

## Parts and Labour Assesment

Description of part	Qty	Unit Price	Amount
FRONT BUMPER	1	801.00 <i>scrub</i>	801.00
FRONT BUMPER LH FOG LAMP	1	275.00 <i>broken</i>	275.00
FRONT BUMPER LH FOG LAMP COVER	1	45.00 <i>broken</i>	45.00
FRONT BUMPER LOWER GARNISH	1	433.00 <i>scrub</i>	433.00
FRONT BUMPER SIDE RETAINER L/R	2	25.00 <i>nt</i>	50.00
FRONT LH ABS SENSOR	1	165.00 <i>X nt</i>	<del>165.00</del> <i>X</i>
FRONT LH FENDER	1	387.00 <i>dnt</i>	387.00
FRONT LH FENDER 'HYBRID' EMBLEM	1	95.00 <i>nt</i>	95.00
FRONT LH FENDER ARCH GARNISH	1	187.00 <i>scrub</i>	187.00
FRONT LH FENDER INNER SHIELD	1	125.00 <i>defam</i>	125.00
FRONT LH HEADLAMP	1	1785.00 <i>crack</i>	1,785.00
FRONT LH HEADLAMP LOWER BRACKET	1	35.00 <i>crack</i>	35.00
FRONT LH HEADLAMP SIDE BRACKET	1	25.00 <i>X nt</i>	<del>25.00</del> <i>X</i>
FRONT LH KNUCKLE ARM	1	245.00 <i>mnt</i>	245.00
FRONT LH KNUCKLE ARM BEARING	1	135.00 <i>nt</i>	135.00
FRONT LH LINKAGE	1	55.00 <i>X nt</i>	<del>55.00</del> <i>X</i>
FRONT LH LOWER ARM	1	371.00 <i>mnt</i>	371.00
FRONT LH LOWER BALL JOINT	1	98.00 <i>mnt</i>	98.00

5,067

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub

2 Kaki Bukit Ave 2

#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27

Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510

E-Mail : sales@n51.com.sg

Company Reg. No. : 200616038C

GST Registration No. : 200616038C

GRAB RENTALS PTE LTD

18 SIN MING LANE #01-08 MIDVIEW CITY

SINGAPORE 573960

Contact : 66550005 96603709

## ESTIMATE

Repair Code : CLM14576

Date in : 07/06/2018

Vehicle Num. : SLR5043G

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31234471/LEB5934485

FRONT LH SHOCK ABSORBER	7215	1	301.00	4 / unit	301.00
FRONT LH SHOCK ABSORBER RUBBER	5772	1	55.00	X Svc	55.00
FRONT LH SHOCK ABSORBER SPONGE		1	30.00	X Svc	30.00
FRONT LH SHOCK ABSORBER TOP MOUNTING		1	45.00	X Svc	45.00
FRONT LH SPORT RIM		1	813.00	813.00	813.00
* FRONT LH STEERING TIE ROD		1	89.00	4 / unit	89.00 X Svc
* FRONT LH STEERING TIE ROD END		1	72.00	2 / unit	72.00 X Svc
FRONT LH WHEEL HUB		1	221.00	2 / unit	221.00
* FRONT UPPER GRILLE		1 - 8627.2	351.00	X Svc	351.00 X Svc
* FRONT UPPER GRILLE 'H' LOGO EMBLEM		2 / 1 = 160540	25.00	X Svc	25.00 X Svc
REAR RH SPORT RIM		1 # 64 21.60	813.00	813.00	813.00
* REAR RH WHEEL BEARING		1	275.00	X Svc	275.00 X Svc
Subtotal before discount					8,402.00
Percentage discount 20%					1,680.40
Sub-total 1					6,721.60
FRONT BUMPER CLIPS - SET		1	50.00	ml.	50.00 30
* FRONT GRILLE CLIPS - SET		1	30.00	X Svc	30.00 X Svc
FRONT LH FENDER ARCH GARNISH CLIPS - SET		1	50.00	ml.	50.00 20

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

# N-51 AUTOMOTIVE PTE LTD

Kaki Bukit AutoHub  
2 Kaki Bukit Ave 2  
#01-17 / #01-18 / Heavy Vehicle #01-08 / Spray Painting #02-27  
Singapore 417921 Tel No. : +65 6842 0051 Fax No. : +65 6741 0510  
E-Mail : sales@n51.com.sg  
Company Reg. No. : 200616038C  
GST Registration No. : 200616038C

GRAB RENTALS PTE LTD  
18 SIN MING LANE #01-08 MIDVIEW CITY  
SINGAPORE 573960

Contact : 66550005 96603709

**LKK Auto Consultants** hereby notify  
the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

## ESTIMATE

Repair Code : CLM14576

Date in : 07/06/2018

Vehicle Num. : SLR5043G

Model : HONDA VEZEL 1.5X HYBRID AT ABS D/AIRBAG 2WD

Chassis/Eng# : RU31234471/LEB5934485

FRONT LH FENDER INNER SHIELD CLIPS - SET	1	50.00	✓	50.00	30
FRONT LH TYRE	1	300.00	✓	300.00	✓
REAR RH TYRE	1	300.00	✓	300.00	✓
Subtotal before discount				80	780.00
Percentage discount 0%					0.00
Sub-total 2					780.00
Parts-total					7,501.60

## LABOUR

To remove, reinstall electrical wiring harness, check lighting. (to FR)

To remove, change front suspension parts, absorber, lower arm, knuckle arm, wheel bearing, bearing hub, drive shaft, anti-roll bar, top-arm and steering rack and pinion.

To road test driving, check and resetting wheel alignments system.

To re-spray painting on the change bodyparts, repair portion, and where consistent to the accident.

To provide labour, workmanship to change the above damaged bodyparts, repair, re-construct and re-align body structure, body alignments and damaged consistent to the accident.

To apply anti-rust chemical on repaired and replaced panel.

Labour Total 1,100 1,910.00  
Parts & Labour Total 9,411.60

\*\*\* This is a computer-generated document which requires no signature.\*\*\*

total 7052  
h/s: 5.6K

5.6K



GST Registration No. : 200616038C

Singapore 573960

Chassis/Eng#: RU31234471/LEB5934485

Contact: 66550005 96603709

## SUPPLEMENTARY ITEMS

No	Description Of Parts		Qty	Unit Price	Amount
1	Steering Rack & Pinion <del>1000</del> 1000	L	1	\$ 1,173.00	\$ 1,173.00
	1000				
	Sub total before discount:				\$ 1,173.00
	Percentage discount 20%:				\$ 234.60
	Sub-total :				\$ 938.40
	Parts Total:				\$ 938.40

No. of Repair Days: 5

enclosed. W.

2/11 10pm @ 7600.00

Date:



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

### Affiliated to Federation Internationale Des Experts En Automobile

FIRST CAPITAL INSURANCE LTD

Ref : CS/FCI18010570/Nsd3e2

36 ROBINSON ROAD  
#16-01 CITY HOUSESINGAPORE 068877

Date : 13-09-2018



Code : FCI2

### 1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	SHC 8390K	Veh. Inspected	SLR 5043G
Policy No.	D-18088936MFSH	Coverage (\$)	0.00
Claim No.	D18004607MFSH	Excess (\$)	0.00
Assign From	MAY CHUA	Assign Date	11/06/2018

### 2. Vehicle Particulars & Condition

Make & Model	HONDA VEZEL	c.c	1496
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	RU31234471	Colour	BROWN
Odometer	-	Steering	IN ORDER
Brakes	IN ORDER	Modification	STANDARD ALLOY RIM
General	FAIR		

### 3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	215/60 R16	DUNLOP	6 mm
L/H Front Tyre	215/60 R16	DUNLOP	6 mm
R/H Rear Tyre	215/60 R16	DUNLOP	6 mm
L/H Rear Tyre	215/60 R16	DUNLOP	6 mm

### 4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE FRONT N/S AND N/S FRONT PORTION. DAMAGES SEE DETAILS.
---

### 5. General Information

Accident Date	07/06/2018	Inspection Date	11/06/2018
Survey held at	N-51 AUTOMOTIVE PL 2 KAKI BUKIT AVE 2 #01-17 KAKI BUKIT AUTOHUB SINGAPORE 417921		

### 5a. Remarks

A) DAMAGES CONSISTENT TO ACCIDENT REPORT. B) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. C) IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.
--

### 5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR:	5 Working Days
-------------------------------------	----------------

**LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

**ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLR 5043G**

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
1	FRONT BUMPER	SCRATCHED	801.00	801.00
1	FRONT BUMPER LH FOGLAMP	BROKEN	275.00	275.00
1	FRONT BUMPER LH FOGLAMP COVER	BROKEN	45.00	45.00
1	FRONT BUMPER LOWER GARNISH	SCRATCHED	433.00	433.00
2	FRONT BUMPER SIDE RETAINER L/R @\$25.00	NECESSARY	50.00	50.00
1	FRONT LH ABS SENSOR	NOT NECESSARY	165.00	-
1	FRONT LH FENDER	DENTED	387.00	387.00
1	FRONT LH FENDER 'HYBRID' EMBLEM	NECESSARY	95.00	95.00
1	FRONT LH FENDER ARCH GARNISH	SCRATCHED	187.00	187.00
1	FRONT LH FENDER INNER SHIELD	DEFORMED	125.00	125.00
1	FRONT LH HEADLAMP	CRACKED	1,785.00	1,785.00
1	FRONT LH HEADLAMP LOWER BRACKET	CRACKED	35.00	35.00
1	FRONT LH HEADLAMP SIDE BRACKET	NOT NECESSARY	25.00	-
1	FRONT LH KNUCKLE ARM	BENT	245.00	245.00
1	FRONT LH KNUCKLE ARM BEARING	NECESSARY	135.00	135.00
1	FRONT LH LINKAGE	NOT NECESSARY	55.00	-
1	FRONT LH LOWER ARM	BENT	371.00	371.00
1	FRONT LH LOWER BALL JOINT	BENT	98.00	98.00
1	FRONT LH SHOCK ABSORBER	BENT	301.00	301.00
1	FRONT LH SHOCK ABSORBER RUBBER	SERVICEABLE	55.00	-
1	FRONT LH SHOCK ABSORBER SPONGE	SERVICEABLE	30.00	-
1	FRONT LH SHOCK ABSORBER TOP MOUNTING	SERVICEABLE	45.00	-
1	FRONT LH SPORT RIM	SCRATCHED	813.00	813.00
1	FRONT LH STEERING TIE ROD	SERVICEABLE	89.00	-
1	FRONT LH STEERING TIE ROD END	SERVICEABLE	72.00	-
1	FRONT LH WHEEL HUB	NECESSARY	221.00	221.00
1	FRONT UPPER GRILLE	SERVICEABLE	351.00	-
1	FRONT UPPER GRILLE 'H' LOGO EMBLEM	SERVICEABLE	25.00	-
1	REAR RH SPORT RIM	SCRATCHED	813.00	813.00
1	FRONT RH WHEEL BEARING	SERVICEABLE	275.00	-
1	STEERING RACJ & PINION	SERVICEABLE	1,173.00	-

Report Ref No. CS/FCI18010570/Nsd3e2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	LESS 20% DISCOUNT		-1,915.00	-1,443.00
			7,660.00	5,772.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	SET FRONT BUMPER CLIPS (SN)	NECESSARY	50.00	30.00
1	SET FRONT GRILLE CLIPS (SN)	SERVICEABLE	30.00	-
1	SET FRONT LH FENDER ARCH GARNISH CLIPS (SN)	NECESSARY	50.00	20.00
1	FRONT LH FENDER INNER SHIELD CLIPS (SN)	NECESSARY	50.00	30.00
1	FRONT LH TYRE (SN)	SERVICEABLE	300.00	-
1	REAR RH TYRE (SN)	SERVICEABLE	300.00	-
			780.00	80.00
	<b><u>LABOUR</u></b>			
	TO REMOVE, REINSTALL ELECTRICAL WIRING HARNESS, CHECK LIGHTING (TO FR)		60.00	20.00
	TO REMOVE, CHANGE FRONT SUSPENSION PARTS, ABSORBER, LOWER ARM, KNUCKLE ARM, WHEEL BEARING, BEARING HUB, DRIVE SHAFT, ANTI-ROLL BAR, TOP-ARM AND STEERING RACK AND PINION.		250.00	200.00
	TO ROAD TEST DRIVING, CHECK AND RESETTNG WHEEL ALIGNMENTS SYSTEM.		120.00	80.00
	TO RE-SPRAY PAINTING ON THE CHANGE BODY PARTS, REPAIR PORTION, AND WHERE CONSISTENT TO THE ACCIDENT.		800.00	500.00
	TO PROVIDE LABOUR, WORKMANSHIP TO CHANGE THE ABOVE DAMAGED BODYPARTS, REPAIR, RE-CONSTRUCT AND RE-ALIGN BODY STRUCTURE, BODY ALIGNMENTS AND DAMAGED CONSISTENT TO THE ACCIDENT.		600.00	400.00
	TO APPLY ANTI-RUST CHEMICAL ON REPAIRED AND REPLACED PANEL.	NOT NECESSARY	80.00	-
			-	-
			-	-
			1,910.00	1,200.00
	<b>GRAND TOTAL</b>		<b>10,350.00</b>	<b>7,052.00</b>
	<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>			<b>5,600.00</b>

Report Ref No. CS/FCI18010570/Nsd3e2



Report Ref No. CS/FCI18010570/Nsd3e2

MUHAMMAD NAZRIL BIN ABDULLAH

Automotive Assessor

ADRIAN LING WAI PING

B.Eng,AMSOE,AMIRTE,AMSAE-A,M.MATAI

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.  
No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.