

22/03/2002

ASS. REC. BY:

REF:

CS3/CTI180/084/V24d362

Special Instruction:

Survivor:
Menmen

Suthya

ASSIGNMENT (Office)

From (Person):

Elaine Cheong

of

CTI

Date/Time:

11/06/18 @ 2.24pm

Estimated Cost:

Bill to:

OD/TP/WS/TP RES / OD RES / EVA / INV / MV / CS

To Inspect Vehicle No:

SLW 5818 L

Insured:

8JK 6315 B

at Workshop m/s

Weng Kee Motor

Tel:

6854 1273

of

Blk 1019 # 01-366 Yishun Ind. park A

Policy No:

DMPCS N3041301700

Claim No:

SNM18D02874C02

Sum Insured:

Excess:

Make of Veh:

(Client's Record)

D.O.A.

05/06/2018

12/06/2018

H.O.D. Endorsement:

CA / REV / REP. / REV 24 HRS (up)

Date/Time:

3.19pm @ 11/6/18

Person Contacted:

Matthew

Vehicle IN/OUT

Date/Time

Action/Instruction

(X)

Estimate

SLW 5818 L - X

8JK 6315 B - X

REF: CT1

ASSIGNMENT

From: Date: 12/6/18

Estimated Cost:

OD ☒ WS / TP RES / OD RES / EVA / INV / MV

To Inspect Vehicle No: SLW 5818L

at Workshop m/s Weng Kee Motor
of BIK 1019 # 01-366 Yishun Ind. Park A

Insured:

Policy No.


Claims No.

Sum Insured: Excess:

(Client's Record)

Make of Veh: Matthew @ G864 1273

(Policy Condition)

Remark: The veh had commenced its
repair at the time of inspection.

Bal. or Market Value:

IDAC Accident Rpt: Consistent? : Yes or No

GIA / PR Seen: Consistent? : Yes or No

Est. Repairs: days Res.: Yes or No

Lum Sum: % 3 Val.: Yes or No

CA / REV / REP. / 24 HRS lwp

Vehicle: IN / OUT

Date: Person Contacted:

Veh No: SLW 5818L Yr Regn: /

Type: ☒ M.Car / M.Cycle / Bus / Van / Lorry / Taxi / Prime Mover /

Truck / Trailer or

Make: Subaru Impreza C.C.

Colour: White A/C: Insured / Std / NI / NA

Sp. Reading: 5440 T/Radio: Insured / Std / NI / NA

Eng/No:

C/No: JF1GT7KL5JG027018

Gen. Cond: Good / ☒ Fair / Poor / BurntSteering: ☒ In order / Jammed / Leaked / Burnt orBrake: ☒ In order / Jammed / Leaked / Burnt orModi: ☒ Nil / S/Rim / STD A/Rim or

Tyre Size: F: 205/50 R17

R: 205/50 R17

☒ BS DUN / EXNOVA / GY / FS / LIZA / MIC / OHTSU / PIR / SUMI /

TOYO / YOKO or

Front

R/Bal. 6 mm

L/Bal. 6 mm

D.O.A.

Rear

R/Bal. 6 mm

L/Bal. 6 mm

D.O.I. 12/6/2018

Survey held at Weng Kee Motor

Des. of Damages: Frt / ☒ Rear / O/S / N/S / U/C / Rooftop or

The U/C / Chassis frame / Body Structure affected due to collision.

Date / Time Action / Instruction

* Repair Estimate : S\$ 3500-4500

* 3 days

21/6/18 Submit the Report.

Date/Time: File Pass to?

☐ : Preli. Report

1)

☐ : Final Report

Date/Time: File Return to?

2)

Days Of Repair:

Resurvey No. of Trip:

Survey Fee:

Transportation

S + RS \$

Photos

Others

TOTAL

Add Fee: ☐ Site Insp (\$)☐ Interview (\$)☐ Tech. Invs (\$)☐ Weekend (\$)

Report Format :

Lump Sum / I.B.I: (\$)

150

150

...CLAIM SUBFOLDER...(New Assignment)

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	11 Jun 2018		11 Jun 2018 14:24 Assign				New Assignment Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by insurer]

Insured:	THYE SWEE MOY, ID: S6975421Z		
Main Claimant:	PHUA SIEW TZE JOYCE, ID: S7724142F		
Vehicle Reg. No.:	SLW5818L	Date of Loss:	05/06/2018 22:00 - :59
Claim Type:	TP / SNM18D02874C02	Policy/Cover Note No.:	DMPCSN3041301700 (Comprehensive)
Vehicle Reg. No. (Insured):	SJK6315B	Policy No. (Claimant):	D18MTPV01003670
		Excess:	S\$0.00
Repairer:	Weng Kee Motor (HQ) Block 1019 #01-366 Yishun Ind. Park A, 768761 Yishun - Tel: 6854 1273		
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]		
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Final Rpt due 21/06/2018]		
Driver/Custodian (Insured):	CLIVE NG KAI CHENG (19 / Male), NRIC: S9832044Z, Tel: +6596176040		
Adj Asg. Remarks:	NO EST, ASSIGN HENRY NG AS SJE.		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

There are no mail for this case.

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Lucas Lee

From: Willow Tuang <wtuang@gmail.com>
Sent: Monday, 11 June, 2018 11:38 AM
To: Elaine Cheong
Cc: Lucas Lee
Subject: Re: (Pre-Repair inspection) Accident involving SLW 5818L & SJK 6315B along Yio Chu Kang Road on 06.06.2018 (CLAIM REF: SNM18D02874C02/5)

Dear Ms Elaine Cheong,

We refer to your email of even date.

We are agreeable of appointing HENRY NG as a Single Joint Expert.

Our client's vehicle is available for pre-repair survey at:

Venue : WENG KEE MOTOR

Block 1019 Yishun Industrial Park A

#01-366

Singapore 768761

Tel: 68541273

Regards

Tuang Willow

CK TEO & CO

Tel: 65354788

On Mon, Jun 11, 2018 at 11:07 AM, Elaine Cheong <elaine.cheong@sg.cntaiping.com> wrote:

WITHOUT PREJUDICE

Dear Willow,

We refer to your email of 08.06.18.

We intend to conduct a pre-repair survey of the damage to your client's vehicle jointly with your client/your motor workshop. We propose to use one of the following motor surveyors to conduct the joint pre-repair survey as a single joint expert.

TAY BENG HEE
DERECK OH SIONG WEE
SEE CHEW SENG
MOHD FADHILAH BIN OSMAN
XING QUO QIANG
KENNETH KONG
SIMON HO
CHUA WEIJIE
MARCUS CHUA
HENRY NG

Please let us know within two(2) working days whether you agree to the appointment of any of these motor surveyors as a single joint expert.

You may select one of the listed motor surveyors and we will bear the cost of the pre-repair survey carried out by the single joint expert.

Regards,

Elaine Cheong

Executive (Motor Claims)

Claims Department

China Taiping Insurance (Singapore) Pte. Ltd.

3 Anson Road #16-00 Springleaf Tower

Singapore 079909

Co. Reg. No. 200208384E

DID: 6389 6530

Fax: 6225 5879

Email: elaine.cheong@sg.cntaiping.com

Website: www.sg.cntaiping.com



From: Willow Tuang [mailto:wtuang@gmail.com]

Sent: Friday, 8 June, 2018 5:14 PM

To: Elaine Cheong <elaine.cheong@sg.cntaiping.com>

Cc: jp_ckteoco@hotmail.sg

Subject: (Pre-Repair inspection) Accident involving SLW 5818L & SJK 6315B along Yio Chu Kang Road on 06.06.2018


Dear Elaine,

We refer to the telephone conversation you had with our Ms Janice this evening.

We enclose copies of the following documents for your attention:

1. Notification of Accident & Pre-Repair Inspection
2. GIA Report of our Client
3. LTA result

Regards



Tuang Willow

CK TEO & CO

Tel: 65354788

Fax: 65354245

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>

This email has been scanned by the Symantec Email Security.cloud service.
For more information please visit <http://www.symanteccloud.com>



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

CHINA TAIPING INSURANCE (S) PTE LTD

Ref : CS3/CTI18010584/Vz4d3

3 ANSON ROAD #16-00
SPRINGLEAF TOWERS SINGAPORE 079909

Date : 11-06-2018



Code : CTI

1. Policy Particulars :- (THIRD PARTY CLAIM)

Insured Veh.	SJK 6315B	Veh. Inspected	SLW 5818L
Policy No.	DMPCSN3041301700	Coverage (\$)	0.00
Claim No.	SNM18D02874C02	Excess (\$)	0.00
Assign From	MERIMEN (ELAINE CHEONG)	Assign Date	11/06/2018

2. Vehicle Particulars & Condition

Make & Model	c.c	0
Engine No.	HIDDEN	Year of Reg.
Chassis No.		Colour
Odometer	-	Steering
Brakes		Modification
General		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre			mm
L/H Front Tyre			mm
R/H Rear Tyre			mm
L/H Rear Tyre			mm

4. Description of Damages

--

5. General Information

Accident Date	05/06/2018	Inspection Date
Survey held at	WENG KEE MOTOR BLK 1019 #01-366 YISHUN INDUSTRIAL PARK A SINGAPORE 768761	

5a. Remarks

A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS. B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION. THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE. C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.
--

WENG KEE MOTOR

DATE: 11-06-2018

REPAIR ESTIMATE

VEHICLE: SLW 5818 L

MODEL: Subaru Impreza

S/n	Description of part	Qty	Estimate
1	Tailgate R	1	876.00
2	Tailgate emblem "impreza" ✓ NEC	1	32.90
3	Tailgate emblem "eyesight" ✓ NEC	1	85.80
4	Tailgate emblem "subaru" ✓ NEC	1	34.40
5	Tailgate emblem "symmetrical awd" ✓ NEC	1	74.30
6	Tailgate weatherstrip ✓ Deform	1	116.00
7	Tailgate outer garnish assembly X	1	258.00
8	Tailgate outer garnish assembly clip - set X	1	40.00
9	Tailgate logo X	1	68.40
10	Tailgate lock mechanism ?	1	187.80
11	Rear windscreen moulding LH/RH ✓ NEC	2	85.00
12	Rear windscreen moulding top ✓ NEC	1	35.00
13	Rear windscreen moulding bottom ✓ NEC	1	32.00
14	Tail lamp LH/RH ?	2	797.60
15	Tail lamp lower bracket LH/RH ?	2	71.60
16	Tail gate lamp LH/RH ?	2	577.40
17	Rear license plate lamp LH/RH X	2	56.80
18	Rear bumper ✓ CRK	1	493.60
19	Rear bumper support bracket LH/RH ?	2	56.40
20	Rear bumper clip - set ✓ NEC	1	30.00
21	Rear bumper side retainer RH/LH ?	2	22.80
22	Rear bumper tow cover ✓ CUT	1	28.00
23	Blindspot sensor LH/RH ?	2	2,160.00
24	Blindspot sensor bracket LH/RH ?	2	34.80
25	Rear bumper lower garnish ✓ OT	1	260.00
26	Rear bumper reflector LH/RH ?	2	24.20
27	Rear bumper reinforcement ?	1	278.70
28	Rear end panel top garnish ✓ CUT	1	88.00
29	Rear end panel ?	1	297.30
Sub-total 1			7,202.80
Less 20%			5,762.24
30	Rear bumper extension grommet screw LH/RH ✓ NEC	2	8.00
31	Rear bumper extension fastener ✓ NEC	2	7.00
32	Rear bumper fastener ✓ NEC	2	8.00
33	Rear reverse sensor ?	4	350.00
34	Windscreen sealant ✓ NEC	1	40.00
35	Windscreen primer ✓ NEC	1	20.00
36	Windscreen support sponge ✓ NEC	1	20.00

WENG KEE MOTOR

37	number plate with holder X	1	45.00
38	Tail lamp pad LH/RH ?	2	30.00
39	Tail gate lamp pad LH/RH ?	2	30.00
40	end panel sealant ?	1	30.00
Sub-total 2			588.00
Parts total			6,350.24

Labour

41	To cut and remove rear end panel. To remove and refit above parts.	800.00 600
42	To putty, re-spray painting and polish affected areas.	800.00 600
43	To remove and refit tailgate upholstery to facilitate repair.	80.00 50
44	To remove and refit rear windscreen	120.00 60
45	To remove and repair rear exhaust silencer	150.00 X
46	To check and rectify wiring system.	80.00 40
47	To remove and install reverse sensors	60.00 ?
48	To rust proof affected areas.	60.00 30
Labour total		2,150.00
Parts & Labour total		8,500.24

Sathya Sai

12/6/2018

sebastianyeang@lkkauto.com

98072012

- Lump Sum Repair
- Question mark item photo
- Photo after paint.

3 days

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification/s is allowed
- Supplementary terms must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature

Date:

...CLAIM SUBFOLDER...(Pending for Survey Report)

CLAIM SUBFOLDER TRACKING							
Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'ed	Status
Main	11 Jun 2018		11 Jun 2018 14:24 Edit Adj Rpt	S\$0.00 Edit Estimates	S\$0.00 View Rpt		Pending for Survey Report Cancel Case

Main	Reference	Claim Details	Documents	Show All					
CLAIM SUBFOLDER DETAILS [Created by insurer]									
Insured:	THYE SWEE MOY, ID: S6975421Z								
Main Claimant:	PHUA SIEW TZE JOYCE, ID: S7724142F								
Vehicle Reg. No.:	SLW5818L	Date of Loss:	05/06/2018 22:00 - :59 [3 Months and 13 Days From LTA Reg Date (Man Yr)]						
Claim Type:	TP / SNM18D02874C02	Policy/Cover Note No.:	DMPCSN3041301700 (Comprehensive)						
Vehicle Reg. No. (Insured):	SJK6315B	Policy No. (Claimant):	D18MTPV01003670						
		Excess:	S\$0.00						
Repairer:	Weng Kee Motor (HQ) Block 1019 #01-366 Yishun Ind. Park A, 768761 Yishun - Tel: 6854 1273								
Handling Insurer:	China Taiping Insurance (Singapore) Pte. Ltd. (HQ) - Tel: 6389 6111 ... [Handled by Elaine Cheong]								
Claimant's Insurer:	Sompo Insurance Singapore Pte. Ltd. (HQ) - Tel: 6461 6555								
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by Sathya Sai Kathirrasen] ... [Final Rpt due 21/06/2018]								
Driver/Custodian (Insured):	CLIVE NG KAI CHENG (19 / Male), NRIC: S9832044Z, Tel: +6596176040								
Adj Asg. Remarks:	NO EST, ASSIGN HENRY NG AS SJE.								
ASSOCIATED MAIL RECEIVED View All Compose Case Mail									
There are no mail for this case.									
ALL ASSOCIATED TASKS View All Search Tasks Create New Task Complete									
Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

*SLW5818L (SNM18D02874C02)

[SJK6315B]

TP

PHUA SIEW TZE JOYCE

Jun 5 2018 10:00PM

[THYE SWEE MOY]

Weng Kee Motor

Upload Documents			Upload Photos			Compose New Letter			View			View in Browser		
Video									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail			Print		
1	06/06/18 14:40	Video - Accident [Linked Accident Report Documents]										Load MP4		
Assessment Reports									1 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail			Print		
1	06/06/18 14:42	Accident Statement										Load HTM		
Photos/Images									3 per page			<input checked="" type="checkbox"/>		
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)							Thumbnail			Print		
1	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
2	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
3	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
4	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
5	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
6	06/06/18 14:40	Accident Photo [Linked Accident Report Documents]										Load JPG		
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)							Thumbnail			Print		
1	14/06/18 10:33	General View										Load JPG		
2	14/06/18 10:33	General View										Load JPG		
3	14/06/18 10:33	General View										Load JPG		
4	14/06/18 10:33	General View										Load JPG		
5	14/06/18 10:33	General View										Load JPG		
6	14/06/18 10:33	General View										Load JPG		
7	14/06/18 10:33	General View										Load JPG		
8	14/06/18 10:33	General View										Load JPG		
9	14/06/18 10:33	General View										Load JPG		
10	14/06/18 10:33	General View										Load JPG		
11	14/06/18 10:33	General View										Load JPG		
12	14/06/18 10:33	General View										Load JPG		
13	14/06/18 10:33	General View										Load JPG		
14	14/06/18 10:33	General View										Load JPG		
15	14/06/18 10:33	General View										Load JPG		
16	14/06/18 10:33	General View										Load JPG		
17	14/06/18 10:33	General View										Load JPG		
18	14/06/18 10:33	General View										Load JPG		
19	14/06/18 10:33	General View										Load JPG		
20	14/06/18 10:33	General View										Load JPG		
21	14/06/18 10:33	General View										Load JPG		

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
22	14/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
23	14/06/18 10:33	Odometer Reading	Load JPG	<input checked="" type="checkbox"/>
24	14/06/18 10:33	Chassis Number	Load JPG	<input checked="" type="checkbox"/>
25	14/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
26	14/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
27	14/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
28	14/06/18 10:33	General View	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	China Taiping Insurance (Singapore) Pte. Ltd. (HQ)	Thumbnail	Print
1	11/06/18 14:24	PRS	Load PDF	
2	11/06/18 14:24	OI GIA REPORT	Load PDF	
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/06/18 14:40	Sketch Plan [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
2	06/06/18 14:40	Sketch Plan #2 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
3	06/06/18 14:40	Sketch Plan #3 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
4	06/06/18 14:40	Sketch Plan #4 [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
5	06/06/18 14:41	Common Statement [Linked Accident Report Documents]	Load JPG	<input checked="" type="checkbox"/>
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	13/06/18 13:54	LKKPhotosIn6-1.pdf	Load PDF	

Linked Accident Report Documents

Video			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/06/18 14:40	Video - Accident	Load MP4	
Assessment Reports			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/06/18 14:42	Accident Statement	Load HTM	
Photos/Images			3 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
2	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
3	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
4	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
5	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
6	06/06/18 14:40	Accident Photo	Load JPG	<input checked="" type="checkbox"/>
Documentation			1 per page	<input checked="" type="checkbox"/>
No	Finalized On	Cheng Hoe Motor Pte Ltd (Yishun)	Thumbnail	Print
1	06/06/18 14:40	Sketch Plan	Load JPG	<input checked="" type="checkbox"/>
2	06/06/18 14:40	Sketch Plan #2	Load JPG	<input checked="" type="checkbox"/>
3	06/06/18 14:40	Sketch Plan #3	Load JPG	<input checked="" type="checkbox"/>
4	06/06/18 14:40	Sketch Plan #4	Load JPG	<input checked="" type="checkbox"/>
5	06/06/18 14:41	Common Statement	Load JPG	<input checked="" type="checkbox"/>

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)**Show Remarks To:** ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CS3/CTI18010584/VZ4D3E2

Date: 27/06/2018

REFERENCE

Handling Insurer: China Taiping Insurance
(Singapore) Pte. Ltd.

Policy No: DMPCSN3041301700

Claimant Vehicle
No : SLW5818LInsured Vehicle
No : SJK6315B

Date of Loss: 05/06/2018

Nature of Claim: TP

Claim
No: SNM18D02874C02

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SLW5818L**

Make & Model: SUBARU IMPREZA WRX, 2.0 GD (M)

Engine No: FB20YC19481

Reg. Date: 23/02/2018 (Man. Year: 2017)

Chassis No: JF1GT7KL5JG027018

Colour: White

Odometer: 5440 km

Engine Capacity: 1995 cc

Market Value/New Car Price: N/A

Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/50 R17	Rear Tyre Size:	205/50 R17
Front Left Side:	Bridgestone 6 mm	Rear Left Side:	Bridgestone 6 mm
Front Right Side:	Bridgestone 6 mm	Rear Right Side:	Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	0.00	0.00	0.00	
Miscellaneous Items	0.00	0.00	0.00	
Labour	0.00	0.00	0.00	
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Nett Amount (S\$)	0.00	0.00	0.00	

INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 12/06/2018 Inspected At:

Weng Kee Motor (HQ)
Block 1019 #01-366 Yishun Ind. Park A
Singapore 768761

Estimated Period of Repair: 3.0 days

Adjuster: Sathya Sai Kathirrasen

Manager: Ho Zhao Tian

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

- A) THE INSPECTION WAS CONDUCTED ON A "WITHOUT PREJUDICE" BASIS.
- B) THE REPAIR ESTIMATE WAS NOT PRESENTED AT THE TIME OF INSPECTION.
THE REPAIRER WAS TOLD TO PREPARE THE ESTIMATE.
- C) ENCLOSED PLEASE FIND DAMAGED VEHICLE PHOTOGRAPHS.

THE ESTIMATED REPAIR COST OF THE DAMAGED VEHICLE IS IN THE REGION OF \$3,500.00 -\$4,500.00

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 27 Jun 2018)
Parts: 143	SUBARU IMPREZA WRX 2.0 GD (M) (Catalogue:Merimen Singapore 1.0)
Labour: Repairer's	(Price-denominated Standard List)
Print Code:	(Unsubmitted, no print-code for SLW5818L)
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page
Further Info: Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

There are no new parts selected.

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

There are no labour items selected.

Report was unsubmitted during this print-out.

< END OF ESTIMATES >