

LKK



SERVICE ESTIMATE

68755 - C00001 SL: SERVICE SALES - PC

Mr Carlton Phillip Anthony

147 Devonshire Road

#04-03 The Beaumont

Singapore 239894

GST Reg.No:M28920628X

Inv.No. . : B&P 0 Page 1

Inv.date. : 08/06/2018

WIP No. . : 10163

Veh.In/Out:

*Tel.No. . : Mobile: 94521950

Reg.No. . : SKD5528K

Reg.date . : 15/12/2011

Mileage .. : 0

Chassis No: SALVA2AG0CH614359

Closed by : Mandy Neo

Svc Consultant :

Remarks : Mr Carlton Phillip A

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|-----------------------------------------------------------------------------|----------|---------|-------|-----|---------------------|------------------|
| 802 | TO REPLACE FRONT BUMPER BRACKET , RH FRONT HEADLAMP BUMPER INSERT, FOG LAMP | 0 | 2400.00 | 0 | | 2,400.00 | \$ 1800 |
| 800 | TO PUTTY SPRAY PAINT ON FRONT BUMPER | 0 | 2200.00 | 0 | | 2,200.00 | \$ 2000 |
| 280 | TO CHECK WIRING INCLUDE RESETTING OF ALL ELECTRICAL MODULES | 0 | 486.00 | 0 | | 486.00 | \$ |
| 280 | TO FOCUS FRONT HEADLAMP | 0 | 162.00 | 0 | | 162.00 | \$ |
| | LLR028262/BUMPER COV | 1.0 EA | 2176.80 | | | 2,176.80 | \$ 00 |
| | BUMPER BRACKET FRT L | 1.0 EA | 46.70 | | | 46.70 | \$ X |
| | LLR026530/BUMPER BRA | 1.0 EA | 47.20 | | | 47.20 | \$ X |
| | LLR026531/BUMPER BRA | 1.0 EA | 80.50 | | | 80.50 | \$ X |
| | LLR026539/BUMPER MOU | 1.0 EA | 363.00 | | | 363.00 | \$ X |
| | LLR026533/BUMPER BRA | 1.0 EA | 396.70 | | | 396.70 | \$ X |
| | LLR026497/BUMPER BEA | 1.0 EA | 1003.00 | | | 1,003.00 | \$ X |
| | LLR035094/FOGLAMP BE | 1.0 EA | 88.20 | | | 88.20 | \$? |

SERVICE ESTIMATE

68755 - C00001 SL: SERVICE SALES - PC

Mr Carlton Phillip Anthony
147 Devonshire Road
#04-03 The Beaumont

Singapore 239894

Closed by : Mandy Neo
Svc Consultant :
Remarks : Mr Carlton Phillip A

GST Reg.No:M28920628X
Inv.No. . . : B&P 0 Page 2
Inv.date. : 08/06/2018
WIP No. . . : 10163
Veh.In/Out:
*Tel.No. . . : Mobile: 94521950
Reg.No. . . : SKD5528K
Reg.date. : 15/12/2011
Mileage . . : 0
Chassis No: SALVA2AG0CH614359

| Op.No | Description | Mech Qty | Price | Disc% | Pkg | Amount | G |
|-------|----------------------|----------|---------|-------|-----|----------|-------|
| | LLR027246/WASHER COV | 1.0 EA | 70.60 | | | 70.60 | S X |
| | LLR024263/HEADLAMP B | 1.0 EA | 3285.30 | | | 3,285.30 | S BS- |
| | BULB HEADLAMP HID EV | 1.0 EA | 553.85 | | | 553.85 | S ? |
| | ADHESIVE TUBE CHEMIC | 4.0 EA | 75.80 | | | 303.20 | S hu- |

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer
Signature:
Date:

Resul
Hp 90010068
4 days
27/06/18 @ 1455
Resurvey bk part

| | | |
|----------------------|--------------|------------------------|
| | Gross Total. | 13,663.05 |
| Labour Total | 5,248.00 | Net..... 13,663.05 |
| Parts Total | 8,415.05 | GST @ 7.0% 956.41 |
| Package Total | 0.00 | Total..... 14,619.45 |
| | | Paid..... 0.00 |
| | | Please Pay.. 14,619.45 |

GST: S=StdRated; 0=OutOfScope; Z=ZeroRated