

LKK Auto Consultants Pte Ltd

(Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com; assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18010677/KDA3Q2

Date: 16/11/2020

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100194388

Claimant
Vehicle No : SHB9789T **Insured Vehicle No :** GX2750X

Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: 0986240585SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SHB9789T	Engine No:	M9R8839C000268
Make & Model:	RENAULT LATITUDE, 2.0 L (A)	Chassis No:	VF1ABL15AUC273316
Reg. Date:	31/07/2013 (Man. Year: 2013)	Odometer:	433630 km
Colour:	Metallic White/Red		
Engine Capacity:	1995 cc		
Market Value/New Car Price:	N/A		
Sum Insured (\$\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	215/60 R16	Rear Tyre Size:	215/60 R16
Front Left Side:	Giti 9 mm	Rear Left Side:	Linglong 8 mm
Front Right Side:	Giti 9 mm	Rear Right Side:	Linglong 8 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	27,635.56	7,725.88	19,909.68	72.04
Miscellaneous Items	0.00	0.00	0.00	
Labour	11,830.00	2,380.00	9,450.00	79.88
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (\$\$)	39,465.56	10,105.88	29,359.68	74.39
Approved Total (Overridden) (\$\$)		8,100.00		
(\$\$)	39,465.56	8,100.00	31,365.56	79.48
+ GST 7.00/7.00% (\$\$)	2,762.59	567.00	2,195.59	79.48
Nett Amount (\$\$)	42,228.15	8,667.00	33,561.15	79.48
Global Sum Settlement (\$\$)		0.00		

INSPECTION

Date of Assignment: 11/06/2018

Date Inspected: 11/06/2018 Inspected At:

Trans-cab Auto Services Pte Ltd
No 2 Ang Mo Kio Street 63
Singapore 569111

Estimated Period of Repair: 6.0 days

Adjuster: KENNETH KONG

Manager: CHAN JIA LE

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FENDER PANEL FRT LH	Bent	783.83 FL	*783.83 FL
2	1		*WHEELARCH FRT LH	Serviceable	278.84 FL	*- FL
3	1		*FENDER BRACKET LOWER LH	Serviceable	15.79 FL	*- FL
4	1		*FENDER INSULATOR LH	Serviceable	130.84 FL	*- FL
5	1		*DOOR PANEL FRT LH	Bent	2,844.66 FL	*2,844.66 FL
6	1		*DOOR HINGE UPPER LH	Repair	261.28 FL	*- FL
7	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
8	1		*DOOR CHECK FRT LH	Serviceable	194.77 FL	*- FL
9	1		*DOOR LOCK FRT LH	Repair	908.75 FL	*- FL
10	1		*DOOR CATCH FRT LH	Serviceable	131.23 FL	*- FL
11	1		*DOOR HANDLE OUTER FRT LH	Dented	477.76 FL	*477.76 FL
12	1		*DOOR HANDLE COVER FRT LH	Serviceable	13.22 FL	*- FL
13	1		*DOOR HANDLE MODULE FRT LH	Serviceable	133.60 FL	*- FL
14	1		*DOOR REGULATOR FRT LH	Repair	505.19 FL	*- FL
15	1		*DOOR REGULATOR MOTOR FRT LH	Repair	796.46 FL	*- FL
16	1		*DOOR REGULATOR GUIDE FRT LH	Serviceable	120.97 FL	*- FL
17	1		*DOOR PANEL REAR LH	Bent	2,844.66 FL	*2,844.66 FL
18	1		*DOOR GUIDE REAR LH	Serviceable	176.82 FL	*- FL
19	1		*DOOR HINGE UPPER LH	Repair	274.50 FL	*- FL
20	1		*DOOR HINGE LOWER LH	Repair	300.55 FL	*- FL
21	1		*DOOR CHECK REAR LH	Serviceable	203.06 FL	*- FL
22	1		*DOOR LOCK REAR LH	Repair	908.75 FL	*- FL
23	1		*DOOR HADLE OUTER REAR LH	Serviceable	126.49 FL	*- FL
24	1		*DOOR HANDLE CAP REAR LH	Serviceable	35.52 FL	*- FL
25	1		*DOOR HANDLE SEAL REAR LH	Serviceable	7.89 FL	*- FL
26	1		*DOOR HANDLE COVER REAR LH	Serviceable	13.22 FL	*- FL
27	1		*DOOR HANDLE MODULE REAR LH	Serviceable	133.60 FL	*- FL
28	1		*DOOR REGULATOR REAR LH	Repair	1,135.10 FL	*- FL
29	1		*DOOR REGULATOR MOTOR REAR LH	Repair	893.75 FL	*- FL
30	1		*DOOR REGULATOR NUT REAR LH	Serviceable	12.43 FL	*- FL
31	1		*DOOR REGULATOR MOTOR SCREW REAR L70Y	Not Necessary	6.31 FL	*- FL
32	1		*DOOR FINISHER REAR LH	Serviceable	423.10 FL	*- FL
33	1		*DOOR MOULDING REAR LH	Serviceable	176.82 FL	*- FL
34	1		*DOOR MOULDING CLIP L70Y	Not Necessary	5.92 FL	*- FL
35	1		*DOOR MOULDING SCREW L70Y	Not Necessary	6.91 FL	*- FL
36	1		*DOOR CASING REAR LH	Serviceable	1,509.06 FL	*- FL
37	1		*DOOR WATER SHIELD REAR LH	Serviceable	30.39 FL	*- FL
38	1		*DOOR CASING CLIP	Not Necessary	12.63 FL	*- FL
39	1		*DOOR CASING LIGHT L70Y	Serviceable	48.74 FL	*- FL
40	1		*DOOR FINISHER INNER REAR LH	Serviceable	323.44 FL	*- FL
41	1		*DOOR FINISHER BRACKET INNER REAR LH	Serviceable	46.97 FL	*- FL
42	1		*DOOR FINISHER BRACKET INNER REAR LH	Serviceable	20.33 FL	*- FL
43	1		*DOOR FINISHER BRACKET INNER REAR LH	Serviceable	20.33 FL	*- FL
44	1		*DOOR FINISHER BRACKET INNER REAR LH	Serviceable	20.33 FL	*- FL
45	1		*DOOR GRAB HANDLE REAR LH	Serviceable	210.96 FL	*- FL
46	1		*DOOR BLIND REAR LH	Serviceable	741.80 FL	*- FL
47	1		*DOOR WEATHERSTRIP REAR LH	Serviceable	410.66 FL	*- FL
48	1		*DOOR SEAL REAR LH	Serviceable	162.02 FL	*- FL
49	1		*DOOR GLASS RUNNER SEAL REAR LH	Serviceable	229.31 FL	*- FL
50	1		*DOOR WAIST SEAL OUTER REAR LH	Serviceable	334.69 FL	*- FL
51	1		*DOOR WAIST SEAL INNER REAR LH	Serviceable	115.64 FL	*- FL
52	1		*FENDER PANEL REAR LH	Repair	3,299.13 FL	*- FL
53	1		*FENDER PANEL INNER TRIM REAR	Serviceable	671.45 FL	*- FL

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
54	1		*WHEELARCH REAR LH	Serviceable	543.47 FL	*- FL
55	1		*DOOR MIRROR ASSY LH	Cracked	1,483.40 FL	*1,483.40 FL
56	1		*ROCKER PANEL INNER GARNISH LH	Serviceable	466.51 FL	*- FL
57	1		*ROCKER PANEL INNER LH	Repair	1,024.79 FL	*- FL
58	1		*ROCKER PANEL CENTER LH	Repair	990.25 FL	*- FL
59	1		*LOWER ARM LH L70Y	Serviceable	685.76 FL	*- FL
60	1		*KNUCKLE ARM LH L70Y	Serviceable	846.98 FL	*- FL
61	1		*ABSORBER FRT LH L70Y	Serviceable	360.54 FL	*- FL
62	1		*SET FRAME FULL SUPPORT PANEL CLIP	Not Necessary	70.00 FS	*- FS
63	2		*FRAME FULL SUPPORT PANEL NUT	Not Necessary	20.00 FS	*- FS
64	2		*FRAME FULL SUPPORT PANEL STUD	Serviceable	30.00 FS	*- FS
65	1		*SET WHEELARCH CLIP FRT LH	Not Necessary	30.50 FS	*- FS
66	1		*FRONT DOOR STICKER TRANS-CAB	Necessary	80.00 FS	*60.00 FS
67	1		*FRONT DOOR STICKER CHASSIS	Necessary	50.00 FS	*15.00 FS
68	1		*REAR DOOR STICKER 6555 3333	Necessary	80.00 FS	*60.00 FS
69	1		*DOOR CHECK BOLT	Not Necessary	22.69 FS	*- FS
70	1		*DOOR GUIDE SCREW	Not Necessary	10.85 FS	*- FS
71	1		*DOOR HINGE BOLT	Not Necessary	10.85 FS	*- FS
72	1		*DOOR HINGE NUT RH	Not Necessary	14.60 FS	*- FS
73	1		*DOOR CHECK BOLT	Serviceable	22.69 FS	*- FS
74	1		*DOOR CHECK NUT	Serviceable	3.75 FS	*- FS
75	1		*DOOR LOCK SCREW L70Y	Serviceable	6.12 FS	*- FS
76	1		*DOOR CATCH SCREW L70Y	Serviceable	10.06 FS	*- FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$)	30,654.83	8,569.31
- List Item Discount on L Items 10.00/10.00% (\$)	3,019.27	843.43
Total Parts (\$)	27,635.56	7,725.88

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
<u>Labour Items</u>				
1	PANEL BEATING ,KNOCKING AND STRAIGHTENING THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME	New	4,500.00	700.00
2	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION	New	4,200.00	1,320.00
3	TO RUST-PROOFING OF THE AFFECTED AREAS	New	170.00	90.00
4	TO REMOVE AND REFIT INTERIOR FITTINGS,TRIMINGS,GARNISH,FITTINGS AND OTHER ,TO ENABLE REPAIR	New	380.00	80.00
5	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT	New	220.00	0.00
6	TO TRANSFER OF TIRE ,RIM AND ON WHEEL BALANCING	New	170.00	0.00
7	TO CHECK ELECTRICAL LIGHTING CONCERNED	New	170.00	20.00
8	TO TRANSFER OF FRONT FENDER FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	0.00
9	TO TRANSFER OF FRONT DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST.	New	380.00	60.00
10	TO TRANSFER OF REAR DOOR FITTINGS ,ATTACHMENTS AND PERFORM WATER SEEPAGE TEST	New	380.00	60.00
11	TOWING FEES	New	120.00	50.00
12	TO PULL AND JACK OUT CHASSIS FRAME AND CORRECT IT TO SYMMETRICAL POSITION WITH THE AIR OF HYDRAULIC PNEUMATIC JACK	New	380.00	0.00
13	LABOUR CHARGE TO MOUNT AND DISMOUNT VEHICLE ON JIG BENCH ,TO FACILITATE REPAIR	New	380.00	0.00
Gross Labour Cost (\$\$)			11,830.00	2,380.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >