



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

General Details

Involving	1 2011 BMW 535 I (SJW1717U)
Date of Loss	May 31, 2018
Time of Loss	18.00
Loss Description	SJW1717U (INSD) HI REAR OF SJZ190D (TP)
Comment	<input type="text"/>

Workshop Details

Total Rebate Amount	<input type="text" value="59242"/>
Nett Loss Amount	\$23,758.00
Assigned Workshop	LKK AUTO CONSULTANTS PTE LTD (OD)
Target Date of Completion *	<input type="text" value="09/20/2018"/>
Days of work completion *	<input type="text" value="100"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Vehicle & Driver Details

Vehicle Registration# SJW1717U


Purchase Date

mm/dd/yyyy 

Registration State

SINGAPORE

Registration Date *

05/12/2011 

Mileage


73045

Age of Vehicle

7

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Manufacturing Year	2011	2011
Make	BMW	B.M.W.
Model	535 I	535I A

Driver Details

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Driver Name	CLAIRE ANGELES FLORES TAY	
Date of Birth	October 3, 1974	mm/dd/yyyy 
Age	43	

CATEGORY	POLICY INFORMATION	ASSESSMENT INFORMATION
Type		<input type="text" value="▼"/>
Type of Paint		<input type="text"/>
Chassis No	WBAFR72050C580914	<input type="text" value="WBAFR72050C5E"/>
Engine No	10757701N55B30A	<input type="text" value="10757701N55B30"/>
Engine Capacity		<input type="text" value="2979"/>
Sum Insured	0	<input type="text" value="0"/>
Market Value	0	<input type="text" value="83000"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Occupation	Unknown	<input type="text"/>
Education Qualification	Other	<input type="text" value="▼"/>
Driving Experience	17	
Driver License #		<input type="text"/>
License Type		<input type="text" value="▼"/>
License Issue Date	January 1, 2001	<input type="text" value="mm/dd/yyyy"/>
License Expiration Date		<input type="text" value="mm/dd/yyyy"/>
Address	176A ORCHARD ROAD #04-55, 238844, Singapore	<input type="text"/>
Address type	Personal Correspondence	<input type="text" value="▼"/>

CATEGORY	FNOL INFORMATION	POST SURVEY INFORMATION
Gender	Female	<input type="text"/>
Marital status	Unknown	<input type="text"/>
Identification #	S7485280G	<input type="text"/>



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Detailed Assessment

Inspection Date *

06/13/2018



Total Loss

Yes

No

Towing Charges

0

Voluntary Excess

0

Compulsory Excess

500

Young/Inexperienced/
Unnamed Driver Excess

0

Other Excess

Condition of Vehicle at time of survey

General condition

Good ▾

Steering (Serviceable)

Yes

No

Footbrake (Serviceable)

Yes

No

Handbrake (Serviceable)

Yes

No

Engine Modification

Yes

No

Pre-accident condition

Good ▾

Tyre Condition

Age of Tyres

Spare wheel

Front Tyre Size

245/40R19

Rear Tyre Size

275/35R19

Front left side

PIRELLI8mm

Rear left side

PIRELLI8mm

Front right side

PIRELLI8mm

Rear right side

PIRELLI8mm



SERVICE REQUESTS

MESSAGES

CLAIMS



Assessment Details

General & Workshop Details

Vehicle & Driver Details

Vehicle Condition

Taxes & Ratio

Parts & Labour

Miscellaneous

Summary

Tax Eligibility & Additional Deduction for Parts

Depr./Bttr%

Salvage%

Discount%

Settlement%

Paint Labour/Material Ratio

Paint Labour Ratio

Paint Material Ratio

Cash Loss

Yes No

Part Supplied by AXA

Yes No

Save

Assessment Details

General & Workshop Details Vehicle & Driver Details Vehicle Condition Taxes & Ratio Parts & Labour Miscellaneous Summary **Parts**

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		1	1			BONNET			Repair	0	0	0	0	0	Deny	
		2	1			BONNET HINGE LH			Repair	0	0	0	0	0	Deny	
		3	1			BONNET HINGE RH			Repair	0	0	0	0	0	Deny	
		4	1			BONNET FRONT WEATHERSTRIP			Serviceable	0	0	0	0	0	Deny	
		5	1			BONNET REAR WEATHERSTRIP			Serviceable	0	0	0	0	0	Deny	
		6	1			FRONT BUMPER (\$1100.00)			Buckled	0				0	Reviewing	
		7	1			FRONT BUMPER SIDE RETAINER LH (NPA)			Serviceable	0	0	0	0	0	Deny	
		8	1			FRONT BUMPER SIDE RETAINER RH (NPA)			Serviceable	0	0	0	0	0	Deny	
		9	10			FRONT BUMPER CLIPS (\$15.00)			Necessary	0				0	Reviewing	
		10	1			FRONT EMBLEM (\$65.00)			Necessary	0				0	Reviewing	
		11	1			FRONT BUMPER UPPER GRILLE LH (\$85.00)			Cracked	0				0	Reviewing	
		12	1			FRONT BUMPER UPPER GRILLE RH (\$85.00)			Cracked	0				0	Reviewing	
		13	1			FRONT BUMPER LOWER GRILLE LH			Serviceable	0	0	0	0	0	Deny	

	EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR/ BTRR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
		14	1			FRONT BUMPER LOWER GRILLE RH			Serviceable	0	0	0	0	0	Deny	
		15	1			FRONT BUMPER LOWER GRILLE CHROME LH			Serviceable	0	0	0	0	0	Deny	
		16	1			FRONT BUMPER LOWER GRILLE CHROME RH			Serviceable	0	0	0	0	0	Deny	
		17	1			FRONT BUMPER TOW COVER			Serviceable	0	0	0	0	0	Deny	
		18	1			FRONT BUMPER NUMBER PLATE GARNISH			Serviceable	0	0	0	0	0	Deny	
		19	1			FRONT BUMPER SENSOR - 4PCS (\$160.00)			Shorted	0				0	Reviewing	
		20	1			FRONT BUMPER REINFORCEMENT			Repair	0	0	0	0	0	Deny	
		21	1			FRONT BUMPER SPONGE (\$35.00)			Cracked	0				0	Reviewing	
		22	1			FRONT FENDER RH			Repair	0	0	0	0	0	Deny	
		23	1			FRONT FENDER SHIELD SECTION FRONT RH			Serviceable	0	0	0	0	0	Deny	
		24	1			FRONT FENDER SHIELD SECTION REAR RH			Serviceable	0	0	0	0	0	Deny	
		25	10			FRONT FENDER SHIELD CLIPS			Serviceable	0	0	0	0	0	Deny	
		26	1			HEAD LAMP RH (\$950.00)			Cracked	0				0	Reviewing	
		27	1			HEAD LAMP BRACKET RH (\$95.00)			Damaged	0				0	Reviewing	

EDIT	SR NO	QUAN TITY	MATERIAL	SIDE	PART NAME	PART NUMBER	REPAIR/REPLACE (PARTS)	CONDITION	LIST PRICE	DEPR./ BTTR%	DISC OUNT%	SALV AGE%	PART PRICE(NET)	ACTION (PARTS)	REMOVE
	28	1			FRONT SUPPORT AIR DUCT ASSY (\$220.00)			Cracked	0				0	Reviewing	

Labour

EDIT	SR NO	REPAIR/REPLACE (LABOUR)	PART NAME	LABOUR R&R	LABOUR REPAIR	PAINT	ACTION (LABOUR)	COMMENT	REMOVE
	1		ANTI-RUST COATING	0	0	0	Deny		
	2		PROVIDE SKILL LABOUR TO REMOVE ALL DAMAGED PARTS, PANEL BEAT, CUT & WELD IF NECESSARY AND ALIGN ALL PANEL AND REINSTALL ALL DAMAGED PARTS	500	0	0	Reviewing		
	3		PROVIDE SKILL LABOUR & MATERIAL TO PUTTY ALL DAMAGED PARTS & PANEL & TO RESPRAY WITH 2K PAINT WITH OVEN SPRAY BOOTH FACILITIES	400	0	0	Reviewing		
	4		PROVIDE SKILL LABOUR TO DISCONNECT AND CHECK ELECTRICAL WIRING	20	0	0	Reviewing		
	5		REMOVE AND REPLACE BUMPER SENSORS	60	0	0	Reviewing		
	6		RESET MEMORY MANAGEMENT SYSTEM WITH DIAGNOSTIC FAULT. EG SENSOR PROGRAMMING	120	0	0	Reviewing		

Assessment Details

- General & Workshop Details
- Vehicle & Driver Details
- Vehicle Condition
- Taxes & Ratio
- Parts & Labour
- Miscellaneous
- Summary

EDIT	SR NO	NAME	ACTION	AMOUNT	COMMENT	REMOVE
<input type="checkbox"/>		1	DAYS OF REPAIR : 4 DAYS	Reviewing		
<input type="checkbox"/>		2	PARTS SUPPLIED BY AXAS SUPPLIER \$3,125.00	Reviewing		
<input type="checkbox"/>		3	SENSOR, PASSENGER PROTECTOR (\$180.00)	Reviewing	NECESSARY (SUPPLEMENTARY)	
<input type="checkbox"/>		4	WIRING SET FOR PDC (\$135.00)	Reviewing	CRACKED (SUPPLEMENTARY)	
<input type="checkbox"/>		5	FRONT NUMBER PLATE	Reviewing	45 BENT	

