

REPAIR ESTIMATE*

A14

VEHICLE NO : SHA 6121U

DATE 11/6/2018 11:50

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover /			\$ 562.30
	Front Bumper Bracket Top (LH) ?			\$ 22.40
	Front Bumper Bracket (LH) ?			\$ 24.60
	Front Fender (LH) /			\$ 619.00
	Front Fender Shield (LH) ?			\$ 169.80
	Front Fender Retainer ?			\$ 9.20
	Frt Wheel Hub Cap, LH /			\$ 150.70
	Front LH in Isome pillar Repair			
	SUB TOTAL			\$ 1,558.00
	LESS 20%			\$ 311.60
	DISCOUNTED TOTAL			\$ 1,246.40
	Labour Charge			
	Panel Beating			\$ 560.00 400
	Spray Painting Charge			\$ 500.00
	Tuff Kote			\$ 50.00
	TOTAL LABOUR			\$ 1,110.00
	ESTIMATE TOTAL			\$ 2,356.40
	Ka Lin 10/11/18			
	11/6/18 1230 hrs.			
	3 Bs			
	45			
	After Repair p LK			
	LKK Auto Consultants hence notify the Repairer of the following:			
	• To resurvey before/after spray painting			
	• To display damaged part(s) during resurvey			
	• Parts prices are subject to confirmation			
	• Third party survey is on a "Without Prejudice" basis			
	• No illegal modification(s) is allowed			
	• Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company			
	Acknowledged by Repairer			
	Signature:			
	Date:			
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				