

REPAIR ESTIMATE*

CHINA

VEHICLE NO : SHB 4424D

DATE 11/6/2018 11:15

MAKE :

MODEL : HYUNDAI i40

Qty	Parts Description/ Labour	Type	Unit Price	Amount
	Front Bumper Cover <i>Deformed</i>			\$ 1,052.20
	Front Bumper Bracket (RH) <i>X 500</i>			\$ 24.60
	Headlamp Support Panel Assy <i>X 500</i>			\$ 1,067.50
	Headlamp (RH) <i>100</i>			\$ 1,388.00
	Front Fender (RH) <i>100</i>			\$ 619.00
	Front Fender Shield (RH) <i>X 500</i>			\$ 169.80
	Frt Wheel Hub Cap, RH <i>X 500</i>			\$ 150.70
	SUB TOTAL			\$ 4,471.80
	LESS 20%			\$ 894.36
	DISCOUNTED TOTAL			\$ 3,577.44
	Labour Charge			
	Panel Beating			\$ 1,000.00 <i>400</i>
	Spray Painting Charge			\$ 500.00 <i>400</i>
	Wiring Charge			\$ 50.00 <i>30</i>
	Tuff Kote			\$ 50.00 <i>20</i>
	Remove/Refix Aircon & Refill Gas			\$ 150.00 <i>X 20</i>
	TOTAL LABOUR			\$ 1,750.00
	ESTIMATE TOTAL			\$ 5,327.44
<i>Kahin 10/11/18</i> <i>11/6/18 1240hrs</i> <i>2 hrs</i> <i>PIP</i> <i>Before P.I.P photo</i>				
LKK Auto Consultants hence notify the Repairer of the following: • To resurvey before/after spray painting • To display damaged part(s) during resurvey • Parts prices are subject to confirmation • Third party survey is on a "Without Prejudice" basis • No illegal modification(s) is allowed • Supplementary item(s) must be resurveyed and is subject to final approval from Insurance Company Acknowledged by Repairer Signature: Date:				
This is an initial estimate based on a visual inspection of the above vehicle. The final repair quantum will be prepared after the vehicle is surveyed by a motor Surveyor appointed by the insurance company.				