

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park
Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC4/III18010706/R1GA3Q2

Date: 14/05/2020

REFERENCE

Handling Insurer: India International Insurance Pte Ltd	Policy No:	M494828
Claimant		
Vehicle No : SLJ6249R	Insured Vehicle No :	SLT5835C
Date of Loss: 10/06/2018	Nature of Claim: TP	Claim No: MC20182511

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ6249R	Engine No:	HIDDEN
Make & Model:	TOYOTA WISH, 1.8 X CVT (A)	Chassis No:	ZGE206034337
Reg. Date:	01/12/2016 (Man. Year: 2016)	Odometer:	76881 km
Colour:	Grey		
Engine Capacity:	1797 cc		
Market Value/New Car Price:	N/A		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	195/65 R15	Rear Tyre Size:	195/65 R15
Front Left Side:	West Lake 6 mm	Rear Left Side:	West Lake 6 mm
Front Right Side:	West Lake 6 mm	Rear Right Side:	West Lake 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	2,194.30	1,133.72	1,060.58	48.33
Miscellaneous Items	0.00	0.00	0.00	
Labour	1,400.00	700.00	700.00	50.00
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	3,594.30	1,833.72	1,760.58	48.98
+ GST 7.00/7.00% (S\$)	251.60	128.36	123.24	48.98
Nett Amount (S\$)	3,845.90	1,962.08	1,883.82	48.98
+ Loss of Use (2.0 x S\$70.00/day) (S\$)		140.00		
+ Car Rental (2.0 x S\$120.00/day) (S\$)		240.00		
+ Doc/Search Fee (S\$)		2.00		
Nett Liability (S\$)		2,344.08		

INSPECTION

Date of Assignment:	13/06/2018	Inspected At:	Allswell Motor Traders (HQ)
Date Inspected:	13/06/2018		25 Defu Lane 9
			Singapore 539266
Estimated Period of Repair:	4.0 days		

Adjuster: MOHD RASUL

Manager: Chong Pui Lin

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Reference

Part Source: MRM-SG	Version: 1.0 (Last Synchronised: 01 Apr 2020)	
Parts: M1-MPV	TOYOTA WISH 1.8 X CVT (A) (Catalogue:Merimen Singapore 1.0)	
Labour: Repairer's	(Price-denominated Standard List)	
Print Code:	(Unsubmitted, no print-code for SLJ6249R)	
Validity:	These estimates are valid only if they contain the print code (above) on all estimate pages, running page numbers with the END OF ESTIMATES marker on the last estimate page	
Further Info:	Items/values not in reference catalogue are prefixed with an asterisk *.	

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*FRONT BUMPER	Deformed	1,109.00 F	*1,109.00 FL
2	1		*RH BUMPER RETAINER	Necessary	102.00 F	*102.00 FL
3	1		*RH FENDER	Repair	690.00 F	*- FL
4	1		*RH FOG COVER (NO HOLE)	Missing	92.00 F	*92.00 FL
5	1		*RH INNER SHIELD	Deformed	179.30 F	*179.30 FL
6	2		*CLIPS	Necessary	22.00 FS	*22.00 FS

F=Franchise part. S=SpcNett. L=ListItemDisc.

Sub Total (\$\$)	2,194.30	1,504.30
- List Item Discount on L Items 0.00/25.00% (\$\$)	0.00	370.58
Total Parts (\$\$)	2,194.30	1,133.72

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	DISMANTLE /ASSEMBLY OF AFFECTED PARTS	New	380.00	300.00
2	SPRAY PAINTING OF ALL PARTS (BUMPER & FENDER)	New	760.00	400.00
3	PANEL BEATING OF RH FENDER	New	260.00	0.00
Gross Labour Cost (\$\$)			1,400.00	700.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >