## BH AUTO SERVICES PTE LTD

Blk 1, Sector C , Sin Ming Industrial Estate #01-111 / 113 / 115 / 117 Singapore 575636 Tel: 6559 8944 / Fax: 6269 2404

Reany After Peny

Date: 12/06/2018

Page: 1 of 2

AIG Asia Pacific Insurance Pte. Ltd

AIG Building 78 Shenton Way #08-16 Singapore (079120)

ATTN: MOTOR CLAIM DEPARTMENT

Tel: 6419 3000 Fax: 6835 7416

**ACCIDENT REPAIR ON: SJZ8694P** 

MODEL: MERC E250 CGI
POLICY NO: 8-V0016870-MVA
CHASSIS NO: WDD2120472A367607
MANUFACTURING YEAR: 2010

DATE / TIME OF ACCIDENT: 08/06/2018 Time: 1035Hrs ALONG TPY CENTRAL HDB HUB CARPARK B3

THIRD PARTY VEHICLE NO: SLV2538U

Appended below are the estimated cost of repair and parts to be replaced for the above vehicle: -

Replace	ment Of Parts	Quantity	Unit Price	Condition	Amount
S/N			S\$	0	, S\$
1	Front Bumper	1	1400.00	BN.	n 1,400.00 -
2	Front Bumper Side Retainer LH	1	38.00		Fee 38.00 X
3	Front Bumper Side Retainer RH	1	38.00		€ 38.00 X
4	Front Bumper Sensor	4	25.00		100.00 ?
5	Front Bumper Sensor Ring	4	12.00		48.00 7
6	Front Bumper Nozzle Cover RH	1	58.00		58.00 7
7	Front Bumper Lower Side Grille RH	1	60.00		60.00 X
8	Front Bumper Lower Side Grille Chrom	e RH 1	115.00		115.00 7
9	Front Bumper Lower Side Daytime Sav		470.00		In 470.00 X
10	Head Lamp RH	1	3065.00		3,065.00 7
11	Head Lamp Bracket RH	1	260.00		M 260.00 X
	LKK Au	to Consultants hence no	tify	Sub-Total:	5,652.00
	the Kep	pairer of the following: rvey before/after spray painting	Less	Discount 10%	565.20
	• To displ	ay damaged part(s) during resi		Total Parts:	5,086.80
	Parts pr	rices are subject to confirmation	urvey		-,
	• Third pa	arty survey is on a "Without Pre	iudice" basis		
Special Nett Items   • No illegal modification		al modification(s) is allowed			
1	Front Pumper Cline Suppler	mentary item(s) must be resurved to final approval from Incurse	eyed and 8 00		Ma 80.00
	is subje	ct to final approval from Insurar	nce Company	Total Parts:	80.00
	Acknowle	dged by Repairer		rotar rantor	00.00
Labour (	Charges For Front RH Portion Signature				
1	Provide skill labour to remove all damage	ged parts, panel bear	t. cut & weld	if	2501
	necessary and align all panel and reinst	tall all damaged parts	S.		600.00
2	Provide skill labour & material to putty all damaged parts & panel & to respray				2501
	with 2K paint with oven spray booth facilities				600.00
3	Provide skill labour to disconnect and check electrical wiring			30.00 201	
4	Reset/Reprogram management system with diagnostic fault e.g Headlamp ECU			350.00	
5	Remove and replace bumper sensor	9	3		100.00
	Total Labour:				1,680.00
			Total Parts	& Labour:	6,846.80
			GST 7%		479.28
			Grand Total:		7,326.08
					.,

## **Estimate Repair Duration**

2-3da

ACCIDENT VEHICLE OF: SJZ8694P

Page: 2 of 2

Remark: Supplementary estimate will be raised in the event additional damaged parts are found in the course of repair.

Yours sincerely,

ESTIMATOR: ANTHONY

Survey attended by:

Name : Kenneth

Company : CICIC

Date : 13/6/18

Time : 11em

Contact Nc: 969,0663

Email