



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 3

### ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. FU 842E

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
	<b><u>REPLACEMENT OF PARTS</u></b>			
2	FRONT HANDLE @ \$120.00	O/S REPLACED / N/S SERVICEABLE	240.00	120.00
2	FRONT HANDLE GRIP @ \$21.00	O/S REPLACED / N/S SERVICEABLE	42.00	21.00
2	FRONT HANDLE BALANCER @ \$15.00	O/S REPLACED / N/S SERVICEABLE	30.00	15.00
1	BRAKE LEVER	REPLACED	45.00	45.00
1	CLUTCH LEVER	SERVICEABLE	45.00	-
1	BRAKE MASTER PUMP	NOT NECESSARY	180.00	-
1	FRONT VIEW MIRROR O/S	REPLACED	55.00	55.00
1	FRONT VIEW MIRROR N/S	SERVICEABLE	55.00	-
1	FRONT VIEW DAMPER	REPLACED	25.00	25.00
2	FRONT INDICATOR LAMP @ \$85.00	O/S REPLACED / N/S SERVICEABLE	170.00	85.00
1	FRONT WINDSHIELD	REPLACED	65.00	65.00
1	HEADLAMP ASSEMBLY	REPLACED	260.00	260.00
1	HEADLAMP ASSY	REPLACED	95.00	95.00
1	FRONT FENDER	REPLACED	190.00	190.00
2	FRONT FORK ASSEMBLY @ \$350.00	REPLACED	700.00	700.00
1	STEERING BEARING / CONE	REPLACED	110.00	110.00
1	FRONT BRAKE DISC	NOT NECESSARY	250.00	-
1	FRONT AXLE	NOT NECESSARY	95.00	-
1	UPPER COWLING	REPLACED	230.00	230.00
1	LOWER COWLING O/S	REPLACED	200.00	200.00
1	LOWER COWLING N/S	NOT NECESSARY	200.00	-
1	INNER COWLING	REPLACED	105.00	105.00
1	SIDE FAIRING O/S	REPLACED	160.00	160.00
1	SIDE FAIRING N/S	REPAIRED SEE LABOUR	160.00	-
1	SET FUEL TANK 'KAWASAKI' DECAL	REPLACED	25.00	25.00
1	CARBURETTOR ASSEMBLY	NOT NECESSARY	320.00	-
1	FRONT REST STEP BAR O/S	REPLACED	46.00	46.00

Report Ref No. CS/AIG18010724/T1qbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	FOOT REST STEP BAR N/S	SERVICEABLE	46.00	-
1	FOOT REST BRACKET O/S	REPLACED	45.00	45.00
1	FOOT REST BRACKET N/S	SERVICEABLE	65.00	-
1	TAIL COVER	REPLACED	65.00	65.00
1	REAR FENDER	SERVICEABLE	60.00	-
1	REAR BRACKET LAMP ASSEMBLY	REPLACED	120.00	120.00
1	EXHAUST MUFFLER / TAILPIPE	REPLACED	285.00	285.00
1	EXHAUST MUFFLER GASKET	REPLACED	18.00	18.00
1	EXHAUST TAILPIPE GASKET	REPLACED	15.00	15.00
	LESS 10% DISCOUNT		-	-310.00
			4,817.00	2,790.00
	<b><u>SPECIAL NETT ITEMS</u></b>			
1	FRONT RIM (LOCAL REPAIR) (SN)	REPLACED	460.00	100.00
1	FUEL TANK ASSEMBLY (LOCAL REPAIR) (SN)	REPLACED	500.00	200.00
1	FRONT LICENCE PLATE (SN)	REPLACED	18.00	18.00
			978.00	318.00
	<b><u>LABOUR</u></b>			
	TO TRANSPORTATION CHARGES. }		1,250.00	40.00
	TO DISMANTLE / RENEW FUEL TANK TO FACILITATE REPAIRS. }		-	50.00
	TO DISMANTLE / RENEW O/S & N/S FRONT FORK (INNER & OUTER) TO FACILITATE REPAIRS. INCLUSIVE OF THE REPAIR OF SIDE FAIRING N/S. }		-	150.00
	TO DISCONNECT FRONT & REAR WIRE HARNESS OF ELECTRICAL COMPONENTS TO FACILITATE REPAIRS, RECONNECT & CHECK FUNCTIONS INCLUDING TO FOCUS HEADLAMPS. }		-	30.00
	TO HEAT, CUT / WELD EXHAUST MUFFLER INCLUDING ALIGN SYSTEM & TO CHECK FOR CARBON MONOXIDE LEAKAGES. }		-	50.00
	TO DISMANTLE / RENEW FRONT TYRE RIM / TYRE INCLUDING TO OSCILLATE / EQUIPOISE COMPONENTS. }		-	30.00
	TO DISMANTLE / RENEW THE ACCIDENT DAMAGED PORTION INCLUDING TO HEAT, KNOCK-OUT, STRAIGHTEN & ALIGN COMPONENTS AS LISTED IN SCHEDULE. }		-	100.00

Report Ref No. CS/AIG18010724/T1qbs2



## LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:3 of 3

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	TO MOUNT MOTORCYCLE ONTO ALIGNMENT BENCH; SET-UP & EQUIPMENT & TO ALIGN / CALIBRATE / CORRECT (FRONT CROSS BRACING, BACK BONE SUB- FRAME, SWING ARM BRACKET SUB-FRAME, REAR FRAME SECTION ETC) TO SYMMETRICAL SPECIFICATIONS. }		-	100.00
			1,250.00	550.00
<b>GRAND TOTAL</b>			<b>7,045.00</b>	<b>3,658.00</b>
<b>RECOMMENDED COST OF LUMP SUM REPAIRS (TO ITS PRE-ACCIDENT CONDITION)</b>				<b>2,900.00</b>

Report Ref No. CS/AIG18010724/T1qbs2

MOHAMAD TAUFIKH

M.MATAI, AMSAE-A

Automotive Assessor

K.K.LAU CPT(RET)

BEng(Hons),B.Bus,MBA,PEng,PE,  
MInstAEA,MASME,MIRTE

REGD Auto Consultant-SAE, Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.