





PRO PLUS AUTOMOBILE ENGINEERS (Inspection photographs)













FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



1/22: Front View



2/22: Rear View



3/22: General View Right

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



4/22: General View Left



5/22: Odometer Reading



6/22: Chassis Number

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



7/22: Photographs of Damaged Items



8/22: Photographs of Damaged Items



9/22: Photographs of Damaged Items

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



10/22: Photographs of Damaged Items



11/22: Photographs of Damaged Items



12/22: Photographs of Damaged Items

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



13/22: Photographs of Damaged Items



14/22: Photographs of Damaged Items



15/22: Photographs of Damaged Items

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



16/22: Photographs of Damaged Items



17/22: Photographs of Damaged Items



18/22: Photographs of Damaged Items

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



19/22: Photographs of Damaged Items



20/22: Photographs of Damaged Items



21/22: Photographs of Damaged Items

FU842E [SDU1996L] - Submitted by: AIG Asia Pacific Insurance Pte. Ltd. (SG)



22/22: Photographs of Damaged Items