Berreyor.	REF: (SI/6	AZ18010726 /W Vber	Special Instruction: PGL of Sur
From (Person): Radio (and of GAL Bill to:	Date/Time: 12061018	Third Parties: Claimant:
Policy No: Sum Insured: Make of Veh: (Client's Record) Date/Time: Date/Time: Date/Time: Action/Instru BD - 56 A	Person Contacted Confirmed with Submit Final Fig 45 3	Claim No: CLMOMV Excess: D.O.A. 3301300 d: Vehicle IN/O Final Fig , days 3/00 , Ldays (Red \$ 1300)	Surveyor: Auto Perfumunu Workshop: M.S. Panul Beding CO0000 2540 H.O.D. Endorsement/Date:
GBD 956K	Δ		
			URGENT
Para(1): Parts found	d not replaced (T	Го highlight <i>R or UB</i> ,	URGENT LR, Etc)
4			
•		damages (Parts Not Cons	
4	on consistency of	damages (Parts Not Cons	
Para(2): Comments Para(3): Nett Value Market Value Salvage Value Nett Value	nlue :alue :	damages (Parts Not Constant of State of	Fee Charged: Date: Basic & Add Transport Photos Others
Para(2): Comments Para(3): Nett Value Market Va Salvage Value Nett Value 1) Date/Time 13 6- typi	RECEIVED alue: alue: File Pass to	damages (Parts Not Considerate of Parts Not Co	Fee Charged: Date: Basic & Add Transport Photos Others Total Date: 250
Para(2): Comments Para(3): Nett Value Market Value Salvage Value	nlue :alue :	damages (Parts Not Considerate of Parts Not Co	Fee Charged: Date: Basic & Add Transport Photos Others Total

Catherine Chong (LKK Auto)

From:

Tan, Rachel <Rachel.Tan@sg.gaig.com>

Sent:

Tuesday, 12 June, 2018 4:22 PM

To:

Catherine Chong (LKK Auto)

Cc: Subject:

assignments@lkkauto.com

CLMOMVC000002540 - GBD9564K (GA) / GBD759A

Attachments:

12062018161903-0001.pdf

Hi Catherine

Attached is report from TP's appointed surveyor.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Catherine Chong (LKK Auto) <admin-d@lkkauto.com>

Sent: Tuesday, June 12, 2018 4:16 PM To: Tan, Rachel <Rachel.Tan@sg.gaig.com>

Cc: assignments@lkkauto.com

Subject: [External] RE: Our Ref: SB/PO/Acc/2018-8638 Your Ref: Insurer of GBD9564K (GA)

Dear Rachel,

As spoken, kindly forward us the survey report and colour photograph for Paper Survey.

Sorry for the inconvenience caused.

Best Regards,

Catherine Chong | Admin

LKK Auto Consultants Pte Ltd

Phone: 6741-8434 | email: assignments@lkkauto.com | fax: 6256-4315 Blk 51, Paya Ubi Industrial Park, Ubi Avenue 1, #02-25 | S(408933)

From: Tan, Rachel [mailto:Rachel.Tan@sg.gaig.com]

Sent: Tuesday, 12 June 2018 2:05 PM

To: SUR < sur@lkkauto.com>

Cc: Denise Tay (LKKAuto) < denisetay@lkkauto.com>

Subject: RE: Our Ref: SB/PO/Acc/2018-8638 Your Ref: Insurer of GBD9564K (GA)

HI LKK

Have you sent Survey report?

I received a 10 days notice from the lawyers!

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Tan, Rachel

Sent: Tuesday, May 15, 2018 7:20 PM

To: 'SUR' < sur@lkkauto.com>

Subject: RE: Our Ref: SB/PO/Acc/2018-8638 Your Ref: Insurer of GBD9564K (GA)

Dear LKK

Please provide survey report urgently.

We received LOD from TP OraceLaw on 18 April 2018.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Tan, Rachel

Sent: Tuesday, January 30, 2018 10:27 AM To: 'Oracle Law Corp' < mail@oraclelaw.sg>

Cc: SUR < sur@lkkauto.com>

Subject: RE: Our Ref: SB/PO/Acc/2018-8638 Your Ref: Insurer of GBD9564K (GA)

Without Prejudice

Dear Sir

We disagree with your list of surveyors indicated on your letter on 30 Jan 2018, and will be appointing LKK to conduct PRS.

Please provide location, time and contact details of the workshop.

Dear LKK

Please accept assignment to conduct PRS, thank you.

Regards

Rachel Tan

Executive, Motor Claims, Great American Insurance Company

Tel: 6804 7846

From: Oracle Law Corp [mailto:mail@oraclelaw.sg]

Sent: Tuesday, January 30, 2018 9:31 AM
To: Tan, Rachel < Rachel. Tan@sg.gaig.com > Cc: Oracle Law Corp < mail@oraclelaw.sg >

Subject: Our Ref: SB/PO/Acc/2018-8638 Your Ref: Insurer of GBD 9564K

Dear Rachel.


PRE-REPAIR INSPECTION

ACCIDENT INVOLVING GBD 759A & GBD 9564K ALONG PIE TOWARDS CHANGI B4 STEVEN ROAD EXIT ON 23-01-2018 @ 3.10 P.M.

Please refer to attachment, the contents of which are self-explanatory.

Regards

Alvin Ong



Advocates & Solicitors
 UEN/GST Reg No. 200904572Z

237 Alexandra Road #04-11
The Alexcier, Singapore 159929
Telephone: 6538 6250 Egosimile:

Telephone: 6538 6250 Facsimile: 6538 1860

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

The content of this e-mail message and any attachments are confidential and may be legally privileged, intended solely for the addressee. If you are not the intended recipient, be advised that any use, dissemination, distribution, or copying of this e-mail is strictly prohibited. If you receive this message in error, please notify the sender immediately by reply email and destroy the message and its attachments.

AUTO PERFORMANCE APPRAISAL



VEHICLE SURVEY REPORTS

AUTOSWIFT RECOVERY PTE LTD C/O M.S. Panel Beating Workshop 2 Kaki Bukit Ave 2 #02-17 AutoHub @ Kaki Bukit Singapore 417921

Reference

Job Reference No

: 18/001622

Claim No

Claim No Claim Type

: Third Party

Accident Date

: 23/01/2018

Survey Date

: 22/03/2018

Survey Report Date

: 27/03/2018

2 Particulars Of Vehicle

Vehicle Registration No

: GBD759A

Make & Model

: Isuzu TFR86JSR

Vehicle Registration Date

: 10/06/2014

Chassis No

: MPATFR86JET001392

Engine No

: Blocked

Colour

: Yellow

Condition Of Vehicle And Tyres Mileage (KM)

Mileage (KM) 160852	Brakes Serviceable	Steering Serviceable	Modification None
Tryes Front RHS	Make Continental	<u>Size</u> 215/70R15C	Balance (MM)
Front LHS	Continental	215/70R15C	5
Rear RHS	Continental	215/70R15C	6
Rear LHS	Continental	215/70R15C	6

Description Of Damages

The vehicle sustained damages at rear portion.

(For information of damages please refer to Parts/Labour/Photographs attached)

5 Instruction

This survey was conducted entirely on a "WITHOUT PREJUDICE" basis, and we have not authorised any repair.

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Ref No:

18/001622

Damage And Repair Cost Adjustment

	<u>S/No</u>	Qty	Parts Description	Comments/condition	Workshop Estimate (\$)	Our Assessment (\$)
•	1 2 3	1 2 1	Taillamp Rear number plate lamp Rear lower spare tyre carrier chain	<u>List Items</u> Broken/cracked Reuse Bent/jammed	11.00	770.00 X
(Less discount 15%	Total :	979.00 146.85 832.15	935.00 140.25 794.75
	4 5 6 7 8 9	1	Rear body panel Rear body panel gate Rear body panel "60km/h" sticker Rear body panel company logo, contact & wedsite sticker Rear number plate Rear lower spare tyre Reverse sensors	Special Nett Items Dented/bent To repair Necessary Necessary Reuse Reuse Malfunction	2,200.00 1,800.00 12.00 450.00	1
,	11	1	Rear security camera	Malfunction Total:	450.00 / 5,792.00	
(.				Total Spare Parts:	6,624.15	4,156.75

654.5 3686.5 3111

AUTO PERFORMANCE APPRAISAL

Vehicle Assessment Reports

Ref No:

18/001622

Damage And Repair Cost Adjustment

Items	Job Description	Workshop Estimate (\$)	Adjusted Costs (\$)
1	To remove, jack out, straighten, panel beating, align and renew replaced parts.	1,000.00	600.00 /
2	To putty and respray painting on affected areas.	1,200.00	700.00 SOO
3	To check wirings and lightings.	40.00	20.00 🗸
4	To supplied and applied anti rust treatments.	50.00 AA	30.00 🙏
	Total Labour :	2,290.00	1,350.00
	Total Spare Parts :	6,624.15	4,156.75
	Total Labour : Total Repair Costs :	2,290.00 8,914.15	1,350.00 5,506.75
	J. Double . L	0,017.10	0,000.70

Assessor's Recommendation

Repairer Estimate :

8,914.15

Our Adjustment:

5,506.75

Remarks

The repairer has agreed to undertake the repair on a lump sum basis of \$4,400.00, with a repair period of 5 working days.

Surveyed By:

Lek Boon Hwee

Automobile Appraiser

3232

Date: 13th June 2018 Your Ref: CLMOMVC000002540

Our Ref: CS1/GAI18010726Uvbe2

M/s Great American Insurance Company

3 Temasek Avenue #16-01 Centennial Tower Singapore 039190 (The Motor Claims Department)

Dear Sir / Madam,

EVALUATION REPORT (PAPER SURVEY) OF ACCIDENT VEHICLE NO: GBD 759A INSURED VEHICLE NO: GBD 9564K ACCIDENT ON 23/01/2018

We thank you for your instruction on 12/06/2018.

We acknowledge receipt of the following documents:-

a) Automobile Inspection Report of GBD 759A from M/s Auto Performance Appraisal.

b) Colour damaged vehicle photographs of GBD 759A.

Based on the documents received from you, we have evaluated the damages of the vehicle and have the following comments:-

1. Information Recorded: -

Registration Number

Make & Mode

: GBD 759A : Isuzu TERO : Isuzu TFR86JSR

Year of Registration

: 2014

Chassis Number

: MPATFR86JET001392

2. We recommend that the repairs of the entire damage require about 4 (Four) working days to complete.

3. We hereby provide our recommendations on the cost of repair to the damaged vehicle as stated in the following page.



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 1

ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. GBD 759A

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
	REPLACEMENT OF PARTS			
1	TAILLAMP	CRACKED	770.00	770.00
2	REAR NUMBER PLATE LAMP	SERVICEABLE	44.00	-
1	REAR LOWER SPARE TYRE CARRIER CHAIN	NOT NECESSARY	165.00	-
	LESS 15% DISCOUNT		-146.85	-115.50
			832.15	654.50
	SPECIAL NETT ITEMS			
1	REAR BODY PANEL (SN)	DENTED / BENT	2,200.00	1,600.00
1	REAR BODY PANEL GATE (SN)	TO REPAIR SEE LABOUR	1,800.00	-
1	REAR BODY PANEL "60KM/H" STICKER (SN)	NECESSARY	12.00	12.00
1	SET REAR BODY PANEL COMPANY LOGO, CONTACT & WEDSITE STICKER (SN)	NECESSARY	450.00	300.00
1	REAR NUMBER PLATE (SN)	NOT NECESSARY	410.00	-
1	REAR LOWER SPARE TYRE (SN)	NOT NECESSARY	220.00	-
1	SET REVERSE SENSOR (SN)	SHORTED	250.00	200.00
1	REAR SECURITY CAMERA (SN)	NOT NECESSARY	450.00	-
			5,792.00	2,112.00
	LABOUR			
	TO REMOVE, JACK OUT, STRAIGHTEN, PANEL BEATING, ALIGN AND RENEW REPLACED PARTS. INCLUSIVE OF THE REPAIR OF REAR BODY PANEL GATE.		1,000.00	600.00
	TO PUTTY AND RESPRAY PAINTING ON AFFECTED AREAS.		1,200.00	500.00
	TO CHECK WIRING AND LIGHTINGS.		40.00	20.00
	TO SUPPLIED AND APPLIED ANTI RUST TREATMENTS.	NOT NECESSARY	50.00	-
			2,290.00	1,120.00
	GRAND TOTAL		8,914.15	3,886.50

RECOMMENDED COST OF LUMP SUM REPAIRS	3,100.00
(TO ITS PRE-ACCIDENT CONDITION)	

Report Ref No. CS1/GAI18010726Uvbe2

CHUA KANG SENG

Licensed Appraiser

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contact or tort, is accepted to any third party who may reply on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.