

EQ / LKK



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Repair Estimates

PC 2983 U

Parts (a) Cost / List Price Items	\$	5,420.00
Plus/Less 25%	\$	1,355.00
Total of Cost / List	\$	4,065.00
(b) Nett Price Items		
Less		
Total of Nett Item		
(c) Special Nett Items	\$	130.00
Total Parts Cost	\$	4,195.00
Labour	\$	3,670.00
Total	\$	7,865.00

Not Authorized
Phony Billing

LKK Auto Consultants hence notify the Repairer of the following:

- To resurvey before/after spray painting
- To display damaged part(s) during resurvey
- Parts prices are subject to confirmation
- Third party survey is on a "Without Prejudice" basis
- No illegal modification(s) is allowed
- Supplementary item(s) must be re-surveyed and is subject to final approval from Insurance Company

Acknowledged by Repairer

Signature:

Date:

The above total will be subjected to 7% G.S.T.

Name of Surveyor : Kennerth
Company : LKK
Survey conducted on : 12/8/18 at _____

Remarks By Surveyor

(a) The repair of this vehicle is authorized / is not authorized until further notice.

(b) Recommended Days of Repair : 06 day(s)

(c) Resurvey : Required / Not Required

(d) Excess : \$ _____

(e) Signature of surveyor : Le Date: 12/8/18



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Spare Parts

Vehicle No. : **PC 2983 U**
Make & Model : **TOYOTA HIACE**
Chassis No : **JTFJT02P400001696**

Submit By : **Carmen Lim**
Year Manufacture : **2014**
Engine No. :
Cost / List

S/No.	Part Description	Qty	Unit Price	Price	Disposition by Surveyor
1	LH front door <i>RA</i>	1	\$1,548.90		<i>X</i>
2	LHF door glass outer moulding <i>SL</i>	1	\$109.50		<i>X</i>
3	LH sliding door <i>B</i>	1	\$1,515.65		<i>✓</i>
4	LH sliding door top hinge	1	\$97.60		<i>?</i>
5	LH sliding door bottom hinge	1	\$175.90		<i>?</i>
6	LH sliding door lock <i>n</i>	1	\$375.60		<i>X</i>
7	LH sliding door sticker "EXCURSION BUS" <i>na</i>	1	\$30.00	S.N	<i>✓</i>
8	LH sliding door glass sealant <i>na</i>	1	\$50.00	S.N	<i>Posn</i>
9	LH rear fender <i>RA</i>	1	\$1,431.75		<i>✓</i>
10	LH rear fender glass sealant <i>na</i>	1	\$50.00	S.N	<i>Posn</i>
11	LH rear hub cab <i>SL</i>	1	\$165.10		<i>✓</i>
12					
13	<i>258</i>				
14					
15					
16					
17					
18					
19					
20					
21					
22					
23					

Note: If any of the quoted parts are recommended to be repaired, then an additional labour charge will be charged accordingly under supplementary.



ESTEEM PERFORMANCE PTE LTD

Blk 5033 Ang Mo Kio, Ind Park 2 #01-251/ 259, 569536.
Tel: +65-6484 1221 Fax: +65-6484 7829 Website: www.esteemperf.com.sg

Labour

Vehicle No. : **PC 2983 U** Submit By : **Carmen Lim**
Make & Model : **TOYOTA HIACE** Year of Manufacture : **2014**

S/No	Labour Description	Estimated Price	Adjusted Price
1	TO RENEW DAMAGED PARTS & KNOCK OUT ACCIDENT REPAIR AREA. (LHF DOOR,LH SLIDING DOOR,LHR FENDER)	\$1,200.00	800
2	TO PUTTY, RESPRAY PAINT FOR AFFECTED ACCIDENT REPAIR AREA. (LHF DOOR,LH SLIDING DOOR,LHR FENDER)	\$1,200.00	500
3	To check wiring	\$50.00	20
5	To tuff coat	\$150.00	60
6	To remove & refit Door trim, door glass, window regulator, door lock to assist work load.(LHF DOOR , LH SLIDING DOOR)	\$350.00	120 180
7	To remove & refit LH REAR FENDER glass to assit work load	\$120.00	100
8	To remove & refit inner seat & upholstery to assist work load.	\$600.00	250

Note: The above estimate of repair is based on visual assessment of the external affected areas. Any additional damages observed during the course of repair will be quote accordingly as a supplementary.