



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:1 of 2

## ADJUSTMENT ON REPAIR COST FOR VEHICLE NO. SLM 3699D

Qty	Description of Parts	Condition	Estimate By Workshop (\$))	Our Adjusted (\$)
<b><u>REPLACEMENT OF PARTS</u></b>				
1	FRONT BUMPER	NOT NECESSARY	826.00	-
1	FRONT BUMPER SIDE RETAINER LHS	NOT NECESSARY	92.00	-
1	FRONT FENDER LHS	BENT	334.00	334.00
1	FRONT FENDER INNER WHEEL HOUSE PANEL LHS	TO REPAIR SEE LABOUR	1,547.00	-
1	FRONT FENDER INNER COWLING LHS	DEFORMED	130.00	130.00
10	FRONT FENDER INNER COWLING CLIPS @\$4.50	NECESSARY	45.00	45.00
2	FRONT FENDER AIR BAFFLE REAR @\$35.00	NOT NECESSARY	70.00	-
2	FRONT FENDER AIR BAFFLE REAR CLIPS @\$5.00	NOT NECESSARY	10.00	-
1	FRONT SHOCK ABSORBER LHS	NOT NECESSARY	287.00	-
1	FRONT SHOCK ABSORBER TOP MOUNT	NOT NECESSARY	92.00	-
1	FRONT LOWER ARM	NECESSARY	485.00	485.00
1	FRONT WHEEL KNUCKLE	NECESSARY	384.00	384.00
1	FRONT WHEEL BEARING WITH HUB	NECESSARY	542.00	542.00
1	FRONT STABILIZER BAR	NOT NECESSARY	1,219.00	-
2	FRONT STABILIZER BAR BUSHING @\$28.50	NOT NECESSARY	57.00	-
2	FRONT STABILIZER BAR LINK @\$65.00	NECESSARY	130.00	130.00
1	FRONT DOOR LHS	TO REPAIR SEE LABOUR	1,062.00	-
1	DOOR LHS HINGE TOP	NOT NECESSARY	42.00	-
1	DOOR LHS HINGE BOTTOM	NOT NECESSARY	40.00	-
1	DOOR SIDE MIRROR COVER	NOT NECESSARY	123.00	-
1	FRONT LH WHEEL COVER	DEFORMED	99.80	99.80
1	DRIVE SHAFT (ADDITIONAL)	NOT NECESSARY	1,336.00	-
1	DRIVE SHAFT OIL SEAL (ADDITIONAL)	NOT NECESSARY	24.00	-
	LESS 20% DISCOUNT		-1,795.36	-429.96
			7,181.44	1,719.84
<b><u>SPECIAL NETT ITEMS</u></b>				
1	FRONT LHS RIM (SN)	NECESSARY	250.00	250.00
1	FRONT LHS TYRE (SN)	NOT NECESSARY	350.00	-

Report Ref No. CC4/QBE18010730/R1ka3q2



# LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Page No.:2 of 2

Qty	Description of Parts	Condition	Estimate By Workshop (\$)	Our Adjusted (\$)
1	GEAR OIL (3.5 PCS) @\$10.00 (SN) (ADDITIONAL)	NOT NECESSARY	35.00	-
			635.00	250.00
	<b>LABOUR</b>			
	TO CHECK ELECTRICAL LIGHTING CONCERNED .	NOT NECESSARY	80.00	-
	TO CHECK STEERING GEOMETRY AND COMPUMPER WHEEL ALIGNMENT.		150.00	60.00
	PANEL BEATING ,KNOCKING AND STRAIGHTEN THE NECESSARY PORTION,REMOVE AND RENEWAL OF PARTS ,ADJUST AND REALIGN THE SAME.INCLUSIVE OF THE REPAIR OF FRONT FENDER INNER WHEEL HOUSE PANEL LHS AND FRONT DOOR LHS .		600.00	300.00
	PUTTY AND SPRAY PAINTING OF THE AFFECTED PORTION .		500.00	400.00
	TO TRANSFER OF DOOR FITTINGS AND PERFORM WATER SEEPAGE TEST.	NOT NECESSARY	120.00	-
	SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF PARTS ,TO PERFORM FINAL CHECKING AND TESTING.	NOT NECESSARY	108.00	-
	TO DISMANTLE SUSPENSION UNDERCARRIAGE PARTS ,REMOVE AND RENEWAL OF PARTS. (ADDITIONAL)		250.00	180.00
			1,808.00	940.00
<b>GRAND TOTAL</b>			<b>9,624.44</b>	<b>2,909.84</b>
<b>RECOMMENDED COST OF REPAIRS</b>				<b>2,909.84</b>

Report Ref No. CC4/QBE18010730/R1ka3q2

MOHAMMED RASUL BIN MOHD YUNUS

Automotive Assessor

HO LEONG CHUAN

Automotive Assessor

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report.

No liability of responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or replying on this Report, in whole or in part, does so at his or her own risk.