

## **LKK Auto Consultants Pte Ltd**

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

| Affiliated to Federation Internationale Des Experts En Automobile   |  |                   |                              |                   |            |  |
|---|--|-------------------|------------------------------|-------------------|------------|--|
| QBE INSURANCE (SINGAPORE) PTE LTD   |  |                   | Ref: CC4/QBE18010730/R1ka3q2 |                   |            |  |
| 1 RAFFLES QUAY #29-10 SOUTH<br>TOWERSINGAPORE 048583  |  |                   | Date :                       | 15-05-2020<br>QBE |            |  |
| 1. Policy Particulars :- THIRD PARTY CLAIM  |  |                   |                              |                   |            |  |
| Insured V   | <b>eh.</b> XD 28                                   | 51S               | Veh. In                      | spected           | SLM 3699D  |  |
| Policy No   | . 8-V000   | )3244-MVA-R007    | Covera                       | age (\$)          | 0.00       |  |
| Claim No.   | VC011  | 567               | Excess                       | s (\$)            | 0.00       |  |
| Assign Fr   | om JOYCE   |                   | Assign                       | n Date            | 12/06/2018 |  |
| 2. Vehicle Particulars & Condition  |  |                   |                              |                   |            |  |
| Make & M  | odel MAZD  | A 3               | c.c                          |                   | 1496       |  |
| Engine No   | ngine No. HIDDEN                                   |                   | Year of Reg.                 |                   | 2017       |  |
| Chassis N   | nassis No. JM6BN22A8H0149528                       |                   | Colour                       |                   | BLACK      |  |
| Odometei  | neter 80105  |                   | Steering                     |                   | IN ORDER   |  |
| Brakes  | akes IN ORDER                                      |                   | Modification                 |                   | SPORTS RIM |  |
| General   | FAIR   |                   |                              |                   |            |  |
| 3. Conditions of Tyres  |  |                   |                              |                   |            |  |
|   | Size   |                   | Make                         |                   | Balance    |  |
| R/H Front   |  |                   | WEST L                       |                   | 6 mm       |  |
| L/H Front   |  |                   | WEST L                       |                   | 6 mm       |  |
| R/H Rear  |  |                   | WEST L                       |                   | 6 mm       |  |
| L/H Rear  | <b>Tyre</b> 205/60                                 |                   | WEST L                       |                   | 6 mm       |  |
| 4. Description of Damages   |  |                   |                              |                   |            |  |
| THE VEHICLE SUSTAINED DAMAGES AT THE N/S FRONT PORTION.   |  |                   |                              |                   |            |  |
| DAMAGES SEE DETAILS.  |  |                   |                              |                   |            |  |
| 5. General Information  |  |                   |                              |                   |            |  |
| Accident  |  |                   |                              | tion Date         | 12/06/2018 |  |
| Survey he   |  | 74 KIAN TECK ROAD |                              |                   |            |  |
|   | Repairer PEGASUS ENGINEERING & TRADING PTE LTD     |                   |                              |                   |            |  |
| 5a. Remarks   |  |                   |                              |                   |            |  |
| A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS. B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS. |  |                   |                              |                   |            |  |
| <b>5b.</b> Estimate Days of Repair  |  |                   |                              |                   |            |  |
| ESTIMATE  | ESTIMATED NORMAL PERIOD FOR REPAIR: 4 Working Days |                   |                              |                   |            |  |