

GST REG. NO : M2 - 0020081 - X

E S T I M A T E

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. : 2 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA31B	A020328	28/03/2018	318iA/4Dr	0

DESCRIPTION

VALUE

To replace electromechanical power steering including program, initialize steering column adjustment and conduct checks for proper function.		885.00
To check steering geometry and conduct wheel alignment according to BMW specification (2x)	902	1,062.00
To replace tyre and wheel rim including balancing. (1x).	80	94.00
To perform brake test including bleed brake system with DSC and conduct checks for leaks.	852	1,003.00
To mount accident vehicle on celette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications.	2,507	2,950.00
To conduct chassis alignment measuring check using Car-O-Liner measuring system accordance with BMW specification.	451	531.00
To replace front dashboard panel and conduct checks for proper function.	677	797.00
To remove and install front seats and carpets to facilitate repairs.	740	870.00
To replace battery positive cable including perform high current tests and charge up battery.	451	531.00
To remove and install fuse box to facilitate front section repairs.	451	531.00
To check electrical wiring systems and lightings including reset and check air bags for proper function.		295.00
To replace air con condenser including to vacuum system, top up freon gas and check for leak. (For all models except for 7 series).	692	1,003.00
To replace both front seat belts and tensioners including reset and checks for proper function.	451	531.00
To replace roof top headlining and ITS head air bag	581	684.00
To replace front dashboard passenger air bag	451	531.00

BMW Dealer

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. : 3 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA31B	A020328	28/03/2018	318iA/4Dr	0

DESCRIPTION

To replace steering wheel and air bag

VALUE
531.00

TO-SUPPLY-TYRE - Bridgestone 225/45 R18 -

432.00

Sundries.

150.00

+ SUPP

Total Labour 1: 39,122.00

DESCRIPTION

INTAKE DUCT
INTAKE DUCT
INTAKE MANIFOLD FRONT
INTAKE SILENCER
RADIATOR MODULE MOUNT RH
ADDITIONAL RADIATOR
RADIATOR
COOLANT HOSE RADIATOR
Hose, radiat
FRAME
CHARGE AIR COOLER
LH ENGINE MOUNT
RH ENGINE MOUNT
GEARBOX MOUNTING
FRONT AXLE SUPPORT
RH WISHBONE
RH TENSION STRUT W/HYDRAULIC MOUNT
WHEEL HUB WITH BEARING FRT
FRT RH CARRIER
FRT SWING SUPPORT
FRT GUIDE SUPPORT
FRT SPRING STRUT RH
FRT SPRING STRUT LH
RH TIE ROD
EXCH STEERING BOX ELECTR. (ZF)
(DG) AIRBAG MODULE DRIVER'S SIDE
SPORT STEERING WHEEL LEATHER
Disc wheel I
HUB CAP WITH CHROME EDGE (BMW)
REGULATING ROD
FRT RH WHEEL HOUSING WITH VI
BONNET
FRT RH SIDE PANEL
FRT RH 2 SIDE PANEL BRACKET
FRT RH 1 SIDE PANEL BRACKET
FRT RH 3 SIDE PANEL BRACKET
BONNET LH HINGE
BONNET RH HINGE

QTY	PRIC	VALUE
1	67.55	67.55
1	67.55	67.55
1	30.75	30.75
1	446.65	446.65
1	75.70	75.70
1	423.65	423.65
1	706.10	706.10
1	130.75	130.75
1	188.90	188.90
1	80.40	80.40
1	609.75	609.75
1	198.55	198.55
1	198.55	198.55
2	39.75	79.50
1	1,317.15	1,317.15
1	262.20	262.20
1	262.20	262.20
1	465.75	465.75
1	439.10	439.10
1	95.35	95.35
2	232.00	464.00
1	484.55	484.55
1	484.55	484.55
1	282.35	282.35
1	3,583.40	3,583.40
1	1,396.45	1,396.45
1	1,144.95	1,144.95
1	1,089.10	1,089.10
1	24.30	24.30
1	18.20	18.20
1	1,914.40	1,914.40
1	1,219.70	1,219.70
1	682.50	682.50
1	32.15	32.15
1	32.15	32.15
1	32.15	32.15
1	32.15	32.15
1	71.50	71.50
1	71.50	71.50

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-X



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. : 4 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA31B	A020328	28/03/2018	318iA/4Dr	0

DESCRIPTION	QTY	PRIC	VALUE	
RIVET	10	0.50	5.00	vec
FRT LH TOP SUPPORT SIDE PANEL	1	18.00 X uu	18.00	
FRT RH TOP SUPPORT SIDE PANEL	1	18.00	18.00	bt
FRT BUMPER TOP MOUNT	1	361.65	361.65	bt
FRT LH DEFORMATION ELEMENT	1	97.40 X uu	97.40	
FRT RH DEFORMATION ELEMENT	1	97.40	97.40	de
FRT LH LOWER DEFORMATION ELEMENT	1	82.65	82.65	de
FRT RH LOWER DEFORMATION ELEMENT	1	82.65 X uu	82.65	
# FRT LH BOTTOM MOUNTING SIDE	1	18.00	18.00	vec
# FRT RH BOTTOM MOUNTING SIDE	1	18.00 X uu	18.00	
INSERT AIR INLET MIDDLE	1	121.95	121.95	de
RH FOG LAMP SUPPORT	1	37.20	37.20	dis
FINISHER ROD CENTRE (SPORT)	1	53.40	53.40	de
RH FINISHER ROD (SPORT)	1	39.25 X uu	39.25	
FRT BUMPER TOWING LUG COVER PRIMED	1	42.20	42.20	de
RH AIR INLET FINISHER (SPORT)	1	51.90	51.90	de
FRT SHOCK ABSORBER ECE	1	52.15	52.15	de
SET MOUNTING PDC/PMA SENSOR FRT	1	84.10	84.10	vec
FRT BUMPER PANEL PRIMED (SPORT LINE	1	982.75	982.75	de
RH PARTIALLY OPEN GRID (SPORT EDITI	1	114.25	114.25	de
MODEL LETTERING SIDE (SPORT LINE)	2	45.20	90.40	vec
GROMMET	2	0.75 X	1.50	
LH LOWER PART OF HOOK LOCK	1	85.80 X	85.80	
RH LOWER PART OF HOOK LOCK	1	85.80 X	85.80	
TWIST PROTECTION	2	5.35 X uu	10.70	
BONNET CATCH BRACKET	2	24.65 X	49.30	
COVER COLUMN A RH	1	62.95 X	62.95	
Cover	1	72.95 X	72.95	
Cover	1	75.00 X uu	75.00	
# MOULDED ROOF LINING (OYSTER)	1	964.70	964.70	vec
# Dashboard wi	1	2,930.90 X vec	2,930.90	
FRONT PANEL V STRUT	1	107.05 X uu	107.05	
RH SUPPORT	1	53.95	53.95	vec
FRT BUMPER LOWER MOUNT	1	128.00	128.00	vec
RH HEADLIGHT BRACKET	1	9.50 X uu	9.50	
FRONT CROSSLINK	1	160.55	160.55	bt
M PERFORMANCE FRONT GRILLE LH BLK	1	135.85 X uu	135.85	
M PERFORMANCE FRONT GRILLE RH BLK	1	135.85	135.85	dis
CLIP	10	1.30	13.00	vec
FRT RH WHEEL HOUSING COVER	1	115.60	115.60	de
# COVER BOTTOM RH	1	138.70	138.70	de
DEFLECTOR LIP RH	1	51.50	51.50	de
AIR DUCT RADIATOR	1	56.65	56.65	de
RH AIR DUCT BRAKE	1	51.50	51.50	de
AIR DUCT FRT BOTTOM	1	51.50 X uu	51.50	
# UNDERHOOD SHIELD	1	194.00 X uu	194.00	
FRONT ENGINE HOOD SEALING	1	24.95 X uu	24.95	
PLAQUE 82MM	1	69.50	69.50	vec
BATTERY CABLE (PLUS POLE)	1	286.35	286.35	wt

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W GST Reg. No M2-0020081-x



303, Alexandra Road
Sime Darby Performance Centre
Singapore 159941
Tel. 63190100 (Sales & Admin)
63190111 (AfterSales)
Fax. 64747770

280, Kampong Arang Road
East Coast Centre
Singapore 438180
Tel. 63190888 (AfterSales)
Fax. 63449773

315, Alexandra Road
Sime Darby Business Centre
Singapore 159944
Tel. 63190528 (AfterSales)
63190533/530 (Motorrad)
Fax. 64796601 (AfterSales)
64796624 (Motorrad)

GST REG. NO : M2 - 0020081 - X

ESTIMATE

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. : 5 of 8

REGN. NO.	CHASSIS NO.	REGN. DATE	MODEL	MILEAGE
SMA31B	A020328	28/03/2018	318iA/4Dr	0

DESCRIPTION	QTY	PRIC	VALUE	
FANFARE HORN HIGH TONE ELECTRONIC	1	92.35	92.35	wt
FANFARE HORN LOW TONE ELECTRONIC	1	92.35 x uu	92.35	
WINDSHIELD CLEANING CONTAINER	1	123.95	123.95	de
# LED display	1	395.80 x uu	395.80	
SET LED MODULE	1	150.55	150.55	dis
# RH LED MODULE DIRECTION INDI	1	786.65 x uu	786.65	
LH HEADLIGHT LED TECHNOLOGY	1	3,044.60 x uu	3,044.60	
RH HEADLIGHT LED TECHNOLOGY	1	3,044.60	3,044.60	cu
CONTROL UNIT FRT LIGHT ELECTRONIC	1	893.90	893.90	dis
RH FOG LIGHT LED	1	391.10	391.10	dis
CONDENSER AIR CONDITIONING	1	979.45 x uu	979.45	
DECOUPLING RING PDC TORQUE CONVERTE	2	5.05 x uu	10.10	
PDC SENSOR ALPINWEISS (300)	2	368.80 x uu	737.60	
(DG) LH BELT TENSIONER	1	263.70 x uu	263.70	
(DG) RH BELT TENSIONER	1	263.70	263.70	wt
(DG) HEAD AIRBAG RH	1	578.05	578.05	wt
(DG) AIRBAG FOR FRONT PASSENGER	1	1,156.10	1,156.10	wt
BLIND RIVET HEMLOCK 813	20	2.65	26.50	vac
BLIND RIVET AVIBVLB	5	0.55	2.75	vac
(DG/SL) ADHESIVE GLUE	1	381.70	381.70	vac
PUNCH RIVET N5	10	0.55	8.25	vac
(DG) CLEANER R1 (100ML)	1	23.85	23.85	vac
BLIND RIVET N7 150 STUCK	45	2.75 x uu	123.75	
(DG/SL) ADHESIVE SET K6	1	53.05	53.05	vac
(S/L) SEAM SEAL 300ML	2	33.80	101.40	vac
ANTI-FREEZE 1.5 LITRES	4	19.75	79.00	vac
Total Parts :			41,570.70	

24768.25

Labour 1	:	39,122.00
Parts	:	41,570.70
Labour 2	:	0.00
Excess	:	0.00
Total GST @ 7%	:	5,648.49
Grand Total	:	86,341.19

** THIS ESTIMATE IS VALID FOR A PERIOD OF 30 DAYS ONLY **
** PRICE FOR PARTS ARE SUBJECTED TO CHANGE WITHOUT PRIOR NOTICE **

93865.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Tan Szue Hann
1 Essex Road
#02-01

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 309329

REGN NO	CHASSIS NO	REGN DATE	MODEL	MILEAGE	
SMA31B	A020328	28/03/2018	318iA/4Dr	0	
DESCRIPTION			ORIGINAL PRICE	DISC. %	NETT
To tow accident vehicle to PML workshop.			195.00		195.00
To replace front bumper and attachments, front RH wheel housing with VIN coded, bonnet and attachments, front RH door and attachments, front RH fender and attachments, front RH defromation element, RH foglamp support, RH support, front lower mount, front crosslink, front RH wheel housing cover, RH bottom cover, air duct radiator and attachments, RH underbody panelling, RH sill trim, horn include to pull and straighten on accident areas, to make good the front LH fender, front LH/RH wheel housing with chassis and knocking out dents caused by the accident			11050.00		11,050.00
To respray front bumper, front RH fender, front LH fender, bonnet, front RH door, front RH wheel house with chassis and front LH wheel house with chassis			5298.00		5,298.00
* To carry out body cavity preservation (3x)			300.00		300.00
To carry out body cavity preservation (For cut panel)			451.00		451.00
* To remove and install engine and auto transmission to facilitate jacking of chassis and mounting of car on celette bench include replacement of damaged parts			1404.00		1,404.00
* To remove and install radiator assembly to facilitate repairs include pressure tests, bleed cooling system and conducting checks for leak			572.00		572.00
* To replace auxiliary radiator assembly include conducting checks for leak			651.00		651.00
To remove and install exhaust pipe, heat shield and * propeller shaft to facilitate repairs			451.00		451.00
* To remove and install front suspension to facilitate the jacking of chassis and mounting of car on celette bench include replacement of damaged parts			2256.00		2,256.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

To check steering geometry and conduct wheel alignment in accordance with BMW specifications (2x)	902.00	902.00
To replace wheel rim include balancing (1x)	80.00	80.00
To perform brake tests include bleeding brake system with DSC and conducting checks for leaks	852.00	852.00
* To mount accident vehicle on celette bench to facilitate re-alignment of body/chassis in accordance with BMW specifications	2507.00	2,507.00
* To conduct chassis alignment check using Car-O-Liner measuring system in accordance with BMW specifications	451.00	451.00
To replace front dashboard panel include conducting checks for proper function	677.00	677.00
To remove and install front seats, garnish and carpets to facilitate repairs	740.00	740.00
* To remove and install fuse box in the front section to facilitate repairs	451.00	451.00
* To reconnect all electrical components, control units and wiring system at the front section include conducting checks for proper function	451.00	451.00 <i>nb</i>
* To remove and install air con condenser include vacuum system, top up freon gas and conducting checks for leak	692.00	692.00 <i>nb</i>
* To replace front seat belt tensioners include resetting and conducting checks for proper function	451.00	451.00
To replace roof top headlining and ITS head air bag include resetting and conducting checks for function	581.00	581.00
* To replace passenger side air bag include resetting and conducting checks for proper function	451.00	451.00
To replace driver's side air bag include resetting and checking air bag system for proper function	451.00	451.00
# To replace engine mountings include re-alignment of engine block to body frame	577.00	577.00
# To replace gearbox mountings include re-alignment of gearbox to cross member and propeller shaft system	577.00	577.00
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00	451.00
* To replace battery positive cable, to perform high current tests and charge up battery	451.00	451.00 <i>nb</i>
# To remove and install front windscreen to facilitate repairs	577.00	577.00

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



FINAL REPORT

# To conduct water leak tests	75.00	75.00
# To replace RH LED technology headlight include programming and conducting tests for proper function	451.00	451.00
Sundries	150.00	150.00

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT * <i>nel</i>	2.00	5.00		-10.00
# BLIND RIVET * <i>nel</i>	1.10	5.00		- 5.50
# BLIND RIVET * <i>nel</i>	3.50	10.00		-35.00
ADDITIONAL RADIATOR	441.85	1.00		441.85
# RADIATOR EXPANSION TANK * <i>del</i>	197.60	1.00		-197.60
FRAME	80.40	1.00		80.40
LH ENGINE MOUNT	198.55	1.00		198.55
RH ENGINE MOUNT	198.55	1.00		198.55
GEARBOX MOUNTING	39.75	1.00		39.75
# GEARBOX MOUNTING *	39.75	1.00		39.75
# FOAM SEAL * <i>nel</i> <i>bt</i>	8.40	2.00		- 16.80
FRONT AXLE SUPPORT	1,317.15	1.00		1,317.15
RH WISHBONE	262.20	1.00		262.20
RH TENSION STRUT W/HYDRAULIC MOUNT	262.20	1.00		262.20
# SPHERICAL COLLAR SCREW M12X1.25X45 * <i>nel</i>	7.70	4.00		- 30.80
WHEEL HUB WITH BEARING FRT	465.75	1.00		465.75
FRT RH CARRIER	439.10	1.00		439.10
FRT SWING SUPPORT	95.35	1.00		95.35
# HEXAGON SCREW WITH FLANGE M10X85 * <i>nel</i>	6.40	1.00		- 6.40
# HEX BOLT WITH WASHER M8X30 * <i>nel</i>	5.40	5.00		- 27.00
FRT GUIDE SUPPORT	232.00	1.00		232.00
# FRT SPRING STRUT * <i>bt</i>	484.55	1.00		- 484.55
RH TIE ROD	282.35	1.00		282.35
(DG) AIRBAG MODULE DRIVER'S SIDE	1,396.45	1.00		1,396.45
# COMBINATION NUT M14X1.5 * <i>nel</i>	5.55	4.00		- 22.20
# HEXAGON NUT WITH COLLAR * <i>nel</i>	2.20	1.00		- 2.20
# HEXAGON NUT WITH COLLAR * <i>nel</i>	2.20	1.00		- 2.20
# BRACKET FOR BRAKE HOSE FRT RH * <i>nel</i>	58.10	1.00		- 58.10
# ALLOY RIM 8Jx18 DOUBLE SPK 397 * <i>del</i>	1,089.10	1.00		-1,089.10
# PRESTOL CAGE M6 ZNS3 * <i>del</i>	3.95	3.00		- 11.85
# FRT RH WHEEL HOUSING WITH VIN CODED * <i>del</i>	1,914.40	1.00		-1,914.40
BONNET	1,219.70	1.00		1,219.70
# FRT RH DOOR * <i>bt</i>	1,236.60	1.00		- 1,236.60
FRT RH SIDE PANEL	682.50	1.00		682.50
FRT RH 2 SIDE PANEL BRACKET	32.15	1.00		32.15
FRT RH 1 SIDE PANEL BRACKET	32.15	1.00		32.15
FRT RH 3 SIDE PANEL BRACKET	32.15	1.00		32.15
BONNET LH HINGE	71.50	1.00		71.50
BONNET RH HINGE	71.50	1.00		71.50
RIVET	0.50	10.00		5.00
FRT RH TOP SUPPORT SIDE PANEL	18.00	1.00		18.00
FRT BUMPER TOP MOUNT	361.65	1.00		361.65
FRT RH DEFORMATION ELEMENT	97.40	1.00		97.40
FRT RH LOWER DEFORMATION ELEMENT	82.65	1.00		82.65
# FRT RH BOTTOM MOUNTING SIDE PANEL *	18.00	1.00		18.00
INSERT AIR INLET MIDDLE	121.95	1.00		121.95
RH FOG LAMP SUPPORT	41.85	1.00		41.85

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

FINISHER ROD CENTRE (SPORT)	53.40	1.00	53.40 -
FRT BUMPER TOWING LUG COVER PRIMED	42.20	1.00	42.20 -
RH AIR INLET FINISHER (SPORT)	51.90	1.00	51.90 -
FRT SHOCK ABSORBER ECE	52.15	1.00	52.15 -
SET MOUNTING PDC/PMA SENSOR FRT	84.10	1.00	84.10 -
FRT BUMPER PANEL PRIMED (SPORT LINE)	982.75	1.00	982.75 -
# LH PARTIALLY OPEN GRID (SPORT EDIT) * <i>de</i> ✓	88.40	1.00	- 88.40
RH PARTIALLY OPEN GRID (SPORT EDIT)	88.40	1.00	88.40 -
MODEL LETTERING SIDE (SPORT LINE)	45.20	1.00	45.20 -
MODEL LETTERING SIDE (SPORT LINE)	45.20	1.00	45.20 -
# COVER WINDSHIELD TOP * <i>de</i> ✓	34.45	1.00	- 34.45
# BUMP STOP * <i>all</i> ✓	3.25	10.00	- 32.50
# FRT DOOR WEATHERSTRIP * <i>all</i> ✓	137.80	1.00	- 137.80
# FRT RH DOOR OUTER CHANNEL SEALING (* <i>all</i> ✓)	123.40	1.00	- 123.40
MOULDED ROOF LINING (OYSTER)	964.70	1.00	964.70 -
# INSTRUMENT PANEL WITH DECOR SEAM BR * <i>dis</i> ✓	2,930.90	1.00	- 2,930.90
RH SUPPORT	53.95	1.00	53.95 -
# BRACKET AUX RADIATOR UPPER RH * <i>bt</i> ✓	34.35	1.00	- 34.35
# BRACKET AUX RADIATOR LOWER RH * <i>bt</i> ✓	27.80	1.00	- 27.80
FRT BUMPER LOWER MOUNT	128.00	1.00	128.00 -
FRONT CROSSLINK	164.95	1.00	164.95 -
M PERFORMANCE FRONT GRILLE RH BLK	145.25	1.00	145.25 -
CLIP	1.30	10.00	13.00 -
FRT RH WHEEL HOUSING COVER	116.55	1.00	116.55 -
COVER BOTTOM RH	116.55	1.00	116.55 -
DEFLECTOR LIP RH	51.50	1.00	51.50 -
AIR DUCT RADIATOR	56.65	1.00	56.65 -
# AIR DUCT FOR AMOEK RH * <i>de</i> ✓	51.50	1.00	- 51.50
# SUPPORT FRT END * <i>de</i> ✓	15.95	1.00	- 15.95
RH AIR DUCT BRAKE	51.50	1.00	51.50 -
# UNDERBODY PANELLING SIDE ON RIGHT * <i>de</i> ✓	110.10	1.00	- 110.10
# SEALING SIDE PANEL RH * <i>all</i> ✓	24.05	1.00	- 24.05
PLAQUE 82MM	69.50	1.00	69.50 -
# RH SILL TRIM PRIMED * <i>de</i> ✓	314.60	1.00	- 314.60
BATTERY CABLE (PLUS POLE)	286.35	1.00	286.35 -
# REPAIR KIT SOCKET HOUSING (2 POL) * <i>dis</i> ✓	28.00	1.00	- 28.00
# PLUG IN CONNECTION BRACKET * <i>dis</i> ✓	7.40	1.00	- 7.40
FANFARE HORN HIGH TONE ELECTRONIC	92.35	1.00	92.35 -
WINDSHIELD CLEANING CONTAINER	123.95	1.00	123.95 -
SET LED MODULE	150.55	1.00	150.55 -
# RH LED MODULE DIRECTION INDICATOR * <i>dis</i> ✓	786.65	1.00	- 786.65
RH HEADLIGHT LED TECHNOLOGY	3,068.40	1.00	3,068.40 -
CONTROL UNIT FRT LIGHT ELECTRONIC	893.90	1.00	893.90 -
RH FOG LIGHT LED	417.15	1.00	417.15 -
(DG) RH BELT TENSIONER	263.70	1.00	263.70 -
(DG) HEAD AIRBAG RH	594.30	1.00	594.30 -
(DG) AIRBAG FOR FRONT PASSENGER	1,188.55	1.00	1,188.55 -
BLIND RIVET HEMLOCK 813	2.65	10.00	26.50 -
BLIND RIVET AVIBVLB	0.55	20.00	11.00 -
(DG/SL) ADHESIVE GLUE	381.70	1.00	381.70 -
PUNCH RIVET N5	0.55	10.00	5.50 -
# PUNCH RIVET N4 * <i>all</i> ✓	0.55	50.00	- 27.50
(DG) CLEANER R1 (100ML)	26.15	1.00	26.15 -
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) * <i>all</i> ✓	131.55	2.00	- 263.10
(DG/SL) ADHESIVE SET K6	53.05	1.00	53.05 -
# (DG/SL) GLASS PRIMER 30ML (VP206) * <i>all</i> ✓	27.85	1.00	- 27.85
(S/L) SEAM SEAL 300ML	33.80	2.00	67.60 -

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



FINAL REPORT

ANTI-FREEZE 1.5 LITRES

19.75

3.00

59.25 ✓

SUPPLEMENTARY ITEMS

Total Labour :	35,674.00
Total Parts :	29,943.50
Total Labour & Parts :	65,617.50
Deduction for Excess :	
Total Repair Costs less Excess:	65,617.50
GST @7%:	4,593.23
Grand Total :	70,210.73

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W. GST Reg. No. M2-0020081-X



SUPPLEMENTARY

Estimate No. : b1 47233
Date Estimated : 08/06/2018
Prepared By : Han Kwan Yong

Page No. :

REPAIR FOR -
Tan Szue Hann
1 Essex Road
#02-01

- ACCOUNT - 121
AIG Asia Pacific Insurance Pte. Ltd.
78 Shenton Way
#08-16 Chartis Building
Singapore 079120

Singapore 309329

REGN NO	CHASSIS NO	REGN DATE	MODEL	M LEAGE		
SMA31B	A020328	28/03/2018	318iA/4Dr	0		
DESCRIPTION	ORIGINAL PRICE	DISC. %	NETT			
# To replace engine mountings include re-alignment of engine block to body frame	577.00		577.00			
# To replace gearbox mountings include re-alignment of gearbox to cross member and propeller shaft system	577.00		577.00			
# To transfer lock mechanism from old to new door include conducting checks on new door power window system for proper function	451.00		451.00			
# To remove and install front windscreen to facilitate repairs	577.00		577.00			
# To conduct water leak tests	75.00		75.00			
# To replace RH LED technology headlight include programming and conducting tests for proper function	451.00		451.00			

DESCRIPTION	UNIT PRICE	QTY	DISC. %	NETT
# EXPANDING NUT *	2.00	5.00		10.00
# BLIND RIVET *	1.10	5.00		5.50
# BLIND RIVET *	3.50	10.00		35.00
# RADIATOR EXPANSION TANK *	197.60	1.00		197.60
# GEARBOX MOUNTING *	39.75	1.00		39.75
# FOAM SEAL *	8.40	2.00		16.80
# SPHERICAL COLLAR SCREW M12X1.25X45 *	7.70	4.00		30.80
# HEXAGON SCREW WITH FLANGE M10X85 *	6.40	1.00		6.40
# HEX BOLT WITH WASHER M8X30 *	5.40	5.00		27.00
# FRT SPRING STRUT *	484.55	1.00		484.55
# COMBINATION NUT M14X1.5 *	5.55	4.00		22.20
# HEXAGON NUT WITH COLLAR *	2.20	1.00		2.20
# HEXAGON NUT WITH COLLAR *	2.20	1.00		2.20
# BRACKET FOR BRAKE HOSE FRT RH *	58.10	1.00		58.10
# ALLOY RIM 8Jx18 DOUBLE SPK 397 *	1,089.10	1.00		1,089.10
# PRESTOL CAGE M6 ZNS3 *	3.95	3.00		11.85
# FRT RH WHEEL HOUSING WITH VIN CODED *	1,914.40	1.00		1,914.40
# FRT RH DOOR *	1,236.60	1.00		1,236.60
# FRT RH BOTTOM MOUNTING SIDE PANEL *	18.00	1.00		18.00
# LH PARTIALLY OPEN GRID (SPORT EDIT) *	88.40	1.00		88.40
# COVER WINDSHIELD TOP *	34.45	1.00		34.45

Performance Motors Limited

A member of the Sime Darby Group
Co. Reg. No. 197401559W, GST Reg. No. M2-0020081-X



SUPPLEMENTARY

# BUMP STOP *	3.25	10.00	32.50
# FRT DOOR WEATHERSTRIP *	137.80	1.00	137.80
# FRT RH DOOR OUTER CHANNEL SEALING (*	123.40	1.00	123.40
# INSTRUMENT PANEL WITH DECOR SEAM BR *	2,930.90	1.00	2,930.90
# BRACKET AUX RADIATOR UPPER RH *	34.35	1.00	34.35
# BRACKET AUX RADIATOR LOWER RH *	27.80	1.00	27.80
# AIR DUCT FOR AMOEK RH *	51.50	1.00	51.50
# SUPPORT FRT END *	15.95	1.00	15.95
# UNDERBODY PANELLING SIDE ON RIGHT *	110.10	1.00	110.10
# SEALING SIDE PANEL RH *	24.05	1.00	24.05
# RH SILL TRIM PRIMED *	314.60	1.00	314.60
# REPAIR KIT SOCKET HOUSING (2 POL) *	28.00	1.00	28.00
# PLUG IN CONNECTION BRACKET *	7.40	1.00	7.40
# RH LED MODULE DIRECTION INDICATOR *	786.65	1.00	786.65
# PUNCH RIVET N4 *	0.55	50.00	27.50
# (DG/SL) W/SCREEN SEALANT (COLD 1 HOUR) *	131.55	2.00	263.10
# (DG/SL) GLASS PRIMER 30ML (VP206) *	27.85	1.00	27.85

Total Labour :	2,708.00
Total Parts :	10,274.35
Total Labour & Parts :	12,982.35

Vic (LKKAUTO)

From: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Sent: Thursday, 3 October, 2019 4:06 PM
To: Vic (LKKAUTO)
Cc: Admin A
Subject: RE: <SEEK MANDATE> Your Ref: 8217749545SG_ACCIDENT INVOLVING VEHICLES SJM 8140P (OI) AND SMA 31B (TP) ON 06/06/2018 LKK REF CC3/AIG18010739/T1hb3

Dear Vic,

Further to the below, we would like to check on your recommendation on towing charges (\$195.00), as we understands that dolly towing charges ranging between \$120-140.

Appreciate your advice.

Best Regards,

Bernard Ler
AIG
Complex Claims Examiner
Claims | AIG Asia Pacific Insurance Pte. Ltd

78 Shenton Way #08-16 Singapore(079120)

Tel +(65) 6419 1946

Bernard-JQ.Ler@aig.com | www.aig.com.sg

From: Vic (LKKAUTO) [mailto:vicalpeh@lkkauto.com]
Sent: 30 September 2019 14:51
To: Ler, Bernard-JQ <Bernard-JQ.Ler@aig.com>
Cc: Admin A <admin-a@lkkauto.com>
Subject: [EXTERNAL] RE: <SEEK MANDATE> Your Ref: 8217749545SG_ACCIDENT INVOLVING VEHICLES SJM 8140P (OI) AND SMA 31B (TP) ON 06/06/2018 LKK REF CC3/AIG18010739/T1hb3

This message is from an external sender; be cautious with links and attachments.

Dear Bernard,

Done.

VEHICLE CONDITION REPORT FORM / JOB RECORD

Allianz 

Worldwide Partners

Date: 7/10/11 Time: 11:00

(21) TIAN
Customer Name: Mr. TIAN

Technician Name: DING

Customer Telephone: 134 4007

Reg. No: SMH 318 Job No:

Make/Model: BMW 1 Series

Odometer Reading (Customer Vehicle):

Location: Mary Hill Road

KM Travelled by Assistance Vehicle: (1 way)

Time on Scene: 125

Fault Reported: AC

Time Job Completed:

Fault Found:

Repaired at Breakdown Scene: Y/N

How was vehicle repaired?

VIN No:

Hubcaps Y/N

Day/Night

Wet/Dry

Clean/Soiled

Spare Wheel Y/N

Please circle the above as appropriate

Tools Y/N

Place X on damaged area for scratch and Y for dent

Audio System Y/N

Keys + Remote Y/N

Aerial Y/N

Cashcard (RM) Y/N

Fuel E ☐ F ☐




Interior Condition:

Front Seats

Rear Seats

Floor Covering

Headlining



Delivery to Dealership / Date and Time:



Vehicle received in the above condition YES/NO

If not stated as above specify difference:

L6 601-

CUSTOMER DECLARATION

- I am entitled to the service requested. In the event of this subsequently not being the case I shall be responsible for the cost of any assistance provided.
- I accept that any roadside repairs will be of a temporary nature and that advice of a franchised dealer should be sought by me as soon as possible.
- In the case of forced entry, I confirm that I specifically requested that the operator forcefully enter the vehicle and that all damages occasioned thereby is and shall be my sole responsibility.
- I accept that any removable items left in the vehicle will not be the responsibility of the emergency service or their agents.

Customers Signature (white copy)		Dealer/Workshop Signature (pink copy)		Operators Signature (yellow copy)	
--	---	---	--	---	---

...CLAIM SUBFOLDER...(Pending for Survey Report)

Express

CLAIM SUBFOLDER TRACKING

Case	Notified	Est Submitted	Adj Assigned	Adj Rpt	Adj Submitted	Ins Auth'd	Status
Main	12 Jun 2018 Edit Reg		12 Jun 2018 00:00 Edit Adj Rpt	S\$65,617.50 Edit Estimates	S\$65,617.50 View Rpt		Pending for Survey Report Cancel Case

Main

Reference

Claim Details

Documents

[Show All](#)

CLAIM SUBFOLDER DETAILS

[Created by adjuster]

Insured:	NIKHILESH KALRA, ID: G3151751L		
Main Claimant:	TAN SZUE HANN, ID: S8377465G		
Vehicle Reg. No.:	SMA31B	Date of Loss:	06/06/2018 23:00 - :59 [2 Months and 9 Days From LTA Reg Date (Man Yr)]
Claim Type:	TP / 8217749545SG	Policy/Cover Note No.:	2100462990-02 (Comprehensive)
Vehicle Reg. No. (Insured):	SJM8140P	Policy No. (Claimant):	GA344477/1
		Excess:	
Repairer:	Performance Motors Limited (Alexandra) 303 Alexandra Road, Sime Darby Performance Centre, 159941 Alexandra - Tel: 63190172/63190174		
Handling Insurer:	AIG Asia Pacific Insurance Pte. Ltd. (Express) - Tel: 65-6419-3000 ... [Handled by Ler, Bernard-JQ] BernardJiQian.Ler@aig.com		
Claimant's Insurer:	AXA Insurance Pte Ltd (HQ) - Tel: 6338 7288		
Adjuster:	LKK Auto Consultants Pte Ltd (HQ) - Tel: 6256-3561 ... [Handled by MOHD TAUFIKH BIN HAMID] ... [Final Rpt due 22/06/2018]		

ASSOCIATED MAIL RECEIVED

[View All](#)[Compose Case Mail](#)

- AIG_SG_EXPRESS (17/10/2019): Alert - Adj Mandate Approved (S\$76010.60) - SMA31B - Claim Handler: Ler, Bernard...
- AIG_SG_EXPRESS (10/10/2019): Alert - Adj Mandate Approved (S\$75415.60) - SMA31B - Claim Handler: Ler, Bernard...

ALL ASSOCIATED TASKS

[View All](#)[Search Tasks](#)[Create New Task](#)[Complete](#)

Due Date	Priority	Type	Task Group	Subject	Handler	Assigned By	Completed On	Created On	Done?
No results.									

Claim Documents

***SMA31B (8217749545SG)
[SJM8140P]**

TP

TAN SZUE HANN

Jun 6 2018 11:45PM

[NIKHILESH KALRA]

Performance Motors Limited

Upload Documents Upload Photos Compose New Letter Upload Video Upload Audio			View View in Browser ▼	
Video				
			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	10/07/18 15:54	Video - Accident	Load MOV	
2	10/07/18 15:54	Video - Accident	Load MOV	
Letters/Correspondences				
			1 per page ▼	☒
No	Finalized On	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	(Draft)	Third Party Express Settlement - Payment Breakdown	Edit	
Assessment Reports				
			1 per page ▼	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
1	13/06/18 14:22	Accident Statement From:OD - Reg. No: SJM8140P, Claimant: NIKHILESH KALRA	Load HTM	
Photos/Images				
			3 per page ▼	☒
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	01/03/19 11:58	General View	Load JPG	☒
2	01/03/19 11:58	General View	Load JPG	☒
3	01/03/19 11:58	General View	Load JPG	☒
4	01/03/19 11:58	General View	Load JPG	☒
5	01/03/19 11:58	General View	Load JPG	☒
6	01/03/19 11:58	General View	Load JPG	☒
7	01/03/19 11:58	General View	Load JPG	☒
8	01/03/19 11:58	General View	Load JPG	☒
9	01/03/19 11:58	General View	Load JPG	☒
10	01/03/19 11:58	General View	Load JPG	☒
11	01/03/19 11:58	General View	Load JPG	☒
12	01/03/19 11:58	General View	Load JPG	☒
13	01/03/19 11:58	General View	Load JPG	☒
14	01/03/19 11:58	General View	Load JPG	☒
15	01/03/19 11:58	General View	Load JPG	☒
16	01/03/19 11:58	General View	Load JPG	☒
17	01/03/19 11:58	General View	Load JPG	☒
18	01/03/19 11:58	General View	Load JPG	☒
19	01/03/19 11:58	General View	Load JPG	☒
20	01/03/19 11:58	General View	Load JPG	☒
21	01/03/19 11:58	General View	Load JPG	☒
22	01/03/19 11:58	General View	Load JPG	☒
23	01/03/19 11:58	General View	Load JPG	☒
24	01/03/19 11:58	General View	Load JPG	☒
25	01/03/19 11:58	General View	Load JPG	☒
26	01/03/19 11:58	General View	Load JPG	☒
27	01/03/19 11:58	General View	Load JPG	☒
28	01/03/19 11:58	General View	Load JPG	☒
29	01/03/19 11:58	General View	Load JPG	☒

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
30	01/03/19 11:58	General View	 Load JPG	☒
31	01/03/19 11:58	General View	 Load JPG	☒
32	01/03/19 11:58	General View	 Load JPG	☒
33	01/03/19 11:58	General View	 Load JPG	☒
34	01/03/19 11:58	General View	 Load JPG	☒
35	01/03/19 11:58	General View	 Load JPG	☒
36	01/03/19 11:58	General View	 Load JPG	☒
37	01/03/19 11:58	General View	 Load JPG	☒
38	01/03/19 11:58	General View	 Load JPG	☒
39	01/03/19 11:58	General View	 Load JPG	☒
40	01/03/19 11:58	General View	 Load JPG	☒
41	01/03/19 11:58	General View	 Load JPG	☒
42	01/03/19 11:58	General View	 Load JPG	☒
43	01/03/19 11:58	General View	 Load JPG	☒
44	01/03/19 11:58	General View	 Load JPG	☒
45	01/03/19 11:58	General View	 Load JPG	☒
46	01/03/19 11:58	General View	 Load JPG	☒
47	01/03/19 11:58	General View	 Load JPG	☒
48	01/03/19 11:58	General View	 Load JPG	☒
49	01/03/19 11:58	General View	 Load JPG	☒
50	01/03/19 11:58	General View	 Load JPG	☒
51	01/03/19 11:58	General View	 Load JPG	☒
52	01/03/19 11:58	General View	 Load JPG	☒
53	01/03/19 11:58	General View	 Load JPG	☒
54	01/03/19 11:58	General View	 Load JPG	☒
55	01/03/19 11:58	General View	 Load JPG	☒
56	01/03/19 11:58	General View	 Load JPG	☒
57	01/03/19 11:58	General View	 Load JPG	☒
58	01/03/19 11:58	General View	 Load JPG	☒
59	01/03/19 11:58	General View	 Load JPG	☒
60	01/03/19 11:58	General View	 Load JPG	☒
61	01/03/19 11:58	General View	 Load JPG	☒
62	01/03/19 11:58	General View	 Load JPG	☒
63	01/03/19 11:58	General View	 Load JPG	☒
64	01/03/19 11:58	General View	 Load JPG	☒
65	01/03/19 11:58	General View	 Load JPG	☒
66	01/03/19 11:58	General View	 Load JPG	☒
67	01/03/19 11:58	General View	 Load JPG	☒
68	01/03/19 11:58	General View	 Load JPG	☒
69	01/03/19 11:58	General View	 Load JPG	☒
70	01/03/19 11:58	General View	 Load JPG	☒
71	01/03/19 11:58	General View	 Load JPG	☒
72	01/03/19 11:58	General View	 Load JPG	☒
73	01/03/19 11:58	General View	 Load JPG	☒
74	01/03/19 11:58	General View	 Load JPG	☒
75	01/03/19 11:58	General View	 Load JPG	☒
76	01/03/19 11:58	General View	 Load JPG	☒
77	01/03/19 11:58	General View	Load JPG	☒
78	01/03/19 11:58	General View	Load JPG	☒
79	01/03/19 11:58	General View	Load JPG	☒
80	01/03/19 11:58	General View	Load JPG	☒
81	01/03/19 11:58	General View	Load JPG	☒
82	01/03/19 11:58	General View	Load JPG	☒

Video			1 per page ▾	✓
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
83	01/03/19 11:58	General View	 Load JPG	✓
84	01/03/19 11:58	General View	 Load JPG	✓
85	01/03/19 11:58	General View	 Load JPG	✓
86	01/03/19 11:58	General View	 Load JPG	✓
87	01/03/19 11:58	General View	 Load JPG	✓
88	01/03/19 11:58	General View	 Load JPG	✓
89	01/03/19 11:58	General View	 Load JPG	✓
90	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
91	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
92	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
93	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
94	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
95	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
96	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
97	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
98	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
99	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
100	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
101	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
102	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
103	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
104	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
105	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
106	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
107	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
108	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
109	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
110	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
111	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
112	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
113	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
114	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
115	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
116	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
117	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
118	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
119	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
120	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
121	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
122	19/07/19 10:37	Reinspection Photo	 Load JPG	✓
123	19/07/19 10:37	Reinspection Photo	 Load JPG	✓

Documentation			1 per page ▾	✓
No	Relabel/Reorder	LKK Auto Consultants Pte Ltd (HQ)	Thumbnail	Print
1	12/06/18 18:17	TP ESTIMATE	 Load TIF	
2	12/06/18 18:17	TP GIA REPORT	 Load PDF	
3	14/06/18 08:53	TP ESTIMATE- MARKED	 Load PDF	
4	10/07/19 09:41	TP RENTAL AGREEMENT AND INVOICES	 Load PDF	
5	10/07/19 09:45	TP MEDICAL BILLS	 Load PDF	
6	10/07/19 10:14	LETTER TO OI	 Load PDF	
7	10/07/19 16:59	AUTHORIZATION LETTER	 Load PDF	
8	10/07/19 17:19	PIR - AGAINST OI	 Load PDF	
9	24/09/19 13:59	DOCTOR'S MEMO	 Load PDF	
10	30/09/19 13:48	TP COE REBATE	 Load PDF	
11	30/09/19 14:50	TP LOD	 Load PDF	
12	30/09/19 14:50	TOWING	Load PDF	

Video			1 per page ▾	☒
No	Finalized On	AIG Asia Pacific Insurance Pte. Ltd. (SG)	Thumbnail	Print
13	18/10/19 14:02	RELEASE VOUCHER		Load PDF
14	18/10/19 14:02	WORKSHOP INVOICE		Load PDF
15	18/10/19 14:02	GIA SEARCH		Load PDF

Documents Checklist

DOCUMENTS CHECKLIST

Reset

Save

Print

There are no document checklists configured.

Our Checklist Remarks - LKK Auto Consultants Pte Ltd (HQ)

Show Remarks To: ☐ Handling Insurer

Note: Remarks are private unless you show it to other parties.

NOTE: TO BE COMPLETED BY SURVEYOR

TEAM _____

THIRD PARTY EXPRESS SETTLEMENT (PAYMENT BREAKDOWN)

Vehicle No:	SJM8140P (Insd veh)	Model:	BMW 318i 2.0 (A)
	SMA31B (TP veh)		
Date of Accident:	06/06/2018		

Global Sum Settlement	:	[] Yes	[X] No	
Repair Estimate	:	\$		100,372.26
Final Repair Cost	:	\$		70,210.73
Loss of Use	:	\$		days at \$0.00 per day
Rental (if any)	:	\$		27 days
LTA / GIA Search Fee	:	\$		2.00
Medical Fee	:	\$		3,062.87
	:	\$		
Final Settlement Sum	:	\$		76,010.60
Is Third Party Workshop GIA Registered? [X] YES [] NO (Kindly indicate below)				
A) For Non GIA Registered Workshop:		Agreed Liability _____ (%)		
B) For GIA Registered Workshop:		BOLA Applicable: Yes/ No BOLA Scenario No: <u>5</u>		
BOLA Liability: <u>100</u> (%)		Assessed Liability (*): _____ (%)		
<i>* Assessed Liability to be filled only for chain collisions and for cases where BOLA does not apply.</i>				
Remarks _____				

Payment Instruction: Payee's Breakdown			
1)	Performance Motors Limited	:	\$ 76,010.360
2)		:	\$
3)		:	\$
4)		:	\$

NUR SHAQILAH BTE ABDOL WAHAB

LKK Auto Consultants Pte Ltd

18 Oct
2019

Date

Please attach all the supporting documents to the form.
(Final Repair Bill; Rental Invoice; Release Voucher; Authorisation to Act; Survey Report; Medical Report/
Bill (if any))

LKK Auto Consultants Pte Ltd (Co.Reg.No:199607198R)

51 Ubi Ave 1 #01-25, Paya Ubi Industrial Park

Singapore 408933

Tel: 6256-3561 Fax: 6844-8805 Email: sur@lkkauto.com;assignments@lkkauto.com

VEHICLE DAMAGE INSPECTION REPORT

Our File No: CC3/AIG18010739/T1HB3S2
Date: 18/10/2019

REFERENCE

Handling Insurer: AIG Asia Pacific Insurance Pte. Ltd. Policy No: 2100462990-02
Claimant Vehicle No : SMA31B **Insured Vehicle No :** SJM8140P
 Date of Loss: 06/06/2018 Nature of Claim: TP Claim No: 8217749545SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No: **SMA31B**
 Make & Model: BMW 318i, 2.0 (A) Engine No: G0361793B38B15A
 Reg. Date: 28/03/2018 (Man. Year: 2017) Chassis No: WBA8E32080A020328
 Colour: White Odometer: 2508 km
 Engine Capacity: 1499 cc
 Market Value/New Car Price: N/A
 Sum Insured (S\$): **Market Value/New Car Price**

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition: Good Steering (Serviceable): Yes Footbrake (Serviceable): Yes
 Handbrake (Serviceable): Yes Engine Modification: No Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size: 225/45R18 Rear Tyre Size: 225/45R18
 Front Left Side: Bridgestone 6 mm Rear Left Side: Bridgestone 6 mm
 Front Right Side: Bridgestone 6 mm Rear Right Side: Bridgestone 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	52,493.85	30,093.50	22,400.35	42.67
Miscellaneous Items	0.00	0.00	0.00	
Labour	41,312.00	35,524.00	5,788.00	14.01
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Gross Total (S\$)	93,805.85	65,617.50	28,188.35	30.05
+ GST 7.00/7.00% (S\$)	6,566.41	4,593.23	1,973.18	30.05
Nett Amount (S\$)	100,372.26	70,210.73	30,161.53	30.05
	+ Medical Costs (S\$)	3,062.87		
	+ Car Rental (S\$)	2,735.00		
	+ Doc/Search Fee (S\$)	2.00		
	Nett Liability (S\$)	76,010.60		

INSPECTION

Date of Assignment: 12/06/2018
 Date Inspected: 12/06/2018 Inspected At: Performance Motors Limited (Alexandra)
 303 Alexandra Road, Sime Darby Performance Centre
 Singapore 159941
 Estimated Period of Repair: 20.0 days

Adjuster: MOHD TAUFIKH BIN HAMID

Manager: VIC ALPEH

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

11

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*INTAKE DUCT	Not Necessary	67.55 FS	*- FS
2	1		*INTAKE DUCT	Not Necessary	67.55 FS	*- FS
3	1		*INTAKE MANIFOLD FRONT	Not Necessary	30.75 FS	*- FS
4	1		*INTAKE SILENCER	Not Necessary	446.65 FS	*- FS
5	1		*RADIATOR MODULE MOUNT RH	Not Necessary	75.70 FS	*- FS
6	1		*ADDITIONAL RADIATOR	Bent	441.85 FS	*441.85 FS
7	1		*RADIATOR	Not Necessary	706.10 FS	*- FS
8	1		*COOLANT HOSE RADIATOR	Not Necessary	130.75 FS	*- FS
9	1		*HOSE, RADIAT	Not Necessary	188.90 FS	*- FS
10	1		*FRAME	Bent	80.40 FS	*80.40 FS
11	1		*CHARGE AIR COOLER	Not Necessary	609.75 FS	*- FS
12	1		*LH ENGINE MOUNT	Bent	198.55 FS	*198.55 FS
13	1		*RH ENGINE MOUNT	Bent	198.55 FS	*198.55 FS
14	2		*GEARBOX MOUNTING	Bent	79.50 FS	*79.50 FS
15	1		*FRONT AXLE SUPPORT	Bent	1,317.15 FS	*1,317.15 FS
16	1		*RH WISHBONE	Bent	262.20 FS	*262.20 FS
17	1		*RH TENSION STRUT W/HYDRAULIC MOUNT	Bent	262.20 FS	*262.20 FS
18	1		*WHEEL HUB BEARING FRT	Bent	465.75 FS	*465.75 FS
19	1		*FRT RH CARRIER	Bent	439.10 FS	*439.10 FS
20	1		*FRT SWING SUPPORT	Bent	95.35 FS	*95.35 FS
21	2		*FRT GUIDE SUPPORT	Deformed	464.00 FS	*232.00 FS
22	1		*FRT SPRING STRUT RH	Not Necessary	484.55 FS	*- FS
23	1		*FRT SPRING STRUT LH	Not Necessary	484.55 FS	*- FS
24	1		*RH TIE ROD	Bent	282.35 FS	*282.35 FS
25	1		*EXCH STEERING BOX ELECTR. (ZF)	Not Necessary	3,583.40 FS	*- FS
26	1		*(DG) AIRBAG MODULE DRIVERS SIDE	Cut	1,396.45 FS	*1,396.45 FS
27	1		*SPORT STEERING WHEEL LEATHER	Not Necessary	1,144.95 FS	*- FS
28	1		*DISC WHEEL I	Not Necessary	1,089.10 FS	*- FS
29	1		*HUP CAP WITH CHROME EDGE (BMW)	Not Necessary	24.30 FS	*- FS
30	1		*REGULATING ROD	Not Necessary	18.20 FS	*- FS
31	1		*FRT RH WHEEL HOUSING WITH VI	Not Necessary	1,914.40 FS	*- FS
32	1		*BONNET	Bent	1,219.70 FS	*1,219.70 FS
33	1		*FRT RH SIDE PANEL	Bent	682.50 FS	*682.50 FS
34	1		*FRT RH 2 SIDE PANEL BRACKET	Bent	32.15 FS	*32.15 FS
35	1		*FRT RH 1 SIDE PANEL BRACKET	Bent	32.15 FS	*32.15 FS
36	1		*FRT RH 3 SIDE PANEL BRACKET	Bent	32.15 FS	*32.15 FS
37	1		*BONNET LH HINGE	Bent	71.50 FS	*71.50 FS
38	1		*BONNET RH HINGE	Bent	71.50 FS	*71.50 FS
39	10		*RIVET	Necessary	5.00 FS	*5.00 FS
40	1		*FRT LH TOP SUPPORT SIDE PANEL	Not Necessary	18.00 FS	*- FS
41	1		*FRT RH TOP SUPPORT SIDE PANEL	Bent	18.00 FS	*18.00 FS
42	1		*FRT BUMPER TOP MOUNT	Bent	361.65 FS	*361.65 FS
43	1		*FRT LH DEFORMATION ELEMENT	Not Necessary	97.40 FS	*- FS
44	1		*FRT RH DEFORMATION ELEMENT	Deformed	97.40 FS	*97.40 FS
45	1		*FRT LH LOWER DEFORMATION ELEMENT	Deformed	82.65 FS	*82.65 FS
46	1		*FRT RH LOWER DEFORMATION ELEMENT	Not Necessary	82.65 FS	*- FS
47	1		*FRT LH BOTTOM MOUNTING SIDE	Necessary	18.00 FS	*18.00 FS
48	1		*FRT RH BOTTOM MOUNTING SIDE	Not Necessary	18.00 FS	*- FS
49	1		*INSERT AIR INLET MIDDLE	Deformed	121.95 FS	*121.95 FS
50	1		*RH FOG LAMP SUPPORT	Distorted	41.85 FS	*41.85 FS
51	1		*FINISHER ROD CENTRE (SPORT)	Deformed	53.40 FS	*53.40 FS
52	1		*RH FINISHER ROD (SPORT)	Not Necessary	39.25 FS	*- FS
53	1		*FRT BUMPER TOWING LUG COVER PRIMED	Deformed	42.20 FS	*42.20 FS
54	1		*RH AIR INLET FINISHER (SPORT)	Deformed	51.90 FS	*51.90 FS
55	1		*FRT SHOCK ABSORBER ECE	Deformed	52.15 FS	*52.15 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
56	1		*SET MOUNTING PDC/PMA SENSOR FRT	Necessary	84.10 FS	*84.10 FS
57	1		*FRT BUMPER PANEL PRIMED (SPORT LINE)	Deformed	982.75 FS	*982.75 FS
58	1		*RH PARTIALLY OPEN GRID (SPORT EDITI)	Deformed	114.25 FS	*88.40 FS
59	2		*MODEL LETTERING SIDE (SPORT LINE)	Necessary	90.40 FS	*90.40 FS
60	2		*GROMMET	Not Necessary	1.50 FS	*- FS
61	1		*LH LOWER PART OF HOOK LOCK	Not Necessary	85.80 FS	*- FS
62	1		*RH LOWER PART OF HOOK LOCK	Not Necessary	85.80 FS	*- FS
63	2		*TWIST PROTECTION	Not Necessary	10.70 FS	*- FS
64	2		*BONNET CATCH BRACKET	Not Necessary	49.30 FS	*- FS
65	1		*COVER COLUMN A RH	Not Necessary	62.95 FS	*- FS
66	1		*COVER	Not Necessary	72.95 FS	*- FS
67	1		*COVER	Not Necessary	75.00 FS	*- FS
68	1		*MODULATED ROOF LINING (OYSTER)	Deformed	964.70 FS	*964.70 FS
69	1		*DASHBOARD WI	Serviceable	2,930.90 FS	*- FS
70	1		*FRONT PANEL V STRUT	Not Necessary	107.05 FS	*- FS
71	1		*RH SUPPORT	Necessary	53.95 FS	*53.95 FS
72	1		*FRT BUMPER LOWER MOUNT	Necessary	128.00 FS	*128.00 FS
73	1		*RH HEADLIGHT BRACKET	Not Necessary	9.50 FS	*- FS
74	1		*FRONT CROSSLINK	Bent	164.95 FS	*164.95 FS
75	1		*M PERFORMANCE FRONT GRILLE LH BLK	Not Necessary	135.85 FS	*- FS
76	1		*M PERFORMANCE FRONT GRILLE RH BLK	Distorted	145.25 FS	*145.25 FS
77	10		*CLIP	Necessary	13.00 FS	*13.00 FS
78	1		*FRT RH WHEEL HOUSING COVER	Deformed	116.55 FS	*116.55 FS
79	1		*COVER BOTTOM RH	Deformed	116.55 FS	*116.55 FS
80	1		*DEFLECTOR LIP RH	Deformed	51.50 FS	*51.50 FS
81	1		*AIR DUCT RADIATOR	Deformed	56.65 FS	*56.65 FS
82	1		*RH AIR DUCT BRAKE	Deformed	51.50 FS	*51.50 FS
83	1		*AIR DUCT FRT BOTTOM	Not Necessary	51.50 FS	*- FS
84	1		*UNDERHOOD SHIELD	Not Necessary	194.00 FS	*- FS
85	1		*FRONT ENGINE HOOD SEALING	Not Necessary	24.95 FS	*- FS
86	1		*PLAQUE 82MM	Necessary	69.50 FS	*69.50 FS
87	1		*BATTERY CABLE (PLUS POLE)	Cut	286.35 FS	*286.35 FS
88	1		*FANFARE HORN HIGH TONE ELECTRONIC	Cut	92.35 FS	*92.35 FS
89	1		*FANFARE HORN LOW TONE ELECTRONIC	Not Necessary	92.35 FS	*- FS
90	1		*WINDSHIELD CLEANING CONTAINER	Deformed	123.95 FS	*123.95 FS
91	1		*LED DISPLAY	Not Necessary	395.80 FS	*- FS
92	1		*SET LED MODULE	Distorted	150.55 FS	*150.55 FS
93	1		*RH LED MODULE DIRECTION INDI	Not Necessary	786.65 FS	*- FS
94	1		*LH HEADLIGHT LED TECHNOLOGY	Serviceable	3,044.60 FS	*- FS
95	1		*RH HEADLIGHT LED TECHNOLOGY	Cracked	3,068.40 FS	*3,068.40 FS
96	1		*CONTROL UNIT FRT LIGHT ELECTRONIC	Distorted	893.90 FS	*893.90 FS
97	1		*RH FOG LIGHT LED	Distorted	417.15 FS	*417.15 FS
98	1		*CONDENSER AIR CONDITIONING	Not Necessary	979.45 FS	*- FS
99	2		*DECOUPLING RING PDC TORQUE CONVERTE	Not Necessary	10.10 FS	*- FS
100	2		*PDC SENSOR ALPINWEISS (300)	Not Necessary	737.60 FS	*- FS
101	1		*(DG) LH BELT TENSIONER	Not Necessary	263.70 FS	*- FS
102	1		*(DG) RH BELT TENSIONER	Cut	263.70 FS	*263.70 FS
103	1		*(DG) HEAD AIRBAG RH	Cut	594.30 FS	*594.30 FS
104	1		*(DG) AIRBAG FOR FRONT PASSENGER	Cut	1,188.55 FS	*1,188.55 FS
105	1		*BLIND RIVET HEML OCK 813 20pcs	Necessary	26.50 FS	*26.50 FS
106	5		*BLIND RIVET AVIBVLB	Necessary	11.00 FS	*11.00 FS
107	1		*(DG/SL) ADHESIVE GLUE	Necessary	381.70 FS	*381.70 FS
108	1		*PUNCH RIVET N5 15pcs	Necessary 10pcs Only	8.25 FS	*5.50 FS
109	1		*(DG) CLEANER R1 (100ML)	Necessary	26.15 FS	*26.15 FS
110	1		*BLIND RIVET N7 150 STUCK 45pcs	Not Necessary	123.75 FS	*- FS
111	1		*(DG/SL) ADHESIVE SET K6	Necessary	53.05 FS	*53.05 FS
112	1		*(S/L) SEAM SEAL 300ML 3pcs	Necessary 2pcs Only	101.40 FS	*67.60 FS

Report was unsubmitted during this print-out.

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
113	1		*ANTI-FREEZE 1.5 LITRES 4pcs	Necessary	79.00 FS	*59.25 FS
114	5		*EXPANDING NUT	Necessary	10.00 FS	*10.00 FS
115	5		*BLIND RIVET	Necessary	5.50 FS	*5.50 FS
116	10		*BLIND RIVET	Necessary	35.00 FS	*35.00 FS
117	1		*RADIATOR EXPANSION TANK	Deformed	197.60 FS	*197.60 FS
118	2		*FOAM SEAL	Necessary / Bent	16.80 FS	*16.80 FS
119	4		*SPHERICAL COLLAR SCREW M12X1.25X45	Necessary	30.80 FS	*30.80 FS
120	1		*HEXAGON SCREW WITH FLANGE M10X85	Necessary	6.40 FS	*6.40 FS
121	5		*HEX BOLT WITH WAHSE M8X30	Necessary	27.00 FS	*27.00 FS
122	1		*FRT SPRING STRUT	Bent	484.55 FS	*484.55 FS
123	4		*COMBINATION NUT M14X1.5	Necessary	22.20 FS	*22.20 FS
124	1		*HEXAGON NUT WITH COLLAR	Necessary	2.20 FS	*2.20 FS
125	1		*HEXAGON NUT WITH COLLAR	Necessary	2.20 FS	*2.20 FS
126	1		*BRACKET FOR BRAKE HOSE FRT RH	Necessary	58.10 FS	*58.10 FS
127	1		*ALLOY RIM 8JX18 DOUBLE SPK 397	Cut	1,089.10 FS	*1,089.10 FS
128	3		*PRESTOL CAGE M6 ZNS3	Distorted	11.85 FS	*11.85 FS
129	1		*FRT RH WHEEL HOUSING WITH VIN CODED	Bent	1,914.40 FS	*1,914.40 FS
130	1		*FRT RH DOOR	Bent	1,236.60 FS	*1,236.60 FS
131	1		*LH PARTIALLY OPEN GRID (SPORT EDITI)	Deformed	88.40 FS	*88.40 FS
132	1		*COVER WINDSHIELD TOP	Deformed	34.45 FS	*34.45 FS
133	10		*BUMP STOP	Necessary	32.50 FS	*32.50 FS
134	1		*FRT DOOR WEATHERSTRIP	Necessary	137.80 FS	*137.80 FS
135	1		*FRT RH DOOR OUTER CHANNEL SEALING	Necessary	123.40 FS	*123.40 FS
136	1		*INSTRUMENT PANEL WITH DECOR SEAM BR	Missing	2,930.90 FS	*2,930.90 FS
137	1		*BRACKET AUX RADIATOR UPPER RH	Bent	34.35 FS	*34.35 FS
138	1		*BRACKET AUX RADIATOR LOWER RH	Bent	27.80 FS	*27.80 FS
139	1		*AIR DUCT FOR AMOEK RH	Deformed	51.50 FS	*51.50 FS
140	1		*SUPPORT FRT END	Deformed	15.95 FS	*15.95 FS
141	1		*UNDERBODY PANELLING SIDE ON RIGHT	Deformed	110.10 FS	*110.10 FS
142	1		*SEALING SIDE PANEL RH	Necessary	24.05 FS	*24.05 FS
143	1		*RH SILL TRIM PRIMED	Deformed	314.60 FS	*314.60 FS
144	1		*REPAIR KIT SOCKET HOUSING (2 POL)	Distorted	28.00 FS	*28.00 FS
145	1		*PLUG IN CONNECTION BRACKET	Distorted	7.40 FS	*7.40 FS
146	1		*RH LED MODULE DIRECTION INDICATOR	Distorted	786.65 FS	*786.65 FS
147	1		*PUNCH RIVET N4	Necessary	27.50 FS	*27.50 FS
148	1		*(DG/SL) W/SCREEN SEALANT (COLD 1 HOUR)	Necessary	263.10 FS	*263.10 FS
149	1		*(DG/SL) GLASS PRIMER 30ML (VP206)	Necessary	27.85 FS	*27.85 FS
150	1		*BRIDGESTONE 225/45 R18	Not Necessary	432.00 FS	*- FS
151	1		*SUNDRIES	Necessary	150.00 FS	*150.00 FS

F=Franchise part. S=SpcNett.

Total Parts (\$\$)	52,493.85	30,093.50
---------------------------	------------------	------------------

Report was unsubmitted during this print-out.

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO TOW ACCIDENT VEHICLE TO PML WORKSHOP.	New	195.00	195.00
2	TO REPLACE FRONT BUMPER & ATTACHMENTS, BONNET, FRONT RIGHT FENDER, FRONT RIGHT WHEEL HOUSE WITH CHASSIS, FRONT CENTER AIR DUCT INCLUDING TO PULL & STRAIGHTEN BOTH FRONT CHASSIS AND TO KNOCK OUT DENTED AREA CAUSED BY THE ACCIDENT.	New	11,900.00	11,050.00
3	TO RESPRAY FRONT BUMPER, FRONT RIGHT FENDER, FRONT LEFT FENDER, BONNET, FRONT RIGHT DOOR, FRONT RIGHT WHEEL HOUSE WITH CHASSIS AND FRONT LEFT WHEEL HOUSE WITH CHASSIS.	New	5,887.00	5,298.00
4	TO CARRY OUT BODY CAVITY PRESERVATION.	New	300.00	300.00
5	TO CARRY OUT BODY CAVITY PRESERVATION. (FOR CUT PANEL)	New	531.00	451.00
6	TO REMOVE AND INSTALL ENGINE AND AUTO TRANSMISSION TO FACILITATE JACKING OF CHASSIS AND MOUNTING OF CAR ON CELETTE BENCH INCLUDING REPLACEMENT OF DAMAGED PARTS.	New	1,652.00	1,404.00
7	TO REPLACE RADIATOR ASSEMBLY INCLUDING PRESSURE TEST, BLEEDING COOLING SYSTEM AND CONDUCT CHECKS FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES).	New	826.00	572.00
8	TO REPLACE AUXILIARY RADIATOR ASSEMBLY INCLUDING TO CONDUCT CHECKS FOR LEAK.	New	767.00	651.00
9	TO REPLACE CHARGE AIR COOLER INCLUDING CONDUCT CHECKS FOR LEAK AND PROPER FUNCTION.	New	531.00	451.00
10	TO REMOVE AND INSTALL EXHAUST PIPE, HEAT SHIELD AND PROPELLER SHAFT TO FACILITATE REPAIRS.	New	531.00	451.00
11	TO REMOVE AND INSTALL FRONT SUSPENSION TO FACILITATE THE JACKING OF CHASSIS AND MOUNTING OF CAR ON CELETTE BENCH INCLUDING REPLACE DAMAGED PARTS.	New	2,655.00	2,256.00
12	TO REPLACE ELECTRONIC MECHANICAL POWER STEERING INCLUDING PROGRAM, INITIALIZE STEERING COLUMN ADJUSTMENT AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	885.00	0.00
13	TO CHECK STEERING GEOMETRY AND COMPUTER WHEEL ALIGNMENT ACCORDING TO BMW SPECIFICATION.	New	1,062.00	902.00
14	TO REPLACE TYRE AND WHEEL RIM INCLUDING BALANCING.	New	94.00	80.00
15	TO PERFORM BAKE TEST INCLUDING BLEED BRAKE SYSTEM WITH DSC AND CONDUCT CHECKS FOR LEAKS.	New	1,003.00	852.00
16	TO MOUNT ACCIDENT VEHICLE ON CELETTE BENCH TO FACILITATE RE-ALIGNMENT OF BODY / CHASSIS IN ACCORDANCE WITH BMW SPECIFICATION.	New	2,950.00	2,507.00
17	TO CONDUCT CHASSIS ALIGNMENT MEASURING CHECK USING CAR-O-LINER MEASURING SYSTEM ACCORDANCE WITH BMW SPECIFICATION.	New	531.00	451.00
18	TO REPLACE FRONT DASHBOARD PANEL AND CONDUCT CHECKS FOR PROPER FUNCTION.	New	797.00	677.00
19	TO REMOVE AND REINSTALL FRONT SEATS AND CARPETS TO FACILITATE REPAIRS.	New	870.00	740.00
20	TO REPLACE BATTERY POSITIVE CABLE INCLUDING PERFORM HIGH CURRENT TESTS AND CHARGE UP BATTERY.	New	531.00	451.00
21	TO REMOVE AND INSTALL FUSE BOX TO FACILITATE FRONT SECTION REPAIRS.	New	531.00	451.00
22	TO CHECK ELECTRICAL WIRING SYSTEMS AND LIGHTINGS INCLUDING RESET AND CHECK AIR BAGS FOR PROPER FUNCTION.	New	295.00	0.00
23	TO REPLACE AIR CON CONDENSER INCLUDING TO VACUUM SYSTEM, TOP UP FREON GAS AND CHECK FOR LEAK. (FOR ALL MODELS EXCEPT 7 SERIES)	New	1,003.00	692.00

Report was unsubmitted during this print-out.

No	Particulars	Lab.Type	Repairer's	Amount
24	TO REPLACE BOTH FRONT SEAT BELTS AND TENSIONERS INCLUDING RESET AND CHECKS FOR PROPER FUNCTION.	New	531.00	451.00
25	TO REPLACE ROOF TOP HEADLINING AND ITS HEAD AIR BAG.	New	684.00	581.00
26	TO REPLACE FRONT DASHBOARD PASSENGER AIR BAG.	New	531.00	451.00
27	TO REPLACE STEERING WHEEL AND AIR BAG.	New	531.00	451.00
28	TO REPLACE ENGINE MOUNTING INCLUDE RE-ALIGNMENT OF ENGINE BLOCK TO BODY FRAME.	New	577.00	577.00
29	TO REPLACE GEARBOX MOUNTINGS INCLUDE RE-ALIGNMENT OF GEARBOX TO CROSS MEMBER AND PROPELLER SHAFT SYSTEM.	New	577.00	577.00
30	TO TRANSFER LOCK MECHANISM FROM OLD TO NEW DOOR INCLUDE CONDUCTING CHECKS ON NEW DOOR POWER WINDOW SYSTEM FOR PROPER FUNCTION.	New	451.00	451.00
31	TO REMOVE AND INSTALL FRONT WINDSCREEN TO FACILITATE REPAIRS.	New	577.00	577.00
32	TO CONDUCT WATER LEAK TESTS.	New	75.00	75.00
33	TO REPLACE RH LED TECHNOLOGY INCLUDE PROGRAMMING AND CONDUCTING TESTS FOR PROPER FUNCTION.	New	451.00	451.00
Gross Labour Cost (\$\$)			41,312.00	35,524.00

Report was unsubmitted during this print-out.

< END OF ESTIMATES >