

VEHICLE DAMAGE INSPECTION REPORT

AIG Asia Pacific Insurance Pte. Ltd.
AIG Building, 78 Shenton Way #07-16
Singapore 079120

Our File No: CC3/AIG18010742/AVBE2
Date: 03/10/2018

REFERENCE

Insured/Claimant:	HUAN PENG	Policy No:	2100492161		
Date of Loss:	05/06/2018	Nature of Claim:	OD	Claim No:	8752460126SG

DESCRIPTION & IDENTIFICATION OF VEHICLE

Reg No:	SLJ1579X	Engine No:	CVN024219
Make & Model:	AUDI A4, 1.4 TFSI S TRONIC (A)	Chassis No:	WAUZZZF48HA066150
Reg. Date:	29/11/2016 (Man. Year: 2016)	Odometer:	21901 km
Colour:	White		
Engine Capacity:	1395 cc		
Market Value/New Car Price:	S\$125,000.00		
Sum Insured (S\$):	Market Value/New Car Price		

CONDITION OF VEHICLE AT THE TIME OF SURVEY

General Condition:	Steering (Serviceable):	Yes	Footbrake (Serviceable):	Yes
Handbrake (Serviceable):	Yes	Engine Modification:	No	Pre-accident Condition:

CONDITION OF TYRES

Front Tyre Size:	205/60R16	Rear Tyre Size:	205/60R16
Front Left Side:	Continental 6 mm	Rear Left Side:	Continental 6 mm
Front Right Side:	Continental 6 mm	Rear Right Side:	Continental 6 mm

The above values represent the remaining tyre treads depth

COST OF CLAIMS	Repairer's	Adjuster's	Difference	Diff %
Parts	11,360.00	8,047.60	3,312.40	29.16
Miscellaneous Items	0.00	0.00	0.00	
Labour	5,232.00	3,752.00	1,480.00	28.29
Paintwork Labour	0.00	0.00	0.00	
Towing	0.00	0.00	0.00	
Calculated Gross Total (S\$)	16,592.00	11,799.60	4,792.40	28.88
- Excess (S\$)	600.00	600.00	0.00	0.00
(S\$)	15,992.00	11,199.60	4,792.40	29.97
+ GST 7.00/7.00% (S\$)	1,119.44	783.97	335.47	29.97
Nett Amount (S\$)	17,111.44	11,983.57	5,127.87	29.97

INSPECTION

Date of Assignment:	12/06/2018		
Date Inspected:	12/06/2018	Inspected At:	Premium Automobiles Pte Ltd (UBI) 55 Ubi Road 1 Singapore 408699
Estimated Period of Repair:	5.0 days		

Adjuster:	ADRIAN LING	Manager:	VERON CHEN
------------------	-------------	-----------------	------------

NOTE: This report represents our findings at the time and place of inspection stated herein. Such inspection has been carried out to the best of our knowledge and ability but any other liability under any other circumstances is hereby expressly excluded.

REPAIR DETAILS

Recommended Parts

No.	Qty	Part No.	Particulars	Condition	Repairer's	Amount
1	1		*BUMPER COVER	Deformed	1,849.00 FS	*1,479.20 FS
2	1		*FIXING PARTS FOR FOR BUMPER	Not Necessary	245.00 FS	*- FS
3	2		*SECURING STRIP	Not Necessary	60.00 FS	*- FS
4	1		*CLOSING ELEMENT-LOWER CENTRE	Not Necessary	180.00 FS	*- FS
5	1		*AIR GUIDE-LH	Not Necessary	73.00 FS	*- FS
6	1		*AIR GUIDE GRILLE-LH	Not Necessary	118.00 FS	*- FS
7	1		*FENDER-LH	Distorted	665.00 FS	*532.00 FS
8	1		*ATTACHMENT PARTS FOR ONE FENDER	Not Necessary	45.00 FS	*- FS
9	1		*CLOSING ELEMENT-LH	Not Necessary	44.00 FS	*- FS
10	1		*BRACKET FOR FENDER-LH	Bent	31.00 FS	*24.16 FS
11	1		*BRACKET FOR DEFORMATION ELEMENT	Necessary	43.00 FS	*34.16 FS
12	1		*BRACE-LH FRONT	Bent	103.00 FS	*82.40 FS
13	1		*WHEEL HOUSING LINER-LH	Torn	215.00 FS	*171.60 FS
14	1		*ATTACHMENT PARTS FOR WHEEL HOUSING LINER	Not Necessary	78.00 FS	*- FS
15	1		*WHEEL SPOILER-LH	Cracked	63.00 FS	*50.16 FS
16	1		*STONE CHIP GUARD	Necessary	44.00 FS	*34.56 FS
17	1		*LED HEADLIGHT-LH	Cut	6,973.00 FS	*5,578.40 FS
18	1		*LIFT CYLINDER-LH	Not Necessary	184.00 FS	*- FS
19	1		*COVER-LH	Necessary	20.00 FS	*15.36 FS
20	1		*COVER-LH	Necessary	27.00 FS	*21.04 FS
21	1		*TYRE (NPA)	Not Necessary	0.00 FS	*- FS
22	1		*SUNDRIES	Necessary	300.00 FS	*24.56 FS

F=Franchise part. S=SpcNett.

Total Parts (S\$) 11,360.00 8,047.60

Recommended Miscellaneous Items

There are no new miscellaneous items selected.

Recommended Labour

No	Particulars	Lab.Type	Repairer's	Amount
Labour Items				
1	TO REMOVE AND TRANSFER FRONT WIRE HARNESS FOR HEADLIGHTS,HORNS,FOG LAMPS.OUTSIDE TEMPERATURE SENSOR AND HEADLIGHT WASHER ASSY	New	360.00	360.00
2	TO DISMANTLE AND RENEW FRONT BUMPER,LHS FRONT FENDER AND HEADLIGHT.RE-ORGANISE FRONT CRASH MANAGEMENT COMPONENTS.REINSTALL ALL PARTS REMOVED	New	2,100.00	1,250.00
3	TO RESPRAY FRONT BUMPER,LHS FRONT FENDER & LHS FRONT DOOR	New	2,000.00	1,650.00
4	TO RENEW LHS FRONT TYRE.CARRY OUT WHEEL ALIGNMENT	New	280.00	-
5	TO CARRY OUT DIAGNOSTIC CHECK	New	192.00	192.00
6	TO REMOVE AND REINSTALL LHS FRONT DOOR PANEL TRIMS,DISMANTLE LHS WING MIRROR ASSY	New	300.00	300.00
Gross Labour Cost (S\$)			5,232.00	3,752.00

LKK Auto Consultants Pte Ltd/SLJ1579X/03/10/2018 07:39

< END OF ESTIMATES >