



Your Ref : S8M00KG1

Date: 26th June 2018

Our Ref : CS/ASM18010777/Nvd3s2

M/s AXA Insurance Pte Ltd
8 Shenton Way #24-01
AXA Tower
Singapore 068811
(The Motor Claims Department)

Attn: Kitty Teo

Dear Sirs/Madam,

**AUTOMOBILE INSPECTION REPORT OF ACCIDENT VEHICLE SKG 6679K
ACCIDENT ON 11/06/2018**

Instruction was received to inspect the vehicle Reg. No. SKG 6679K. The inspection was conducted on 13/06/2018 at the premises of M/s Hua Hong Pte Ltd, 25D Sungei Kadut Street 1 Singapore 729332.

The following vehicle information was recorded:

Registration Number	: SKG 6679K
Make/Model	: Mini Cooper S Coupe
Year of Registration	: 2012
Body Colour	: Silver
Chassis Number	: WMWSX32090T139719
Engine Capacity	: 1598 cc
Speedometer Reading	: Burnt

The vehicle badly burnt. (Details see photographs enclosed)

In view of this, we are of the opinion that it would be **uneconomical** to proceed with the repairs due to extensive repair cost and recommend it to be written off as **“Total Loss”**.

Market Value	S\$	66,000.00
Less: LTA Reimbursement Value (RV)	(S\$	46,899.00)
Nett Liability	S\$	<u>19,101.00</u>


Vehicle Inspected By:



MUHD NAZRIL (NAZ)

Technical Investigator

LL.B. (Hons) London



K.K.LAU

*MSc(Eng M), B Eng(Hons), Peng(UK),
MASME(USA), B Bus(Aust), MBA(UK),
IEng(UK), MIIE(mech), MinstAEA, MFIEA,
MIRTE, MIMI, MSAE, MCIAd, AM, NIJAAR(USA),
AM CATARI(CAN), M.MATA(USA), M.MdATA(USA),
Licensed Appraiser*

DISCLAIMER OF LIABILITY TO THIRD PARTIES:- This Report is made solely for the use and benefit of the Client named on the front page of this Report. No liability or responsibility whatsoever, in contract or tort, is accepted to any third party who may rely on the Report wholly or in part. Any third party acting or relying on this Report, in whole or in part, does so at his or her own risk.