



LKK Auto Consultants Pte Ltd

51 Ubi Ave 1 #01-25 Paya Ubi Industrial Park, Singapore 408933

TEL: 6256 3561 FAX: 6256 4315

Reg. No: 199607198R GST Reg. No. 19-9607198-R

Affiliated to Federation Internationale Des Experts En Automobile

AXA INSURANCE PTE LTD

Ref : CC4/ASM18010832/Kga3q2

8 SHENTON WAY #24-01
AXA TOWERSINGAPORE 068811
ATTN:KIAN CHUAN

Date : 11-09-2020



Code : ASM

1. Policy Particulars :- THIRD PARTY CLAIM

Insured Veh.	FT 3155R	Veh. Inspected	GBG 6711G
Policy No.	P0385183	Coverage (\$)	0.00
Claim No.	S8M00JZW	Excess (\$)	0.00
Assign From		Assign Date	13/06/2018

2. Vehicle Particulars & Condition

Make & Model	TOYOTA DYNA	c.c	2982
Engine No.	HIDDEN	Year of Reg.	2017
Chassis No.	JTFAT35Y50K209080	Colour	SILVER
Odometer	49919	Steering	IN ORDER
Brakes	IN ORDER	Modification	NIL
General	GOOD		

3. Conditions of Tyres

	Size	Make	Balance
R/H Front Tyre	195/75 R15	BRIDGESTONE	9 mm
L/H Front Tyre	195/75 R15	BRIDGESTONE	9 mm
R/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	9/9 mm
L/H Rear Tyre	155 R12X8 (D)	BRIDGESTONE	9/9 mm

4. Description of Damages

THE VEHICLE SUSTAINED DAMAGES AT THE REAR O/S PORTION.
DAMAGES SEE DETAILS.

5. General Information

Accident Date	06/06/2018	Inspection Date	08/03/2019
Survey held at	LIM YEW BOO SPRAY PAINT CO BLOCK 10, SECTOR C SIN MING ROAD INDUSTRIAL ESTATE, #01-10 SINGAPORE 575645.		

5a. Remarks

A)THE INSPECTION WAS CONDUCTED ON A"WITHOUT PREJUDICE" BASIS.
B)IN ACCORDANCE TO YOUR INSTRUCTIONS, WE HAVE NOT AUTHORISED REPAIRS.

5b. Estimate Days of Repair

ESTIMATED NORMAL PERIOD FOR REPAIR: **3 Working Days**